

ADAPT-A-LIFT GROUP PTY LTD

Service History Listing Active Units

Date: 13/03/2024
Time: 11:08:53AM

For Equipment Code From: H12711 To: H12711
For Date Posted From: All To: All
Don't Show Cost
For Customer Code From: All To: All
For Branch Code From: All To: All

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1548633	DECOMMISSION, REMOVAL AND DAMAGES QUOTE	DHEAD	12/07/2023	External	13720.0	
1518176	Dehire tyre inspection	BIG TRUCK WA	15/03/2023	Internal	13619.0	Dismantle and removal of unit, as per quote 17396 and as per signed STR Agreement
1511101	13500 II 500hr Service	611 Planning A	2/03/2023	Internal	13619.0	
1509601	After hours callout	DHEAD	25/01/2023	External	13619.0	Travel to site, Remove ancillary items and Repair Wiring as necessary, Refit ancillary items, Replace faulty gas strut on armrest. Replace faulty seat belt test , run ok
1505365	13000 1000hr service	DHEAD	9/01/2023	Internal	13558.0	Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.
1000hr Service						
Carry out 1000 hr service Replace engine oil and filter Replace cabin filter and air filter. Fill grease pods and grease other points Replace fuel filter and bleed fuel system Replace transmission oil and filters. Calibrate transmission. Adjust inching sensor and calibrate. Replace steer hub oil.						
Carry out inspection						
Labour						

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1505316	Repair aux fault	DHEAD	6/01/2023	Internal	13552.0	Carry out Inspection and Diagnosis of Attachment Assist dan diagnosing fault. Pick up parts at store. Carry out equipment condition assessment Remove ancillary items and Repair Wiring as necessary, Refit ancillary items, travel to site, set up Locate fault with machine. Leg sensor staying on but still no functions. Checked wiring and circuit boards, still couldnt find fault. Swap over joysticks as no functions coming up on hyd interface. Replace joystick. Return toservice
1480084	6 Monthly Fire Suppression Service Fire Suppression System Service - 6 Months	611 Planning A	14/11/2022	Internal	12491.0	
1487449	Fire suppression fault	611 Planning B	20/10/2022	Internal	12794.0	
1485797	Supply 4* drive rims	611 Planning A	13/10/2022	Internal	12794.0	
1483758	Unit is shutting down, no alarms. Do process & re-start. Pkt 224950	AALIGANTE	5/10/2022	Internal	12794.0	Travel to site, Travel to site. Found out that the unit is for big truck. Rang one of the big truck techs. I was advised that I have no access on site (induction). Rang KAren that she needs to send Big truck for this one. Remove ancillary items and Repair Wiring as necessary, Refit ancillary items, Travel to site, signed in and located machine, begin to trouble shoot unit cutting out, reported that fork track screen apears on for a few seconds then unit shuts down, forktrack screen is not working on the unit. pulled side cover to fuse box off and unit shut down , suspected wiring issues, continued diagnosis and found that wiggling the deutsch plug to the ignition switch the unit would shut off, replaced deutsch plug found that too much wire had been stripped off for the crimps could be the issue , one all back together run machine whilst wiggling wiring and could not get to fault, left machine running whilst i tidied up all the wiring and did not shut off, checked over machine found right steer hub leaking, fire suppresion fault and grease pod fault. sent unit back

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1468347	Brake pressure issues	DHEAD	9/09/2022	Internal	12491.0	Replace Hydraulic Control Valve, Pick up part and travel to site. Sign in and set up, had to get escorted to location of forklift. Remove old brake manifold and fit new manifold. Run up machine and test operation. Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. SIF numbers Eng 43275965 Trans 43275959 Hydraulic 43275958
1467585	12500 II 500hr service Hyster Laden Container Handler H117 - 500hr Service Kit. 0500 Hour Service	DHEAD	9/09/2022	Internal	12300.0	
1466338	Further Works; Cabin filter & manifold harness.	BPIGGOTT	3/08/2022	Internal	12300.0	
1463856	FL402 - right-hand side ,Amber landed light not functioning .	EBLAKE	7/07/2022	Internal	12300.0	Removed lights off spare attachment out the back of PN , not sent to unit DH has light ASSM
1463450	FL402 Unit wont tilt backwards - Site contact GLenn 0411 256 364	EBLAKE	6/07/2022	Internal	12267.0	Remove ancillary items and Repair Wiring as necessary, Refit ancillary items,
1459679	Wearpads on the spreader have fallen	BPIGGOTT	21/06/2022	Internal	12216.0	repaired wire fault at tilt sensor Repair Attachment as necessary, Replace Battery, Travel to site locate machine. upon locating machine identified that the batteries have been left un-isolated and unit would not start. using DPworlds jumppack, jumpstarted machine and moved into position to work. identified that 2x wearpads and brackets had come loose and fallen off of the attachment. Repair damaged threads on attachment, get longer bolts from luke, fit new wearpads and brackets attempted to start unit again but wouldnt start, travel to Power crank and pick up new batteries, travel back to site and fit to unit, test unit operates correctly send unit back to service.

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1454275	13000 II 1000hr service.	DHEAD	9/06/2022	Internal	12300.0	3000hr Service Remove ancillary items and Repair Hydraulic Oil Leak as necessary. Refit ancillary items, Steam clean equipment as necessary. Carry out 3000 hr service Replace engine oil and filter Replace transmission oil and filter Replace fuel filters Replace air filters and cabin filter Replace steer hub, front plantary and diff oils. Replace brake filter housing. Replaced coolant due to being just water Remove ancillary items and Repair Wiring as necessary, Refit ancillary items, Carried out wiring repairs to over mast harness , tested operation returned to service assist ethan Repair Ignition Circuit as required,
1456789	T/lock issue - Not locking on containers	EBLAKE	7/06/2022	Internal	12340.0	Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items,
1453907	Replace Hoses	DHEAD	25/05/2022	Internal	11993.0	Carried out wiring repairs to over mast harness , tested operation returned to service assist ethan Repair Ignition Circuit as required, Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items,
1452112	Crane Sublet From Cab Repair	BIG TRUCK VIC	18/05/2022	Internal	11993.0	DISMANTLE AND REMOVAL OF UNIT FROM WEST MELBOURNE Prepare For Hire - Field Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items,
1451835	AC needed to be regased and new hoses	311 Planning S	17/05/2022	Internal	11993.0	
1413856	DEHIRE AND REMOVAL OF UNIT	BIG TRUCK VIC	7/03/2022	External	11993.0	
1433110	H12711 - TRANSPORT AND MOBILISATION (DEMOBILISATION) OF UNIT AT FREMANTLE WA - KERRY GRACE	DHEAD	21/02/2022	External	13995.0	Prepare For Sale - Field H12711 - TRANSPORT AND MOBILISATION (DEMOBILISATION) OF UNIT AT FREMANTLE WA - KERRY GRACE

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1422656	DAMAGED CAB	JTINAO	11/01/2022	External	11993.0	- Attend site - Carry out safe work establishment - Isolate unit and disconnect batteries - Organise auto elec to de gas air con system - Remove any damaged components from around cab, e.g bent exhaust and damaged condenser - Disconnect all wiring harness from under cab leaving all interior components assembled where possible - Disconnect all hoses and pipe work from under the cab - Remove any components to allow access to lifting points - Assess job objectives with crane operators and fill out the relevant safe works permits to conduct the lift on site - organise traffic management plan with site manager - Lift cab off the chassis and on the back of the truck - Cap off and secure any open hoses pipes and wiring harnesses Workshop Repair - Once cab is back at the workshop, strip down donor cab for painting - Organise and remove all exterior components off damaged cab - Reuse as much components off damaged cab as possible - Fit interior components out of damaged cab into freshly painted donor cab - Fit all exterior components and accessories as required to freshly painted donor cab Onsite Fitment of new cab - Attend site - Carry out safe work establishment - Assess job objectives with crane operators and fill out the relevant safe works permits to conduct the lift on site - organise traffic management plan with site manager - Prep chassis components e.g. cab mounts - Lift cab onto chassis and bolt down, have crane pack up - Start plumbing up all pipes and hoses along with all electrical harness - Fit all new exhaust components and rails as required - Once cab is wired up and all hoses connected check for any fault codes - Start unit up and test operation of all controls and cabin components - Organise auto elec to re gas air con system once unit is running leave any covers off to test for leaks

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
						- Test drive unit for 30 min to make sure all gauges and controls are working - Check unit over after the test drive and check for any leaks - Clean up work area
1422257	Additional Crane Cost Refer 1400676	BIG TRUCK VIC	21/12/2021	Internal	11993.0	
1422255	Additional Crane Sublet refer 1400676	BIG TRUCK VIC	21/12/2021	Internal	11993.0	
1416810	Crane hire relating to job 1400676	311 Planning S	24/11/2021	Internal	11993.0	
1413337	Customer Damage - Water added in the engine oil	MOWENS	9/11/2021	External	11993.0	Change Engine Oil as required, Drive to site, complete take 5, make site safe, found oil coming out of the breather tube, drained oil and removed oil filter, Found that their was around 70l of oil that came out of the sump(engine only takes 38L) Found that some one has put water in the oil, Organised Cummins to come in. Filled with new oil then flashed it again, put new oil in engine and informed manger that oil still looked like it had water in it Travelled to site, gained access to machine - Connected Insight and captured downloads and checked codes, multiple stored codes for low coolant - Located operator and discussed issue, operator accidentally poured water into oil fill of engine - Removed machine covers to access engine - Removed filler cap and checked for signs of water in oil, no signs of oil/water contamination on cap - Checked oil level, slightly above on dip stick - Drained contaminated engine oil approx. 38L - Removed oil filter - Replaced filter - Filled engine oil - Started and ran engine and checked for oil pressure, engine operated fine oil pressure okay - Returned to branch, cut open and inspected oil filter, no signs of material in filter matter

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1409998	Leg lift is bent and camera has come off	JMAQUE	22/10/2021	Internal	11888.0	Travel to site, Remove ancillary items and Attachment Cylinder , Strip, Inspect and report, Labour Repair Attachment Cylinder as necessary , Check/Inspect/Diagnose Cylinder Repair Attachment as necessary, ordered parts,waited for parts,travelled to site,filled up T5,removed cylinder,repaiired cylinder greasing port as not the same fittings,travelled to Total tools and bought NPT thread tap,travelled to site,repaiired grease line,drill and thread tap,ok,installed cylinder,tested ok,repaiired attachment and adjusted twistlock cylider as out of alignment,ok,picked up container for testing ok,returned small forklift to warehouse,packed up EWP and towed back to P.N,unit good to go,need to install leg camera as camera missing. Carry out equipment condition assessment Replace Attachment Cylinder , Adjust Attachment Cylinder to correct specification ,
1402179	Scheduled Service - 12 Monthly Fire Suppression Service .Fire Suppression System Service - 12 Months	311 Planning B	13/10/2021	Internal	11717.0	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1406774	Camera broken on lift leg. Coolant leak Leak in engine mount	JTINAO	8/10/2021	Internal	11783.0	Labour Repair Air Conditioner as necessary, Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items, Fit Full Camera Kit, Repair Attachment as necessary, Grease All Points on Unit, Carry out equipment condition assessment Picked up consumables,travelled to Drop Point, Travelled to site, filled up T5, Isolated Unit and pre work area, Removed bonnet and removed ancillary items, inspected heater core found heater core and tap leaking, ordered parts, reinstalled ancillary items, travelled to P.N and Repaired and Weld Camera Bracket as got smashed, travelled back to site, Installed camera, rejoined and repaired camera wiring, adjusted ok, repaired attachment greasing line as got pulled out due to wear and tear, replaced ok, top up grease cannister, completed Auto greasing duty cycle, adjusted RHS twistlock as out of angle, found cylinder got mushroom, ok, carried out Unit appraisal, reported to Customer Unit good to go Carry out Inspection and Diagnosis of Mast/Carriage Remove ancillary items and Chain Sheave, Strip, Inspect and report, Repair Mast as necessary, 250hr Service performed 250hrs service as per hyster service programe, blow out the radiator core pins, grease all points on fittings, performed inspection the attachment. machine breakdown.
1398099	Scheduled Service - 11,750hr service II 250hr type (refer to note) .0250 Hour Service	GCAPUS	20/09/2021	Internal	11716.0	
1401873	Replacement of injector	JTINAO	14/09/2021	Internal	11716.0	
1401872	E13 error code and replacement grease canister needed	JTINAO	14/09/2021	Internal	11716.0	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1400676	Mast bearing making a lot of noise	GCAPUS	8/09/2021	Internal	11716.0	Travel to site, Carry out equipment condition assessment Repair Attachment as necessary, check up the unit,set up the cheery picker and i found out on the R/H side roller bearing is damage and need to replace, so i tag out the unit. Labour Repair Mast as necessary, performed strip out the top roller on the mast and other parts related the function group.pull out roller guide of the hoses and pull out the main chain.and we struggle to pull out the pin due to the pin totally worn out so we suggested next time to proceed this job we need tm line boring there present to analize and make the proper tool(hydraulic jack) to pull out the pin. machine is in breakdown. Carry out Inspection and Diagnosis of Mast/Carriage Remove ancillary items and Chain Sheave, Strip, Inspect and report, check and prepared the unit,pick up the cheery picker,assisted the welder,pull out the sheave and other parts related to the function group,performed cutting the pin so we can take it out the pin damage. machine still breakdown. Replace Chain Sheave, Adjust Lift Chain to correct specification, performed the unit,and assemble the the sheave and repack the bearing with the grease, and installation all the parts been requested, and installation of all hoses and lift cahin and other parts related to the function group,grease all the fittings specially on the sheave bearing,test and run the unit. P/S

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1388998	Scheduled Service - 11,500hr service II 500hr type .0500 Hour Service	MOWENS	23/08/2021	Internal	11302.0	assited the welder and the tyre guy to finish up the unit R3. machine is on operational. Travel to site, Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. Assisted Technician with servicing. Adjust Attachment to correct specification , Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items, Check/Inspect/Diagnose Cylinder inspect unit, complete take 5, found blown orings, replace orings, test unit all ok
1387882	Error code E0235 - coolant maybe? Plus a small oil leak underneath engine cover too.	MOWENS	8/07/2021	Internal	11261.0	
1385889	Afterhours Callout - 29/06/21	JMAQUE	29/06/2021	External	11195.0	Called out to site Unit stuck on box Unlock unit on the box and inspect unit for damage Unit is good and no damage found Returned unit to customer
1381978	Scheduled Service - 11,250hr service II 250hr type. .0250 Hour Service	311 Planning B	7/06/2021	Internal	11033.0	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1372597	Twist locking issue . Windscreen wiper may need to be replaced as not working properly - Tech to assess	JMAQUE	28/05/2021	Internal	10740.0	Travel to site, Adjust Attachment to correct specification , Went to site and adjusted twistlocks/ lhs twistlocks cylinder needs replacement due to it has excessive play on it so what i did is just tighten the adjustments to correct the movement/ All twistlocks need to be replaced its very worn and 2 amber lights damage/ Check wipers need replacement too/ Carry out equipment condition assessment Labour Repair Attachment as necessary, Carry out Inspection and Diagnosis of Attachment Piked up parts,travelled to site,filled up take 5,isolated pre work area and unit,replaced Twistlock and ancillary items,replaced twistlock cylinder,grease twistlock,tested Unit pre work operation,picked up 40 footer container for testing,found ok,need to replace red led light on twistlock module as led light not lighting up.Cleaned pre work area,reported to customer Unit's good to go. Replace Attachment Cylinder , Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items, ordered parts,pick up parts,cleaned cylinder,returned to parts as exchanged core,locate parts for attachment,ordered parts,throw rubbish and used twistlock,steam cleaned service van
1374086	Scheduled Service - 11,000hr service II 1000hr type. .1000 Hour Service	311 Planning B	24/05/2021	Internal	10762.0	picked up parts

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1371823	Oil leak in the engine bay	Tmikulic	22/04/2021	Internal	10712.0	Check/Inspect/Diagnose Hydraulic Oil Leak and test operation, Remove ancillary items and Repair Hydraulic Oil Leak as necessary. Refit ancillary items, checked and found oil leaking from steering control valve replaced o rings and inspected again machine is good to go
1371362	Needs new alternator not charging	MOWENS	21/04/2021	Internal	10702.0	
1371342	Fork is stuck in a container on a truck with no power.	MOWENS	20/04/2021	Internal	10715.0	Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items,
1365846	Scheduled Service - 10,500hr service II 500hr type	311 Planning B	19/04/2021	Internal	10542.0	Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. Carry out Inspection and Diagnosis of Attachment
1369868	Twist lock sensor is playing up & one of the cameras is loose. Tomorrow morning requested.	JTINAO	13/04/2021	Internal	10665.0	Adjust Switch/es Check/Inspect/Diagnose Hydraulic Oil Leak and test operation, Waited for Unit,filled up take 5,set up pre wok area,isolate Unit,Inspected twistlock landing pin ok,adjusted proxi switches of landing pin,ok,repared Camera Housing as missing bolts,tested Unit pre work operation ok,inspected oil leaking found HYD oil leak from the combination valve,repared window glass as can't open,Unit's good to go
1365847	Scheduled Service - Fire Suppresion Service; LOP type; Level 1 - 6 monthly. Fire Suppression System Service	311 Planning B	29/03/2021	Internal	10542.0	
1358571	Additional 5000hr Service Labour - Ref Job # 1340773	JTINAO	16/02/2021	Internal	10280.0	5000hr Service Assisted Tech Johny Carried out S.M 5000hrs
1340773	Scheduled Service - 10,000hr service II 5000hr type	JMAQUE	8/02/2021	Internal	9780.0	Travel to site, 5000hr Service Assisted primary Technician,Towed EWP,returned EWP to P.N Labour Travel to site,

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1342073	H12711 dynon rd - Scales need to be recalibrated	BIG TRUCK VIC	25/01/2021	Internal	9815.0	Carry out Inspection and Diagnosis of Electrical System Reported to site, filled up Take 5, isolated work area, inspected Unit weighing scale, Waited for Unit as it picked up testing container, couldnt callibrate weighing scale. Tag out Unit Repair Visual display unit as necessary , Repair Main Electrical Control Panel as necessary,

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1340348	H12711 Dynon rd - At the top of the roller there is a bearing & its falling out of the main roller - Parked up.	JTINAO	25/11/2020	Internal	6229.0	Travel to site, Carry out Inspection and Diagnosis of Mast/Carriage Labour Travelled to site,waited for EWP,Isolated Pre work area,Assisted Primary Tech.,Inspected LHS chain sheeve,found bearing gone(damaged),also found mast wear pad on LHS crack and deteriorated,Unit Tag out Travelled to pick up parts,inspected parts found lack of parts(oil seal),spoked to Henry about parts,waited for Henry's confirmation where to get parts,ok. Sample parts needed to bring @ Hytech Seals tomorrow morning to make seal. Remove ancillary items and Chain Sheave, Strip, Inspect and report, Replace Chain Sheave, Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items, Assisted Crane to site,Isolated Pre work area, Travelled to Parts(opens 8:30 am),waited for parts,travelled to D. P & picked up parts,Travelled to site,filled up take 5,review JSA & permit,Isolated Unit,inspected & set up EWP,ok,put jack stand to support Mast weight,Removed chain and ancillary items,removed chain sheave onn LHS,Struggled to remove Pin as the bearing seized to the pin,Assembled new Sheaves and ancillary items,Installed chain sheave & ancillary items,installed chain & ancillary items,replaced chain oil dripper, Tested Unit pre work operation,ok,packed up EWP,cleaned pre work area,Reported to customer,unit good to go,throw rubbish & scrap metal. Carry out Inspection and Diagnosis of Attachment Travelled to Repco & picked up Tools,filled up take 5,JSA & work on height permit,isolated pre work area,isolated Unit,set up EWP,replaced chain sheaves and ancillary items,ok,tested Unit pre work operation,ok,towed EWP back to P.N Parking area.
1333522	Scheduled Service - 9750hr service II 250hr type	JTINAO	25/11/2020	Internal	9815.0	250hr Service Labour 250hr Service Travelled to picked up parts,travelled to site,Job postponed Replaced engine oil and water separator,top up grease cannister,inspected chain wear .3% ok

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1332725	Hyd hose leak	NBANGOT	12/10/2020	Internal	9504.0	Carry out equipment condition assessment -Find the site but Can't enter the site need induction. Check/Inspect/Diagnose Hydraulic Oil Leak and test operation, Remove ancillary items and Hydraulic Hose/s, inspect and report, Labour Replace Hydraulic Hose/s and ancillary items,
1328508	Scheduled Service - 9500hr service II 500hr type	311-SUB-APs	12/10/2020	Internal	9319.0	
1325819	Scheduled Service - 9250hr service II 250hr type	311 Planning B	21/09/2020	Internal	9204.0	
1323423	Hydraulic hose need replacing	RBLAIN	28/08/2020	Internal	9077.0	Replace Hydraulic Hose/s and ancillary items, Went to pertik to get new hoses/ Replaced hydraulic control valve hose and o-rings/ Test the unit all is good and operational Labour
1316852	Scheduled Service - 9000hr service II 3000hr type. Level E Service	JMAQUE	27/08/2020	Internal	9078.0	Travel to site, 3000hr Service Performed 3000 hrs service on the unit replaced engine oil and transmission oil/ Replaced engine filter, trans filter, brake filter, air filter and cabin filter/ Performed mast inspection and repair chain oil lubers/ Replaced transmission temperature switch and sensor/ Replaced wear pads and clean operators cab/ Test run unit all is working and operational
1317602	Secure the camera	GCAPUS	31/07/2020	Internal	8837.0	Travel to site, Remove and Replace Camera, check up the unit regarding for the camera,and all bolt for the camera is broken on left side,replaced the bolt and repaired the camera on the right angel.test and run the unit. machine is in operational.

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1316320	Check spreader lights	RJONASSEN	24/07/2020	Internal	8774.0	Travel to job site to inspect and carry out repairs to spreader light.
						Arrange for welder to to carry out structural repairs to mast light bracket. Replaced LH rear leg buffer Tested successfully and released machine back into service .
1314529	Scheduled Service - 12 Monthly Fire Suppression Service .Fire Suppression System Service	311 Planning B	17/07/2020	Internal	8695.0	
1314516	Welding repairs	311 Planning A	17/07/2020	Internal	8695.0	
1303065	Scheduled Service - 8500hr service II 500hr type.	RJONASSEN	13/07/2020	Internal	8659.0	Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.
						Labour
						Travel to site,
1292516	Further Works: Replace top/ rear & front wipers.	311 Planning B	23/06/2020	Internal	7995.0	
1297652	Scheduled Service - 8250hr service II 250hr type	311 Planning B	11/06/2020	Internal	8157.0	
1305191	Hydraulic Leak	AMACNEIL	9/06/2020	Internal	8392.0	Travel to site,
						Check/Inspect/Diagnose Hydraulic Oil Leak and test operation,
						Remove ancillary items and Repair Hydraulic Oil Leak as necessary. Refit ancillary items,
						Repair Hydraulic Hose/s as necessary,
						checked unit for hydraulic oil leak found inner hose over the mast has a leak. picked up ewp and set up work area. removed both hoses and had paul male hoses refit and tensioned. tested all ok clean cab and windscreen.
1304578	Damaged Leg Mount	MOWENS	5/06/2020	External	83701.0	
1292514	**APPROVAL PENDING** Further Works: Replace steer cylinder	311 Planning B	27/05/2020	Internal	7995.0	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1286394	Scheduled Service - 8000hr service II 2000hr type. Level D Service	JKOLARITSCH	27/04/2020	Internal	8073.0	2000hr Service Pick up parts from drop point travel to site talk to Peter set up work aera fill out oil samples Travelled to site,took oil sample,replaced engine oil and filter,replaced trans oil,blown out rad.core,blewn out inside cabin,replaced cab filter,replaced air filter (inner,outer),Replaced engine belt,ordered parts(trans oil filter),as only received 1 on service kit,travelled to P.N and throw rabbish out of service,travelled to CC containers and picked up parts with Tech Matty,also look for oil transfer pump,assisted Tech Melo replacement of diff oil and hub oil(drive,steering).Unit servicable notes:See P.M.I for remaining job. Change differential oil Change hub oil front and rear replace transmission filter replace fuel filter Repair Attachment as necessary,
1290579	Camera Not Working	DWILSON	14/04/2020	Internal	7995.0	
1289451	Losing Locking Lights	JTINAO	6/04/2020	Internal	7976.0	inspect unit camera not working, found loom is missing, auto elec has came out and replaced the loom. Travel to site, Carry out Inspection and Diagnosis of Attachment Adjust Attachment to correct specification, travelled to site,isolated pre work area,waited for unit,inspected unit green light issue,inspected twistlock found,out of angle,adjusted twistlock,tested unit pre work opertaion found still faulty,inspected tie rod end and found bent,ordered parts,unit servicable Labour Repair Attachment as necessary, Travelled to pick up parts at Brooklyn yard,travelled to site,Replaced twistlock cylinder,found,internal leaking,tested unit pre work operation,found ok,Unit good to go
1285517	Repair Camera Bracket	BIG TRUCK VIC	20/03/2020	Internal	7851.0	
1277693	Scheduled Service - 7750hr service II 250hr type	MOWENS	18/03/2020	Internal	7596.0	Travel to site, Carry out Inspection and Diagnosis of Attachment Carry out Inspection and Diagnosis of Electrical System Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items,
1276664	Camera Cable Broken	JTINAO	24/02/2020	Internal	7551.0	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1274653	External and engine bay wash	BIG TRUCK VIC	5/02/2020	Internal	7477.0	
1268129	Scheduled Service - Fire Suppresion Service; LOP type; Level 1 - 6 monthly. Fire Suppression System Service	311 Planning B	30/01/2020	Internal	7292.0	
1267715	Scheduled Service - 7500hr service II 500hr type. Level B Service	GCAPUS	30/01/2020	Internal	7432.0	Labour Travel to site, Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. conducted 500hrs service programme,blow out the radiator core pins,grease all points of unit,and assist the pertik for check up the fire suppression. Labour
1267851	Replace Lift Chains	JTINAO	15/01/2020	Internal	7336.0	Labour Pick up parts from trug then drop off at site Replace Lift Chain, Repair Mast as necessary, Grease All Points on Unit, Assisted on replacing lift chain/ Repair mast light bracket/ Grease all cannister and inspect spreader/Throw rubbish at PN/ Test run unit all is good to go Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items, Carry out Inspection and Diagnosis of Attachment Replacement of lift chain,filled up J.S.A and work height permit,isolated work area,removed lift chain,cut out excess linkages on chain,installed new lift chin,installed new chain lube dripper,lubricate chain as necessary,repaired attachment indicator lamp housing as it was dented,inspected attachment and found loosed bolt and missing bolt on attachment cylinder pin,retightened bolt as necessary,installed new bolt on attachment pin cylinder,grease all points on attachment,tested unit operation found ok,unit good to go,throw rabbish ,old chain and old load roller at PacNat,clean work area.job done

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1268067	Transmission Slipping	JMAQUE	8/01/2020	Internal	7300.0	Carry out Inspection and Diagnosis of Transmission Travel to site and coordinate with the operator/Check fault codes and errors found out t6201 occurs 32 times already today/ Check speed sensor found out sensor play up sometimes/ Order sensor and waiting for parts availability/Check all wiring harness for shorted and fuses all is good/Clean the sensor and test many times but same issue is occurring/ WAITING FOR THE NEW SPEED SENSOR Remove ancillary items and Repair Wiring as necessary, Refit ancillary items, Pick up parts at drop point/Replace new speed sensor/ Recalibrate tranny and clean wire connectors/ Test run unit all is good and operational Repair Water Pump Inspected unit oil leaked complaint,and found coolant leaking on water pump,ordered parts needed,tagout unit. Replace Water Pump, Flush and Replace Cooling System Coolant Replace Battery, Drain coolant and replace water pump/Flush and refill coolant/Replace batteries/Install all ancillary items/ Test unit all is good/
1266425	Water Pump Leaking	JTINAO	30/12/2019	Internal	7123.0	Attachment inspection will be done tomorrow
1266225	Low Fluid Warnings on Dash	RJONASSEN	27/12/2019	Internal	7270.0	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1261209	Sensor Issue and Horn Not Working	AFOX	4/12/2019	Internal	7185.0	Carry out Inspection and Diagnosis of Electrical System Repair Attachment as necessary, check the unit,adjust the twistlock,and adjust the approximately sensor Remove ancillary items and Repair Wiring as necessary, Refit ancillary items, Labour Travel to site, installation of joystick and calibrate. 1000hr Service
1246442	Scheduled Service - 7000hr service II 1000hr type. Level C Service	JKOLARITSCH	3/12/2019	Internal	7123.0	Carry out service change engine oil and filters oil,fuel and air change transmission oil and filters and calibrate top up auto greasers and lube tail shaft and check bolts/nuts on shaft blow out coolers replace three missing wear pad bolts and adjust twist locks. need to carry out mast inspection with cherry picker Carry out mast inspection found out lift chain is at 3% and need to replace urgently/Tag out the unit and order the parts 250hr Service
1234341	Scheduled Service - 6750hr service II 250hr type	AMACNEIL	9/10/2019	Internal	6656.0	Carried out 250hrs. service inspected engine oil level ok,trans oil level low top up 20 ltrs of trans oil,diff oil ok,hub oil ok,coolant level ok,inspected visible damage on unit,inspected mast for sign of damage,crack,dent,deformities,flacking paint and crack welding,Inspected Chain wear and reads, 1.2% to 1.6%
1234340	3 Monthly Wash	311 Planning B	3/10/2019	Internal	6501.0	
1242113	A/C Service	BIG TRUCK VIC	19/09/2019	Internal	6501.0	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1221715	Field Service Bulletin - FPI 18-807	RJONASSEN	11/09/2019	External	6651.0	Labour Travel to site, Remove ancillary items and Attachment, Strip, Inspect and report, Replace Attachment, Pick parts up from Pacific National then travel to job site. Remove old engine heat screen. Refit new enhanced engine bay fire protection screen to manufacture specifications. Remove ancillary items and Repair Wiring as necessary, Refit ancillary items, Travel to site, Repair Attachment as necessary, Grease All Points on Unit, -check and inspect the twistlock malfunction. -one of the twistlock not seated properly. -adjusted twistlock in the right specification. -test and run the machine. -grease all points in the machine. -machine is in operational.
1227711	Inspect Twistlocks - Intermittent Locking Issues	GCAPUS	26/07/2019	Internal	6374.0	Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. Travel to site, Pick up parts from trug travel to site Fill out and take oil samples carry out mast inspection found lift chains @ 1.5% found left hand twist lock cylinder rod worn replace with reco cylinder carry out service order 2x wear pad retainers for drop point tomorrow Adjust Attachment to correct specification , Replace 2x wear pad brackets and adjust left hand twistlock return unit to service
1223280	Scheduled Service - 6500hr service II 500hr type. Level B Service	JKOLARITSCH	24/07/2019	Internal	6384.0	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1205240	Scheduled Service - Fire Suppresion Service; LOP type; Level 2 - 12 monthly. Fire Suppression System Service	311 Planning B	16/07/2019	Internal	5828.0	Scheduled Service -
1220642	Inspect Horn - Button on Joystick Faulty	JTINAO	2/07/2019	Internal	6234.0	Labour Repair Switch/es repaired joystick horn trigger button,went to Qube Enterprize to pick up parts from old spare. ordered new parts unit servicable Travel to site,
1217108	Horn Not Working	JDOBELL	18/06/2019	Internal	6129.0	Repair Horn -Travel to site -Wait for truck on weigh bridge -Call site contact for instructions to proceed -Get to unit and inspect issue -Horn is working fine -ring site contact and he mentionend it may have something to do with the horn pad -Could not fault the system, informed site contact of my findings and i instructed him that the issue may be intermittant and to call the issue in again if it fails.
1205247	Scheduled Service - 6000hr service II 3000hr type. Level E Service	EGREEN	5/06/2019	Internal	6074.0	Scheduled Service - 6000hr service II 3000hr type. Level E Service Labour
1205246	3 Monthly Wash	311 Planning B	28/05/2019	Internal	5828.0	3000hr Service
1202759	Flat battery	EGREEN	23/04/2019	Internal	5768.0	Scheduled Service - 3 Monthly Wash Flat battery
1202020	Transmission Fault	RWALKER	17/04/2019	Internal	5754.0	Repair Battery Charger as required, Transmission Fault Carry out Inspection and Diagnosis of Transmission check up the transmission error code T5304,check wiring harness goig to the console,and performed test.need to calibrate the transmission. Repair Inching Valve as necessary,

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1165525	Scheduled Service - 5000hr service II 5000hr type inc TWISTLOCKS. Level F Service	JKOLARITSCH	13/03/2019	Internal	5632.0	Scheduled Service - 5000hr service II 5000hr type inc TWISTLOCKS. Level F Service 5000hr Service Carry out service take oil samples and prep for service Change transmission oil, filters. Replace fan belt. hydraulic tank breather filters and replace cabin filter Travel to site, Pick up hyd oil in tank filters and oring from trug pick up cherry picker from coode rd carry out valve adjustment adjust twist locks Continue 5,000 hour service. Pick up transfer pump. Remove all hydraulic fluid from tank, replace 3 tank filters, and secondary filters. Pump fresh hydraulic oil into tank. Assitst with valve clearance check. Labour travel to trug workshop assisted by tech Jay to removed gearbox in the trailler and put 3 drums of hydraulic oil on to the trailler, travel back to Qube site. carried out mast inspection for cracks and weld, replaced wear pads. carried out valve lash adjustment return the EWP to coode road. Change steer hub oil top up auto greasers repace chain oilers lube lift chain replace one missing bolt on spreader wear pad clean hand rails and windscreen carry out trans calibration and test cycles of auto greaser Drain engine coolant, top up with 30 liters of fresh coolant. Tightened hose to water pump as was leaking, tested ok. Pressure tested to 15psi for 30 minutes, held well.

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1189985	Repair Wearpad	AFOX	5/03/2019	Internal	5475.0	Repair Wearpad Repair Attachment as necessary,
1184042	Stuck on a box	MWHITTINGTON	12/02/2019	Internal	5600.0	Refit wear pad in attachment. Stuck on a box Travel to site, Repair Attachment as necessary, Travelled to site, found twistlocks incorrectly positioned on 40ft box and unable to override as they were physically jammed on outer edge of container. Had to remove one twistlock to release spreader from box. Found rest of twistlocks badly worn, advised to replace all twistlocks. Moved unit to work area, Rena Jonassen travelled to parts truck to collect new twistlocks while I removed original ones. Replaced all twistlocks and greased, adjusted freelay and tested on box, all fine.... Topped up both grease tanks.
1173001	Error Code	NSARTORI	28/12/2018	Internal	4937.0	Labour Error Code Replace Transmission Control Lever, Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items, repair unit shift lever, order new part, unit back in service. INTERIM SAFETY CHECK- 4750hrs
1157434	INTERIM SAFETY CHECK- 4750hrs	MWHITTINGTON	23/11/2018	Internal	4544.0	
1157996	Additional Labour - Job #1147946	BIG TRUCK VIC	1/11/2018	Internal	4562.0	Additional Labour - Job #1147946
1150736	Scheduled Service - Fire Suppression Service *SUBLET TO QTEC*; LOP type; Level 1 - 6 monthly. Fire Suppression System Service	311 Planning B	24/10/2018	Internal	4386.0	Scheduled Service -
1147946	Scheduled Service- 4500hr service II 500hr type. Level B Service	JKOLARITSCH	18/10/2018	Internal	4463.0	Scheduled Service- 4500hr service II 500hr type. Level B Service Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. Carry out service

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1153213	Won't go into gear	JKOLARITSCH	15/10/2018	Internal	4463.0	Won't go into gear Check/Inspect/Diagnose Cylinder Remove ancillary items and Solenoid from unit. Replace Solenoid and Refit to unit. Refit ancillary items, Inspect unit for no drive found park brake will not release check wiring order new solenoid Travel to site, Borrow park brake solenoid from truck work shop and will swap over when parts received travel to site fit solenoid and test return unit to service Adjust Hydraulic Pressure Settings to correct specification, Check unit for loss of hydraulics functions and accumulator pressure inspect valves and wiring contact clean plugs on manifold test
1152947	Brake Issue	NSARTORI	15/10/2018	Internal	4463.0	Brake Issue Carry out Inspection and Diagnosis of Brake System Labour drive to site, found brake accumulator to not be charging, found filters to be dirty, drove to truck to source new filters, fitted filters and didn't fix issue, removed valves and cleaned, found sticky valve causing issue cleaned valve and retested machine, machine started charging its brakes again, ran machine through 3 charge cycles and tested out ok drive to site, assess issue, found brakes not charging, checked over machine and found issue to be a stuck valve, cleaned up valve and freed it, test run machine
1151448	A/C Check	BIG TRUCKS VIC SUB	9/10/2018	Internal	4414.0	A/C Check INTERIM SAFETY CHECK- 4250hrs
1138913	INTERIM SAFETY CHECK- 4250hrs	311 Planning B	12/09/2018	Internal	4068.0	
1143456	3 Monthly Wash	BIG TRUCK VIC	7/09/2018	Internal	4187.0	This service job has been missed. Next service has been brought forward. Jas Hayer- NMP 25/9/18. 3 Monthly Wash

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1141498	Repair Camera Mounts	WROSENOW	30/08/2018	Internal	4131.0	Repair Camera Mounts Fit Full Camera Kit, repair leg camera bracket and refit with new bolts Issue getting the leg lift arms down - Site Contact: Peter 0417 335 553 drive to site, work legs up and down about 10 times couldnt faault machiene, cleaned sensors and contacting surfaces, told operator to seee how it goes and let us know if it plays up Scheduled Service - 4000hr service II 2000hr type 2000hr Service Carry out service Labour Travel to site, Carry out mast inspection carried out mast and attachment inspection....replaced chain lube bottles, filled grease tanks. Adjusted twistlocks. Fire Suppression Alarm Going Off, Unit Shutdown
1140545	Issue getting the leg lift arms down - Site Contact: Peter 0417 335 553	NSARTORI	27/08/2018	Internal	4071.0	
1129801	Scheduled Service - 4000hr service II 2000hr type	NMOORE	6/08/2018	Internal	4000.0	
1133353	Fire Suppression Alarm Going Off, Unit Shutdown	BIG TRUCKS VIC SUB	31/07/2018	Internal	3928.0	
1131180	Won't Start	JKOLARITSCH	23/07/2018	Internal	3796.0	Won't Start Replace Fire Extinguisher, Inspect unit found fire system alarm on with fault,engine shut down,active. call up to get fire tech out Intermodal Leg Sensor Adjustment Adjust Attachment to correct specification, adjust drop down leg sensors. tag unit out requires 4 drive tyres. Repair Attachment as necessary, adlust lock proxy on legs
1123537	Intermodal Leg Sensor Adjustment	RMIFSUD	26/06/2018	Internal	3716.0	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1116518	Scheduled Service - 3750hr service II 250hr type	311 Planning A	26/06/2018	Internal	3738.0	Scheduled Service - 3750hr service II 250hr type 250hr Service carried out 250hr inspection ok, unable to do mast inspection due to cherry picker being unavailable Replace Twistlock Cylinder
1114515	Replace Twistlock Cylinder	FLUNN	25/05/2018	Internal	3515.0	Repair Attachment as necessary, Twist lock cylinder worn. Tried to adjust it and it was no good. Pick up new cylinder and fitted it and adjusted twist locks. Tested ok. Scheduled Service- 3500hr service II 500hr type
1108907	Scheduled Service- 3500hr service II 500hr type	FLUNN	22/05/2018	Internal	3515.0	23/05/2018 - Drop pointed to Frank L Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. 500hr service complete. No cracks found. Twist lock cylinder was changed out on a different job. Grease pots filled. Tail shaft greased. Landing light bracket bent. Unable to inspect mast due to not being able to get hold of an EWP. Machine is in good condition. collected equipment and drove to site. carried out service and inspection of machine. l/h twistlock cylinder needed replacing twistlocks needed adjusting. frank drove to get new cylinder and fitted. finished service and test drove machine. tidied worksite and drove to enterprize road to dispose of rubbish and waste oil. Scheduled Service - 3 Monthly Wash
1108795	Scheduled Service - 3 Monthly Wash.	311 Planning B	22/05/2018	Internal	3359.0	
1112810	Leg Stuck Down	JKOLARITSCH	21/05/2018	Internal	3486.0	Leg Stuck Down Carry out Inspection and Diagnosis of Attachment tested and could not fault , opperator error , if issue continues please get operator to show me how it is faulting Adjust Switch/es Unable to fault

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1110503	Inspect Transmission issue, noise present when shifting through 3rd gear	WROSENOW	11/05/2018	Internal	3398.0	Inspect Transmission issue, noise present when shifting through 3rd gear Carry out Inspection and Diagnosis of Transmission drove truck could not get trick to fault , weather is very cold may need to retest on a wwarmmer day couldnt get tran to make noise goin into fourth gear... unsucessfull getting video sound and footage of fault, was a very cold day on this day, perhaps it squawks on warmer days. Suggest retesting on a warmer day.
1101795	Scheduled Service - 3250hr service II 250hr type	311 Planning B	25/04/2018	Internal	3083.0	Scheduled Service - 3250hr service II 250hr type 250hr Service
1099152	Scheduled Service - Fire Suppresion Service *SUBLET TO QTEC*; LOP type; Level 2 - 12 monthly. Fire Suppression System Service	311 Planning B	18/04/2018	Internal	3083.0	Scheduled Service -
1091839	Scheduled Service - 3000hr service II 3000hr type	311 Planning A	21/03/2018	Internal	3076.0	Scheduled Service - 3000hr service II 3000hr type 27/3/2018 - Jay picked up 3000hr Service Carry out service change reverse beeper replace 1x missing stauff clamp calibrate transmission blown hose
1093853	blown hose	WROSENOW	13/03/2018	Internal	2972.0	
1092577	A/C Repair	BIG TRUCKS VIC SUB	7/03/2018	Internal	2861.0	Replace Hydraulic Hose/s and ancillary items, A/C Repair
1076617	Scheduled Service - 2500hr service II 500hr type	311 Planning B	21/02/2018	Internal	2320.0	Scheduled Service - 2500hr service II 500hr type 31/1/2018 - service picked up by APS (Ray)

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1087629	Grease Error Codes and Weight Scale needs recalibration	SMARINER	19/02/2018	Internal	2799.0	Grease Error Codes and Weight Scale needs recalibration Grease All Points on Unit, refill grease pot Adjust Murphy Gauge components to correct specification, Carry out Inspection and Diagnosis of Telemetry System Inspect found weight scale not working found plug off transducer clean and refit plug test found scales not returning to zero but reading -1700kg Check hypass couldnt find any info on system Ring trulla found out there is no manuel for this system trulla is chasing a manuel and will let me know asap Scheduled Service - 2250hr service II 250hr type
1068110	Scheduled Service - 2250hr service II 250hr type	RWALKER	1/12/2017	Internal	2083.0	This service has been cancelled as it could not be completed ontime due to workload and truck availability issues. The 500hr service was brought forward. Jas Hayer- National Maintenance Planner, 7/3/18.
1061305	Intermodal Cylinder Damaged	FLUNN	29/11/2017	External	2095.0	Intermodal Cylinder Damaged LH cylinder at knuckle to fold down first leg has broken. Damaged camera loom was also repaired. Machine has been tagged out. Removed cylinder. Picked up replacement cylinder and fitted it to the machine and it tested ok. Cleaned up work area and dropped off damaged cylinder to repairer . Repair Hydraulic Tilt Cylinder as required , Replace Left Hydraulic Tilt Cylinder , Removed replacement cylinder and refitted original cylinder. Tested all ok Steam Clean Equipment

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1049567	Fit Intermodal Mechanical indicator and stripe for "Mast Vertical" to LH Tilt Cylinder; Fit "SLEWED BACK" light; *CALL BRAD* *ADJUST LEG SEQUENCING VALVES*	NMOORE	29/11/2017	Internal	1289.0	Fit Intermodal Mechanical indicator and stripe for "Mast Vertical" to LH Tilt Cylinder *CALL BRAD* *BPRICE 10/10: Ordered parts for "slewed back" mod Adjust Hydraulic Pressure Settings to correct specification, Repair Attachment as necessary, Repair Main Electrical Control Panel as necessary, assist with modify of tilt and slu operation Remove ancillary items and Repair Wiring as necessary, Refit ancillary items, Adjust Attachment to correct specification , mounted green light to l/h tilt cyl, wired into loom for full slewed back sensors, checked operation of mast vertical mechanical indicator and fully slewed back green light custom made bracket and fitted for mast vertical indicator, fitted green light and made wiring loom to l/h mast vertical for when attachment is fully slewed
1061039	Scheduled Service - 2000hr service II 2000hr type	RWALKER	21/11/2017	Internal	2044.0	Adjust Hydraulic Control Valve to correct specification , Scheduled Service - 2000hr service II 2000hr type Travel to site, 2000hr Service Labour carry out 2000hr service as per service sheet , will be back tomorrow to complete service, complete 2000hr service 2000hr service complete
1065382	Additional labour for job #1060159	BIG TRUCKS VIC SUB	20/11/2017	Internal	1914.0	
1065042	A/C Checks	BIG TRUCKS VIC SUB	17/11/2017	Internal	1914.0	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1064505	Oil leak when intermodal leg operated	BIG TRUCKS VIC SUB	15/11/2017	Internal	1914.0	Oil leak on spreader Remove ancillary items and Repair Hydraulic Oil Leak as necessary. Refit ancillary items, Engine bay wash
1063929	Engine bay wash	BIG TRUCK VIC	14/11/2017	Internal	1914.0	Engine bay wash
1062931	Refit Camera	RWALKER	10/11/2017	Internal	2050.0	Refit Camera
1060159	Oil leak	RWALKER	1/11/2017	Internal	1898.0	Repair Attachment as necessary, Remove ancillary items and Repair Hydraulic Oil Leak as necessary. Refit ancillary items, Check/Inspect/Diagnose Hydraulic Oil Leak and test operation, Top up Hydraulic Oil to correct level, Scheduled Service - 1750hr service li 250hr type
1053603	Scheduled Service - 1750hr service li 250hr type	CMASON	18/10/2017	Internal	1834.0	250hr Service carry out 250 hr inspection re,tension fuel return line
1041044	Scheduled Service - 1500hr service 500hr type	RWALKER	27/09/2017	Internal	1623.0	Scheduled Service - 1500hr service 500hr type 11/9/17 - Ryan Walker picked up at 7am Labour Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.
1049520	Adjust Rear Feet Seqency valves; A/C Not Working	RWALKER	25/09/2017	Internal	1289.0	Adjust Rear Feet Seqency valves; A/C Not Working Repair Air Conditioner as necessary, Adjust Hydraulic Pressure Settings to correct specification,
1045562	1x camera inop; IH max posiont psensor not working correctly. Allowing legs to come down without attachment all the way forward	RWALKER	8/09/2017	Internal	1459.0	1x camera inop; IH max posiont psensor not working correctly. Allowing legs to come down without attachment all the way forward Replace Light/s removed broken bolts replaced camera mount ok Repair Attachment as necessary,

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1030972	Scheduled Service - 1250hr service 1000hr type (missed services)	311 Planning C	23/08/2017	Internal	1315.0	Scheduled Service - 1000hr service 1000hr type Parts picked up by Jack / Corey 22/08/17 - Service parts supplied again, as Corey away, and he has parts on board. Parts to be taken off, if and when returned. Labour 1000hr Service drove to trug to pick up parts. drove to site and carried out 1000hr service.
1039698	Fabricating Camera Brackets Ref JN 1033882	BIG TRUCKS VIC SUB	16/08/2017	Internal	1250.0	
1039132	Camera Fabrication	BIG TRUCK VIC	14/08/2017	Internal	1226.0	
1037901	1000HR SERVICE *MISSED*	311 Planning B	8/08/2017	Internal	1173.0	1000HR SERVICE *MISSED*
1033882	One of the cameras isnt working Site contact Josh 0421 619 677	RMIFSUD	24/07/2017	Internal	1024.0	One of the cameras isnt working Site contact Josh 0421 619 677 Remove ancillary items and Attachment, Strip, Inspect and report, Repair Attachment as necessary, 750hr service 250hr type *MISSED* Adjust Attachment to correct specification , Travel to site and repair drop down leg fault. found the drop down leg hitting the mast. found the mast slew ram sensor at fault. Ajusted the sensors and pick up blocks. Tested then put unit back into service.
1030970	750hr service 250hr type *MISSED*	311 Planning C	12/07/2017	Internal	925.0	
1027672	Drop down leg fault	WSHARKETT	29/06/2017	Internal	800.0	Broken bracket on the mast. Site contact Josh 0421 619 677 Repair Light Bracket as required, remove bent bracket and use oxy to heat up and straiten , refit . will need a new light set and rubber mounts and lhr camera bracket and camera straiten for now
1027563	missed invoice 563242 / 906737	BIG TRUCK VIC	29/06/2017	Internal	800.0	
1024125	Broken bracket on the mast. Site contact Josh 0421 619 677	BNORTON	16/06/2017	Internal	685.0	
1021872	A/C not working	BIG TRUCKS VIC SUB	7/06/2017	External	614.0	Repair Mast as necessary,

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1020369	Scheduled Service - 500 Hr	BIG TRUCK VIC	1/06/2017	Internal	614.0	Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. 500 hr service complete please further works for customer damage to landing lights bracket carry out 500hr service ac inop auto elec to repair Lsding light smashed email sent about parts light bracket is broken and Parked Josh 0421 619 677
1018557	light bracket is broken and Parked Josh 0421 619 677	ACHENOWETH	25/05/2017	Internal	502.0	Repair Attachment as necessary, Travel to site and assess bent bracket. Report back to Sam for repairs later on day.
1015111	BENT BRAKET	ACHENOWETH	11/05/2017	Internal	378.0	Job already completed on 25/5/17 Repair Mast as necessary, Unit has a bent bracket on carriage. Straighten parts and test ok.
1013507	Wk20 Scheduled 250hr Visual Inspection 6:30am	ACHENOWETH	4/05/2017	Internal	389.0	Repair Attachment as necessary, Wk20 Scheduled 250hr Visual Inspection 6:30am 250hr Service
1013006	Twistlock problem Site Contact: Josh Phone: 0421 619 677	NMOORE	3/05/2017	Internal	306.0	Carry out 250 hr inspection. Top up hyd oil level. Test unit. Twistlock problem Site Contact: Josh Phone: 0421 619 677 Repair Attachment as necessary,
1008570	AFTER HOURS CALL OUT	JLOWIS	11/04/2017	External	144.0	twistlocks locked off box. clamped landing pins and override unlocked. TECHNICIAN INITIATED JOB Repair Attachment as necessary, Emailed Josh A for PO - 12/4/17 - BR

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1007985	Leaking hydraulic oil and right hand slew is not working APS ATTENDING Site contact is Phil prior to 1pm and Ashleigh after 1pm at the gatehouse	JLOWIS	10/04/2017	External	34.0	Leaking hydraulic oil and right hand slew is not working APS ATTENDING Site contact is Phil prior to 1pm and Ashleigh after 1pm at the gatehouse Steam clean equipment as necessary. Contacted APS - requested job card and copy of invoice for work completed, so can be submitetd with claim- JM Wk15 auto greasing hose on the spreader. Appears to be a loose connection and its pumping out grease all over the place.
1005554	Wk15 auto greasing hose on the spreader. Appears to be a loose connection and its pumping out grease all over the place.	BIG TRUCK VIC	30/03/2017	Internal	60.0	Carry out Inspection and Diagnosis of Attachment repair auto grease lines and fill grease pot,help adjust speeds , inspect and check proys Claim Denied - This adsutment should be part of the normal daily routine/PM. slow
1004762	slow	ACHENOWETH	28/03/2017	Internal	44.0	Carry out Inspection and Diagnosis of Transmission Unit is going slower than the reduced speed limit of 10 kmh. Connect computer and confirm that unit is going at 7.5 kmh when loaded, even though it is set at 10 kmh. Refer this fault to Andrew.
1004270	CAMERA BROKEN	NMOORE	27/03/2017	Internal	43.0	ANDREW & ANTHONY ATTENDING - TUESDAY 4/4/17 CAMERA BROKEN Remove ancillary items and Repair Hydraulic Oil Leak as necessary. Refit ancillary items, Repair Attachment as necessary, repaired oil leak on main control valve. removed twistlock lights and repaired bracket. repaired leg camera bracket.new brackets ordered and need to be repositioned on inside of legs drilled and tapped new mounts for camera brackets. refit cameras and new brackets and tested.

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	
Owner: ADAP001						
Equip. Code: H12711		Description: HYSTER H52.00XM-16CH				
Make: HYSTER		Model: H52.00XM-16CH		Serial No.: H117E01608P		
1004162	AFTER HOURS CALL OUT - LEG NOT FOLDING	WROSENOW	25/03/2017	External	0.0	Carry out Inspection and Diagnosis of Attachment
						LHR leg stuck down , after serveral hours of testing finaly found that it was operator error due to not unlocking drop legs correctly - Attachement out of sequence
999244	Supply and install a Prov Vision 10'4 camera CCTV system	BIG TRUCK VIC	7/03/2017	Internal	0.0	Supply and install a Prov Vision 10'4 camera CCTV system
1005759	mount and wire fire suspression system REF NO 906373	BIG TRUCK VIC	27/02/2017	Internal	64.0	mount and wire fire suspression system REF NO 906373
906737	Prep for Rental - Qube Dynon	RWALKER	13/02/2017	Cap Prep	14.0	Doolans booked too move 2.5t fork & cage from Enterprize to Dynon - 14/2/17 -BR
						Return transport from Dynoon to Enterprize - Doolans - 15/02/217 - BR
						Return Enterprze to Dynon - 2.5t fork and cage - 17/2/17 - BR
						Prepare For Hire - Field
						picked up trailer to move cage from enterprize to dynon which wasnt taken with fork, job was delayed due to issues on wharf, got fork and cage returned to enterprize returned trailer
						Begin preparation for rental.
						Prepare for hire.
						Fit Attachment and ancillary items,
						Repair Fleet Management System as required,
						Prep for rental assist Andrew Fox.