

911373 ALBERTA
 LLANS MECHANICAL LTD.
 623, MANNING, AB T0H 2M0
 836.2011 FAX: 780.836.3901
 llansmechanical@outlook.com
 GST# 86252 2919 RT0001

with stone veneers

PROVINCE POSTAL CODE MILEMETERS

10 km W900 P.O.

5950402

SERVICES REQUESTED / DESCRIPTION OF WORK

AMOUNT

DATE 1 Dec 5/25

CONTACT NAME

CONTACT NUMBER

UNIT OR PLATE NUMBER 21-P664

2	1/2 L. Nut	
2	1/2 F. Washer	
2	K1289130RBx mod valve	400
1	7/16 x 2 1/2	
1	7/16 F. Washer	
1	TU-1031 Ant. sail bracket	
1	1469-4A fitting	
1	1408-8-24C-SW	
2	1/4 x 3 bolt	
2	1/4 L. Nut	
4	1/4 F. Washer	
1	40110155 brake adj	
1	05-1215 clevis pin	
1	04-319 cam clip	
2	01-472 cam washer	4
1	04-329 cam washer	
23	zips	
6	shrinks	
1	54143 marker light	6
2	66861 pigtail	3
2	45823 marker light	
1	44302 R3 light	1
3'	3 wire cord	
1	4707 brake	
1	standard drum	
1	4120910 fan belt	
I hereby authorize the above repair work to be done along the necessary material. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express lien under the Repair and Storage Act is acknowledged on above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to the vehicles or articles left in vehicles in case of fire, theft or any other cause beyond your control.		
SIGNATURE		
CUSTOMER EMAIL:		
TOTAL PAR		
TOTAL LABO		
SUBTOTAL		
GST		
TOTAL		

Lower clutch linkage ends.
 axles in right rear hood
 Install new nose clamp
 steering pump. Rotate
 Hours @ \$ 165.00
 Hours @ \$ 4290.00