

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71459 Station Name: Funk Mechanical

Technician #: 91482 Technician Name: Kyle Bryson

Signing Officer #: 88859 Signing Officer Name: Patty Lindsay

Customer Details:

Name: Wayne Megli Address: Box 607, Carrot River, Saskatchewan, S0E0L0

Vehicle Details:

VIN: 2L9A15381NH003311 Hubometer Reading:

Year: 2022 Vehicle Make/Model: LORNES TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
х				Vehicle Identification (5)	
х				Fire Extinguisher (5)	
х				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		х		Lamps (6)	ID light out, repaired;
х				Reflex Reflectors (6)	
х				Retro Reflective Markings (6)	
х				Trailer Hitch (10)	
Х				Attached Equipment (8)	
х				Cargo Bodies/Vessels (8)	
х				Mud Flaps/Fenders (8)	
Х				Landing Gear (8)	
х				Rear Impact Guard (8)	
Х				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
х				Fuel System (1)	
х				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
Х				Hyd Brake System/Components (3.1)	
		х		Air Brake System/Components (3.2)	Middle right brake shoe springs unhooked, repaired
		Х		Elec Brake System/Components (3.1)	Middle & Front right ABS wires unhooked, repaired;
		х		Wheel Bearings (9)	Rear left wheel seal, repaired; Middle right hub cap looks heated, replaced;
х				Tires/Wheels (9)	
Х				Self-Steering Axle (2&4)	
Х				Frame/Crossmembers/Mounts (8)	
Х				Suspension/Axles (2)	
Х				Exhaust/Emission System (1)	
х				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 4 mm

Brake(1): No Brake

N/A

Wheel2-On: Tire Tread Depth: 11 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: .557 in • Cam Rotation: 75.0 degrees • Brake Stroke: 1 1/2 in

Wheel3-On: Tire Tread Depth: 6 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: .503 in • Cam Rotation: 75.0 degrees • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 7 mm

Brake(1): No Brake

N/A

Axle 2-Pass

Wheel1 : Tire Tread Depth: 9 mm

Brake(1): No Brake

N/A

Wheel2-On: Tire Tread Depth: 8 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: .573 in • Cam Rotation: 72.0 degrees • Brake Stroke: 1 1/2 in

Wheel3-On: Tire Tread Depth: 7 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: .468 in • Cam Rotation: 97 degrees • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 9 mm

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 6 mm

Brake(1): No Brake

N/A

Wheel2-On: Tire Tread Depth: 1 mm

Brake(1): S-CAM Brake

Min Brake Lining/Pad: .473 in
Cam Rotation: 93.0 degrees
Brake Stroke: 1 1/2 in

Wheel3-On: Tire Tread Depth: 5 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: .411 in • Cam Rotation: 100.0 degrees • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 9 mm

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # A217536

Inspection Completed Date: 28Oct2025