PC Freight Services Service Schdule – A Service

| Date: 14-8-20 | Odometer: 860234 Km | |
|-----------------------|---------------------|--|
| Registration: AOG 213 | | |

| Check Engine Oil Level | |
|--|--|
| Check Coolant Level & Record Concentration | |
| Inspect Steering Oil Level & Check for Leaks | |
| Check all lights | |
| Check batteries – Level & Terminals | |
| Grease Chassis & Turntable | |
| Report & Replace Any Nipples Not Taking Grease | |
| Inspect Universal Joints | |
| Check Centre Bearing | |
| Adjust Brakes – Check for Air Leaks | |

| | Remarks/Com | ments | | | |
|---|-------------|---------|-------|---------------|---------------|
| | PERULD | CRORIED | OUT B | CHAMINS | WORONGA. |
| | MECICIED | Curules | WIE | (Ciri ilinii) | WON CIVICIN . |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| l | | | | | |
| l | | | | | |
| l | | | | | |
| l | | | | | |
| l | | | | | |
| l | | | | | |
| l | | | | | |
| l | | | | | |
| l | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| L | | | | | |

- Tot-

Admin | PC Freight

From:

Troy D Venaskie <troy.venaskie@cummins.com> on behalf of 325service

<325service@cummins.com>

Sent:

Wednesday, 10 September 2025 5:17 PM

To:

Admin | PC Freight

Cc:

325service; Kaine Norman

Subject:

Service history

Good afternoon,

Major service history for the 2 trucks are below.

XV00EQ (ESN 79981216) had a Low liner repair on 27/3/2020 at 653223 Kms.

AOG213 (ESN 79950240) had a Rebuild w/Cyl Head on 5/8/2020 at 860185 Kms.

Regards,

Troy D Venaskie

Service Advisor

troy.venaskie@cummins.com

Cummins Inc. 9-11 McKoy Street Wodonga Victoria 3690 Australia



255 McKOY STREET WEST WODONGA VIC 3691

TELEPHONE: (02) 6049 8877 FACSIMILE: (02) 6049 8878

Invoice No.:

EMAIL: service@twincitytruckcentre.com.au WEB: www.twincitytruckcentre.com.au

* * * DOCUMENT COPY * * *

Invoice To:

P C Freight Services Pty Ltd PO Box 1071

WODONGA VIC 3689

Owner:

P C Freight Services Pty Ltd 687 Chiltern - Barnawartha Rd BARNAWARTHA VIC 3688

SERVICE TAX INVOICE

Invoice Date: 23/11/2022 Cust. Ord. No.: Account No.: 1746 Customer ABN: 18 408 800 345 Rego No.: 3AOG.213 Fleet No.: Model: 2017 KENWORTH K200 Vehicle ID No.: 6F5000000HA458069 Engine No.: 79950240 Delivery Date: 11/06/2017 Odometer: 310076

 Repair Order No.:
 5182982

 Page:
 1 of 3

 Dealer Code:
 DCODE/1135510

Paccar Privileges: CLOY/A00774

COOLANT LOSS

Begin troubleshooting as per symptom tree and remove cylinder head. Confirm failed headgasket cylinder 2. Measure liner protrusion and found low. Remove piston and liner assemblies. Inspect and found broken shims cylinders 2 & 5 and all lower counterbores fretted. Machine counterbores to 0.0032". Fit new liners using kit and measure protrusion all ok. Inspect cylinder head and found cylinder 2 fire ring to have 0.002" wear over spec. Fit new cylinder head Refit all components and fill with new oil. Replace filter. Test drive and recheck all ok.

\$5,333.27

1700821

^{*}TCTC workshop goodwill of 10hrs.

| Part Number | Part Description | Quantity | Nett Value | Total Cost |
|----------------|-------------------------------|----------|------------|------------|
| 2882081 | KIT ENGINE BRAKE OVERHAUL | 1.00 | 1,011.38 | 1,011.38 |
| K041-808-25P0L | SETSCREW-6X25MM SST304 | 1.00 | 4.35 | 4.35 |
| 3896408 | SCREW HEXAGON FLANGE HEAD CAP | 3.00 | 24.27 | 72.81 |
| 4386606 | MANIFOLD EXHAUST | 1.00 | 1,441.49 | 1,441.49 |
| 5693737 | KIT OVERHAUL E5 | 0.70 | 10,621.61 | 7,435.13 |
| 2882570 | SHAFT ROCKER LEVER | 1.00 | 649.93 | 649.93 |
| ORX008 | NO. 8 O'RING EACH | 1.00 | 0.23 | 0.23 |
| ORX006 | NO.6 O'RING EACH | 3.00 | 0.49 | 1.47 |
| 1/2HDWASHZP | WASHER,FLAT 1/2" | 4.00 | 0.63 | 2.52 |
| 3685173 | SEAL OIL | 1.00 | 248.91 | 248.91 |
| M12X30 | METRIC BOLT (232) | 4.00 | 0.98 | 3.92 |
| 3686358 | SHAFT IDLER | 1.00 | 375.20 | 375.20 |
| 3689641 | GEAR IDLER | 1.00 | 998.08 | 998.08 |
| 3823258 | PAD CLEANING SCOTCHBRITE 7447 | 4.00 | 6.79 | 27.16 |
| | | | | |

^{*}Worn rocker shafts replaced.

^{*}Replaced scored timing gear and idler

^{*}Cummins have covered 30% of overhaul kit and labour to machine counterbores

^{*}Customer portion to cover labour and 70% of overhaul kit.



255 McKOY STREET WEST WODONGA VIC 3691

TELEPHONE: (02) 6049 8877 FACSIMILE: (02) 6049 8878

EMAIL: service@twincitytruckcentre.com.au WEB: www.twincitytruckcentre.com.au

* * * DOCUMENT COPY * * *

Invoice To:

P C Freight Services Pty Ltd PO Box 1071 WODONGA VIC 3689

Owner:

P C Freight Services Pty Ltd 687 Chiltern - Barnawartha Rd BARNAWARTHA VIC 3688

SERVICE TAX INVOICE

Invoice No.: 1700821 Invoice Date: 23/11/2022 Cust. Ord. No.: Account No.: 1746 Customer ABN: 18 408 800 345 Rego No.: 3AOG.213 Fleet No.: Model: 2017 KENWORTH K200 Vehicle ID No.: 6F5000000HA458069 Engine No.: 79950240 Delivery Date: 11/06/2017 Odometer: 310076 Repair Order No.: 5182982 Page: 2 of 3 DCODE/1135510 Dealer Code: Paccar Privileges: CLOY/A00774

COOLANT LOSS

| D1030-2299A-EACH | SIL HOSE 1" (PER CM) FROM 3' LENGTH | 1.00 | 2.90 | 2.90 | |
|------------------|-------------------------------------|------|----------|----------|--|
| 4026884 | GASKET TURBOCHARGER | 1.00 | 40.42 | 40.42 | |
| P-4100 | 6MM NUTSERT ALUMINIUM | 1.00 | 1.35 | 1.35 | |
| 4988280 | GASKET - POWER STEERING PUMP | 1.00 | 18.13 | 18.13 | |
| 3678506 | SCREW HEXAGON FLANGE HEAD CAP | 1.00 | 84.49 | 84.49 | |
| 6PK1590 | A/C BELT | 1.00 | 42.15 | 42.15 | |
| FS19764 | FUEL/WATER SEPARATOR | 1.00 | 34.71 | 34.71 | |
| 5/16FNYL | NYLOC NUT UNF (3349) | 1.00 | 0.20 | 0.20 | |
| 3354820 | RED RUBBER GREASE 500G | 1.00 | 27.21 | 27.21 | |
| 56410 | TIE-CABLE BLK 7.6X370 (PKT OF 100) | 1.00 | 34.75 | 34.75 | |
| L0C39145 | LOCTITE BLACK MAXX SIL | 1.00 | 17.22 | 17.22 | |
| K251-571 | FILTER-FREON, RECEIVER | 1.00 | 113.94 | 113.94 | |
| L0C51827 | LOCTITE 518 FLANGE SEAL | 1.00 | 23.60 | 23.60 | |
| 301-4.8/W | CABLE TIE PK 100 301X4.8MM | 1.00 | 16.52 | 16.52 | |
| 5658203RX | RECON CYL HEAD ISXE5 | 1.00 | 7,774.17 | 7,774.17 | |
| 2866337CUM | GASKET 5" | 1.00 | 28.85 | 28.85 | |
| 3163075 | PAINT ""300 APEX RED"" 12.05OZ" | 1.00 | 60.54 | 60.54 | |
| 1/4HDWASHZP | WASHER | 1.00 | 0.21 | 0.21 | |
| 10-595-6405 | NIPPLE & DUST CAP ASSEMBLY | 1.00 | 64.07 | 64.07 | |
| B9228-0275B | CLAMP 2 1/2" TO 2 3/4" | 4.00 | 10.24 | 40.96 | |
| 6X25MG304BHSS | SKT HD 6X25 SS BTN HEA | 1.00 | 0.52 | 0.52 | |
| HS016-20-EACH | HOSE CLAMP 21-38MM | 4.00 | 3.46 | 13.84 | |
| MH006-20-EACH | HOSE CLAMP 8-22MM | 2.00 | 1.95 | 3.90 | |
| DCT110H1RW-10P | CABLE TIE BRAKE HOSE (PKT OF 10) | 1.00 | 47.09 | 47.09 | |
| K066-177 | BUSH-ANTI VIBRATION | 2.00 | 44.50 | 89.00 | |
| | | | | | |



ABN 66 084 346 221

255 McKOY STREET WEST WODONGA VIC 3691

TELEPHONE: (02) 6049 8877 FACSIMILE: (02) 6049 8878

service@twincitytruckcentre.com.au EMAIL: WEB: www.twincitytruckcentre.com.au

* * * DOCUMENT COPY * * *

Invoice To:

P C Freight Services Pty Ltd PO Box 1071 WODONGA VIC 3689

Owner:

P C Freight Services Pty Ltd 687 Chiltern - Barnawartha Rd **BARNAWARTHA VIC 3688**

COOLANT LOSS

CRC-5005 CRC 5.56 400 GRAM AEROSOL 1.00 10.02 10.02 D1030-2650A-EACH SIL HOSE 2 1/2" (PER CM) 1.00 2.19 2.19 D84-1000-3122380 **BELT-FAN DRIVE** 1.00 161.54 161.54 2882571 SHAFT ROCKER LEVER 671.44 671.44 1.00 63.70

HORTON

REMOVE HORTON FAN ASSEMBLY AND DISMANTLE, CLEAN UP ALL PARTS, INSTALL REPAIR KIT AND RE-ASSEMBLE. RE-INSTALL HORTON FAN ASSEMBLY AND ADJUST BELTS, CHECK OPERATION, ALL OK.

Part Number Part Description F350080B HT/S OUTBACK UPGRADE KIT

Miscellaneous Charges

Environmental Levy \$10.00 Workshop Consumables

SERVICE TAX INVOICE

Invoice No.: 1700821 Invoice Date: 23/11/2022

Cust. Ord. No.:

Account No.: 1746 Customer ABN: 18 408 800 345 Rego No.: 3AOG.213

Fleet No.:

Model: 2017 KENWORTH K200 Vehicle ID No.: 6F5000000HA458069 Engine No.: 79950240 Delivery Date: 11/06/2017 Odometer: 310076 Repair Order No.: 5182982 Page: 3 of 3 Dealer Code: DCODE/1135510 CLOY/A00774 Paccar Privileges:

\$21,698.51

Nett Value

852.04

Quantity

1.00 1.00

Total:

\$147.60

\$852.04

\$30,900.56

\$50.00

Total Cost

852.04

Sub Total for All: \$28,091.42 Rounding: \$0.00 GST: \$2,809.14

Advisor: Jacob Brook

Direct Deposit:

Bank: Bendigo Bank Branch: BSB: 633000 Account No.: 135823573 Account Name: Twin City Truck Centre Pty Ltd



255 McKOY STREET WEST WODONGA VIC 3691

TELEPHONE: (02) 6049 8877 FACSIMILE: (02) 6049 8878

EMAIL: service@twincitytruckcentre.com.au WEB: www.twincitytruckcentre.com.au

* * * DOCUMENT COPY * * *

Invoice To:

P C Freight Services Pty Ltd PO Box 1071 WODONGA VIC 3689

Owner:

P C Freight Services Pty Ltd 687 Chiltern - Barnawartha Rd BARNAWARTHA VIC 3688

SERVICE TAX INVOICE

 Invoice No.:
 1407718

 Invoice Date:
 3/07/2017

Cust. Ord. No.:

Account No.: 1746
Customer ABN: 18 408 800 345
Rego No.: 3AOG.213

Fleet No.: Model: 2017 KENWORTH K200 Vehicle ID No.: 6F5000000HA458069 Engine No.: 79950240 Delivery Date: 9/03/2017 Odometer: 14750 Repair Order No.: 5144783 Page: 1 of 2 DCODE/1135510 Dealer Code: CLOY/A00774 Paccar Privileges:

1KWFS

- ***COMPLIMENTARY NO CUSTOMER LABOUR CHARGE KENWORTH TRUCK 1st SERVICE POLICY ***
- ***CUSTOMER RESPONSIBLE FOR ALL PARTS REQUIRED FOR 1st SERVICE***

The following 1st service inspection for P.C Freight Pty Ltd, to a K200 Kenworth Truck, Chassis#458069, included:

- * Removed/replaced engine filter & oil, specification used Premium Blue
- * Check all engine operation & components
- * Removed/replaced transmission oil filter
- * Removed/replaced Transmission Oil, specification used Eaton PS 386 synthetic oil
- * Removed/replaced power steering filter & gasket
- * Removed/replaced differential oil, specification used 85W140
- * Removed/replaced fuel filter
- * Check cooling system & pressure test
- * Check all belts, idler pulleys, fan, shrouds & adjust to specification
- * Check all electrical routing, wiring looms, switches, sensors & components
- * Check all hydraulic lines fitting & level lubricant levels to specification
- * Check all wheel equipment & steering components
- * Check all braking & adjust to specification
- * Check clutching & adjust to specification
- * Check all suspension components
- * Check all internal cabin operation, components & adjust to specification
- * Check all external cabin components & adjust to specification
- * Check windscreen washers, wipers, refill & test operation
- * Lubricate, adjust relevant components as required
- * Re torque all fitting & fixtures
- * Road test & wash vehicle

GREASE \$8.95



ABN 66 084 346 221

255 McKOY STREET WEST WODONGA VIC 3691

TELEPHONE: (02) 6049 8877 (02) 6049 8878 FACSIMILE:

service@twincitytruckcentre.com.au EMAIL: WEB: www.twincitytruckcentre.com.au

* * * DOCUMENT COPY * * *

Invoice To:

P C Freight Services Pty Ltd PO Box 1071

WODONGA VIC 3689

Owner:

P C Freight Services Pty Ltd 687 Chiltern - Barnawartha Rd **BARNAWARTHA VIC 3688**

SERVICE TAX INVOICE

Invoice No.: 1407718 Invoice Date: 3/07/2017

Cust. Ord. No.:

Account No.: 1746 Customer ABN: 18 408 800 345 Rego No.: 3AOG.213

Fleet No.:

Model: 2017 KENWORTH K200 Vehicle ID No.: 6F5000000HA458069 Engine No.: 79950240 Delivery Date: 9/03/2017 Odometer: 14750 Repair Order No.: 5144783 Page: 2 of 2 DCODE/1135510 Dealer Code: CLOY/A00774 Paccar Privileges:

1KWFS

| Part Number | Part Description | Quantity | Nett Value | Total Cost | |
|--------------------|--------------------------------------|----------|------------|------------|------|
| 17237 | GEARBOX OIL FILTER | 1.00 | 25.94 | 25.94 | |
| PBE | ****USE "L" PBE**** | 47.00 | 5.83 | 274.01 | |
| AL85W140-1000-EACH | DIFF OIL 85/140 PER LITRE | 38.00 | 6.89 | 261.82 | |
| A3380W1687 | FILTER (MERITOR DIFF) | 1.00 | 18.10 | 18.10 | |
| PS386-17 | EATON PS-386 SYNTHETIC G/BOX OIL 17L | 1.00 | 412.37 | 412.37 | |
| FS19764 | FUEL/WATER SEPARATOR | 1.00 | 26.05 | 26.05 | |
| 3381101 | ATF DEX III 4LTR | 1.00 | 39.03 | 39.03 | |
| WF2127 | FILTER-WATER | 1.00 | 40.00 | 40.00 | |
| LF14000NN | ***USE "K" LF14000NN*** | 1.00 | 72.15 | 72.15 | |
| FF5776 | FILTER FUEL | 1.00 | 45.01 | 45.01 | |
| AS2474 | AIR/OIL SEPARATOR E5 DOSER | 1.00 | 11.47 | 11.47 | |
| LF637 | LUBE FILTER-P/STEER | 1.00 | 24.56 | 24.56 | |
| | | 95.00 | \$1,25 | | 0.51 |

Sub Total for All: \$1,259.46 Rounding: \$0.00 GST: \$125.95 Total: \$1,385.41

Advisor: Thomas Colvin

Direct Deposit:

Bank: Bendigo Bank Branch: BSB: 633000 Account No.: 135823573 Account Name: Twin City Truck Centre Pty Ltd



ABN 66 084 346 221

255 McKOY STREET WEST WODONGA VIC 3691

TELEPHONE: (02) 6049 8877 (02) 6049 8878 FACSIMILE:

service@twincitytruckcentre.com.au EMAIL: WEB: www.twincitytruckcentre.com.au

* * * DOCUMENT COPY * * *

Invoice To:

New Truck Dept - Wheel Alignment

Owner:

P C Freight Services Pty Ltd 687 Chiltern - Barnawartha Rd **BARNAWARTHA VIC 3688**

SBLTHUMETRUCKTECHNIC

SUBLET: 7211559 CARRY OUT ALIGNMENT AS REQUIRED.

SERVICE TAX INVOICE

Invoice No.: 1435688 Invoice Date: 6/02/2018

Cust. Ord. No.:

Account No.: 9992

Customer ABN:

Rego No.: 3AOG.213

Fleet No.:

Model: 2017 KENWORTH K200 Vehicle ID No.: 6F5000000HA458069 Engine No.: 79950240 Delivery Date: 11/06/2017 Odometer: 181000 Repair Order No.: 5149067 Page: 1 of 1 DCODE/1135510 Dealer Code: CLOY/A00774 Paccar Privileges:

\$520.00

Sub Total for All: \$520.00 Rounding: \$0.00 GST: \$0.00 Total: \$520.00

Advisor: Thomas Colvin

Direct Deposit:

Bank: Bendigo Bank Branch:



ABN 66 084 346 221

255 McKOY STREET WEST WODONGA VIC 3691

TELEPHONE: (02) 6049 8877 (02) 6049 8878 FACSIMILE:

service@twincitytruckcentre.com.au EMAIL: WEB: www.twincitytruckcentre.com.au

* * * DOCUMENT COPY * * *

Invoice To:

Cash Transactions

Owner:

P C Freight Services Pty Ltd 687 Chiltern - Barnawartha Rd **BARNAWARTHA VIC 3688**

SERVICE TAX INVOICE

Invoice No.: 1462621 Invoice Date: 24/08/2018

Cust. Ord. No.:

Account No.: 1770

Customer ABN:

Rego No.: 3AOG.213

Fleet No.:

Model: 2017 KENWORTH K200 Vehicle ID No.: 6F5000000HA458069 Engine No.: 79950240 Delivery Date: 11/06/2017

Odometer:

Repair Order No.: 5153117 Page: 1 of 1 DCODE/1135510 Dealer Code: CLOY/A00774 Paccar Privileges:

AIR DRIER

CUSTOMER REPORTS THAT AIR DRIER IS LEAKING OUT THE UNLOADER AND TRUCK WILL NOT BUILD UP AIR,

\$125.00

- * Inspect air system
- * Disconnect airlines and remove air drier assembly
- * Disassemble and inspect air drier
- * Remove unloader valve assembly and found piece of metal causing unloader valve to be stuck

Suspected reed valve failure

- * Re-kit air drier
- * Refit air drier and connect airlines
- * Test and confirm repair

Part Number Part Description T2000SK-P KIT AIR DRYER

1.00 304.72 304.72

Nett Value

Quantity

1.00 \$304.72

Total Cost

Miscellaneous Charges

Environmental Levy \$10.00 Workshop Consumables \$3.75

> **Sub Total for All:** \$443.47 Rounding: \$0.00 GST: \$44.35 Total: \$487.82

Advisor: Thomas Colvin

Direct Deposit:

Bank: Bendigo Bank Branch:



ABN 66 084 346 221

255 McKOY STREET WEST WODONGA VIC 3691

TELEPHONE: (02) 6049 8877 (02) 6049 8878 FACSIMILE:

service@twincitytruckcentre.com.au EMAIL: WEB: www.twincitytruckcentre.com.au

* * * DOCUMENT COPY * * *

Invoice To:

Kenworth Warranty

Owner:

P C Freight Services Pty Ltd 687 Chiltern - Barnawartha Rd **BARNAWARTHA VIC 3688**

SERVICE TAX INVOICE

Invoice No.: 1468182 Invoice Date: 3/10/2018 Cust. Ord. No.: WARRANTY Account No.: 20001 Customer ABN: 43004669667 Rego No.: 3AOG.213

Fleet No.: Model: 2017 KENWORTH K200 Vehicle ID No.: 6F5000000HA458069 Engine No.: 79950240 Delivery Date: 11/06/2017 Odometer: 355995 Repair Order No.: 5149886 Page: 1 of 1 DCODE/1135510 Dealer Code: CLOY/A00774 Paccar Privileges:

DIFF LEAK-INPUT SEAL

CUSTOMER REPORTS FRONT DIFF PINION SEAL IS LEAKING.

\$158.21

CONFIRM LEAK. REMOVE DRIVESHAFT, FLANGE NUT & FLANGE. REMOVE & REPLACE SEAL. REFIT FLANGE WITH NEW NUT & TENSION TO SPEC. REFIT DRIVESHAFT WITH NEW BOLTS & TENSION TO SPEC.

Claim #358009 FPN # A1-1205X2728 VMRS 002 003 020 1.3 hr, R & R Seal

Make Meritor Model # Z13200V2049 Serial # 1703224767455

> Part Number Part Description **BOLT - RPL DRIVELINE** CSC82052 K1T2638 KIT PINION NUT A1-1205X2728 SEAL MULTI LIP FRT INPUT

Total Cost Nett Value Quantity 14.56 4.00 3.64 1.00 34.46 34.46 1.00 71.06 71.06 6.00 \$120.08

> **Sub Total for All:** \$278.29 Rounding: \$0.00 GST: \$0.00 Total: \$278.29

Advisor: Thomas Colvin

Direct Deposit:

Bank: Bendigo Bank Branch:



ABN 66 084 346 221

255 McKOY STREET WEST WODONGA VIC 3691

TELEPHONE: (02) 6049 8877 (02) 6049 8878 FACSIMILE:

service@twincitytruckcentre.com.au EMAIL: WEB: www.twincitytruckcentre.com.au

* * * DOCUMENT COPY * * *

Invoice To:

Cummins Warranty

Owner:

P C Freight Services Pty Ltd 687 Chiltern - Barnawartha Rd **BARNAWARTHA VIC 3688**

SERVICE TAX INVOICE

Invoice No.: 1472427 Invoice Date: 2/11/2018

Cust. Ord. No.:

Account No.: 20080

Customer ABN:

Rego No.: 3AOG.213

Fleet No.: Model: 2017 KENWORTH K200 Vehicle ID No.: 6F5000000HA458069 Engine No.: 79950240 Delivery Date: 11/06/2017 Odometer: 362259 Repair Order No.: 5153999 Page: 1 of 1 DCODE/1135510 Dealer Code: CLOY/A00774 Paccar Privileges:

BREAKDOWN

Promo id 1008725. Connect to Insite and download. Found high counts of inactive code 125. Lower bull bar and raise cab. Begin troubleshooting as per T05-125. 1a, No other fault codes present. 2a, Inspect charge air system for damage & leaks. Carry out CAC pressure test and found system rapidly loosing pressure through turbo wastegate, found wastegate rod clip missing causing rod to come away and wastegate has moved to fully open. Set wastegate rod travel and refit with new clip. Recheck for leaks, ok. 5a, ECM calibration up to date. 5b, Clear code as per conditons for clearing code. Repair complete.

\$207.59

Sub Total for All: \$207.59 Rounding: \$0.00 GST: \$0.00 Total: \$207.59

Advisor: Kirsty Jackson

Direct Deposit:

Bank: Bendigo Bank Branch:



ABN 66 084 346 221

255 McKOY STREET WEST WODONGA VIC 3691

TELEPHONE: (02) 6049 8877 (02) 6049 8878 FACSIMILE:

service@twincitytruckcentre.com.au EMAIL: WEB: www.twincitytruckcentre.com.au

* * * DOCUMENT COPY * * *

Invoice To:

Cummins Warranty

Owner:

P C Freight Services Pty Ltd 687 Chiltern - Barnawartha Rd **BARNAWARTHA VIC 3688**

WATER PUMP

REPAIR WATER PUMP

Part Number Part Description 4386577 WATER PUMP E5 **CALL-OUT** PARTS CALL-OUT FEE(AFTER HOURS) ELC40-5M PACGEN ELC40 PREMIX 5L ELC40-20M PACGEN ELC40 PREMIX 20L 3684384 O-RING SEAL - WATERPUMP

SERVICE TAX INVOICE

Invoice No.: 1481298 Invoice Date: 15/01/2019

Cust. Ord. No.:

Account No.: 20080

Customer ABN:

Rego No.: 3AOG.213

Fleet No.:

Model: 2017 KENWORTH K200 Vehicle ID No.: 6F5000000HA458069 Engine No.: 79950240 Delivery Date: 11/06/2017 Odometer: 398463 Repair Order No.: 5155563 Page: 1 of 1 DCODE/1135510 Dealer Code: CLOY/A00774 Paccar Privileges:

\$78.29

Quantity Nett Value **Total Cost** 1.00 688.16 688.16 1.00 150.00 150.00 23.81 23.81 1.00 1.00 95.33 95.33 27.21 1.00 27.21

5.00 \$984.51

Sub Total for All: \$1,062.80 Rounding: \$0.00 GST: \$0.00 Total: \$1,062.80

Advisor: Kevin Riseborough

Direct Deposit:

Bank: Bendigo Bank Branch: