

# Invoice

## Dave's Diesel Ltd

835 Monticello Way  
 Winkler, MB  
 R0G 3N0  
 Ph: 1-204-362-6865

Date	Invoice #
2024-11-22	1871

<b>Invoice To :</b>
Dale Klippenstein

<b>Customer :</b>
2020 Peterbilt 579 Vin: LD637032 Miles: 600932 Plate # CPN 175 Unit # 225

Quantity	Item	Description	Price Each	Amount
1.25	Labour	November 16, 2024 Serviced truck. Torqued all wheels to 525ft/lbs as per customer. Replaced engine air filter supplied by customer.	100.00	125.00
1	prt	K37-1022 Fuel Filter	91.81	91.81
1	prt	2277129PE Fuel Filter	114.28	114.28
1	prt	2234788PE Oil Filter	80.14	80.14
1	prt	1922496PE Oil Filter	102.30	102.30
44	Shell Rotell...	Shell Rotella 15W-40	5.61	246.84
1	Delo Grease	Delo Starplex EP2 Grease	5.62	5.62

**Sales Tax Summary**

GST@5.0%	38.30
Total Tax	38.30

<b>Total</b>		\$804.29
--------------	--	----------

**Dave's Diesel Ltd**

835 Monticello Way  
 Winkler, MB  
 R0G 3N0  
 Ph: 1-204-362-6865

**Invoice**

Date	Invoice #
2025-09-09	2392

<b>Invoice To :</b>
Dale Klippenstein

<b>Customer :</b>
2020 Peterbilt 579 Vin: LD637032 Kms: 653778 Plate # CPU 562 Unit # 225

Quantity	Item	Description	Price Each	Amount
2.5	Labour	September 13, 2025 Tried replacing starter solenoid customer had supplied, removed old solenoid but wasn't the same as the new one. Found out you cant replaced just the solenoid. Replaced complete starter. Starter billed to customers account at Loadline. ABS modulator valve bracket was hanging down, welded mounting studs back on and fastened bracket.	100.00	250.00
1	prt	Shop Supplies	5.00	5.00

**Sales Tax Summary**

GST@5.0% 12.75  
 Total Tax 12.75

	<b>Total</b>	<b>\$267.75</b>
--	--------------	-----------------

**Dave's Diesel Ltd**

835 Monticello Way  
 Winkler, MB  
 R0G 3N0  
 Ph: 1-204-362-6865

**Invoice**

Date	Invoice #
2024-11-29	1887

<b>Invoice To :</b>
Dale Klippenstein

<b>Customer :</b>
2020 Peterbilt 579 Vin: LD637032 Miles: 607169 Plate # CPN 175 Unit # 225

Quantity	Item	Description	Price Each	Amount
6	Labour	November 30, 2024 Removed air cleaner + air duct and checked/set top end, reassembled. Installed 1/4 turn valves in both fuel tank return lines (supplied by customer) Replaced crankcase breather filter. Removed stones between RH side fuel tank and fuel strap and filled crack with silicone.	100.00	600.00
1	prt	2299013PE CV Replacement Filter	157.74	157.74
2	prt	GL-G1416-06-06 SAE Flare Male Connector	2.85	5.70
1	prt	Shop Supplies	5.00	5.00

**Sales Tax Summary**

GST@5.0% 38.42  
 Total Tax 38.42

<b>Total</b>			<b>\$806.86</b>
--------------	--	--	-----------------

GST/HST No. 761327667

**Dave's Diesel Ltd**

835 Monticello Way  
 Winkler, MB  
 R0G 3N0  
 Ph: 1-204-362-6865

**Invoice**

Date	Invoice #
2025-04-06	2065

<b>Invoice To :</b>
Dale Klippenstein

<b>Customer :</b>
2020 Peterbilt 579 Vin: LD637032 Kms: 632144 Plate # CPN 175 Unit # 225

Quantity	Item	Description	Price Each	Amount
3	Labour	April 7, 2025 Serviced truck, minus fuel filters and 5th wheel grease. Replaced engine air filter. Replaced oil pressure sensor as per customer (sensor supplied by customer) Diagnose ABS, active code for axle 2 RH side. Replaced sensor and cleared code. Took truck for test drive and code stayed cleared.	100.00	300.00
1	prt	LF16368 Oil Filter	53.86	53.86
1	prt	CS41044 Oil Filter	71.44	71.44
1	prt	K181265 ABS Sensor	98.54	98.54
1	prt	P621725 Air Filter	267.67	267.67
0.5	Delo Grease	Delo Starplex EP2 Grease	5.62	2.81
44	Shell Rotell...	Shell Rotella 15W-40	5.61	246.84
0.5	CC7101	Antifreeze green concentrate	16.98	8.49
1	Computer h...		60.00	60.00

**Sales Tax Summary**

GST@5.0%	55.48
Total Tax	55.48

<b>Total</b>			\$1,165.13
--------------	--	--	------------

**Dave's Diesel Ltd**

835 Monticello Way  
 Winkler, MB  
 R0G 3N0  
 Ph: 1-204-362-6865

**Invoice**

Date	Invoice #
2024-12-09	1903

<b>Invoice To :</b>
Dale Klippenstein

<b>Customer :</b>
2020 Peterbilt 579 Vin: LD637032 Miles: 608912 Plate # CPN 175 Unit # 225

Quantity	Item	Description	Price Each	Amount
6	Labour	December 10, 2024 Serviced truck. Brief look over, replaced leaking air control valve in cab. Replaced loose U-joint on axle 3 input. Yoke nut on transmission yoke was backed off and yoke had play, fastened with new nut. Adjusted brakes.	100.00	600.00
1	prt	4306520 Crimped Hex Flange Nut	43.87	43.87
1	prt	5-280X U-Joint 1710 Full RND	92.70	92.70
1	prt	K85DF Air Valve	169.88	169.88
1	prt	LF691A Oil Filter	25.81	25.81
1	prt	AF1968M Air Filter	82.82	82.82
1	prt	FS1000 Fuel Filter	22.26	22.26
1	prt	FF5264 Fuel Filter	19.52	19.52
1	Delo Grease	Delo Starplex EP2 Grease	5.62	5.62
1	prt	Shop Supplies	5.00	5.00

**Sales Tax Summary**

GST@5.0%	53.37
Total Tax	53.37

	<b>Total</b>	<b>\$1,120.85</b>
--	--------------	-------------------

GST/HST No. 761327667

# Invoice

**Dave's Diesel Ltd**

145 Clearview Drive  
 RM Of Rhineland, MB  
 PO Box 11  
 Ph: 1-204-362-6865

Date	Invoice #
2025-11-16	2542

<b>Invoice To :</b>
Dale Klippenstein

<b>Customer :</b>
2020 Peterbilt 579 Vin: LD637032 Miles: 674689 Plate # CPU 562 Unit # 225

Quantity	Item	Description	Price Each	Amount
2	Labour	November 28, 2025 Replaced batteries with good used supplied by customer. Replaced bunk heater fuse and checked wiring. Noticed one of the main battery cables wasn't hooked up, connected cable.	100.00	200.00

<b>Sales Tax Summary</b>	
GST@5.0%	10.00
Total Tax	10.00

	<b>Total</b>	\$210.00
--	--------------	----------

# Invoice

## Dave's Diesel Ltd

835 Monticello Way  
 Winkler, MB  
 R0G 3N0  
 Ph: 1-204-362-6865

Date	Invoice #
2025-10-22	2446

<b>Invoice To :</b>
Dale Klippenstein

<b>Customer :</b>
2020 Peterbilt 579 Vin: LD637032 Kms: 661432 Plate # CPU 562 Unit # 225

Quantity	Item	Description	Price Each	Amount
7.75	Labour	October 16, 2025 Diagnose bunk heater not working, replaced burnt out fuse. Replaced both brake drums on axle 2. Replaced torsion bar on axle 2 RH side. Replaced hanger bearing. Replaced 5th wheel bushings. Replaced license plate light. Serviced truck. Replaced LH side windshield washer nozzle, still didn't spray as should, found cut in washer fluid hose, cut out damaged piece and coupled with connector.	100.00	775.00
1	Schedule B ...	Schedule B Truck Safety Check	250.00	250.00
2	prt	3600AX Brake Drum	181.88	363.76
1	prt	60661 LED License Lamp	15.96	15.96
1	prt	W612-1 Washer Nozzle	4.62	4.62
1	prt	TMR537 Torque Rod Front	160.35	160.35
1	prt	RKPKT2 Pocket Insert Kit	74.56	74.56
1	prt	RK-10605 Repair Kit Pin	102.09	102.09
1	prt	10094142 Hanger Bearing	121.11	121.11
1	prt	LF16368 Oil Filter	56.81	56.81
1	prt	CS41044 Oil Filter	74.43	74.43
1	prt	FS20208 Fuel Filter	59.73	59.73
1	prt	FS20260 Fuel Filter	99.26	99.26
2	WWAF	Windshield Washer Fluid 4L Jug	5.64	11.28
2	prt	9862 Windshield Washer Hose Connector	2.84	5.68
44	Shell Rotell...	Shell Rotella 15W-40	5.61	246.84
0.75	Delo Grease	Delo Starplex EP2 Grease	5.92	4.44

**Sales Tax Summary**

GST@5.0%	121.30
Total Tax	121.30

<b>Total</b>		<b>\$2,547.22</b>
--------------	--	-------------------

**Dave's Diesel Ltd**

145 Clearview Drive  
 RM Of Rhineland, MB  
 PO Box 11  
 Ph: 1-204-362-6865

**Invoice**

Date	Invoice #
2026-01-08	2656

<b>Invoice To :</b>
Dale Klippenstein

<b>Customer :</b>
2020 Peterbilt 579 Vin: LD637032 Kms: 682220 Plate # CPU 562 Unit # 225

Quantity	Item	Description	Price Each	Amount
11.25	Labour	January 8, 2026 Diagnose engine light on and derated. Truck had 31 active emission codes, contacted shop that had done delete, ran truck for 15 minutes and cleared codes as per their mechanic. Codes all cleared except 4, active code for egr valve + bpv valve + humidity sensor stayed active, causing derate code. Replaced EGR valve and humidity sensor with good used, (bpv was physically broken but new valve was expensive and couldn't find good used) took truck for test drive, codes came back but didn't seem to be derated (got 25psi boost) customer picked up truck but brought back right away because it was derated again. Reinstalled original egr valve and humidity sensor. Diagnose back pressure valve code, found engine power fuse kept popping when un plugging and plugging bpv back in, relay looked corroded. Replaced back pressure valve, bushing for NOx sensor broke with removal, replaced bushing and reassembled. Codes went inactive, cleared and took for test drive, got over 30psi boost and it worked as should. No codes came back from test drive.	100.00	1,125.00
2	prt	1917870PE Exhaust Gasket	22.17	44.34
1	prt	1469-10D 90 degree elbow compression fitting 5/8T X 1/2MPT	5.84	5.84
1	prt	2022708PE Bushing (For NOx Sensor)	168.14	168.14
1	prt	CB12755 Relay	27.22	27.22
1	prt	2426254PE Back Pressure Valve	5,800.00	5,800.00
1	prt	1886111PE Exhaust Gasket	26.28	26.28
1	Computer h...		60.00	60.00
1	prt	Shop Supplies	5.00	5.00

**Sales Tax Summary**

GST@5.0%	363.09
Total Tax	363.09

<b>Total</b>	<b>\$7,624.91</b>
--------------	-------------------

# Invoice

## Dave's Diesel Ltd

145 Clearview Drive  
 RM Of Rhineland, MB  
 PO Box 11  
 Ph: 1-204-362-6865

Date	Invoice #
2026-01-19	2684

<b>Invoice To :</b>
Dale Klippenstein

<b>Customer :</b>
2020 Peterbilt 579 Vin: LD637032 Kms: 684723 Plate # CPU 562 Unit # 225

Quantity	Item	Description	Price Each	Amount
0.5	Labour	January 22, 2026 Replaced NOx sensor after turbo. Cleared codes. Replaced battery terminal on bunk heater power wire and reconnected.	100.00	50.00
1	prt	NOXPXX010-RWA Inlet NOx Sensor EPA 13/27	0.00	0.00
1	prt	Incoming Freight	0.00	0.00
1	prt	EGR Test Unit Rental Fee (hadn't billed on previous invoice # 2656)	142.50	142.50
1	prt	Shop Supplies	5.00	5.00

### Sales Tax Summary

GST@5.0%	9.88
<b>Total Tax</b>	<b>9.88</b>

<b>Total</b>			<b>\$207.38</b>
--------------	--	--	-----------------

**Dave's Diesel Ltd**

145 Clearview Drive  
 RM Of Rhineland, MB  
 PO Box 11  
 Ph: 1-204-362-6865

**Invoice**

Date	Invoice #
2026-02-13	2762

<b>Invoice To :</b>
Dale Klippenstein

<b>Customer :</b>
2020 Peterbilt 579 Vin: LD637032 Kms: 693926 Plate # CPU 562 Unit # 225

Quantity	Item	Description	Price Each	Amount
2.5	Labour	February 17, 2026 Truck service. Oil drain plug (1/4 turn plug) was finger loose when locked, replaced plug. Check and diagnose engine light on, same code for NOx sensor was present, replaced NOx sensor with new sensor and cleared codes.	100.00	250.00
1	prt	LF16368 Oil Filter	57.02	57.02
1	prt	CS41044 Oil Filter	73.75	73.75
1	prt	FS20260 Fuel Filter	99.61	99.61
1	prt	FS20208 Fuel Filter	59.25	59.25
44	Shell Rotell...	Shell Rotella 15W-40	5.61	246.84
1	Delo Grease	Delo Starplex EP2 Grease	5.92	5.92
1	prt	NOXPXX010-RWA Inlet NOx Sensor EPA 13/17	0.00	0.00
1	prt	Purolator Air Freight	0.00	0.00
1	prt	1982821PE Oil Drain Plug	14.96	14.96
1	prt	Shop Supplies	5.00	5.00

**Sales Tax Summary**

GST@5.0%	40.62
Total Tax	40.62

<b>Total</b>			<b>\$852.97</b>
--------------	--	--	-----------------

GST/HST No. 761327667

**Dave's Diesel Ltd**

145 Clearview Drive  
 RM Of Rhineland, MB  
 PO Box 11  
 Ph: 1-204-362-6865

**Invoice**

Date	Invoice #
2026-02-26	2788

<b>Invoice To :</b>
Dale Klippenstein

<b>Customer :</b>
2020 Peterbilt 579 Vin: LD637032 Kms: 696250 Plate # CPU 562 Unit # 225

Quantity	Item	Description	Price Each	Amount
0.5	Labour	February 26, 2026	100.00	50.00
1	prt	Replaced aftermarket NOx sensor and cleared codes. 2236409PEX NOX Sensor	1,300.90	1,300.90

**Sales Tax Summary**

GST@5.0% 67.55  
 Total Tax 67.55

<b>Total</b>			\$1,418.45
--------------	--	--	------------

GST/HST No. 761327667

**Dave's Diesel Ltd**

145 Clearview Drive  
 RM Of Rhineland, MB  
 PO Box 11  
 Ph: 1-204-362-6865

**Invoice**

Date	Invoice #
2026-03-12	2840

<b>Invoice To :</b>
Dale Klippenstein

<b>Customer :</b>
2020 Peterbilt 579 Vin: LD637032 Miles: 700302 Plate # CPU 562 Unit # 225

Quantity	Item	Description	Price Each	Amount
13	Labour	March 9, 2026 Truck was towed to shop, had 28 random codes, most were voltage too high and short circuit to supply codes. Checked battery + frame + cab + starter connections, all checked good. Checked main wiring harnesses for damage, found harness on back of engine drive side rubbed through and one wire damaged, repaired wires but codes remained. Checked multiple 5 volt supply sensors and circuits from ecm, checked good. ECM would intermittently not send out 5volt supply. Swapped ecms with another paccar, didn't make a difference. Noticed coolant pump was turning rough and sounded like metal on metal while turning by hand at certain spots. Replaced coolant pump and all codes cleared. Took for test drive, worked well. Driver side tool box handle was loose, drilled out rivets and fastened with new rivets.	100.00	1,300.00
1	prt	2184203-HAW Paccar MX13 EPA17 Water Pump	847.53	847.53
1	prt	Freight	55.00	55.00
1	Computer h...		60.00	60.00
1	prt	Shop Supplies	5.00	5.00

**Sales Tax Summary**

GST@5.0% 113.38  
 Total Tax 113.38

<b>Total</b>			\$2,380.91
--------------	--	--	------------

**Dave's Diesel Ltd**

145 Clearview Drive  
 RM Of Rhineland, MB  
 PO Box 11  
 Ph: 1-204-362-6865

**Invoice**

Date	Invoice #
2026-04-01	2883

<b>Invoice To :</b>
Dale Klippenstein

<b>Customer :</b>
2020 Peterbilt 579 Vin: LD637032 Kms: 706983 Plate # CPU 562 Unit # 225

Quantity	Item	Description	Price Each	Amount
8.25	Labour	March 30, 2026 Removed coolant filter housing and replaced O-ring on leaking 1/4 turn valve. Reassembled with new O-rings and replaced coolant filter. Replaced leaking coolant hose on engine heater. Replaced both fuel filters. Replaced leaking air compressor discharge hose. Replaced fuel return check valve on the back of engine. Diagnose tail lights not working, repaired multiple corroded wires in frame rail. Diagnose AC not working, found system was low after recovering remaining refrigerant. Pressure tested system, vacuumed, and filled to spec.	110.00	907.50
1	prt	FS20208 Fuel Filter	59.25	59.25
1	prt	FS20260 Fuel Filter	99.61	99.61
2	prt	SR528-1212 Reusable End 3/4-3/4	17.48	34.96
1	prt	WF2122 Coolant Filter	65.45	65.45
1	prt	1953296PE Non Return Fuel Check Valve	142.28	142.28
3	prt	2179472PE O-ring	1.43	4.29
8	prt	HO151-12 DOT Fabric Covered Hose	8.80	70.40
2	5526-075	3/4" Silicon Heater Hose PER/FT	5.66	11.32
1	Nitrogen	Nitrogen Fill	10.00	10.00
5	2480	A/C Pag oil	3.25	16.25
1	R134a	R134a Freon	32.00	32.00
1	prt	Shop Supplies	5.00	5.00

**Sales Tax Summary**

GST@5.0%	72.92
Total Tax	72.92

<b>Total</b>	<b>\$1,531.23</b>
--------------	-------------------