




Mound Services Inc.

Box 240
 129 Publow Ave.
 Pilot Mound, Manitoba R0G 1P0
 Canada
 moundinc@gmail.com

INVOICE

Invoice No.: [REDACTED]
 Date: [REDACTED]
 Ship Date: [REDACTED]
 Page: 1
 Re: Order No. [REDACTED]



Business No.: 122895295RP0001

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
			2004 Freightliner Columbia (441,423km) Customer Request: MB Safety Inspection			
SAF- HD TRUCK	Each	1.0	MB Safety - HD Tandem Truck	GP	250.00	250.00
Labour		2.0	- Remove all wheels to measure brakes.	GP	105.00	210.00
Labour		5.0	- Air leak behind dash. Remove dash covers and unscrew panels to access air manifold. Remove air lines and pressure switches. Changed out air manifold and re-connected everything. Had to order one switch. Installed switch and reassemble dash.	GP	105.00	525.00
Labour		1.5	- Replace bulbs on a couple of gauges. Test and confirm proper operation.	GP	105.00	157.50
Labour		0.5	- Cab of truck had low air flow. Replace cabin air filter.	GP	105.00	52.50
Labour		2.0	- Left side convex mirror broken. Removed old mirror and disconnect wires. Install new mirror and connect wires. Test and confirm proper operation.	GP	105.00	210.00
Labour		3.0	- Window washer not working. Remove and replace washer tank and install new pump that came with tank. Found nozzles were plugged. Remove and replace nozzles. Confirm proper operation.	GP	105.00	315.00
Labour		1.0	- Remove and replace both windshield wipers. Resecure mirrors on hood as they were loose.	GP	105.00	105.00
Labour		1.6	- Re-secure passenger step and bumper on left side.	GP	105.00	168.00
Labour		0.5	- Repair one clearance light	GP	105.00	52.50
Labour		2.0	- Power steering leak at reservoir. Removed and replaced supply line to pump. Changed filter and cap seal.	GP	105.00	210.00
Labour		1.5	- Locate and repair air leak at firewall	GP	105.00	157.50
Labour		1.5	- Re-secure left side fender. Put two bolts through the fender onto two brackets that were secured onto the frame of the truck.	GP	105.00	157.50
Labour		2.0	- Cleaned up all battery connections and sprayed batteries down with protector.	GP	105.00	210.00

Terms: Net 15. Due Aug 08, 2025.
 Comment: 25% RESTOCKING ON ALL RETURNED PARTS (*RETORQUE ALL REMOVED WHEELS WITHIN 100 KM)

Continue...




Mound Services Inc.

Box 240
129 Publow Ave.
Pilot Mound, Manitoba R0G 1P0
Canada
moundinc@gmail.com


INVOICE

Invoice No.: [REDACTED]
Date: Jul 24, 2025
Ship Date:
Page: 2
Re. Order No.

Sold to:



Ship to:



Business No.: 122895295RP0001

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
Labour		1.0	- Coolant leak on right side of engine. Clamps on coolant hose loose. Tightened clamps up and confirmed leaks were no longer present.	GP	105.00	105.00
Labour		2.0	- One brake pot needed to be changed from short stroke to long stroke. Air up tank and release brake. Disconnect slack adjuster from pot. Remove lines and bolts. Replaced brake pot. Installed all lines and connections and confirm proper operation.	GP	105.00	210.00
Labour		0.5	- Fitting on top of right rear air bag loose. Tightened up fitting and confirm no more leaks.	GP	105.00	52.50
Labour		2.0	- Re-install all wheels and torque to spec.	GP	105.00	210.00
Labour		1.0	- Adjust all brakes. Grease chassis and blow out hub vents.	GP	105.00	105.00
Misc.		1.0	Misc. Hardware- nuts, bolts, washers, zipties	GP	15.20	15.20
15-214x52	Each	1.0	Bug Wash	GP	5.55	5.55
123036		2.0	ATF +4 1L	GP	13.34	26.68
550027558	Each	1.0	Grease	GP	10.85	10.85
75088	Each	1.0	Brakleen Non-Chlorin (890.9107)	GP	7.67	7.67
97-21		2.0	Wiper blade	GP	15.86	31.72
WA3030TL		1.0	Brake pot	GP	127.96	127.96
FS-800516N		1.0	Control Valve	GP	435.15	435.15
G7046-04-06		2.0	Air brake fitting	GP	6.53	13.06
24318		1.0	Filter	GP	36.54	36.54
37CP		10.0	Miniature lamp	GP	0.78	7.80
85CP		10.0	Miniature lamp	GP	1.01	10.10
540873P		1.0	Side marker socket	GP	7.41	7.41
RRAUM575.10117		1.0	Washer tank	GP	165.03	165.03
RR101D/A12-1473		1.0	Air manifold	GP	407.66	407.66
6-003		1.0	Freight	GP	20.00	20.00
FRT		1.0	Power steering fluid	GP	34.92	34.92
57557		1.0	Premium Hose	GP	6.80	6.80
G234-075		1.0	45 Degree Brass elbow	GP	13.83	13.83
54-8C		6.0	Washers	GP	0.67	4.02
162-400		1.0	Washer nozzle	GP	35.24	35.24
47191		1.0	Fill Cap	GP	58.72	58.72
FRTLNRQ347367		1.0	PS Reservoir Gasket	GP	12.94	12.94
FRTLNR- Q79699		1.0	Convex mirror	GP	156.15	156.15
FRTLNR15401002		1.0	Freight	GP	15.00	15.00

Terms: Net 15. Due Aug 08, 2025.

Comment: 25% RESTOCKING ON ALL RETURNED PARTS (*RETORQUE ALL REMOVED WHEELS WITHIN 100 KM)

Continue...



Mound Services Inc.

Box 240
129 Publow Ave.
Pilot Mound, Manitoba R0G 1P0
Canada
moundinc@gmail.com

INVOICE



Date: Jul 24, 2025

Ship Date:

Page: 3

Re: Order No.



Business No.: 122895295RP0001

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount	
226/FSC2749-210		1.0	PR Switch	GP	40.63	40.63	
8							
FRT		1.0	Freight	GP	15.00	15.00	
		1.0	Shop Supplies	GP	65.00	65.00	
			Subtotal:			5,249.63	
			GP - GST 5%, PST 7%				
			GST			262.52	
			PST			367.52	
Mound Services Inc. GST: #R122895295 Mound Services Inc. PST: #PST#147767-6							
Shipped By: Tracking Number:					Total Amount	5,879.67	
Terms: Net 15. Due Aug 08, 2025.						Amount Paid	0.00
Comment: 25% RESTOCKING ON ALL RETURNED PARTS (*RETORQUE ALL REMOVED WHEELS WITHIN 100 KM)						Amount Owng	5,879.67
Sold By:							