Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
NOT COLD						
Labor Service - A/C HOLE.	HOSE, LOW SIDE, TO COM	PRESSOR LEAKING FROM A PIN	2.00		85.00	170.00
Sublet	A/C HOSE			1.00	68.00	68.00
New	REFRIGER	ANT		3.00	7.00	21.00
RIGHT MUD FLAP RIPE	PED OFF					
Labor Service - RIC	SHT MUD FLAP		0.50		85.00	42.50
New	MUDFLAP	24X30-1/2"		1.00	32.35	32.35
NOISE COMING FROM	SERPENTINE BELT UNDER	100D		W	1000 110 110 210 100 100	
Labor Service - SE NEED TO BE REPI		PULLEY BEARINGS ARE BAD AND	1.00		85.00	85.00
New	BEARING			2.00	14.13	28.26
.EPLACE RESERVIOR	SEAL					
Labor Service - RE	PLACE SEAL ON RESERVIOR	2	0.50		85.00	42.50
New	M61 - POW GASKET	ER STEERING RESERVOIR		1.00	7.10	7.10

Warranty	Posted 7/29/25 4:33PM		Invoice Summary	
COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30 DAY WARRANTY.  ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A 12 MONTH 12,000 MILE WARRANTY  I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thorato. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for attorneys fees in the event that defaults made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged.		504.43	Parts Labor Sublet Fluids	67.71 340.00 68.00 21.00
X Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.  Customer acknowledges receipt of merchandise and services.	Tax Breakdown: AZ State Tucson City	5.41 2.31	Sub Total Sales Tax (AZ)	496.71 7.72
Page 1 of 1 Discard old parts	Original Estimate:	504.43	Total	504.43



Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
REPLACE POWER STE	EERING FILTER					
Labor Service - R 8	R POWER STEERING FILTE	R	1.00		85.00	85.00
New	M41 - POWER STEERING FILTER			1.00	16.51	16.51
The vehicle needs a Cl	nassis Lubrication, Oil and Oi	If Filter maintenance service.	27		16.5	
SERVICE IS A LIT		ER, AIR FILTER, AND FUEL FILTER.  MPLE DUE TO A GALLON OF ATF IN  STEERING PUMP	1.00		85.00	85.00
New	15W40 P66	GUARDOL ECT CK4		11.00	17.61	193.71
New	AIRFILTER	₹		1.00	68.77	68.77
New	FILTER			1.00	18.73	18.73
New	OILFILTER	?		1.00	51.15	51.15
			Add On	Charges B	reakdown	
				EPA Disg	osal	4.00

Warranty	Posted 7/16/25 8:34A	M	Invoice Summary	
COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30 DAY WARRANTY.  ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A 12 MONTH 12,000 MILE WARRANTY	A/R Charge	553.22	Parts Labor Fluids	155.16 170.00 193.71
Thereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employe as may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs therefor. You will not be held or assorted for loss or dramage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for attorneys fells in the event that disfaults made in any payment due, if vehicle is returned to customer without repair service being performed, a diagnostic and handling fire (including reassembly) may be charged.  X  Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is complished may be subject to a storage fee.	Tax Breakdown: AZ State Tucson City	21.28 9.07	Add On Charges  Sub Total Sales Tax (AZ)	4.00 522.87
Customer acknowledges receipt of merchandise and services.			Dales tax (AZ)	30.35

22/2/1

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
REPLACE FRONT DRIV	E TIRES		***************************************			
Labor Service - MO TIRES	UNT 4 NEW FRONT DRIVE T	IRES. LABOR DONE BY ROBERTS			85.00	0.00
New	11R22.5 UN ALL-POS 1	NIROYAL HS2/MIXED SERVICE 6		4.00	336.75	1,347.00
POWER STEERING ST	LL HARD TO TURN					
LEAKED OUT OF F	Labor Service - TECH INSTALLED A USED PUMP LAST TIME AFTER OLD PUMP LEAKED OUT OF FRONT SEAL, NOW THE STEERING IS HARD TO TURN, TECH WILL ATTEMPT A NEW PUMP AND SEE IF PROBLEM CONTINUES.		2.00		85.00	170.00
New	M41 - POW	ER STEERING PUMP		1.00	382.38	382.38
			Add On	Charges B		18.64

Warranty COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30 DAY WARRANTY. ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A 12 MONTH 12,000 MILE WARRANTY Thereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for altorneys fees in the event that defaults made in any payment due. If we hicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged.	Posted 7/15/25 10:58AM A/R Charge	2,068.47	Invoice Summary Parts Labor Add On Charges	1,729.38 170.00 18.64
X Terms. CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.  X Customer acknowledges receipt of merchandise and services.	Tax Breakdown: AZ State Tucson City	105.49 44.96	Sub Total Sales Tax (AZ)	1,918.02 150.45
Page 1 of 1 Discard old parts	Original Estimate:	2,068.47	Total	2,068.47

Requests for Service	Services Performed	Hrs	Qty	Price	Ext
ITCH BROKEN				8	
NUMBER 2 PUSHER SWITC	CH BROKE AND NEEDS TO BE	1.00		85.00	85.00
REPLACED  New M18 - PUSHER SWITCH ( ON DASH )			1.00	79.42	79.42
			0,0		
Labor Service - THE POWER STEERING PUMP IS LEAKING FLUID INTO THE ENGINE. REMOVE AND REPLACE PUMP. PUMP IS A GOOD USED PUMP THAT CAME OFF OF M41 LAST YEAR.				85.00	170.00
YLINDER HOSE LEAKING (	воттом)				
	STRONG ARM CYLINDER.	1.50		85.00	127.50
3/4 HYDRA	ULIC HOSE		1,00	75.11	75.11
	POWER STEERING PUMP LAST YEAR.  YLINDER HOSE FOR RIGHT	NUMBER 2 PUSHER SWITCH BROKE AND NEEDS TO BE  M18 - PUSHER SWITCH ( ON DASH )  POWER STEERING PUMP IS LEAKING FLUID INTO THE AND REPLACE PUMP. PUMP IS A GOOD USED PUMP THAT LAST YEAR.  YLINDER HOSE LEAKING ( BOTTOM )  R LOWER HOSE FOR RIGHT STRONG ARM CYLINDER.	NUMBER 2 PUSHER SWITCH BROKE AND NEEDS TO BE  M18 - PUSHER SWITCH ( ON DASH )  POWER STEERING PUMP IS LEAKING FLUID INTO THE AND REPLACE PUMP. PUMP IS A GOOD USED PUMP THAT LAST YEAR.  YLINDER HOSE LEAKING ( BOTTOM )  R LOWER HOSE FOR RIGHT STRONG ARM CYLINDER.  1.50	NUMBER 2 PUSHER SWITCH BROKE AND NEEDS TO BE  M18 - PUSHER SWITCH ( ON DASH )  1.00  POWER STEERING PUMP IS LEAKING FLUID INTO THE AND REPLACE PUMP. PUMP IS A GOOD USED PUMP THAT LAST YEAR.  YLINDER HOSE LEAKING ( BOTTOM )  R LOWER HOSE FOR RIGHT STRONG ARM CYLINDER.  1.50	NUMBER 2 PUSHER SWITCH BROKE AND NEEDS TO BE  M18 - PUSHER SWITCH ( ON DASH )  1.00 79.42  POWER STEERING PUMP IS LEAKING FLUID INTO THE AND REPLACE PUMP. PUMP IS A GOOD USED PUMP THAT LAST YEAR.  YLINDER HOSE LEAKING (BOTTOM )  R LOWER HOSE FOR RIGHT STRONG ARM CYLINDER.  1.50 85.00

Warranty	Posted 7/11/25 1:24PM		Invoice Summary	
COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30 DAY WARRANTY.	A/R Charge	555.91	Parts Labor	154.53 382.50
ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A 12 MONTH 12,000 MILE WARRANTY			Supply Charge	5.00
I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An expression is acknowledged on said vehicle to secure the amount of repairs therefor. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, thoti, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for attorneys fees in the event that default is made in any payment due, if vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged.				
X	Tax Breakdown: AZ State	9.73		
Termis: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.	Tucson City	4.15		
_X	,		Sub Total	542.03
Customer acknowledges receipt of merchandise and services.			Sales Tax (AZ)	13.88
Page 1 of 1 Discard old parts	Original Estimate:	575.42	Total	555.91

52/01/2-

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
CHECK AND ADVISE O	ON COOLANT LEAK.				\$	
Labor Service - CO	OLANT HEADER / MANIFOLD	GASKET ON THE RIGHT SIDE OF	10.00		85.00	850.0
THE BLOCK IS LE	AKING AND NEEDS TO BE R	EPLACED, BIG JOB				00010
New	M61 - COO	LANT GASKET ( WATER HEADER		1.00	93.89	93.89
	COVER)	, , , , , , , , , , , , , , , , , , , ,			00.00	00.0
New	SIMPLE - S	EAL O RING		2.00	2.74	5.4
New	M61 - OIL 0	COOLER GASKET ( LOWER )		2.00	3.86	7.7
New		RECTANGULAR RING		2.00	7.14	14.28
New	M61 - SEAL			1.00	6.05	6.05
New	M61 - GAS	KET		1.00	2.22	2.22
New	FREIGHTLI	NER - WATER PUMP O RING		1.00	8.17	8.17
New	SEAL, THE	RMOSTAT		1.00	19.55	19.5
New	GASKET, S	SUPPORT		1.00	18.56	18.56
New	THERMOS	TAT		1.00	76.95	76.9
New	M17 - SEAL	., O RING		2.00	2.11	4.22
New	M61 - HEA	TER HOUSING GASKET		1.00	9.27	9.27
New	03 - TURBO	GASKET		1.00	2.34	2.34
New	SEAL O RI	'NG		1.00	7.63	7.63
New	SIMPLE - O	RING		1.00	2.98	2.98
New	SEAL, O RI	ING		1.00	7.63	7.63
New	SIMPLE - S	EAL		4.00	2.69	10.76
New	M61 - SEAL	. O RING		1.00	27.95	27.99
New	M61 - SEAL	. O RING		1.00	3.85	3.85
New		LANT FILTER		1.00	12.51	12.5
New	SEAL, O RI	NG .		2.00	2.18	4,36
New	M17 - SEAL	O RING		2.00	2.11	4.22
New	HEAVY DU	TY ELC DIESEL 50/50 (RED)		8.00	7.01	56.08
CHECK AND ADVISE O	N HYDRAULIC FLUID LEAK					
Labor Service - R &	R LARGE HYDRAULIC HOSE	UNDER REAR OF BED FOR	2.00		85.00	170.00
STRONG ARM						
New	ID HYDRAL	JLIC HOSE ASSY		1.00	130.00	130.00
New	MAXXPRO	3/MERCON		25.00	13.95	348.75
REPLACE RIGHT WIND	SHIELD					
Labor Service - R &	R RIGHT WINDSHIELD ( LAR	GE CRACK )				0.00
Sublet	*	BROKEN WINDSHIELD		1.00	125.00	125.08
New		SHIELD (RIGHT)		1.00	53.01	53.0
	19110 - 191146	orners (morn)		1.00	55.01	53.0



Warranty	Posted 7/07/25 11:58AM		Invoice Summary	
COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30	A/R Charge	2,181.38	Parts	533.60
DAY WARRANTY.			Labor	1,020.00
ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A			Sublet	125.00
12 MONTH 12,000 MILE WARRANTY  Thereby authorize the repair work listed herein, including sublet work, to be done along with necessary			Fluids	404.83
materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An expressiven is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all coffection costs and for attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged.			Supply Charge	15.00
X Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.	Tax Breakdown: AZ State Tucson City	58.16 24.79		
X Customer ac nowledges receipt of merchandise and services.	Tuddor Oily	24.70	Sub Total Sales Tax (AZ)	2,098.4 82.95
Discard old parts	Original Estimate:	2 231 60	Total	2 181 38

Page 2 of 2 Discard old parts Original Estimate: 2,231.60 **Total 2,181.38** 

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
CHECK AND ADVISE C	ON AIR LEAK FROM MUD FLA	PCHAMBER				
Labor Service - REI	PLACE MUD FLAP BRAKE CH BRAKE CH	HAMBER AMBER T20	2.00	1.00	85.00 67.55	170.00 67.55
BUILDING TOO MUCH	UP PRESSURE					
Labor Service - R & P/N : 72403073	R UP PRESSURE SWITCH.	PART SUPPLIED BY CUSTOMER	1.00		85.00	85.00

Warranty  COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30 DAY WARRANTY.  ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A 12 MONTH 12,000 MILE WARRANTY  I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express her is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for attorneys fees in the event that defeult is made in any purpment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged.	Posted 6/16/25 1:18PM A/R Charge	328.43	Invoice Summary Parts Labor	67.55 255.00
X Termis: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.  Customer acknowledges receipt of merchandise and services.	Tax Breakdown: AZ State Tucson City	4.12 1.76	Sub Total Sales Tax (AZ)	322.55 5.88
Page 1 of 1 Discard old parts	Original Estimate:	328.43	Total	328.43



Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
LEFT REAR DRIVE BR	AKE SHOES BROKEN					
	E LEFT REAR DRIVE BRAKE W SHOES NEEDED	SHOES LOST RIVETS AND LINING	1.00		85.00	85.00
New	REMAN SH	OE KIT		1.00	61.99	61.99
Core	Core Recei	ved		1.00	0.00	0.00
MULTIPLE DASH LIGH	TS			1100		
Labor Service - INS	TALL NEW BULBS FOR THE	RPM AND SPEED GAUGES	1.00		85.00	85.00
New	BULB, MINI			4.00	0.69	2.76

Warranty COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30 DAY WARRANTY. ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A 12 MONTH 12,000 MILE WARRANTY I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged.	Posted 6/11/25 4:03PM A/R Charge	245.81	Invoice Summary Parts Labor Supply Charge	64.75 170.00 5.00
X Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.  X Customer acknowledges receipt of merchandise and services.	Tax Breakdown: AZ State Tucson City	4.25 1.81	Sub Total Sales Tax (AZ)	239.75 6.06
Page 1 of 1 Discard old parts	Original Estimate:	251.47	Total	245.81



Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
The vehicle needs a Ch	nassis Lubrication, Oil and Oil	Filter maintenance service.		10		
Labor Service - CH, New New New New		ER, AIR FILTER, AND FUEL FILTER GUARDOL ECT CK4	1.00	11.00 1.00 1.00 1.00	85.00 17.61 67.35 18.68 47.64	85.00 193.7 67.39 18.66 47.6
CHECK AND ADVISE O	ON AIR LEAK			5000		
TO BE REPLACED	. IT IS A 2 SECTION HOSE AN	SSOR HAS A PIN HOLE AND NEEDS ND THE SECOND SECTION HAS E SECTION FROM KW AND ONE	1.50		85.00	127.50
New New	New 1/2 ID HYDRAULIC HOSE				68.20 128.83	68.20 128.8
HECK AND ADVISE O	N AIR LEAK WHILE BRAKING					
Labor Service - AIR BRAKE HOSE AT RIGHT REAR OF BED FOR STRONG ARM New 3/8 BRAKE HOSE		1.00	1.00	85.00 72.00	85.00 72.00	
LATCHES INOP						
Labor Service - PAS AND NEEDS TO BE		FOR LATCHES LEAKING BADLY	1.00		85.00	85.0
New	M34 - TAILG	GATE BRAKE POD		1.00	209.99	209.9
SEAL TAILGATE						
Labor Service - SE	AL TAILGATE WITH ROUND S	втоск	3.00		85.00	255.00
INSTALL RIVETS IN DR	RIVER DOOR				- X	
Labor Service - INS	STALL RIVETS		0.50		85.00	42.50
ROAD SERVICE						
Labor Service - ROAD SERVICE FOR MISSING MUD FLAP  1.00  Add On Char  EF		IUD FLAP	1.00		85.00	85.00
		Charges B EPA Disp		4,00		

5/22/25

Warranty	Posted 6/05/25 12:19PM		Invoice Summary	
COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30 DAY WARRANTY.  ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A 12 MONTH 12,000 MILE WARRANTY  I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials, You and your employees may operate like described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles lot in vehicle in case of fire, thoff, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for attomays fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and hendling fee (including reassembly) may be charged.	A/R Charge	1,667.30	Parts Labor Fluids Supply Charge Add On Charges	612.69 765.00 193.71 20.00 4.00
X Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage lea. X Customer acknowledges receipt of merchandise and services.	Tax Breakdown: AZ State Tucson City	50.41 21.49	Sub Total Sales Tax (AZ)	1,595.4 71.90
Page 2 of 2 Discard old parts	Original Estimate:	1,667.30	Total	1,667.30

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
RIGHT REAR PUSHER	TIRE					
Labor Service - MO New New	UNT A NEW RIGHT REAR PU 215/75R17. VALVE STE	5 UNIROYAL RS2 / REGIONAL AP	0.50	1.00	85.00 210.46 2.50	42.50 210.46 2.50
REPLACE STEER SHO	CKS					
Labor Service - REPLACE FRONT SHOCKS  New M18 - SHOCK (STEER)		1.00	2.00	85.00 75.45	85.00 150.90	
			Add On	Charges B	reakdown Fax	4.21

Warranty  COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30 DAY WARRANTY.  ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A 12 MONTH 12,000 MILE WARRANTY  Thereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or dramage to vohicle or articles loft in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for alturneys fees in the event that default is made in any payment due, if vehicle is returned to gustomer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged.	Posted 5/15/25 5:41PM A/R Charge	527.23	Invoice Summary Parts Labor Add On Charges	363.86 127.50 4.21
Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee  X  Customer acknowledges receipt of merchandise and services.	Tax Breakdown: AZ State Tucson City	22.20 9.46	Sub Total Sales Tax (AZ)	495.57 31.66
Page 1 of 1 Discard old parts	Original Estimate:	527.23	Total	527.23

25/21/2

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
PULLING RIGHT WHILI	E BRAKING					
		STER IS NOT STAYING ADJUSTED. SLACK ADJUSTER TO REPAIR	1.00		85.00	85.00
New M18 - SLACK ADJUSTER ( STEER )				1.00	108.99	108.99
DOT INSPECTION						
Labor Service - ANNUAL INSPECTION  New ANNUAL INSPECTION REPORT SHEETS.				1.00	100.00 9.99	100.00 9.99
BLOWER MOTOR NOT	BLOWING ON HIGH					
Labor Service - THERE IS A BURNT WIRE ON THE BACK OF THE BLOWER MOTOR SWITCH, TECH WILL CUT AND INSTALL A SPADE END ON WIRE TO REPAIR.					85,00	85.00
REAR PUSHER BRAKE	VALVE LEAKING					
	R BRAKE VALVE ON NUMBE		2.00		85.00	170.00
New	M34 - PUS	HER RELAY VALVE		1.00	42.79	42.79

Warranty COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30 DAY WARRANTY. ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A 12 MONTH 12,000 MILE WARRANTY  Thereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials, You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vohicle in case of fire, theft accident or any other cause beyond your control. Customer agrees to pay all collection costs and for attorneys fees in the event that default is made in any payment due, if vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged.  X  Terms: CASH unless arrangements made prior to authorization. Vehicles teft after repair is completed may be subject to a storage fee.  Customer acknowledges receipt of merchandise and services.	Posted 5/07/25 2:23PM A/R Charge  Tax Breakdown: AZ State Tucson City	10.17 4.34	Invoice Summary Parts Labor Supply Charge  Sub Total Sales Tax (AZ)	161.77 440.00 5.00
Page 1 of 1 Discard old parts	Original Estimate:	644.54	Total	621.28

2015/5

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
REPLACE RIGHT STRO	ONG ARM LIGHT AND GROM	WET			1	
Labor Service - R &	R LIGHT		0.50		85.00	42.50
New	2" ROUND I	LED RED ( 2 DIODE )		1.00	2.10	2.10
New		NIRE SEALED MARKER LAMP		1.00	2.12	2.12
New	GROMMET	- 2 INCH		1.00	1.07	1.07
REPLACE STRONG AR	M TIRES					
Labor Service - MO	UNT 2 NEW STRONG ARM T	IRES DUE TO BEING 5 YEARS OLD	1.00		85.00	85.00
New	11R22.5 SA	NLUN S605EFT LHS		2.00	290.99	581.98
New	VALVE STE	M		2.00	2.50	5.00
CHECK AND ADVISE O	N AIR LEAK WHEN BRAKING			11.00	12000	
Labor Service - R &	R BRAKE RELAY VALVE FO	R MIDDLE PUSHER	2.00		85.00	170.00
New	M34 - PUSI	HER RELAY VALVE		1.00	44.18	44.18
			Add On	Charges B	reakdown	
				AZ Tire 1	Тах	9,32

Warranty  COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30 DAY WARRANTY.  ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A 12 MONTH 12,000 MILE WARRANTY  I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of rapairs therefor. You will not be held responsible for loss or damage to vehicle or articles test in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for attorneys fees in the event that disfault is made in any payment due, if vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged.	Posted 4/25/25 4:12PM A/R Charge	1,009.51	Invoice Summary Parts Labor Supply Charge Add On Charges	636.45 297.50 10.00 9.32
Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.  X Customer acknowledges receipt of merchandise and services.	Tax Breakdown: AZ State Tucson City	39.43 16.81	Sub Total Sales Tax (AZ)	953.27 56.24
Page 1 of 1 Discard old parts	Original Estimate:	1,009.51	Total	1,009.51

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
NSTALL 3 LIGHT BAR					S to the state of	*
Labor Service - INST, New	ALL 3 LIGHT BAR. TRUCK I		1.00	4.00	85.00	85.00
		R		1.00	12.99	12.99
LEFT TAILLIGHT BROKE	N					
Labor Service - R & F New	R LIGHT LIGHT LED		0.50		85.00	42.50
				1.00	43.51	43.51
CHECK AND ADVISE ON	AIR LEAK					
Labor Service - REPL	ACE THE NUMBER 3 PUSH	BER VALVE UNDER WARRANTY	1.50		85.00	127.50
The vehicle needs a Cha	ssis Lubrication, Oil and Oi	Filter maintenance service.				
		ER, AIR FILTER, AND FUEL FILTER	1.00		85.00	85.00
New		GUARDOL ECT CK4		11.00	17.61	193.71
New	AIRFILTER			1.00	62.92	62.92
New New	FILTER			1.00	18.68	18.68
IVEW	OILFILTER			1.00	46.73	46.73
RIGHT MIDDLE PUSHER	SLACK ADJUSTER NEEDS	SHIMS				
Labor Service - THE NEEDS SHIMS ADDE		ACK ADJUSTER IS LOOSE AND	0.50		85.00	42.50
ADJUST THE BRAKES				200	1/2011	
Labor Service - BRAI	KE ADJUSTMENT		0.50		85.00	42.50
FRONT PUSHER SHAKIN	IG					
MULTIPLE BOLTS A	FRONT PUSHER IS SHAKIN ND SHIMMED ARMS BUT F SHOCKS TO REPAIR,	IG THE TRUCK, TECH TIGHTENED PROBLEM CONTINUED, NECESSARY	2.50		85.00	212.50
New	STEERING	STABILIZER		2.00	68.99	137.98
SPRAYER BROKEN / MIS	SSING					
Labor Service - INST	ALL SPRAYER		0.50		85.00	42.50
New	M34 - BRAS			1.00	11.62	11.62
New	M34 - BRAS	SS SPRAYER		1.00	40.64	40.64
LEFT TAILGATE LATCH	STICKING				700000	
Labor Service - CLEA	N OUT DEBRIS		0.50		85.00	42.50
			Add On	Charges B	reakdown	
				EPA Disp	osal	4,00

3113/25

Warranty	Posted 3/27/25 1:38PM		Invoice Summary	
COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30	A/R Charge	1,361.07	Parts	375.07
DAY WARRANTY.			Labor	722.50
ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A 2 MONTH 12,000 MILE WARRANTY			Fluids	193.71
hereby authorize the repair work listed herein, including sublet work, to be done along with necessary			Supply Charge	15.00
materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or atticles left in vehicle in cases of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged.			Add On Charges	4.00
	Tax Breakdown:			
X	AZ State	35.61		
Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.	Tucson City	15.18		
X			Sub Total	1,310.
Customer acknowledges receipt of merchandise and services.			Sales Tax (AZ)	50.79
Page 2 of 2 Discard old parts	Original Estimate:	1,361.07	Total	1,361.07

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
REPLACE TIP					S to be public the sales of the	
Labor Service - RE	PLACE SPRAYER TIP		0.50		85.00	42.50
New	M34 - BRA	SS NOZZLE		1.00	11.62	11.62
CHECK AND ADVISE O	N AIR LEAK WHILE BRAKIN	G				
	LIED. NECESSARY TO REMO	KE CHAMBER IS LEAKING WHEN DVE AND REPLACE THE BRAKE	1.00		85.00	85.00
New	TYPE 12 B	RAKE CHAMBER		1.00	29.99	29.99
RIGHT STEER MUD FL	AP REPAIR.					
		S FOR SOME REASON GOING THE WILL FLIP MUD FLAP TO REPAIR.	0.50		85.00	42.50
OLD COOLANT LEAK						
ENGINE FROM A F	ERE IS A COLD COOLANT LE FITTING, SYSTEM WILL NEE ED AND TEFLONED, AND RI		3.00		85.00	255.00
LEFT STEER HUB CAP	CRACKED			- 3	1900	
Labor Service - THE REPLACED	LEFT STEER HUB CAP HAS	S A CRACK AND NEEDS TO BE	0.50		85.00	42.50
New	94 - HUB C	AP ( STEER )		1.00	32.22	32,22
The Wiper Blades need	replacement.					
Labor Service - REI New	PLACE WIPER BLADES WIPER BLA	ADE HD	0.50	2.00	85.00 11.99	42.50 23.98
INSTALL USED/REPAIR	RED TARP					
	RP IS RIPPED. TECH WILL IN DUSLY REPAIRED ACROSS	ISTALL A GOOD USED TARP THAT THE STREET	1.00		85.00	85.00
LEFT REAR PUSHER W	HEEL WOBBLE					
Labor Service - ADJ	UST THE BEARINGS ON TH	E LEFT REAR PUSHER	0.50		85.00	42.50
WIRES HANGING						
Labor Service - ADD	BOLT AND HANGER TO ST	RONG ARM FOR WIRING	0.50		85.00	42.50
REPLACE NUMBER 2 F	PUSHER SHOCKS			500		
	PLACE THE SHOCK STABILIZ	ZERS FOR THE NUMBER 2 PUSHER	1.00		85.00	85.00
New	STEERING	STABILIZER		2.00	68.99	137.98
REPLACE RIGHT HEAD	PLIGHT HOUSING	powering Army C			11.0	- WE-WE
		NG HAS STRIPPED HOLES AND ARY TO REPLACE THE HOUSING TO	2.50		85.00	212.50
New	05 - HEADL	IGHT HOUSING		1,00	109.99	109.99



20 81 25

Warranty	Posted 3/06/25 11:12AM		Invoice Summary	
COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30	A/R Charge	1,577.17	Parts	395.28
DAY WARRANTY.			Labor	1,147.50
ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A 12 MONTH 12,000 MILE WARRANTY				
hereby authorize the repair work listed herein, including sublet work, to be done along with necessary naterials. You and your employees may operate the described vehicle for the purposes of testing, nespection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of operats therefor. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay affection costs and for attorneys loss in the event that default is made in any payment due, if vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged.				
	Tax Breakdown:			
Χ	AZ State	24.11		
Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee	Tucson City	10.28		
Y	, , , , , , , , , , , , , , , , , , , ,		Sub Total	1,542.7
Customer acknowledges receipt of merchandise and services.			Sales Tax (AZ)	34.39
Page 2 of 2 Discard old parts	Original Estimate:	1,577.17	Total	1,577.17

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
REPLACEMENT					1	
	E DRIVER SIDE WINDSHIELD OOL CAT WILL INSTALL WIND	TOOK A LARGE ROCK TO IT A	ND			0.00
Sublet	REPLACE &	BROKEN WINDSHIELD.		1.00	131.00	131.00
New	M18 - WINE	SHIELD ( LEFT )		1.00	50.73	50.73
EFT REAR INSIDE TIP	RE FLAT					
Labor Service - PA	TCH THE LEFT REAR INSIDE	DRIVE TIRE	0.50		85.00	42.50

Warranty COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30 DAY WARRANTY. ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A 12 MONTH 12,000 MILE WARRANTY  Thereby authorize the repair worklisted herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs therato. You will not be hold responsible for loss or damage to vehicle or articles loft in vehicle in case of fire theft accident or any other cause beyond your control. Customer agrees to pay all collection costs and for altorneys fees in the event that default is made in any payment due. If whicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged.	Posted 2/07/25 10:21AM A/R Charge	234.08	Invoice Summary Parts Labor Sublet Supply Charge	50.73 42.50 131.00 5.00
X Terms: CASH unless arrangements made prior to authorization. Vahicles left after repair is completed may be subject to a storage fee. X Customer acknowledges receipt of merchandise and services.	Tax Breakdown: AZ State Tucson City	3.40 1.45	Sub Total Sales Tax (AZ)	229.23 4.85
Page 1 of 1 Discard old parts	Original Estimate:	234.08	Total	234.08

25 0 5

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
EFT MUD FLAP MISSI	NG		14.10			
Labor Service - THE TO BACK DAYS	LEFT MUD FLAP IS MISSIN	IG. INSTALL NEW MUD FLAP. BACK	1.00		85.00	85.00
New	MUDFLAP	24X30-1/2"		2.00	32.35	64.70
MUD FLAP SWITCH FE	LL OUT OF MOUNT					
	MUD FLAP SWITCH FELL ( ND RE INSTALL WITH NEW	OUT OF THE MOUNT. NECESSARY NUT TO REPAIR.	0.50		85.00	42.50
WASHERS INOP						
	ON SWITCH NOT WORKING	RE NOT WORKING. TECH FOUND . NECESSARY TO REMOVE AND	2.00		85.00	170.00
New	M41 - TURI	SIGNAL SWITCH		1.00	114.68	114.6
GHT REAR INNER DE	IVE TIRE FLAT					
STICKING VALVE O		ULD NOT FIND LEAK, POSSIBLE LE. WILL CHECK AGAIN IN A DAY OR	1.00		85.00	85.00
ADJUST HEADLIGHTS						
Labor Service - ADJ	UST HEADLIGHTS		0.50		85.00	42.50
RIGHT REAR PUSHER	BOLT MISSING					A SULL CONTRACTOR OF THE SURVEY
		T FOR THE LOWER ARM ( RAISE L NEW BOLT, NUT, AND WASHERS	1.00		85.00	85.00
CHECK AND ADVISE O	N AIR LEAK		-			
Labor Service - MIS	C AIR LEAK REPAIR WHILE	MATT WAS GONE FOR THE DAY	1.00		85.00	85.00
ROAD SERVICE						
	AD SERVICE FOR LEFT STE AND KEEP RIGHT TIRE AS	ER TIRE FLAT. TECH WILL INSTALL :	2 3.00		85.00	255.00
New	385/65R22. SERVICE A	5 SUMITOMO ST720 MIXED		2.00	476.04	952.00
New	VALVE STE			2.00	2.50	5.00



Warranty	Posted 2/05/25 2:00PM	2 006 20	Invoice Summary	1,136.46
COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30 DAY WARRANTY.  ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A 12 MONTH 12,000 MILE WARRANTY	A/R Charge	2,096.20	Parts Labor Supply Charge	850.00 10.00
I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express len is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be hold responsible for loss or damage to vehicle or articles left in vehicle in case of fire. Theft, accident or any other cause beyond your control. Customer agrees to pay aff collection costs and for allomeys fees in the event that defaults made in any payment due. If whicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged.				
X Terms: CASH unless arrangements made prior to authorization. Vulnicles left after repair is completed may be subject to a storage lee.  X Customer acknowledges receipt of merchandise and services.	Tax Breakdown: AZ State Tucson City	69.93 29.81	Sub Totai Sales Tax (AZ)	1,996. 99,74
Page 2 of 2 Discard old parts	Original Estimate:	2,493.71	Total	2,096.20

Page 2 of 2

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
TOP OF HYDRAULIC F	LUID					
Labor Service - HYD New		3/MERCON	0.25	3.00	85.00 18.28	21.25 54.84
RIGHT REAR DRIVE BE	RAKE SHOES FELL APART					
Labor Service - THE BE REPLACED SS		SHOES FELL APART AND NEED TO	1.50		85.00	127.50
New	REMAN SH	OE KIT		1.00	57.94	57.94
Core	Core Recei	ved		1.00	0.00	0.00
RIGHT STRONG ARM L	IGHT INTERMITTENT			-	- 11	
Labor Service - R & New	R LIGHT	RED LIGHT	0.50	1.00	85.00 8.34	42.50 8.34
EPAIR MUD FLAPS						
Labor Service - REF	PAIR MUD FLAPS		0.50		85.00	42.50
Technician Certification	ons:		-			

Warranty COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30 DAY WARRANTY. ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A 12 MONTH 12,000 MILE WARRANTY I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in caso of fire, theft accident or any other cause beyond your control. Customer agrees to pay all collection costs and for alturneys fees in the event that defaults made in any payment due, if vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged.	Posted 1/21/25 10:17AM A/R Charge	370.84	Invoice Summary Parts Labor Fluids Supply Charge	66.28 233.75 54.84 5.00
Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.  Customer acknowledges receipt of merchandise and services.	Tax Breakdown: AZ State Tucson City	7.69 3.28	Sub Total Sales Tax (AZ)	359.87 10.97
Page 1 of 1 Discard old parts	Original Estimate:	380.65	Total	370.84

25/21/1			

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
CHECK AND ADVISE	ON AIR LEAK NUMBER 3 PU	ISHER				
Labor Service - NU	MBER 3 PUSHER VALVE LE	EAKING AIR WHEN PUSHER IS DOWN.	2.50		85.00	212.5
TECH WILL INSTA	LL A NEW VALVE TO REPA			4.00		
IVEW	M18 - PU	SHER VALVE ( AFTERMARKET )		1.00	77.09	77.0
REMOVE SAMPLE DO	OR FROM TAILGATE				- 200	
Labor Service - RE CAUSING ISSUES		OM CENTER OF TAILGATE DUE TO IT	5.00		85.00	425.0
RIGHT STRONG ARM	LIGHT INOP		100			
Labor Service - R	& R LIGHT		0.50		85.00	42.50
SPRAYER NOT SPRA	YING GREAT		State			
Labor Service - MI	SC SPRAYER REPAIR		0,50		85.00	42,50
EFT MUD FLAP NEE	OS REPLACED					
	E LEFT MUD FLAP IS DAMA	AGED AND NEEDS TO BE REPLACED	0.50		85.00	42.5
New	MUDFLAI	P 1/2X24X36 ANTI SAIL/SPRAY		1.00	33.01	33.0
REPLACE 4 REAR DR	IVE TIRES					
	PLACE 4 REAR DRIVE TIRE	ES	2.00		85.00	170.0
New	11R22.5 U ALL-POS	UNIROYAL HS2/MIXED SERVICE		4.00	355.72	1,422.8
New	VALVE S			4.00	2.50	10.0
REPLACE POWER ST	EERING FILTER					
Labor Service - R 8	R FILTER AND DRAIN AND	O FILL SYSTEM	1.00		85.00	85.00
New	M41 - PO	WER STEERING FILTER		1.00	16.51	16.5
New	MAXXPR	O 3/MERCON		2.00	18.28	36.50
The vehicle needs a C	hassis Lubrication, Oil and (	Oil Filter maintenance service.			- 33.51	
	-	TER, AIR FILTER, AND FUEL FILTER	1.00		85.00	85.0
New		66 GUARDOL ECT CK4		11.00	17.61	193.7
New New	AIR FILTE FILTER	ER .		1.00	62.92	62.9
New	OILFILTE	ER .		1.00 1.00	17.90 46.73	17.99 46.73
			Add On	Charges B	reakdown	
				AZ Tire 1		8.0
				EPA Disp		4.0

15 08 51

Narranty San Control of the Control	Posted 1/09/25 9:48AM		Invoice Summary	
COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30	A/R Charge	3,228,29	Parts	1,687.04
DAY WARRANTY.			Labor	1,105.00
ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A			Fluids	230.27
12 MONTH 12,000 MILE WARRANTY  hereby authorize the repair work listed herein, including sublet work, to be done along with necessary			Supply Charge	25.00
materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express ken is acknowledged on said vehicle to secure the amount of apairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft accident or any other cause beyond your control. Customer agrees to pay all collection costs and for altomeys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) way one charged.			Add On Charges	12.00
X  Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.  X	Tax Breakdown: AZ State Tucson City	118,48 50,50	Sub Total	3,059.3
Customer acknowledges receipt of merchandise and services.	Original Estimates	2 222 22	Sales Tax (AZ)	168.98
Page 2 of 2 Discard old parts	Original Estimate;	3,228.29	Total	3,228.2

Page 2 of 2

85.00 42.5 11.31 11.3
11.31 11.3
18.28 18.2
85.00 42.5
49.50 49.5
85.00 42.5 2.69 5.3
85.00 85.0

Warranty  COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30 DAY WARRANTY.  ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A 12 MONTH 12,000 MILE WARRANTY  Increby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing inspection or delivery at myrisk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be hold responsible for loss or damage to vehicle or articles left in vehicle in case of fire, thoft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged.	Posted 12/18/24 1:52PM A/R Charge	304.32	Invoice Summary Parts Labor Fluids	66.19 212.50 18.28
X Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee X Customer acknowledges receipt of merchandise and services.	Tax Breakdown: AZ State Tucson City	5.15 2.20	Sub Total Sales Tax (AZ)	296.97 7.35
Page 1 of 1 Discard old parts	Original Estimate:	304.32	Total	304.32

145 101 5

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext	
ADJUST HEADLIGHTS					*		
Labor Service - AD	JUST HEADLIGHTS FR		0.50		85.00	42.50	
ADJUST THE BRAKES							
Labor Service - ADJUST ALL BRAKES AND REPAIR THE RIGHT REAR DRIVE. RIGHT REAR DRIVE MISSING PINS FOR SLACK ADJUSTER FR			1.00		85.00	85.00	
BED CAMERA INOP			X				
Labor Service - DRIVER SOMEHOW MESSED UP THE CAMERA. TECH WAS ABLE TO PUSH A BUNCH OF BUTTONS TO REPAIR FR		0.50 85.00		85.00	42.50		
Technician Certification	ons:				777070	-	
• FR							

Warranty	Posted 12/09/24 1:12PM		Invoice Summary	
COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30 DAY WARRANTY.	A/R Charge	175.44	Labor	170.00
ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A 12 MONTH 12,000 MILE WARRANTY			Supply Charge	5.00
I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An expressilen is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or actions left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for altorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged.				
X Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed	Tax Breakdown: AZ State	0.31		
may be subject to a storage fee	Tucson City	0.13		
Customer acknowledges receipt of merchandise and services.			Sub Total Sales Tax (AZ)	175.00 0.44
Page 1 of 1 Discard old parts	Original Estimate:	181.09	Total	175.44

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
PASSENGER MIRROR	LOOSE					
Labor Service - TIGHTEN MIRRORS		0.25		85.00	21.25	
TIP DAMAGED						
Labor Service - INS New	STALL NEW SPRAYER TIP M34 - BRAS	SS NOZZLE	0.25	1.00	85.00 9.99	21.25 9.99

Warranty COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30 DAY WARRANTY.  ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A 12 MONTH 12,000 MILE WARRANTY  Thereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials, You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be hold responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft accident or any other cause beyond your control. Customer agrees to pay all collection costs and for atterneys fees in the event that default is made in any payment due, (I vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged.		53.36	Invoice Summary Parts Labor	9.99 42.50
Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.  X  Customer acknowledges receipt of merchandise and services.	Tax Breakdown: AZ State Tucson City	0.61 0.26	Sub Total Sales Tax (AZ)	52.49 0.87
Page 1 of 1 Discard old parts	Original Estimate:	56.13	Total	53.36

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
BOTH MUD FLAPS DA	MAGED					
Labor Service - BO' CUT TO FIT ) SS	TH MUD FLAPS ARE DAMAG	ED AND NEED TO BE REPLACED (	0.50		85.00	42.50
New	MUD FLAP	24X40-12"		2.00	49.50	99.00
LEFT REAR OUTSIDE I	DRIVE TIRE FLAT					
Labor Service - THE LEFT REAR OUTSIDE DRIVE TIRE IS FLAT AND NEEDS TO BE REPAIRED SS, FR		0.50		85.00	42.50	
CHECK AND ADVISE C	N AIR LEAK WHILE BRAKING	3				-
Labor Service - THE LEFT REAR PUSHER BRAKE CHAMBER IS LEAKING INTERNALLY WHEN BRAKING. NECESSARY TO REMOVE AND REPLACE THE BRAKE CHAMBER TO REPAIR		1.00		85.00	85.00	
New	TYPE 12 BI	RAKE CHAMBER		1.00	32.99	32.99

- FF
- SS

Warranty COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30 DAY WARRANTY.	Posted 12/03/24 12:53PM A/R Charge	313.47	Invoice Summary Parts	131.99
ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A 12 MONTH 12,000 MILE WARRANTY  Thereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thoroto. You will not be hold responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for altorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged.			Labor	170.00
Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.  Customer acknowledges receipt of merchandise and services.	Tax Breakdown: AZ State Tucson City	8.05 3.43	Sub Total Sales Tax (AZ)	301.99 11.48
Page 1 of 1 Discard old parts	Original Estimate:	313.47	Total	313.47

HS 21 //

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
CHECK AND ADVISE O	N AIR LEAK WHILE BRAKIN	G	•			
	HT REAR DRIVE BRAKE CH. ST RUBBED ALL THE WAY 1	AMBER IS LEAKING AND HOSES THROUGH FR	2.00		85.00	170.00
New	3/8 BRAKE	HOSE		1.00	41,27	41.27
New	BRAKE CH	IAMBER 3030 COMBO		1.00	44.19	44.19
CHECK AND ADVISE O	N OIL LEAK					
Labor Service - TIGHTEN DIPSTICK TUBE ( LEAKING ) FR		0.50		85.00	42.50	
PRESSURE WASH VEH	ICLE					
Labor Service - PO\	VER WASH		2.00		85.00	170.00
CHECK AND ADVISE O	N HYDRAULIC FLUID LEAK			8-0		777
THE STRONG ARM	MANIFOLD HAVE COME OF	FILTER HOUSING ON THE SIDE OF UT WITH THE THREADS. TECH WILL DITEST TO REPAIR. MW, SS	4.00		85.00	340.00
New	MAXXPRO	3/MERCON		25.00	18.28	457.00

#### **Technician Certifications:**

- FR MW

Warranty	Posted 11/13/24 4:06F	PM	Invoice Summary	
COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30 DAY WARRANTY.  ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A 12 MONTH 12,000 MILE WARRANTY  Thereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to excure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire theft accident or any other cause beyond your control. Customer agrees to pay all collection costs and for attorneys fees in the event that defaults made in any payment due, if vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged.	A/R Charge	1,355.63	Parts Labor Fluids Supply Charge	85.46 722.50 457.00 40.00
X Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.  X Customer acknowledges receipt of merchandise and services.	Tax Breakdown: AZ State Tucson City	35.53 15.14	Sub Total Sales Tax (AZ)	1,304.96 50.67
Page 1 of 1 Discard old parts	Original Estimat	e: 1,355.63	Total	1,355.63

HS 18 31

Requests for Service	Services Performed	Hrs	Qty	Price	Ext
LIGHTS					
		0.50		85.00	42.50
PIG I AIL-3-	WIRE PLUG IN		1.00	2.32	2.32
IRE NEEDS REPLACED					****
	HAS A HOLE IN THE SIDEWALL AND	0.50		85.00	42.50
215/75R17.	5 UNIROYAL RS2 / REGIONAL AP		1.00	210.46	210.46
assis Lubrication, Oil and Oi	l Filter maintenance service.				
ANGE ENGINE OIL, OIL FILT	ER, AIR FILTER, AND FUEL FILTER	1.00		85.00	85.00
15W40 P66	GUARDOL ECT CK4		11.00	17.61	193.71
			1.00	62.92	62.92
			1.00	17.90	17.90
OILFILTER	1000		1.00	59.94	59.94
ons:					
				11:37.2	
		Add On	Charges B	reakdown	
			AZ Tire	Тах	2.00
			EPA Disp	posal	4.00
	IRE NEEDS REPLACED  LEFT REAR PUSHER TIRE  SS  215/75R17.  ANGE ENGINE OIL, OIL FILTI  15W40 P66  AIR FILTER  FILTER	PAIR LIGHTS SS  PIGTAIL-3-WIRE PLUG IN  IRE NEEDS REPLACED  LEFT REAR PUSHER TIRE HAS A HOLE IN THE SIDEWALL AND OSS  215/75R17.5 UNIROYAL RS2 / REGIONAL AP  MASSIS Lubrication, Oil and Oil Filter maintenance service.  ANGE ENGINE OIL, OIL FILTER, AIR FILTER, AND FUEL FILTER  15W40 P66 GUARDOL ECT CK4  AIR FILTER  OIL FILTER  OIL FILTER	PAIR LIGHTS SS PIGTAIL-3-WIRE PLUG IN  IRE NEEDS REPLACED  LEFT REAR PUSHER TIRE HAS A HOLE IN THE SIDEWALL AND 0.50 SS 215/75R17.5 UNIROYAL RS2 / REGIONAL AP  LASSIS Lubrication, Oil and Oil Filter maintenance service.  ANGE ENGINE OIL, OIL FILTER, AIR FILTER, AND FUEL FILTER 1.00 15W40 P66 GUARDOL ECT CK4 AIR FILTER FILTER OIL FILTER OIL FILTER	PAIR LIGHTS SS  PIGTAIL-3-WIRE PLUG IN  IRE NEEDS REPLACED  LEFT REAR PUSHER TIRE HAS A HOLE IN THE SIDEWALL AND 0.50  OSS  215/75R17.5 UNIROYAL RS2 / REGIONAL AP  1.00  LANGE ENGINE OIL, OIL FILTER, AIR FILTER, AND FUEL FILTER 1.00  AIR FILTER 1.00  OIL FILTER 1.00	PAIR LIGHTS   SS

Warranty  COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30 DAY WARRANTY.  ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A 12 MONTH 12,000 MILE WARRANTY  Thereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An expression is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be hold responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and /or altroneys fees in the event that dufault is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged.	- Control of the cont	770.86	Invoice Summary Parts Labor Fluids Add On Charges	353.54 170.00 193.71 6.00
X Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.  X Customer acknowledges receipt of merchandise and services.	AZ State Tucson City	33.38 14.23	Sub Total Sales Tax (AZ)	723.25 47.61
Page 1 of 1 Discard old parts	Original Estimate	781.94	Total	770.86

125/24

-

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
FRONT ENGINE MOUN	ITS GONE					
Labor Service - FRONT ENGINE MOUNTS ARE COMPLETELY WORN OUT AND NEED TO BE REPLACED SS		1.50		85.00	127.50	
New	94 - ENGIN	E MOUNT KIT ( FRONT )		1.00	166.75	166.75
DRAGGING NOISE					201000	
	TH FRONT DRIVE AXLE BAC H WILL REMOVE BACKING P	KING PLATES ARE DRAGGING ON LATES TO REPAIR. SS, FR	1.00		85.00	85.00
EXHAUST LEAK FROM	ENGINE AREA.					
Labor Service - MA	NIFOLD GASKETS LEAKING	FR	8.00		85.00	680.00
New	03 - TURBO	) GASKET		1.00	2.48	2.48
New	SIMPLE - O	RING		1.00	2.92	2.92
New	M18 - SEAL	, O RING		1.00	2.79	2.79
New	03 - EXHAL	IST MANIFOLD GASKET		4.00	6.96	27.84
New	M61 EXH	AUST MANIFOLD GASKET		2.00	7,17	14.34
New	03 - TURBO	) GASKET		1.00	10,66	10.66
CHECK AND ADVISE O	ON COOLANT LEAK.					
Labor Service - R 8	R WATER PUMP, LEAKING	FROM WEEP HOLE FR	3.00		85.00	255.00
New	M18 - WAT			1.00	1.012.68	1.012.6
Sublet	SHIPPING (	CHARGES		1.00	50.00	50.00
New	HEAVY DU	TY ELC DIESEL 50/50 (RED)		5.00	6.61	33.09
New	FREIGHTLI HOUSING)	NER - HOSE (THERMOSTAT		1.00	36.53	36.53
Technician Certificati	ons:	1000-0				3/1
• FR						
• SS						

## Continued from previous page

Ma of of

Warranty	Posted 10/18/24	5:37PM		Invoice Summary	
COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30	A/R Charge		2,632.38	Parts	1,276.99
DAY WARRANTY.				Labor	1,147.50
ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A 12 MONTH 12,000 MILE WARRANTY				Sublet	50.00
hereby authorize the repair work listed herein, including sublet work, to be done along with necessary				Fluids	33.05
materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or deliviery at my risk. An expression is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for altomeys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged.				Supply Charge	10.00
	Tax Breakdown:				
X	AZ State		80.52		
Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.	Tucson City		34.32		
X				Sub Total	2,517.5
Customer acknowledges receipt of merchandise and services.				Sales Tax (AZ)	114.84
Page 2 of 2 Discard old parts	Original Es	stimate;	2,632.38	Total	2,632.38

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
RIGHT MUD FLAP TOR	N					
Labor Service - INST	TALL NEW RIGHT MUD FLAF	FR	0.50		85.00	42.50
New	MUD FLAP	24X36X1/2		1.00	17.00	17.00
SERVICE POWER STEE	RING FLUID					
Labor Service - ADE A SHOP SUPPLY S		TIONER TO SYSTEM. CHARGED AS	1.00		85.00	85.00
REMOVE LIGHTS FROM	UNDER DOORS	10 211				10-20
Labor Service - REM	NOVE LIGHTS FROM UNDER	THE DOORS FR	0.50		85.00	42.50
MUD FLAP SWITCH NE	EDS REPAIRED					
	MUD FLAP SWITCH FELL II IED OUT AND RE INSTALLE	NTO THE CENTER CONSOL AND D SS	0.50		85.00	42.50
KEPAIR SPRAYER						
Labor Service - REP	AIR SPRAYER NOZZLES ( C	LEAN OUT DEBRIS ) FR	0.50		85.00	42,50
CHECK AND ADVISE O	N AIR LEAK					
Labor Service - R & FR	R FRONT PUSHER VALVE.	LEAKING AIR FROM EXHAUST PORT	2.50		85.00	212.50
New	M18 - PUSI	HER VALVE		1.00	175.28	175.28
LEFT REAR PUSHER W	HEEL SEAL LEAKING					
Labor Service - THE OUTER BEARING IS		EL SEAL IS LEAKING AND THE	1.50		85.00	127.50
New	M17 - PUSH	ER BEARING (OUTER)		1.00	43.90	43.90
REPAIR DASH			W-1984			
Labor Service - REP	AIR DASH FR		0.50		85.00	42.50
PRESSURE STUCK AT	120 PSI.		HIIO .	HUSICH"	(1	
Labor Service - R &	R GOVERNOR SS		0.50		85.00	42.50
New	SUPER - V	ALVE KIT ( DRYER / GOVERNER)	-	1.00	115.32	115.32
WELD DOOR ON TAILG	ATE	1000		S-14.0-1		
Labor Service - WEL FUNCTION SS	D DOOR HANDLES TO MAI	KE LITTLE TAILGATE DOOR	0.50		85,00	42.50
Recommended Repair	s and Services:					
EXHAUST LEA	K FROM ENGINE AREA.					50.37
· CHECK AND A	DVISE ON COOLANT LEAK.					1,062.68

- FR SS

## Continued from previous page

112 HE 6

Warranty	Posted 10/07/24 2:52PM		Invoice Summary	
COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30	A/R Charge	1,126.32	Parts	351.50
DAY WARRANTY.			Labor	722.50
ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A I2 MONTH 12,000 MILE WARRANTY			Supply Charge	20.00
hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, nepection or delivery at my risk. An expressilent is acknowledged on said vehicle to secure the amount of epairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for attorneys less in the event that defaults made in any payment due, if vehicles returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged.				
X  Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.	Tax Breakdown: AZ State Tucson City	22. <b>6</b> 6 9.66		
X Customer acknowledges receipt of merchandise and services	,		Sub Total Sales Tax (AZ)	1,094.0 32.32
Page 2 of 2 Discard old parts	Original Estimate:	1,930.55	Total	1,126,32

Page 2 of 2

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
HYDRAULIC FLUID				1	1	
Labor Service - HY New	DRAULIC FLUID SS MAXXPRO	3/MERCON		2.00	85.00 18.28	0.00 36.56
BED CAMERA INOP						
Labor Service - TECH FOUND A BROKEN WIRE FOR THE POWER TO THE CAMERA. NECESSARY TO BUTT CONNECT WIRE TO REPAIR. SS			0.50		85.00	42.50
LEFT REAR OUTER DU	JAL FLAT					
Labor Service - FLA	AT REPAIR SS		0.50		85.00	42.50
Recommended Repair	rs and Services:		100			
. EVWALIGT LE	AK FROM ENGINE AREA.					50.37

Warranty COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30	Posted 9/19/24 12:40PM A/R Charge	130.18	Invoice Summary Labor	85.00
DAY WARRANTY. ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A		100.10	Fluids	36.56
12 MONTH 12,000 MILE WARRANTY			Supply Charge	5.00
I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the discribed vehicle for the purposes of testing inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for attorneys fees in the event that default is made in any payment due. (I vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged.				
X  Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed.	Tax Breakdown: AZ State	2.54		
may be subject to a storage fee.	Tucson City	1.08	Sub Total	126.56
Customer acknowledges receipt of merchandise and services.			Sales Tax (AZ)	3.62
Page 1 of 1 Discard old parts	Original Estimate:	130.28	Total	130.18

Vehicle Problems	Requests for Service	Services Performed	Hrs Qty	Price	Ext
LEFT STEER OUTER H	UB SEAL LEAKING	1			
Labor Service - THE REPLACED SS	E LEFT STEER HUB CAP SE	AL IS LEAKING AND NEEDS TO BE	0.50	85.00	42.50
CHECK AND ADVISE O	ON AIR LEAK UNDER CAB		Man -		
Labor Service - REF	PAIR 2 AIR HOSES UNDER C	AB SS, FR	1.00	85.00	85.00
ADJUST NEW CLUTCH	1				
Labor Service - AD.	JUST NEW CLUTCH AFTER 2	DAYS OF USE SS, FR	0.50	85.00	42.50
STEERING LOOSE				198	
Labor Service - TIG	HTEN GEAR BOX AND TIGH	TEN PITMAN ARM BOLT FR, MW	1.00	85.00	85.00
Recommended Repair	rs and Services:	A 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	18,000		
EXHAUST LEA	AK FROM ENGINE AREA.				50.37
Technician Certification	ons:	0.000.00			

- FR MW SS

Warranty	Posted 9/12/24 3:31PM		Invoice Summary	
COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30 DAY WARRANTY. ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A 12 MONTH 12,000 MILE WARRANTY	A/R Charge	255.00	Labor	255.00
I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An expression is acknowledged on said vehicle to secure the amount of repairs therefor. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged.				
X Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed	Tax Breakdown.			
may be subject to a storage fee.			Sub Total	255.00
Customer acknowledges receipt of merchandise and services.			Sales Tax (AZ)	255.00
Customer authorities are services.				

vs/g| 0

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
RONT LEAF SPRING	BUSHINGS				1	
Labor Service - TH	BERE IS A POPPING SOUND IN	THE FRONT END. THE FRONT	6.00		85.00	510.00
LEAF SPRING BU	SHINGS ARE WORN OUT AND I	EED TO BE REPLACED FR. SS			00.00	010.00
New	01 - FRONT L	EAF SPRING PINS		2.00	69.90	139.80
New	01 - FRONT L	EAF SPRING PIN ( REAR )		4.00	66.35	265.40
New	M18 - LEAF S	PRING BUSHING (STEER)		6.00	18.67	112.02
New	M18 - U BOL			4.00	34.61	138.44
REPLACE CLUTCH AS	SSEMBLY					
Labor Service -			10.00		85.00	850.00
	E TRANSMISSION IS NEEDED 1 HLE TRANSMISSION IS OUT. FI	O ACCESS, TECH WILL INSTALL	A			
Sublet	Resurface FI	wheel		1.00	75.00	75.00
New	M18 - CLUTC	H		1.00	612.49	612.49
New	110 - PILOT E	BEARING		1.00	8.99	8.99
New	CLUTCH BRA	KE		1.00	22.29	22.29
MAIN BEARINGS						22.20
	SAMPLE CAME BACK BAD A	AD AND CORDED TECHNOLOGIC				
OF THE MAIN BEA	L SAMPLE CAME BACK BAD, LE ARINGS BAD. ROD BEARINGS E INSTALL NEW MAIN BEARINGS	AD AND COPPER. TECH FOUND ' .OOK OK AT THIS TIME. TO REPAIR. FR, OE	1 5.00		85.00	425.00
New	OIL DRAIN V	NL VE		1,00	39.95	39.95
New		ER - OIL PAN GASKET		1.00	47.87	47.87
New	M17 - SEAL C	RING (PICK UP TUBE)		1.00	4.25	4.25
New	FREIGHTLINE	ER-MAIN BEARING SET		1.00	337.39	337.39
LEFT STEER WHEEL	SEAL LEAKING					
Labor Service - TH REPLACED FR	IE LEFT STEER WHEEL SEAL IS	LEAKING AND NEEDS TO BE	1.00		85.00	85.00
New	M19 - WHEEL	SEAL (STEER)		1.00	50.81	50.81
TRANSMISSION LEAK						
Labor Service - RE	PAIR PTO LEAK ( STRONG ARM	A PTO ) EP	2.00		85.00	470.00
New	04 - PTO SEA		2.00	1.00	94.00	170.00
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	07 7 7 0 OL7	L. 141		1.00	54.00	94.00
Recommenued Repai	irs and Services:					
•	AK FROM ENGINE AREA.					50,37
Technician Certificati	ions:				100	
• FR						
• 0E						
• SS						
	266					



## Continued from previous page

Warranty  COMMERCIAL/ FLEET REPAIRS UNLESS OTHER WISE NOTED CARRY A 30 DAY WARRANTY.  ALL NON- COMMERCIAL REPAIRS UNLESS OTHER WISE NOTED CARRY A 12 MONTH 12,000 MILE WARRANTY  I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in cause of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for attorneys fees in the event that default is made in any payment due. If withicle is returned to	Posted 9/09/24 12:03PM A/R Charge	4,189.76	Invoice Summary Parts Labor Sublet Supply Charge	1,873.70 2,040.00 75.00 35.00
X Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage (ee.  X Customer acknowledges receipt of merchandise and services.	Tax Breakdown: AZ State Tucson City	116.43 49.63	Sub Total Sales Tax (AZ)	4,023.
Page 2 of 2 Discard old parts	Original Estimate:	4,189.76	Total	4,189.76

# PRODUCT SPOTLIGHT

ATRO PARTS
ENGINEERED | DURABLE | RELIABLE
MANUFACTUREO IN ST. CLAIR, MISSOURI | U.S.A.

### **VOLVO T-RIDE® SUSPENSION**

The Volvo T-Ride® suspension is for both on- and off-highway applications. It features a parabolic tapered spring pack that is upside-down and mounted outside the frame rails. There is a cushion that sits on each axle that is bolted to the end of each spring to absorb shock and vibration. Four lower torque rods control braking and acceleration forces. These suspensions are popular on waste haulers.

#### **BENEFITS OF ATRO COMPONENTS**

ATRO's T-Ride® components are chemically resistant to the common contaminants that most fleets face.

All T-Ride® torque rods and V-rod bushings have rotating pins for easier installation & elimination of torsional stress.

#### Load Spring:


 Proprietary polyurethane formulated to absorb shock & dampen vibration improving ride quality

### **Lower Torque Rods:**

- Complete fixed length & adjustable torque rods, all with rotating pins for easier installation
- OE lower torque rods rebushes with rotating TS96-22700 bushing for easier installation

#### Upper V-Rods:

- TH96-22200 apex bushing uses a low friction, high abrasion & wear resistant polyurethane for durability & longevity
- TS96-22600 & TS96-22286 end bushings have a split outer sleeve to ease installation & conform to inconsistent eye sizes



## **VOLVO T-RIDE® PARTS**

## ATRO PARTS ENGINEERED DURABLE RELIABLE

MANUFACTURED IN ST. CLAIR, MISSOURI U.S.A.

#### V-RODS AND TORQUE RODS



TR96-44004 V-Rod Assembly

Replaces:

Volvo 20367004, 20507262; 20741695; 20741703; 22318833

Length: 26 1/2" c-c

Mount Plate Bolt Hole: 19mm

Contains:

(2) TS96-22600 Bushing (1) TH96-22200 Bushing

Qty Per Vehicle: 2



TR96-44829 V-Rod Assembly

Replaces:

Volvo 3172829, 8073569

Length: 26 3/4" c-c

Mount Plate Bolt Hole: 19mm

Contains:

(2) TS96-22286 Bushing (1) TH96-22200 Bushing

Qty Per Vehicle: 2



TR96-45568 Torque Rod, Adjustable (Offset)

Replaces:

Volvo 20509568

Length: 23 5/8" c-c

Adjustable 22 7/8"-24 3/8" c-c

Contains:

(2) TS96-22700 Bushing

Qty Per Vehicle: 2



TR96-49046 **Torque Rod** (1 7/8" Offset)

Replaces:

Volvo 20443046

Length: 22 5/8" c-c

Contains:

(2) TS96-22700 Bushing

Qty Per Vehicle: 2

### V-RODS AND TORQUE ROD BUSHINGS



TS96-22286 V-Rod End Bushing

Replaces:

Volvo 20547286, 271187 3092452

**OD:** 75mm

Length: 112-118mm c-c

(slotted)

**Bolt Hole: 17mm** 

Contains:

(1) Bushing (1) Snap Ring

Qtv Per Vehicle: 4



TS96-22600 V-Rod End Bushing

Replaces:

Volvo Fits in TR96-44004

00: 75mm

Length: 115mm c-c Bolt Hole: 19mm

Contains:

(1) Bushing (1) Snap Ring

Qty Per Vehicle: 4



TS96-22700 Straddle Bushing

Replaces:

Volvo Fits in TR96-45568

& TR96-49046

**OD:** 75mm

Length: 115mm c-c Bolt Hole: 17mm

Contains:

(1) Bushing

(1) Snap Ring

Qty Per Vehicle: 4



TH96-22200 V-Rod Apex Bushing

Replaces:

Volvo 20741710

**OD:** 72mm

Contains:

(1) Apex Bushing

(1) Retainer Washer

(1) Bolt

(1) Snap Ring

(1) Bushing Cap

Qty Per Vehicle: 2

### LOAD SPRING



LP96-24657 **Load Spring** 

Replaces:

Volvo 1089501. 1577873, 1609657, 1629553, 20390836. 3090971,8151413,

V1609657 V1629553

Height: 5 7/8" Width: 5 7/8" Length: 8 1/41 Top Bolt Size: 9/16" Bottom Bolt Size: 1/2" Top Bolt Pattern:

2 bolt - 7 1/16" Base Bolt Pattern:

4 bolt - 6 9/32 x4 9/16

Qty Per Vehicle: 4

PT96-52200 Install/Removal Tool for use with TS96-22286, TS96-22600 & TS96-22700 PT96-52300 Install/Removal Tool for use with TH96-22200



POLYURETHANE PARTS | SOLUTIONS FOR HEAVY TRUCKS

ATROBUSHING.COM ©2017 ATRO ENGINEERED SYSTEMS, INC

6 Bolte Lane St. Clair, Missouri 63077 | U.S.A. (800) 325.6114 | Fax (866) 920.2005