



Cummins South Pacific Pty. Ltd.

WORKSHOP TAX INVOICE

ABN NO. 42006332949
Mildura
4 Sandown Drive
Mildura VIC 3500
Ph: 0350220800
Fax: 0350232330

INVOICE NUMBER

8237592

INVOICE DATE

10/07/19

PAGE

1

COPY

Invoice To
AccountNumber

Engine Model:	SIGNATURE/ISX/QSX	Eng No:	79732888	Equip Make:	KENWORTH
FleetNo:		Reg No:	705YDX	Cust Ord NO:	
Date in Service:	03/07/14	KLMS:	854311	HRS:	14923
Repair Date:	02/07/19	Chassis NO:	452196	Currency:	AUD
C.O.No.	6385728	Work ordNo.	2533605	Facility	327

Complaint:

FC 1887

Cause:

Nox sensor failed

Correction:

Guidanz Number: CSS-00478294

Hrs/Klms:854311

Correction:

- Move truck into position, capture download, set up safe area.
- Complete JSA.
- Check fault code history and diagnose high counts of fault code 1887.
- Advise customer of finding and best course of action to repair.
- R&R sensor, update calibration and road test to perform high nox reset.
- Carried out repair and passed test.
- Returned to service.

*****Banking Details*****

Cummins South Pacific Pty Ltd
Australia and New Zealand Banking Group Limited (ANZ)
Level 4, 100 Queen Street, Melbourne VIC 3000
Account No: 836551902 BSB:013 479
Swift Code: ANZBAU3M

Include Account and Invoice Numbers in Payment Reference

Description	Operation	Unit price	Qty	Extension
	3285	133.00	2.00	266.00

Labour

All goods and services provided in line with Cummins Terms and Conditions of Sale

Payment Terms Cash/Cleared Funds



Cummins South Pacific Pty. Ltd.

Mildura
4 Sandown Drive
Mildura VIC 3500
Ph: 0350220800
Fax: 0350232330
Invoice To
Account Number

WORKSHOP TAX INVOICE

INVOICE NUMBER 8237592
INVOICE DATE 10/07/19
PAGE 2

Customer

Description	Operation	Unit price	Qty	Extension
266.00		LABOUR TOTAL		
Material				
2894943RX	SENSOR, NITROGEN OXIDE (E	931.51	1	931.51
		MATERIAL TOTAL		931.51
		SUB-TOTAL		1197.51
		G.S.T		119.75
		INVOICE TOTAL		1317.26