

801-27



Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A340549

Station #: 71682

Station Name: Garry's Heavy Equipment Repair

Technician #: 88237

Technician Name: Darcy Poole

Signing Officer #: 88238

Signing Officer Name: Jodie Poole

Customer Details:

Name: 101056947 Sask Ltd. John Warrington Address: Box 146, Mervin, Saskatchewan, S0M 1Y0

Inspection Completed Date: 15Jul2026

Inspection Expiry Date: 31Jul2027

Vehicle Details:

VIN: 2LDAH302XDV056336

Hubometer Reading: 504922 km

Year: 2013

Vehicle Make/Model: LOAD KING/TRAILER

Plate: 927 LNC

Jurisdiction: Saskatchewan

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71682

Station Name: Garry's Heavy Equipment Repair

Technician #: 88237

Technician Name: Darcy Poole

Signing Officer #: 88238

Signing Officer Name: Jodie Poole

Customer Details:

Name: 101056947 Sask Ltd. John Warrington

Address: Box 146, Mervin, Saskatchewan, S0M 1Y0

Vehicle Details:

VIN: 2LDAH302XDV056336

Hubometer Reading: 504922 km

Year: 2013

Vehicle Make/Model: LOAD KING TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	-changed out marker light on right side of trailer
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
		x		Landing Gear (8)	-fixed landing gear handle
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	-changed out both glad hand rubbers -fixed abs system -changed out 2nd axle right brakepot
x				Elec Brake System/Components (3.1)	
		x		Wheel Bearings (9)	-changed 1st axle left hubcap -changed 2nd axle right hubcap -changed 2nd axle left hubcap -changed 1st axle right hubcap
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
		x		Suspension/Axles (2)	-changed out 2nd axle right air bag -changed out 2nd axle right lift axle air bag -changed out 1st axle both air bags -changed out 1st axle left shock -changed out 1st axle left suspension bushings and wear washers
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 11 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 11 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 53.0 degrees • Brake Stroke: 1 1/4 in

Wheel3-On : Tire Tread Depth: 11 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 38.0 degrees • Brake Stroke: 1 1/4 in

Wheel4 : Tire Tread Depth: 11 mm

Brake(1): No Brake

N/A

Axle 2-Pass

Wheel1 : Tire Tread Depth: 11 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 11 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 36.0 degrees • Brake Stroke: 1 1/4 in

Wheel3-On : Tire Tread Depth: 9 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 34.0 degrees • Brake Stroke: 1 1/4 in

Wheel4 : Tire Tread Depth: 8 mm

Brake(1): No Brake

N/A

PASS - vehicle passes inspection	Decal # A340549	Inspection Completed Date: 15Jul2026
----------------------------------	-----------------	--------------------------------------