

033-2



# Commercial Vehicle Inspection Report

Decal Number: GK52817  
Decal Expiry Date: 2026-May-31  
Inspection Number: 21574822

Inspection Result:  
**PASS**

FACILITY: RJAMES WESTERN STAR / S7341 INSP. TYPE: Complete INSP. START: 2025-Nov-19 10:15 AM PST  
INSPECTOR: Houska, Anthony Allan / 112560 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more INSP. COMPLETE: 2025-Nov-20 12:56 PM PST  
WORK ORDER #: 017694 INSP. REASON: Semi-annual

VEHICLE JUR: British Columbia REGI: 14191730 VIN: 5KKHALDR8EPFL3093  
PLATE #: SR7557 UNIT/FLEET#: 559 OWNER/LESSEE NAME: PITURA ENTERPRISES LTD., PITURA ENTERPRISES LTD.  
LICENCED GVW(kg): 55600 BODY STYLE: Dump Truck ADDRESS: 3139 APPALOOSA RD  
VEHICLE YEAR: 2014 ODOMETER: 322944 KM Kelowna, British Columbia  
MAKE: WESTERN ST HUB ODOMETER: V1V2G9, Canada  
MODEL: BRAKE TYPE: Air  
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Repaired (same day) TRAQNSMISSION U-JOINT WORN. - OIL FILTER HOUSING LEAKING.
Section 2 - Suspension	Repaired (same day) REAR DRIVE AXLE AIR LINER BUSHING PINS MOVING FREELY IN EYES.
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) RELAY VALVE LEAKING ABOVE 90 PSI WHEN BRAKES RELEASED.
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxillary Equipment	Passed
Section 6 - Lamps	Repaired (same day) L HIGH BEAM LENS BROKEN.
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) CRACKS IN TAIL GATE. - TAIL GATE NOT SEALING AGAINST BOX FLOOR. - CHANGED TORN WIPER BLADES.
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24L	Automatic	27	29	6			9	✓
2	Clamp	30L	Automatic	35	38	9	9	8	7	
3	Clamp	30L	Automatic	32	32	9	10	9	10	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum		Left	Right
1	38	30	Lining (Shoe)	20	22	Drum			
2	60	75	Lining (Shoe)	16	15	Drum			
3	73	50	Lining (Shoe)	15	20	Drum			

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

### Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: \_\_\_\_\_ Road Tester: \_\_\_\_\_  
Inspector: Houska, Anthony Allan Signature: \_\_\_\_\_

This Inspection Report was submitted to CVSE on 2025-Nov-20 12:56 PMPST  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

### NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCAVIP at the Commercial Vehicle Safety Enforcement

CVSE014  
11/20/2025 12:56:50 PM PST