

FACILITY:	TRAILCON LEASING INC. / S13860	INSP. TYPE:	Complete	INSP. START:	2026-Feb-24 02:00 PM PST
INSPECTOR:	LUO, CHENG / 202916	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2026-Feb-24 03:00 PM PST
WORK ORDER #:	R1200768	INSP. REASON:	Annual		
VEHICLE JUR:	Alberta	REGI:		VIN:	527SR5325PL029407
PLATE #:	6KS766	UNIT/FLEET#:	53RBS2272	OWNER/LESSEE NAME:	BIG RIG TRAILERS & LEASING INC, WALMART
LICENCED GVW(kg):	99999	BODY STYLE:	Semi Trailer	ADDRESS:	9115 52 ST SE, 9115 52 ST SE
VEHICLE YEAR:	2023	ODOMETER:			CALGARY, Alberta
MAKE:	VANGUARD	HUB ODOMETER:			T2C 2R4, Canada
MODEL:	COOLGLOBE	BRAKE TYPE:	Air		
		FUEL TYPE:	Not Applicable		

x20-58

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	38	40	11.1	7.1	4.8	6.4	
2	Clamp	30	Automatic	40	40	5.6	6.4	5.6	4.8	
Comment:						Comment:				


Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	25	25	Lining (Shoe)	21	21	Drum	419.10	419.10
2	25	25	Lining (Shoe)	21	21	Drum	419.10	419.10
Comment:			Comment:			Comment:		

Inspection Comments:

Has this Vehicle been road tested? No

Inspector: LUO, CHENG

Road Test Date:

Signature: 

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Feb-24 03:46 PM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.