



H.F. NODES CONSTRUCTION

EX73 – Deere 290G Excavator

Old History

10:01 AM 5/14/2014

HOURS 500

7:34 AM 03/06/2015

1913 NEXT SERVICE DUE AT 2163

SERVICETECH RANDY

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

TOOK ENGINE OIL SAMPLES

7:28 AM 17/08/2016

HOURS 2425 NEXT SERVICE DUE 2648

SERVICE TECH RYAN

7:41 AM 01/09/2016

HOURS 2475 NEXT 2648

OPERATORS CHECK LIST

DATED AUG 26 2016

OPERATOR DARREN DEAK

LOCATION 4-7 ENCANA

COMMENTS

WORKING WELL

COULD USE A RADIO



H.F. NODES CONSTRUCTION

5:23 PM 07/09/2016

HOURS 2425 NEXT SERVICE DUE AT 2648

SERVICE TECH RYAN

CHECKED MACHINE OVER

CHANGED FINAL DRIVE OIL

INSTALLED A NEW OIL FILLER CAP ON THE HYD OIL TANK

FIRE EXT APRIL 2016

10:35 AM 01/10/2016

HOURS 2671 NEXT SERVICE DUE AT 2925

SERVICE TECH GORDON

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

8:00 AM 27/06/2017

HOURS 3305 NEXT SERVICE DUE AT 3555

SERVICE TECH BRAXTON

SERVICED THE ENGINE 15/40

REPLACED THE AIR OIL AND FUEL FILTERS

FIRE EXT JUNE 2017

REPAIRED THE PIPING ON THE CHUCK BLADE

6:05 AM 15/02/2018

HOURS 3480 SERVICE DUE AT 3730

SERVICE TECH RANDY

SERVICED THE ENGINE 10/30

FIRE EXT JUNE 2017



H.F. NODES CONSTRUCTION

10:43 AM 02/03/2018

HOURS 3559 NEXT SERVICE DUE AT 3730

SERVICE TECH NEIL

CHECKED MACHINE OVER

CHANGED OIL IN THE HYD AND REPLACED THE FILTER

CHANGED FINAL DRIVE OIL

CHANGED OIL IN THE SWING DRIVE AND PUMP DRIVE GEAR BOX

REPLACED THE SEALS ON THE HYD OIL RETURN LINE

FIRE EXT MAY 2017

10:53 AM 14/06/2018

HOURS

SERVICE TECH RANDY

THE OPERATOR COMPLAINED THAT WHEN THE MACHINE IS COLD IT MISSES

CHECKED THE CODES DID NOT FIND ANY

6:12 AM 01/08/2018

HOURS 3780 NEXT SERVICE DUE AT 4030

SERVICE TECH NEIL AND MURRAY

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

CUT ICE LUGS

FIRE EXT JUNE 2018

2:32 PM 06/09/2018

HOURS 4023 NEXT SERVICE DUE AT 4273

SERVICE TECH SLADE

SERVICED THE ENGINE 15/40



H.F. NODES CONSTRUCTION

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT SEPT 2018

4:00 PM 16/10/2018

HOURS 4215 NEXT SERVICE DUE AT 4273

SERVICE TECH RANDY

CHECKED MACHINE OVER

REPLACED THE DONUTS ON THE OIL COOLER PIPES

REMOVED THE EXHAUST CLAMPS OFF THE PIPES

REPLACED SOME OF THE HEATER HOSES

REPLACED THE TRACK GROUPS

4:23 PM 22/10/2018

SERVICE TECH JASON

SENT THE MACHINE TO THE WELDING SHOP TO GET THE Q/C

PINS AND BUSHINGS DONE

JASON SHIMMED THE SIDE TO SIDE

REMOVED THE CHUCK BLADE

RIGGED UP ANOTHER CHUCK BLADE WITH TOP CON

11:20 AM 31/12/2018

HOURS 4329 NEXT SERVICE DUE AT 4579

SERVICE TECH MURRAY

INSTALLED THE ROAD RADIO

CHECKED MACHINE OVER

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT OCT 2018



H.F. NODES CONSTRUCTION

4:15 PM 11/02/2019

SERVICE TECH DENNIS/AYDEN

HOURS 4385 NEXT SERVICE DUE AT 4579

FIXED TWO LIGHTS

REPLACED TWO STEPS

FEB27/2019

HOURS 4390 NEXT SERVICE 4579

SERVICE TECH DENNIS

MACHINE THROWING CODES FOR PLUGGED FUEL FILTERS.

INSTALLED A RISER TUBE INTO FUEL SUPPLY FITTING IN TANK

CHANGED THE FUEL FILTERS

FIRE EXT OCT/2018

4:33 PM 11/04/2019

HOURS 4522 NEXT SERVICE DUE AT 4579

SERVICE TECH NEIL;

REMOVED THE FAILED EGR COOLER

INSTALLED A NEW COOLER FROM BRANDT

1:35 PM 27/04/2019

HOURS 4530 SERVICE DUE AT 4780

SERVICE TECH AYDEN

SERVICED THE ENGINE,15W40 OIL. REPLACED THE AIR OIL AND FUEL FILTERS

REPLACED GASKET ON TURBO RETURN LINE.RE LEVELED THE GASKET SEALING SURFACE.

FIRE EXT OCT/2018



H.F. NODES CONSTRUCTION

7:41 AM 10/09/2019

HOURS 4783 NEXT SERVICE DUE AT 5033

SERVICE TECH MURRAY /AYDEN

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT MARCH 2019

2:16 PM 16/09/2019

HOURS 4860 NEXT SERVICE DUE AT 5033

SERVICE TECH AYDEN

RELPLACED THE EGR VALVE

7:18 AM 25/09/2019

HOURS 4926 NEXT SERVICE DUE AT 5033

SERVICE TECH SLADE

CHECKED THE CODES

REPLACED THE TURBO ACTUATOR

5:08 PM 07/11/2019

HOURS 5054 NEXT SERVICE DUE AT 5304

SERVICE TECH MURRAY

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT AUG 2019

1:42 PM 20/02/2020

HOURS

SERVICE TECH DENNIS



H.F. NODES CONSTRUCTION

REPLACED THE CORNER BITS AND TURNED THE EDGES

REPLACED THE BATTERY CABLE

7:04 AM 29/05/2020

HOURS 5308 NEXT SERVICE DUE AT 5558

SERVICE TECH MURRAY

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

9:00 AM 17/11/2020

HOURS 5571 NEXT SERVICE DUE AT 5871

SERVICE TECH COLE

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTER

CHANGED OIL IN THE PUMP DRIVE

FILLED THE SWING DRIVE WITH OIL

THE RIGHT FINAL DRIVE WAS VERY LOW ON OIL

FIRE EXT JULY 2020

4:34 PM 12/03/2021

HOURS 5877 NEXT SERVICE DUE AT 6177

SERVICE TECH SLADE

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

THE RIGHT HAND FINAL WAS LOW ON OIL

THE OIL FILTER LINES ARE WEEPING

FIRE EXT JULY 2020



H.F. NODES CONSTRUCTION

1:50 PM 26/03/2021

HOURS 5917 NEXT SERVICE DUE AT 6177

SERVICE TECH SLADE

INSTALLED NEW HOSES ON THE ENGINE OIL FILTER REMOTE MOUNT

REPAIRE THE THUMB GAURD

TIGHTEN THE TRACKS

REPLACED THE BROKEN FITTING ON THE CHUCK BLADE

INSTALLED A/C BELTREPLACED THE SEAL ON THE OIL FILLER CAP

INSTALLED A NEW PUMP DRIVE DIPSTICK

11:18 AM 27/07/2021

HOURS 5945 NEXT SERVICE DUE AT 6177

SERVICE TECH AYDEN

COMPLAINTS OF MACHINE PUFFING WHITE SMOKE

SENT AYDEN DOWN TO PIPESTONE TO CHECK IT OUT

FOUND THE EGR COOLER HAD FAILED, INTAKE WAS FULL OF COOLENT.

INSTALLED NEW COOLER, NEW EGR VALVE.

CLEANED COOLENT OUT AS REQUIRED.

ENGINE OIL HAD COOLENT DILUSION, DRAINED AND RE FILLED WITH NEW OIL/FILTER.

MACHINE SEEMS TO RUN FINE, WILL MONITOR.

*****MACHINE NEEDS R/H FINAL DRIVE SEAL REPLACED*****

4:47 PM 06/08/2021

HOURS 6030 NEXT SERVICE DUE AT 6177

SERVICE TECH BARR NONE

REPLACED THE RIGHT HAND DUO CONE FINAL DRIVE SEAL

FILLED WITH OIL

REPLACED BOTH FRONT IDLERS



INSTALLED THE TRACKS

11:11 AM 11/12/2022

HOURS 6787 NEXT SERVICE DUE AT 7087

SERVICE TECH ROB B.

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

INSTALLED NEW HYD PUMPS

CHANGED HYD OIL

2:02 PM 05/07/2024

HOURS 7091 NEXT SERVICE DUE AT 7391

SERVICE TECH ROB

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

INSTALLED NEW PINS AND BUSHINGS IN THE Q/C LINK