STONY INSPECTION SERVICES NC.

21-52211 Range Road 275, Spruce Grove, Alberta T7X 3V1 (780)963-6820 admin@stonyinspection.ca

Balinvalley Enterprises Ltd. 766 Wheeler Road Edmonton, Alberta T6M 2E6

Attention: Leo Davis

12 March 2025

Re:

Certification of Liebherr AT crane

Model: LTM 1080/1

Serial: 061443

Year: --- Capacity: 100 tons

Unit: VG21

Stony Inspection Services Job: 56967

Dear Sir/Madame:

An inspection of the structural elements of the above AT crane was completed by Stony Inspection Services, acting under our direction (Stony Inspection Services Job 56967, dated 12 March 2025, copy attached). The inspection was structural only; no load tests or operational tests were performed. In addition to this structural inspection, the owner and operator are responsible for complying with original equipment manufacturer specifications, OH&S regulations, and the applicable CSA Z-150 and/or ASME B30.5 codes with respect to all inspection, maintenance, and operations of the unit.

Based on this inspection, the above unit is considered structurally fit for continued service.



Gaylene D. K. Layden, P.Eng. Stony Engineering Inc.

J3041		
Association of	Professional Engi of Saskatchev	neers & Geoscientists van
CERTI	FICATE OF AUT Stony Engineerin Number 398	ig Inc.
P	ermission to Consul	t held by
Discipline	Sk. Reg. No.	Signature
	21061	(hy

59847

STONY INSPECTION

SERVICES INC.

21-52211 Range Road 275 Spruce Grove, AB T7X 3V1 780-963-6820 office@stonyinspection.ca

Balinvalley Enterprises Ltd. 766 Wheeler Road Edmonton, Alberta T6M 2E6

Attention: Leo Davis

9 March 2024

TEN YEAR BOOM TEAR DOWN AS PER CSA Z150 STANDARD

Re: Certification of Liebherr Crane Boom Sections

Model: LTM 1080/1 Serial: 061443 Year: --- Capacity: 100 Ton


Unit: VG21

Stony Inspection Services Job: 51932

Dear Sir/Madame:

Further to the inspection of the structural elements of the above disassembled crane boom by Stony Inspection Services, acting under our direction (Stony Inspections Services Job 51932, dated 9 March 2024, copy attached), the above sections are considered structurally fit for continued service.

Yours truly,



Gaylene D. K. Layden, P. Eng. Stony Engineering Inc.

STONY INSPECTION

SERVICES INC.

21-52211 Range Road 275 Spruce Grove, AB T7X 3V1 780-963-6820 office@stonyinspection.ca

Balinvalley Enterprises Ltd. 766 Wheeler Road Edmonton, Alberta T6M 2E6

20 March 2024

FIVE-YEAR LOAD BLOCK TEARDOWN AS PER CSA Z150 STANDARD

Re:

Certification of Liebherr Block

Load Block Model: 910243308 Serial: 34242 Capacity: 63 tonne

Stony Inspection Services Job: 52142

Dear Sir:

Further to the inspection of the structural elements of the above disassembled block by Stony Inspection Services, acting under our direction (Stony Inspections Services Job 52142, dated 20 March 2024, copy attached), the above unit is considered structurally fit for continued service.

Yours truly,





Gaylene D. K. Layden, P. Eng. Stony Engineering Inc.

Association of	Professional Engin of Saskatchewa	ieers & Geoscientists an
CERTI	FICATE OF AUTH	IORIZATION
	Stony Engineering	Inc.
	Number 3985	
р	ermission to Consult	held by:
Discipline	Sk. Reg. No.	Signature
	21061	1 Luis

RM SIGNATURE _	G. Lander
RM APEGA ID #	59847
DATE	2024-03-20