



Inland Truck & Equipment
 816 Industrial Rd No. 1
 Cranbrook, BC V1C 4C6
 inland-group.com

VEHICLE INSPECTION REPORT

DATE: Aug 7/24	MECHANIC:	CUSTOMER: Lance Fiddler
VEHICLE #: 19251	MILEAGE: 1	RO#: 18584 obs

		REPAIR	REPLACE	CAUTION
1	Tarp bar insecure	✓		
2	Rear Lights flicker when signaling	✓		
3	RH mid ship Light out	✓		
4	Lower Frame Rail supports Cracked	✓		
5	the Chain pins at Rear worn/Falling out	✓		
6	Lic Plate Light out	✓		
7	lights above middle Rear Light 5 out	✓		
8	#2 LH hub Has no oil	✓		
9	Box Rail Rides welds are cracked	✓		
10	Box Sides Have cracks/marked with paint	✓		
11	Vin tag is painted over cant Read	✓		
12	Service pot for box latch at front slow break	✗	✓	
13				
14				
15				
16				
17				
18				
19				
20				
21				

BRAKES				L.H.					R.H.				
AXLE	TYPE	SIZE	SLACK	TRAVEL	ROTATION	LINING	Outside tire	Inside tire	TRAVEL	ROTATION	LINING	Inside tire	Outside tire
1	C	30	Q/M	1.5	65	8	15	15	1.5	50	8	12	12
2	C	30	Q/M	1.5	45	8	12	12	6.5	60	6	14	14
3	C	30	Q/M	1.5	45	10	8	8	1.5	50	8	5	5
4			A/M										
5			A/M										

Repaired to Pass CUP