

CUSTOM MECHANICS

GST:743455883 rt:0001

9601 82 Ave Grande Prairie AB T8V 5W9

Invoice

Submitted on 26/05/2025

Invoice for

PVT Energy Ltd.

Invoice

21621

Description

Total price

Sandblasting and painting the interior of a vac
truck

\$2,000

Materials: Paint: \$500, Sand:\$450, Diesel:\$180

\$1,130

GST: \$100

Note: 1 pale of paint paid by PVT: \$1,020

Subtotal **\$3,230**

\$3,230



ETS GRANDE PRAIRIE

10602-82 Avenue Clairmont, Alberta T0H 0W0
Phone 780.830.3063 | Toll Free 1.877.962.8195
Fax 780.830.3089 | www.edmontontrailer.com

INVOICE

GST # 89398 4799 RT0001

A Division of EDMONTON TRAILER SALES & LEASING LTD.

Parts Invoice Customer Copy

Date: 06/16/2025 1:25:12 PM

User jasonr Page 1

Customer No PERFORMANCE
Attn: GRANDE PRAIRIE

PVT GROUP LTD.
721071 RANGE ROAD 53 Unit 93
COUNTY OF GRANDE PRAIRIE NO. 1, AB T8X 0N4

Home (780) 830-0045 **Bus** (780) 830-0045
Cell (780) 831-6938 **Fax** (780) 830-5164
Email ap.energy@pvtgroup.com

Ship Date 06/16/2025 1:25:12 PM

Invoice Number 419795

PO # 65032 **Sales** TAYLOR **Account Number** PERFORMANC
Type Taylor **Terms** Charge
Reference CUSTOMER PICKED UP
Ship Via
Ship To PVT GROUP LTD.
721071 RANGE ROAD 53
COUNTY OF GRANDE PRAIRIE NO. 1, AB, T8X 0N4
(780) 830-0045

REQ	SH	ORD	PART NUMBER	DESCRIPTION	RETAIL	NET	SALE
1	1	0	CK-2000TL-4GAL	CERAM-KOTE - WHITE 4 GALLON KIT	1,582.99	942.76	942.76
1	1	0					942.76

PARTS SALE	942.76
TOTAL PARTS SALES	942.76
GST	47.14
NET TOTAL PARTS	989.90
TOTAL INVOICE	989.90

Remit Payment To: Edmonton Trailer Sales & Leasing LTD | 28520 - 114 Avenue, Acheson, AB, T7X 6E6

- No Refunds or Exchange on Parts after 30 days.
- No Refunds or Exchange on Electrical Items or Special Orders.
- Parts Returned for Credit that have been Supplied as Ordered are Subject to a 25% Handling Charge

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE, NET 30 DAYS, INTEREST OF 2% PER MONTH (24% PER ANNUM) CHARGED ON ALL OVERDUE ACCOUNTS.

DATE _____ CUSTOMER SIGNATURE _____



PVT Energy Group Inc.
 93-721071 Range Road 53
 County of Grande Prairie, AB, T8X 0N4
 Phone: 780-830-0045
 Fax: 780-830-5164

Equipment: TP3011

Work Order #: 43940

Date: 11/30/23

Completed Date: 11/30/23

Year: 2006
 Make: Advance
 Model: STIFFPOLE 12WL

Serial Number: 2AESPVKH26E000193

Labor

Category	Description	Mechanic	Quantity/Hours	Price/Rate	Amount
LABOUR INTERNAL (PVT ...	1) GO THROUGH UNIT AS IT IS GOING TO B.C. Greased unit	Kreutz, Ben	1.50	60.00	90.00
LABOUR INTERNAL (PVT ...	3) ALL BRAKES, SCAMS & SLACKS Re&Re shoes, drums, slacks and scams. Reinstall wheels & torque. Greased entire unit.	Rea, Jacob	3.00	60.00	180.00
LABOUR INTERNAL (PVT ...	3) Pulled tires, drums, brakes, scams, cleaned & reinstalled scams, brakes, drums & tires	Debre, Matthew	3.00	60.00	180.00
LABOUR INTERNAL (PVT ...	3) Checked over tires, pulled bad ones & grabbed new ones. Lined up with Kal Tire. Put drums and tires on & torqued tires.	Jackson, Braydon	2.50	60.00	150.00
LABOUR INTERNAL (PVT ...	4) ABOVE #2 AXLE BRAKE VALVE LEAKING R&R brake valve, replace air line fitting.	Burseay, Justice	1.50	60.00	90.00
LABOUR INTERNAL (PVT ...	Checked over unit	Farquhar, Brian	1.00	60.00	60.00

Parts

Description	Quantity/Hours	Price/Rate	Amount
93600, Brake Drum, 16.5 x 7	6.00	129.95	779.70
04-529351, CAM23.50 RH	3.00	46.90	140.70
04-592352, CAM 23.50 LH	3.00	46.90	140.70
08-132100, CAM BUSHING KIT	6.00	21.57	129.42
03-209A, CAM SUPPORT	6.00	8.42	50.52
FAS1133, SLACK ADJUSTER	6.00	79.95	479.70
KN28600, VALVE FF2 3/4	1.00	126.50	126.50
KL-GR1830, ULTRA TAC RED EP2 GREASE	2.00	7.40	14.80
XSS714707QPK, SHOE KIT, MERITOR Q+ 16.5X7	6.00	48.47	290.82
WAB ACC5903, WHEEL SAVER	6.00	5.95	35.70

1) GO THROUGH UNIT AS IT IS GOING TO B.C.
Greased unit

2) DVIR REPAIRS

3) ALL BRAKES, SCAMS & SLACKS
Re&Re shoes, drums, slacks and scams. Reinstall wheels & torque. Greased entire unit.

Pulled tires, drums, brakes, scams, cleaned & reinstalled scams, brakes, drums & tires

Checked over tires, pulled bad ones & grabbed new ones. Lined up with Kal Tire. Put drums and tires on & torqued tires.

4) ABOVE #2 AXLE BRAKE VALVE LEAKING
R&R brake valve, replace air line fitting.

Total Labor	750.00
Total Parts	2,188.56
Total Returns	.00



PVT Energy Group Inc.
93-721071 Range Road 53
County of Grande Prairie, AB, T8X 0N4
Phone: 780-830-0045
Fax: 780-830-5164

Total Sublet	.00
Shop Supplies	37.50
Invoice Total	<u>2,976.06</u>



PVT Energy Group Inc.
 93-721071 Range Road 53
 County of Grande Prairie, AB, T8X 0N4
 Phone: 780-830-0045
 Fax: 780-830-5164

Equipment: TP3011

Work Order #: 47899
 Date: 07/01/24

Completed Date: 07/05/24

Year: 2006
 Make: Advance
 Model: STIFFPOLE 12WL
 Odometer: 149,082

Serial Number: 2AESPVKH26E000193

Labor

Category	Description	Mechanic	Quantity/Hours	Price/Rate	Amount
LABOUR INTERNAL (PVT ...		Buck, Cory	13.50	60.00	810.00
LABOUR INTERNAL (PVT ...		Debre, Matthew	13.50	60.00	810.00
LABOUR INTERNAL (PVT ...		Sabado, Paul	10.50	60.00	630.00

Parts

Description	Quantity/Hours	Price/Rate	Amount
KN28600, VALVE FF2 3/4	2.00	137.22	274.44
11904, 3/8 x 38/ FITTING	12.00	5.62	67.44
OR229859, QR-1 QUICK RELEASE VALVE	1.00	14.95	14.95
372-7097, SEAL, WHEEL TRAILER	5.00	51.33	256.65
330-3009, Stemco Gasket	6.00	2.57	15.42
03-209A, CAM SUPPORT	6.00	8.81	52.86
372-7097, SEAL, WHEEL TRAILER	6.00	51.33	307.98
100.4515.22, Q+ HARDWARE KIT	6.00	14.12	84.72
04-592351, CAM 2350" 1.5-10 1.5 RH	6.00	48.58	291.48
08-132100, CAM BUSHING KIT	3.00	22.46	67.38

1) CVIP

Performed CVIP - Cory(3) Matt(3)
 Set brakes and torqued wheels. - Paul(1) Cory(1)

2) S CAMS AND BUSHINGS ALL AXLES

All s cams and bushings had not a drop of grease in them and lots of excess play. Removed all s cams and bushings, measured specs to order parts. Installed s cams and bushings, installed all wheel hubs with new wheel seals. - Cory(8) Matt(8) Paul(1)

3) QUICK RELEASE VALVE ON AXLE #3 NOT WORKING

Removed and replaced quick release valve, valve was corroded and not exhausting properly. Had to troubleshoot and fixing. - Paul(1) Cory(.5) Matt(.5)

4) MULTIFUNCTIONAL VALVE ON AXLE #2 NOT WORKING

Removed and replaced both multi functional valves, they were also corroded, leaking and not exhausting. - Paul(4.5) Cory(1) Matt(2)

5) AXLE #2 RIGHT SIDE BRAKE POT FULL OF DEBRIS

Removed and replace brake pot. - Paul(2)

Total Labor	2,250.00
Total Parts	1,433.32



PVT Energy Group Inc.
93-721071 Range Road 53
County of Grande Prairie, AB, T8X 0N4
Phone: 780-830-0045
Fax: 780-830-5164

Total Returns	.00
Total Sublet	.00
Shop Supplies	112.50
Invoice Total	<u>3,795.82</u>



PVT Energy Group Inc.
 93-721071 Range Road 53
 County of Grande Prairie, AB, T8X 0N4
 Phone: 780-830-0045
 Fax: 780-830-5164

Equipment: TP3011

Work Order #: 53660

Date: 05/05/25

Completed Date: 05/29/25

Year: 2006
 Make: Advance
 Model: STIFFPOLE 12WL
 Odometer: 3,646

Serial Number: 2AESPVKH26E000193

Labor

Category	Description	Mechanic	Quantity/Hours	Price/Rate	Amount
LABOUR INTERNAL (PVT ...		Colley, Jason	10.50	60.00	630.00
LABOUR INTERNAL (PVT ...		Mulcahy, Travis	23.00	60.00	1,380.00
LABOUR INTERNAL (PVT ...		Mulbah, David F	6.00	60.00	360.00
LABOUR INTERNAL (PVT ...		Sabado, Paul	5.50	60.00	330.00
LABOUR INTERNAL (PVT ...		Farquhar, Brian	2.00	60.00	120.00
LABOUR INTERNAL (PVT ...		Jackson, Braydon	1.50	60.00	90.00

Parts

Description	Quantity/Hours	Price/Rate	Amount
90034815, REPLACEMENT PINION PLATE - 0 DEG	2.00	19.95	39.90
90034817, REPLACEMENT PINION PLATE	4.00	20.51	82.04
E15017B, GUNIT STYLE ASA	4.00	87.25	349.00
85000, SHOCK, FLEETLINE/GABRIEL	6.00	46.75	280.50
SSD6722, BRAKE DRUM16.50X7.00 10 HOLE - SUB PRT# 3600A	2.00	100.85	201.70
XSS714707QPK, SHOE KIT, MERITOR Q+ 16.5X7	5.00	56.65	283.25
E5521, CAM, 1-1/2,10SP, 23-1/2, RH	3.00	36.70	110.10
E5520, CAM, 1-1/2, 10SP, 1/2, L/H	2.00	37.00	74.00
E1318AHD, CAM SUPPORT BRACKET	6.00	10.03	60.18
E15017B, GUNIT STYLE ASA	2.00	87.25	174.50
372-7097, SEAL, WHEEL TRAILER	6.00	48.40	290.40
KN26020, MULTI FUNCTION TRAILER VALVE	1.00	214.25	214.25
16-0523, WING NUT ASSY	1.00	215.00	215.00
16-0551, WING BOLT ASSY	1.00	173.40	173.40
SSCK2287, KIT, CAM STF A19S MODEL	1.00	14.40	14.40
E11449, BUSHING, CAM 2" OD 1-1/2 ID	1.00	26.90	26.90
E4738A, TUBE, CAM 21"	6.00	49.65	297.90
330-3009, Stemco Gasket	6.00	4.12	24.72
85934, Shock	6.00	67.40	404.40
10212Y, AMBER ABS MARKER LAMP	1.00	6.32	6.32
24X24, 24X24 MUDFLAP BLACK	2.00	30.25	60.50
E886, DUST SHIELD TRAILER BOLT	1.00	18.35	18.35
WJ201A, 4-7/8" RUBBER HOOD CATCH	2.00	5.46	10.92
67050, PIGTAIL, 2 WIRE PLUG IN	1.00	1.66	1.66
60261, LAMP, LICENSE PLATE	1.00	4.03	4.03
839-BP, BLK & RED CLIPS	1.00	10.00	10.00
4050, LAMP, RED STOP/TAIL TURN LED 4"	1.00	20.63	20.63
67090, PIGTAIL 3 WIRE 90	1.00	2.22	2.22
91740, 4" GROMMET	1.00	1.92	1.92

1) CVIP.

Repair: Took unit off jack stands (Jason - 5HR). Adjust all brakes to spec (Jason - .5HR). Replace two damaged mud flap from the front of the unit (Jason - 1HR). rotate the front D/S mud flap anti-sail bracket to match the others in the correct orientation (Jason - .5HR).

Hooked trailer up to get inside, jacked up axles and put on stands. Took tires off and brakes. Took tires, brake shoes and drum measurements for inspection. - Paul(5.5)

Checked for cvip and failed - Brian(2)

Helped driver hook up to trailer and close rear hatch, assisted with air leak under trailer as well. - Braydon(1)

2) TANK INSPECTION

Being completed at High Prairie.

3) HOIST CYLINDER

parts on order

4) NEEDS ALL 6 SHOCKS

Replaced all 6 shocks with new. - DM(6)

5) 3RD AXLE BRAKE SHOES AND DRUM BOTH SIDES

Replaced on like 7.

6) COMPARTMENT BOX RUBBER LATCH NEEDS REPLACING. (Jason - .5HR)

Repair: Replace worn out rubber latches

7) NEEDS 5 SLACK ADJUSTER (3RD AXLE D/S GOOD)

Inspected brakes, s cams and bushings worn out. Needs new brakes, spiders worn out, will not fit new bushings properly. Installed weld on s cam tubes. Removed and cleaned all hubs. Install new slacks, shoes and s cams. Installed all wheel hubs and filled. Replaced brake shoes, drums, s cams, slack adjuster on axle #1 and 2 left and right and axle #3 left and right - Travis(18)

8) 2ND AXLE D/S DUSTSHIELD. (Jason - .5HR)

Repair: install new dustshield

9) FRONT RIGHT MARKER LIGHTS NOT WORKING. (Jason - 2HRS)

Diag: test power at lamp (only had 3 volts). Follow wire under unit and found a section of the wire wrapped with tape (unwrap wire and found badly corroded butt connects)

Repair: Repair wires and test the voltage at lamp once again (the voltage was 12.2V until a load was applied). follow wire to the junction box where a pin hole in the wire was found and repaired (tested lamps after rear - works as the should)

10) LICENCE PLATE LIGHT NOT WORKING. (Jason - .5HR)

Diag: remove old lamp and test voltage (12.4V)

Repair: Replace lamp and test (Work as it should)

11) ABS LAMP NOT WORKING

Abs light not working, not getting power to light. Power in junction box, ran new cord and replaced light, abs functions properly now. - Travis(3)

12) REPLACE OLD HYDRAULIC LINES THAT GOES BETWEEN TOWING VEHICLE AND CONTROL VALVE/ VALVE BANK. (Jason - 3HRS)

Repair: Remove old high and low pressure hydraulic hoses measure the length then made new lines. Install new lines and secure them with P-clamps

Removed hydraulic box on front of trailer, shortened coolant hoses. - Travis(2)

13) Leaking full function valve above # 2 axle. (Jason - 1.5HR)

Diag: using a vise grip to pinch the supply line to each valve until the back flow stop pointing to the Faulty Full function valve.

Repair: Replace faulty valve and test after installation (no more back flowing)

14) REAR RIGHT MARKER/SIGNAL OUT

Replaced light and pigtail for rear outer light. - Braydon(.5)



PVT Energy Group Inc.
93-721071 Range Road 53
County of Grande Prairie, AB, T8X 0N4
Phone: 780-830-0045
Fax: 780-830-5164

Total Labor	2,910.00
Total Parts	3,453.09
Total Returns	.00
Total Sublet	.00
Shop Supplies	145.50
Invoice Total	6,508.59