



SERVICE HISTORY - 1RW8410DKMF925256

8RT 410

BillingDate	Invoice	Description	Hours	TransactionID
S 20210830	W71321	Service - Engine Break-In	298	5202108130054152
S 20210930	W71544	500Hr Service	531	5202109170059513
S 20211012	W71578	Track Alignment	538	5202109230060416
S 20211014	W71548	GreenStar electrical issue - Warranty	538	5202109200059621
S 20220215	W72136	1000Hr Service	1169	5202112200074996
S 20220325	W72478	1500Hr Service	1613	5202203160088555
S 20220401	W72379	Replace faulty fuel sender - Warranty	1613	5202202160084096
S 20220512	W71590	Update software per DTAC	1778	5202109270060724
S 20220615	W72459	Track Alignment	1855	5202203090087491
S 20220617	W71991	PIP 21RW937A - Seat	1873	5202111240070317
S 20220719	W73096	2000Hr Service	2134	5202207010105414
S 20221220	W73759	2500Hr Service	2655	5202211230128049
S 20230107	W73805	Track Alignment	2672	5202212010129564
S 20230214	W74121	Turbo failure Repair - Warranty	2830	5202301270137818
S 20230323	W74334	3000Hr Service	3062	5202303060144612
S 20230405	W74285	Replace 2 x Tracks	3097	5202302270143325
S 20230719	W74368	Engine Repairs - Warranty	3436	5202303130145919
S 20230721	W75313	PIP 22RW955A - MTG	3448	5202307040166096
S 20230801	W75461	3500Hr Service	3485	5202307240169205
S 20230802	W75492	Draft Arm Repair	3491	5202307270169997
S 20230907	W75347	Replace failed oil pressure sensor	3690	5202307100166947
S 20230919	W75725	Replace failed temperature sensor	3728	5202308290175439
S 20231128	W76196	4000Hr Service	3968	5202311100187825
S 20231201	W76261	PIP 21RW949A - Accumulator Bracket	3968	5202311210189757
S 20240709	W77575	4500 Hr Service	4500	5202406270229991