



CERTIFIED INSPECTION SERVICES LTD



www.certifiedinspection.ca



Manitoba - (204)777-2475 cim@cisndt.ca
Saskatchewan - (306)737-7371 cis@cisndt.ca

STRUCTURAL INSPECTION AND NDT OF ALTEC BUCKET TRUCK – UNIT #B4

Attention: Bill Schroeder	Date: 29-Dec-25
Client: Alliance Tree Care	File #: 9453-25
Address: 42 Ryan Wirth Way, East St. Paul, R2E 0R2	Report #: 1 Rev. 0
	PO #:



Equipment Details

Owner: Alliance Tree Care	Unit #: B4
Make: Altec	Mfg Year: 2013
Model: AT37-G	Capacity: 400 lbs
Serial #: 0613DE15586	Colour: White

Inspection General

Inspection Scope:	Visual inspection and magnetic particle
Inspection Code:	CSA C225
Procedure:	CIS-01 QC / CIS-02 VT / CIS-04 MT
Surface Condition:	In service Painted
Surface Temp:	> 5°C < 49°C
Date of Inspection:	December 29, 2025
Location of Inspection:	42 Ryan Wirth Way, East St. Paul, MB
Inspector:	Chad Winzinowich Connor Wizinak

Visual Inspection

Accessible members inspected for:	Damage - Wear - Loose - Missing - Corrosion
Accessible welds inspected for:	Defects
Equipment:	Flashlight



CERTIFIED INSPECTION SERVICES LTD

www.certifiedinspection.ca



Manitoba - (204)777-2475 cim@cisndt.ca
Saskatchewan - (306)737-7371 cis@cisndt.ca

Magnetic Particle Testing

Areas Tested:	Suspect areas
Method of Test:	Dry Powder Continuous
Equipment:	Magnaflux Y-2 AC Yoke - Serial #N1476
Consumables:	Circle Systems #68 Blue Dry Powder - Batch #21102
Current:	AC
Demagnetization:	No

Inspection Results:

Component	Accept	Reject	Repaired & Accepted
• Base and Frame	☒	☐	☐
• Pedestal	☒	☐	☐
• Mast	☒	☐	☐
• Lower Boom Arms	☒	☐	☐
• Knuckle Section	☒	☐	☐
• Upper Boom #1	☒	☐	☐
• Upper Boom #2	☒	☐	☐
• Bucket Attachment	☒	☐	☐
• Tie-off Point	☒	☐	☐

Disclaimers:

This inspection is based on the equipment, mounting and any previous repairs or modifications being performed as recommended by the manufacturer or under the direction of a professional engineer.

We recommend re-inspection one year from the date of our inspection.

We recommend re-inspection after any incident, deviation of normal operation or structural repairs authorized by others.

Our inspection is for all the accessible structural elements of the equipment and is supplemental to the mechanical inspections that are completed by others.

Attachments:

None

Comments: No structural defects were noted on above listed components at the time of our inspection.

Regards,

Chad Winzinowich, C.E.T.

CSA W178.2 Level 3 / NACE Coating Level 1

CGSB Level 2 MT, PT, 1 UT/ SNT Level 2 MT, PT, UT



File #: 9453-25

Alliance Tree Care

Page 2 of 2

Report #:1 Rev.0

CIS-FORM-02-JAN 2016