

H01-2



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GH08224
Decal Expiry Date: 2026-Feb-28
Inspection Number: 21237393

Inspection Result:
PASS

FACILITY: FIRST TRUCK CENTRE INC. / S20099
INSPECTOR: HARPER, CURTIS DWAYNE / 203396
WORK ORDER #: 38527
ORIGINAL INSP. #: 21223993
INSP. TYPE: Re-inspection
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2025-Feb-13 02:11 PM PST
INSP. COMPLETE: 2025-Feb-13 03:11 PM PST

VEHICLE JUR: British Columbia
PLATE #: 38283K
LICENCED GVW(kg): 0
VEHICLE YEAR: 2020
MAKE: ABU
MODEL:
REG#: 13401271
UNIT/FLEET#: 167
BODY STYLE: Flat Deck Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Electric
FUEL TYPE:
VIN: 4UGFG3034LD035188
OWNER/LESSEE NAME: HYDRO INC., VOITH
ADDRESS: 180-9955 RUE, DE CHATEAUNEUF
BROSSARD, Quebec
JAZ 3V5, Canada

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Repaired (same day)	BRAKES NOT WORKING ON #1 AXLE RIGHT SIDE BRAKAWAY BRAKE SYSTEM NOT WORKING/REPLACED FAILED BRAKAWAY BRAKES ON #1 AXLE RIGHT SIDE REPAIRED
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Not Applicable	
Section 6 - Lamps	Repaired (same day)	RIGHT REAR MARKER FAILED/REPLACED LEFT FRONT MARKER FAILED/REPLACED MISSING LISENCE PLATE LIGHT/REPAIRED
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Repaired (same day)	#2 AXLE RIGHT INSIDE TIRE FLAT TIRE WAS REPLACED
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Failed	BRAKES NOT WORKING ON #1 AXLE RIGHT SIDE BRAKAWAY BRAKE SYSTEM NOT WORKING
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Not Applicable	
Section 6 - Lamps	Failed	RIGHT REAR MARKER FAILED LEFT FRONT MARKER FAILED MISSING LISENCE PLATE LIGHT
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Failed	#2 AXLE RIGHT INSIDE TIRE FLAT
Section 9B - Wheels	Failed	WHEEL SEALS ON AXLE #1 AND RIGHT SIDE AXLE #2 LEAKING
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Tire Tread Depth (mm)						Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Outer L	Inner L	Inner R	Outer R	Steering	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	8	9	9	9		Lining (Shoe)	7.3	7.3	Drum	312.77	312.41
2	8	11	10	11		Lining (Shoe)	7.1	7.8	Drum	312.79	312.80
3	9	9	10	10		Lining (Shoe)	8.4	7.8	Drum	312.83	312.82

Comment:

Comment:

Comment:

Inspection Comments:

Has this Vehicle been road tested? Yes
Inspector: HARPER, CURTIS DWAYNE
Road Test Date: Before Inspection
Signature:
Road Tester: CURTIS HARPER

This Inspection Report was submitted to CVSE on 2025-Feb-13 03:13 PMPST
The Inspector's signature above is confirmation that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulatory matters, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVSP at the Commercial Vehicle Safety Enforcement.

CVSE0014

21/02/2025 13:13 PMPST