

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	3,872 hr & 648,858 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 16, 2024	Mar 16, 2024		Mar 16, 2024 1:12 PM	Mar 16, 2024 1:12 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00

Notes

Greased t42

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
grease tubes	Kropp Shop		4.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	4,027 hr & 654,745 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 17, 2024	Mar 17, 2024		Mar 17, 2024 10:10 AM	Mar 25, 2024 5:42 PM

Line	Task	Parts	Labor	Total		
1	✓ Steer brake pot leaking	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Front LH steer pot leaking					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	service brake pot	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Greased t42					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	grease tubes	Kropp Shop		3.0	\$0.00	\$0.00
3	✓ Convex mirror	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Convex mirror t800	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ Windshield cracked	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Windshield LH	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ Rerar drive axle quick release vlavle leaking	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	QR-1 - Quick release valve	Kropp Shop		1.0	\$0.00	\$0.00

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 1041

Trent Court

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	4,005 hr & 653,976 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 23, 2024	Mar 23, 2024		Mar 23, 2024 2:39 PM	Mar 23, 2024 2:39 PM

Line	Task			Parts	Labor	Total
1	✓ Oil change			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	oil 15w-40	Kropp Shop		42.0	\$0.00	\$0.00
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	FF5825NN - Cummins fuel filter	Kropp Shop		1.0	\$0.00	\$0.00
	FS20172 - Cummins water separator filter	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	4,160 hr & 659,620 km

Type	Created	Scheduled	Due	Started	Closed
	May 9, 2024	May 9, 2024		May 9, 2024 3:32 PM	May 9, 2024 3:32 PM

Line	Task	Parts	Labor	Total
1	✓ Air conditioning not working	\$0.00	\$0.00	\$0.00

Notes

Top condenser oring loose

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
R134a	Kropp Shop		3.8	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	4,160 hr & 659,620 km

Type	Scheduled	Due	Started	Closed
electrical	May 14, 2024		May 14, 2024 9:22 AM	May 14, 2024 9:22 AM

Line	Task	Parts	Labor	Total
1	✓ Vehicle speed sensor	\$0.00	\$0.00	\$0.00

Notes

Remove rear transmission, housing, clean tone, ring, and Reinstall

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Notes

Notes	User	Time
Speedometer signal is erratic	Trent Court	May 14, 2024 9:22 AM

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	4,199 hr & 661,029 km

Type	Created	Scheduled	Due	Started	Closed
	May 23, 2024	May 23, 2024		May 23, 2024 5:28 PM	May 23, 2024 5:28 PM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	grease tubes	Kropp Shop		2.0	\$0.00	\$0.00
2	✓ Wheels off CVIP inspection	\$0.00	\$0.00	\$0.00		
3	✓ loose t rail bolts	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3/4 bolts	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ RH headlight out low beam	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	25A fuse	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ RH high beam bulb broke	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	2 prong bulb	Kropp Shop		1.0	\$0.00	\$0.00
6	✓ Mirror cracked, replace	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	T800 west coast mirror	Kropp Shop		1.0	\$0.00	\$0.00
7	✓ Replace missing/tore mudflaps	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	24" plastic mudflap	Kropp Shop		2.0	\$0.00	\$0.00
	anti sail bracket	Kropp Shop		2.0	\$0.00	\$0.00
8	✓ rear light bar pigtail tore off	\$0.00	\$0.00	\$0.00		

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3 wire pigtail	Kropp Shop		1.0	\$0.00	\$0.00
9	✓ change diff filters			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF3311 - Rockwell diff filter	Kropp Shop		2.0	\$0.00	\$0.00
10	✓ Air filters			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	air filters	Kropp Shop		2.0	\$0.00	\$0.00
11	✓ loose yoke on diff			\$0.00	\$0.00	\$0.00
<u>Notes</u>						
	front diff output					
12	✓ RH front drive slack adjuster bar loose			\$0.00	\$0.00	\$0.00
Part Cost						\$0.00
Labor						\$0.00
Subtotal						\$0.00
Tax 1 (0.0%)						\$0.00
Tax 2 (0.0%)						\$0.00
Credit						(\$0.00)
Total Cost						\$0.00

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 1208

Cam Nadeau

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	4,218 hr & 661,414 km

Type	Scheduled	Due	Started	Closed
Service	Jul 23, 2024	Jul 23, 2024	Jul 23, 2024 11:00 AM	Jul 23, 2024 11:00 AM

Line	Task	Parts	Labor	Total
1	✓ Exhaust leak	\$0.00	\$0.00	\$0.00

Notes

Change DOC inlet pipe, two new clamps, two new device gaskets

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	4,261 hr & 662,865 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 1, 2024	Aug 1, 2024		Aug 1, 2024 4:36 AM	Aug 1, 2024 4:36 AM

Line	Task	Parts	Labor	Total
1	✓ diagnose Check engine light	\$0.00	\$0.00	\$0.00

Notes

Turbocharger speed low code @ 109 counts replaced speed sensor

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Turbo speed sensor	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	4,634 hr & 681,613 km

Type	Created	Scheduled	Due	Started	Closed
	Sep 16, 2024	Sep 16, 2024		Oct 12, 2024 10:36 AM	Oct 12, 2024 10:36 AM

Line	Task			Parts	Labor	Total
1	✓ Def derate codes			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Egr temp sensor	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	4,595 hr & 679,953 km

Type	Created	Scheduled	Due	Started	Closed
Service	Sep 16, 2024	Sep 16, 2024	Sep 16, 2024	Sep 16, 2024 5:20 PM	Sep 16, 2024 5:22 PM

Line	Task	Parts	Labor	Total
1	✓ Broken spring <u>Notes</u> Replaced with used spring	\$0.00	\$0.00	\$0.00
2	✓ Replace shock <u>Notes</u> L/H steer shock	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 1285

Cam Nadeau

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	4,595 hr & 679,953 km

Type	Scheduled	Due	Started	Closed
	Sep 16, 2024		Sep 16, 2024 5:25 PM	Sep 16, 2024 5:25 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Unassigned

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	4,595 hr & 679,953 km

Type	Created	Scheduled	Due	Started	Closed
	Sep 16, 2024	Sep 16, 2024		Sep 16, 2024 6:16 PM	Sep 16, 2024 6:16 PM

Line	Task	Parts	Labor	Total
1	✓ Oil change	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	4,634 hr & 681,613 km

Type	Created	Scheduled	Due	Started	Closed
	Sep 30, 2024	Sep 30, 2024		Sep 30, 2024 12:01 PM	Sep 30, 2024 12:01 PM

Line	Task	Parts	Labor	Total		
1	✓ Drive tires (set of 12)	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Truck - Drive tire	Kropp Shop		12.0	\$0.00	\$0.00
2	✓ Air leak behind dash	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Bull head in firewall had blown o ring made new line and joined line					
3	✓ MV-3 valve loose in dash	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Made new bracket to mount in dash					
		Part Cost				\$0.00
		Labor				\$0.00
		Subtotal				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	4,635 hr & 681,615 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 23, 2024	Oct 23, 2024		Oct 23, 2024 4:50 PM	Oct 23, 2024 4:50 PM

Line	Task	Parts	Labor	Total												
1	✓ Brake Accessories	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	Rh rear drive brakes wore out															
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>Es2 shoe kit</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	Es2 shoe kit	Kropp Shop		1.0	\$0.00	\$0.00			
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost											
Es2 shoe kit	Kropp Shop		1.0	\$0.00	\$0.00											
2	✓ DPF box	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	DOC,DPF face plugged															
3	✓ Driveline	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	Transmission output u joint no good															
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>SPL250-3x - SPL 250 U joint</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	SPL250-3x - SPL 250 U joint	Kropp Shop		1.0	\$0.00	\$0.00			
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost											
SPL250-3x - SPL 250 U joint	Kropp Shop		1.0	\$0.00	\$0.00											
4	✓ Engine	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	wrench light on															
5	✓ Exhaust	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	stack bushings no good															
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost									
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost											

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

	EM75-69000-HT - Stack bushing kit	Kropp Shop	2.0	\$0.00	\$0.00	
6	✓ Frame & Assembly		\$0.00	\$0.00	\$0.00	
	<u>Notes</u>					
	T rail bolts loose					
7	✓ Lights - All		\$0.00	\$0.00	\$0.00	
	<u>Notes</u>					
	lh hood light out					
8	✓ Mirrors		\$0.00	\$0.00	\$0.00	
	<u>Notes</u>					
	lh convex broke					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Convex mirror t800	Kropp Shop		1.0	\$0.00	\$0.00
9	✓ Other		\$0.00	\$0.00	\$0.00	
	<u>Notes</u>					
	RH plastic fender NFG					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	plastic fender	Kropp Shop		1.0	\$0.00	\$0.00
10	✓ Rear End		\$0.00	\$0.00	\$0.00	
	<u>Notes</u>					
	middle diff output seal leaking					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	R945008 - Rockwell output seal	Kropp Shop		1.0	\$0.00	\$0.00
11	✓ Service Brakes		\$0.00	\$0.00	\$0.00	
	<u>Notes</u>					
	front RH service line loose					

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 1369
Nate Vandenberghe, Sam Hawksley

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	4,710 hr & 685,275 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 30, 2024	Oct 30, 2024		Oct 30, 2024 8:03 PM	Oct 30, 2024 8:03 PM

Line	Task	Parts	Labor	Total
1	✓ No defrost	\$0.00	\$0.00	\$0.00

Notes

Blower box falling off replaced bolts, found jammed blend door freed up and tested

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 1402
Sam Hawksley, Nate Vandenberghe

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	4,720 hr & 685,746 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 2, 2024	Nov 2, 2024		Nov 2, 2024 7:29 PM	Nov 2, 2024 7:29 PM

Line	Task	Parts	Labor	Total
1	✓ Lights - All	\$0.00	\$0.00	\$0.00

Notes

Rh headlight out top LH MM light out

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 1420

Sam Hawksley

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	4,720 hr & 685,746 km

Type	Scheduled	Due	Started	Closed
	Nov 8, 2024		Nov 8, 2024 6:01 AM	Nov 8, 2024 6:01 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	4,831 hr & 691,707 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 16, 2024	Nov 16, 2024		Nov 16, 2024 7:54 AM	Nov 16, 2024 1:43 PM

Line	Task	Parts	Labor	Total		
1	✓ LH mirror cracked	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	T800 west coast mirror	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ RH mirror cracked	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	T800 west coast mirror	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ coolant leaks	\$0.00	\$0.00	\$0.00		
4	✓ top LH work light	\$0.00	\$0.00	\$0.00		
	Technician	Hours	Rate	Cost		
	Sam Hawksley	0.0	\$0.00	\$0.00		
5	✓ Air leak by air dryer	\$0.00	\$0.00	\$0.00		
	Technician	Hours	Rate	Cost		
	Everett Twin	0.0	\$0.00	\$0.00		
6	✓ Airbag Trailer - Repair	\$0.00	\$0.00	\$0.00		
	Technician	Hours	Rate	Cost		
	Sam Hawksley	0.0	\$0.00	\$0.00		
7	✓ Broken Crossmember	\$0.00	\$0.00	\$0.00		
8	✓ Bunk Cracked-Weld	\$0.00	\$0.00	\$0.00		
	Technician	Hours	Rate	Cost		
	Everett Twin	0.0	\$0.00	\$0.00		

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 1432

Nate Vandenberghe

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 1450

Sam Hawksley

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	4,831 hr & 691,707 km

Type	Scheduled	Due	Started	Closed
	Nov 17, 2024		Nov 17, 2024 3:07 PM	Nov 17, 2024 3:07 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
2	✓ Oil change	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	5,036 hr & 701,928 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 12, 2024	Dec 12, 2024		Dec 12, 2024 3:43 AM	Dec 12, 2024 3:43 AM

Line	Task			Parts	Labor	Total
1	✓ RH hood damage			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	K256-880-4R - RH hood bucket	Kropp Shop		1.0	\$0.00	\$0.00
	3-2048-3 - Headlight bezel	Kropp Shop		1.0	\$0.00	\$0.00
	0551771 - Speaker low beam bulb	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 1510
Trent Court, Everett Twin

CLOSED



875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	5,036 hr & 701,928 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 12, 2024	Dec 12, 2024		Dec 12, 2024 4:12 AM	Dec 12, 2024 4:12 AM

Line	Task	Parts	Labor	Total
1	✓ Steer Tires	\$0.00	\$0.00	\$0.00

Notes

150,000km replaced

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
steer tires	Kropp Shop		2.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 1533

Nate Vandenberghe

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	5,067 hr & 703,385 km

Type	Scheduled	Due	Started	Closed
	Dec 15, 2024		Dec 15, 2024 6:58 PM	Dec 15, 2024 6:58 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	5,096 hr & 704,658 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 18, 2024	Dec 18, 2024		Dec 18, 2024 2:21 PM	Dec 18, 2024 2:21 PM

Line	Task	Parts	Labor	Total
1	✓ DEF codes	\$0.00	\$0.00	\$0.00

Notes

No line heat 3, found broken wire along frame and repaired...
verified voltage and line heater and have 4.9V, checked codes went
inactive

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 1575
Nate Vandenberghe, Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	5,359 hr & 716,773 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 16, 2025	Jan 16, 2025		Jan 17, 2025 2:34 PM	Jan 17, 2025 2:34 PM

Line	Task	Parts	Labor	Total
1	✓ inspect front end from going off the road	\$0.00	\$0.00	\$0.00
2	✓ LH drag link NFG	\$0.00	\$0.00	\$0.00
3	✓ Tie rod bar bent	\$0.00	\$0.00	\$0.00
4	✓ RH "X" block slid back	\$0.00	\$0.00	\$0.00
5	✓ RH steer axle u bolts bent	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	5,373 hr & 717,308 km

Type	Scheduled	Due	Started	Closed
	Jan 19, 2025		Jan 19, 2025 7:21 AM	Jan 19, 2025 7:21 AM

Line	Task	Parts	Labor	Total
1	✓ Air Lines <u>Notes</u> blue glad hand line leaking	\$0.00	\$0.00	\$0.00
2	✓ Exhaust <u>Notes</u> egr outlet leaking	\$0.00	\$0.00	\$0.00
3	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
4	✓ Lights - All <u>Notes</u> top rh micky mouse light out, top rh work light	\$0.00	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 1599

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	5,373 hr & 717,308 km

Type	Scheduled	Due	Started	Closed
	Jan 19, 2025		Jan 19, 2025 6:24 PM	Jan 19, 2025 6:24 PM

Line	Task	Parts	Labor	Total
1	✓ Oil change	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 1651

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	5,537 hr & 723,431 km

Type	Scheduled	Due	Started	Closed
	Feb 2, 2025		Feb 2, 2025 7:16 PM	Feb 2, 2025 7:16 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	5,537 hr & 723,431 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 10, 2025	Feb 10, 2025		Feb 13, 2025 10:16 AM	Feb 13, 2025 10:16 AM

Line	Task	Parts	Labor	Total
1	✓ ABS codes	\$0.00	\$0.00	\$0.00
2	✓ Front steer slack adjusters not functioning	\$0.00	\$0.00	\$0.00

Notes

self adjusting not functioning, gear internal broke will not move

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
6" slack adjuster CC	Kropp Shop		2.0	\$0.00	\$0.00

3	✓ Front drive RH airlines rubbing on diff	\$0.00	\$0.00	\$0.00
---	---	--------	--------	--------

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
HAB 8 28 FS - Rubber air brake service 28" long	Kropp Shop		1.0	\$0.00	\$0.00

4	✓ Rear diff air lines rubbing in driveshaft	\$0.00	\$0.00	\$0.00
---	---	--------	--------	--------

Notes

tied up and moved no fraying of plys

5	✓ RH hood signal out	\$0.00	\$0.00	\$0.00
---	----------------------	--------	--------	--------

6	✓ Rear light bar wires ripped off	\$0.00	\$0.00	\$0.00
---	-----------------------------------	--------	--------	--------

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Notes

Notes	User	Time
Level 1 scale Repairs	Trent Court	Feb 11, 2025 9:09 AM

Alberta
COMMERCIAL VEHICLE INSPECTION REPORT

INSPECTION LEVEL: 1
Vehicle(s) Inspected on: February 2025 at 14:04 hours at: Trent Lake VSS

INSPECTION RESULT: OUT OF SERVICE
VEHICLE(S) OUT OF SERVICE UNTIL OUT OF SERVICE DEFECT RESULT(S) BELOW ARE CORRECTED
FAILURE TO REPORT INDICATED REPAIRS BY 2025/02/19 MAY RESULT IN PROSECUTION

ANY DEFECTS NOTED ON THIS DOCUMENT MAY RESULT IN PROSECUTION

VEH DEFECT	DESCRIPTION	ACT / SECTION	TYT / Appearance Number	RESULT
1	1. Large Encumbrance Outside top of longest not secured by 2 cross beams Fasteners not tight. Moveable by hand, only 1 tight fit shown on front check.	TSA NSC Standard 10 26(2)		Out of Service
1	1. Lighting Devices (Part 2 Section 9 DORS only) Tail lamp not capable of emitting red light visible at least 100 m to rear Tail lamps not working on power unit	TSA AR 1220009 140F		Requires Attention
1	1. Lighting Devices (Part 2 Section 9 DORS only) Brake lamp fail to light up when service brake applied Brake lamps not working on power unit	TSA AR 1220009 26(2)		Requires Attention
1	1. Lighting Devices (Part 2 Section 9 DORS only) Turn signal lamps not emit amber light visible from at least 200 m ahead when left Right signal not working on truck	TSA AR 1220009 230(2C)		Requires Attention
1	1. Lighting Devices (Part 2 Section 9 DORS only) Turn signal lamps not emit red/amber light visible from at least 200 m to rear Signal lamps not working on power unit	TSA AR 1220009 230(2C)		Requires Attention
2	2. Brake Adjustment Operating or parking sensor to operate an unsafe commercial vehicle on highway More than 20 brake defective on combination @ 14 trucks	TSA AR 1210009 9		Out of Service
2	2. Brake Systems No mechanical or structural part must be misaligned or worn as to render it ineffective in stopping or holding the vehicle on level ground or on a grade. Discarded or damaged parts must be replaced with parts of equal or better quality. Auto 4 right brake disconnected broken. And checked to work on testing system MAJOR DEFECT	TSA AR 1210009 S-02 12(A)		Requires Attention
2	2. Brake Systems No mechanical or structural part must be misaligned or worn as to render it ineffective in stopping or holding the vehicle on level ground or on a grade. Discarded or damaged parts must be replaced with parts of equal or better quality. Auto 3 right brake being not contacting when service brake applied MAJOR DEFECT	TSA AR 1210009 S-02 12(A)		Requires Attention
2	2. Brake Systems Tail or main and side lighting system in good working order. Unable to find ABS lamp on trailer to test. Checked vehicle driver side	TSA AR 1220009 8(2)		Requires Attention
2	2. Brake Systems No mechanical or structural part must be misaligned or worn as to render it ineffective in stopping or holding the vehicle on level ground or on a grade. Discarded or damaged parts must be replaced with parts of equal or better quality. Auto 3 left brake being not contacting when service brake applied MAJOR DEFECT	TSA AR 1210009 S-02 12(A)		Requires Attention

Officer: R. HOULT 8386 P#: 780-645-7389 Agency: North West Other Officer: K. MELDAHL 2988 Time Out: 19:42

REFER TO LAST PAGE OF INSPECTION FOR DETAILS REGARDING COMPLIANCE

DRIVER IS RESPONSIBLE FOR PROVIDING CARRIER WITH A COPY OF THIS REPORT

CHW-EJ Rev (2015/1)

CLOSED



Powered by www.mtcproweb.com

Parent: T42 - 2016 Gerrys

Trent Court

CLOSED



INSPECTION LEVEL: 1
 (suspended) inspected this 20th of February 2020 at 16:06 hours at/for Steve Lark YR

COMMERCIAL VEHICLE INSPECTION REPORT

CVSA
 COMMERCIAL VEHICLE INSPECTION REPORT

AR264760E
 Page 1 of 2

Driver: _____

INSPECTION RESULT: OUT OF SERVICE

VEHICLE(S) OUT OF SERVICE UNTIL OUT OF SERVICE DEFECT RESULT BELOW ARE CORRECTED
 FAILURE TO REPORT INDICATED REPAIRS BY BUSINESS MAY RESULT IN PROSECUTION

Owner: KNOPE CONTRACTING LTD.
Address: Box 237
 City: Steve Lake
Jur: AB **Postal/Zip Code:** T9G 3A0 **MVD:** 0308 12034

Owner: Steve Lark YR
Vehicle: 2010 HYUNDAI

VEHICLE MAKE: HYUNDAI
VEHICLE MODEL: ELANTRA

	1	2	3	4	5	6	7
Auto 1	3	4	1	1	2	2	0
Auto 2	3	4	1	1	2	2	0
Auto 3	3	4	1	1	2	2	0

Vehicle	Plate	Jur	CVSA Seal
1 Power Unit	E68882	AB	
2 Semi Trailer	42X990	AB	

ANY DEFECTS NOTED ON THIS DOCUMENT MAY RESULT IN PROSECUTION

VEHICLE	DESCRIPTION	ACT / SECTION	TYPI Appearance Rating	RESULT
1 Brake System	Operating or attempting operation to operate an unsafe commercial vehicle as designed or intended to perform more than 20 tonnes performance on combination B-14 brake.	TSA AR 121-0059 3 E13183121M		Out of Service
1 Brake System	Brake not adjusted to manufacturer's specifications without brake drag. Auto 1 Left Tire 24 Long stroke, Allowed 2 1/2 inches, measured at 3 1/4 inches. Auto 2 Right Tire 24 Long stroke, Allowed 2 1/2 inches, measured at 3 1/8 inches.	TSA AR 121-0059 S-02 10(5)		Requires Attention
1 Brake System	Self-adjusting brake not maintained/operating properly. Auto 1 both.	TSA AR 121-0059 S-02 10(7)		Requires Attention
1 Brake System	Hydraulic connections in air brake system not regulated within limit. Auto 4 airline reduced on differential valve. Flat spot on airline.	TSA AR 121-0059 S-02 10(10)		Requires Attention
1 Brake System	Hydraulic connections in air brake system not regulated within limit. Auto 4 right airline rubbing differential. Worn through.	TSA AR 121-0059 S-02 10A(8)		Requires Attention
1 Brake System	Hydraulic connections in air brake system not regulated within limit. Auto 3 right airline rubbing differential. Worn through.	TSA AR 121-0059 S-02 10A(9)		Out of Service
1 Brake System	Flat in maintain and lock braking system in good working order. Auto 1 ramp air in cab.	TSA AR 122-0059 5(7)(2)		Requires Attention
1 Cargo Securement	Driver fail to secure load/unload unit when vehicle on highway. Trayover 2 boxes and movable by hand.	TSA NSC Standard 10 19(2)		Requires Attention

Officer: **R. HOULT 8386** PH: 780-448-7388 Location: North West

Officer: **K. ALDAN 3588** Title: Out 18-42

REFER TO LAST PAGE OF INSPECTION FOR DETAILS REGARDING CORRECTIONS

THE SIGNATURE OF THIS INSPECTOR DOES NOT GUARANTEE THE ACCURACY OF THE CHECKED INFORMATION OR CERTIFY ALL DEFECTS LISTED. IT IS THE RESPONSIBILITY OF THE DRIVER TO CORRECT ANY DEFECTS LISTED AND TO RETURN THE VEHICLE TO THE INSPECTOR FOR RE-EVALUATION.

AR264760E1

DRIVER IS RESPONSIBLE FOR PROVIDING CARRIER WITH A COPY OF THIS REPORT

CVSA E-Rep 2017/01

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	5,777 hr & 734,460 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 25, 2025	Feb 25, 2025		Feb 27, 2025 11:37 AM	Feb 27, 2025 11:37 AM

Line	Task	Parts	Labor	Total
1	✓ DEF codes	\$0.00	\$0.00	\$0.00
Notes				
NO def pressure, pump not turning on, checked fuse found broken power wire along chassis harness				
2	✓ top RH work light not working	\$0.00	\$0.00	\$0.00
3	✓ LH side drive mud flap tore off	\$0.00	\$0.00	\$0.00
4	✓ middle diff input yoke loose	\$0.00	\$0.00	\$0.00
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 1719

Nate Vandenberghe

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	5,802 hr & 735,485 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 3, 2025	Mar 3, 2025		Mar 5, 2025 8:16 PM	Mar 5, 2025 8:16 PM

Line	Task	Parts	Labor	Total
1	✓ Air Lines <u>Notes</u> air leak behind dash	\$0.00	\$0.00	\$0.00
2	✓ Lights - All <u>Notes</u> RH mickey mouse light out	\$0.00	\$0.00	\$0.00
3	✓ Windows <u>Notes</u> RH windshield cracked	\$0.00	\$0.00	\$0.00
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	5,865 hr & 738,343 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 8, 2025	Mar 8, 2025		Mar 8, 2025 6:15 PM	Mar 8, 2025 6:15 PM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	oil 15w-40	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 1871

Everett Twin

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	6,293 hr & 758,988 km

Type	Created	Scheduled	Due	Started	Closed
	May 23, 2025	May 23, 2025		Jul 3, 2025 8:09 AM	Jul 3, 2025 8:09 AM

Line	Task	Parts	Labor	Total
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
2	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	6,183 hr & 753,017 km

Type	Created	Scheduled	Due	Started	Closed
	Jun 6, 2025	Jun 6, 2025		Jun 6, 2025 6:31 AM	Jun 6, 2025 6:31 AM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Top rad hose	\$0.00	\$0.00	\$0.00
---	----------------	--------	--------	--------

Notes

Leaking top rotted hose changed with new part

2	✓ Air conditioning	\$0.00	\$0.00	\$0.00
---	--------------------	--------	--------	--------

Notes

Replace leaking O-ring, re-charged

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 1927

Cam Nadeau

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	6,285 hr & 758,512 km

Type	Scheduled	Due	Started	Closed
	Jun 23, 2025		Jun 23, 2025 8:08 AM	Jun 23, 2025 8:08 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	6,293 hr & 758,988 km

Type	Created	Scheduled	Due	Started	Closed
	Jun 23, 2025	Jun 23, 2025		Jun 23, 2025 4:01 PM	Jun 23, 2025 4:01 PM

Line	Task	Parts	Labor	Total
1	✓ Adjust clutch	\$0.00	\$0.00	\$0.00
	Technician	Hours	Rate	Cost
	Everett Twin	0.0	\$0.00	\$0.00
2	✓ coolant leaks	\$0.00	\$0.00	\$0.00
	Technician	Hours	Rate	Cost
	Trent Court	0.0	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Subtotal			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	6,293 hr & 758,988 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 3, 2025	Jul 3, 2025		Jul 6, 2025 2:40 PM	Jul 6, 2025 2:40 PM

Line	Task	Parts	Labor	Total
1	✓ Lights inop	\$0.00	\$0.00	\$0.00

Notes

LHS MM light, no marker or signal. Found poor ground in sleeper bus bar, clean ground and splice new ground connections. Found marker still INOP. Found power near fuel tank but not at MM connector. Splice new 4 wire from fuel tank-MM connector. Found marker circuit operational.

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	6,293 hr & 758,988 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 6, 2025	Jul 6, 2025		Jul 6, 2025 2:40 PM	Jul 6, 2025 2:40 PM

Line	Task	Parts	Labor	Total
1	✓ ABS codes	\$0.00	\$0.00	\$0.00

Notes

DA left DA right AA left AA right replaced

All WSS on drives

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
K181265 - Wheel speed sensor	Kropp Shop		4.0	\$0.00	\$0.00

2	✓ Low coolant	\$0.00	\$0.00	\$0.00
---	---------------	--------	--------	--------

Notes

Lower rad hose clamp loose. Tighten and topped up

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	6,405 hr & 765,143 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 6, 2025	Aug 6, 2025		Aug 6, 2025 5:54 PM	Aug 6, 2025 5:54 PM

Line	Task	Parts	Labor	Total
1	✓ Ac not working	\$0.00	\$0.00	\$0.00

Notes

Replace low side o rings

2	✓ Oil change	\$0.00	\$0.00	\$0.00
---	--------------	--------	--------	--------

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
FS20172 - Cummins water separator filter	Kropp Shop		1.0	\$0.00	\$0.00
FF5825NN - Cummins fuel filter	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	6,716 hr & 783,728 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 18, 2025	Aug 18, 2025		Aug 24, 2025 11:51 AM	Aug 24, 2025 11:51 AM

Line	Task	Parts	Labor	Total
1	✓ Exhaust leak	\$0.00	\$0.00	\$0.00

Notes

Bellows hole, loose clamp behind turbo gasket MIA doc inlet pipe
clamp loose gasket MIA

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
EBPB11861 - Bellows kit	Kropp Shop		1.0	\$0.00	\$0.00
90-0012 - 4" v clamp	Kropp Shop		2.0	\$0.00	\$0.00
2866636 - 4" exhaust gasket	Kropp Shop		2.0	\$0.00	\$0.00

2	✓ No AC	\$0.00	\$0.00	\$0.00
---	---------	--------	--------	--------

Notes

Low pressure hose compressor to dryer nfg

3	✓ Heater doesn't work	\$0.00	\$0.00	\$0.00
---	-----------------------	--------	--------	--------

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	6,755 hr & 785,973 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 28, 2025	Aug 28, 2025		Aug 28, 2025 3:29 PM	Aug 28, 2025 5:00 PM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ Transmission failed	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	RTLO-18918B - Transmission	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Hood lights half lit up	\$0.00	\$0.00	\$0.00		
4	✓ Blending door not moving to defrost	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Found glasses in defrost blend door					
5	✓ Force regen required	\$0.00	\$0.00	\$0.00		
		Part Cost			\$0.00	
		Labor			\$0.00	
		Subtotal			\$0.00	
		Tax 1 (0.0%)			\$0.00	
		Tax 2 (0.0%)			\$0.00	
		Credit			(\$0.00)	
		Total Cost			\$0.00	

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	6,864 hr & 792,356 km

Type	Created	Scheduled	Due	Started	Closed
	Sep 10, 2025	Sep 10, 2025		Sep 10, 2025 1:12 PM	Sep 10, 2025 1:12 PM

Line	Task			Parts	Labor	Total
1	✓ LH front steer nfg			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	steer tires	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 2143

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	6,931 hr & 796,392 km

Type	Scheduled	Due	Started	Closed
	Sep 22, 2025		Sep 22, 2025 1:27 PM	Sep 22, 2025 1:27 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	6,931 hr & 796,392 km

Type	Created	Scheduled	Due	Started	Closed
	Sep 23, 2025	Sep 23, 2025		Sep 23, 2025 8:15 AM	Sep 23, 2025 8:15 AM

Line	Task	Parts	Labor	Total		
1	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Fill first and 3rd diff	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Subtotal				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	6,986 hr & 799,415 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 1, 2025	Oct 1, 2025		Oct 1, 2025 8:16 AM	Oct 1, 2025 8:16 AM

Line	Task	Parts	Labor	Total
1	✓ Lights INOP	\$0.00	\$0.00	\$0.00

Notes

Found multiple chafed wires, replace harness and found lights to be operational

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Mickey Mouse light harness	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 2210
Trent Court, Aiden Kenny
CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	7,121 hr & 806,196 km

Type	Scheduled	Due	Started	Closed
	Oct 23, 2025		Oct 23, 2025 7:18 PM	Oct 23, 2025 7:18 PM

Line	Task	Parts	Labor	Total
1	✓ Steer Tires	\$0.00	\$0.00	\$0.00
2	✓ Top rh work light	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	7,121 hr & 806,196 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 28, 2025	Oct 28, 2025		Oct 28, 2025 7:30 PM	Oct 28, 2025 7:30 PM

Line	Task			Parts	Labor	Total
1	✓ Altnator failed			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	D27-1019-0200P - Alternator Cummins	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	7,155 hr & 807,777 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 3, 2025	Nov 3, 2025		Nov 3, 2025 5:38 PM	Nov 4, 2025 5:01 PM

Line	Task	Parts	Labor	Total												
1	✓ loose yoke on diff	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	#1 output & #2 input yolk															
2	✓ Anti sail	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	RHS															
3	✓ Transmission output u joint loose	\$0.00	\$0.00	\$0.00												
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>SPL250-3x - SPL 250 U joint</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	SPL250-3x - SPL 250 U joint	Kropp Shop		1.0	\$0.00	\$0.00			
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost											
SPL250-3x - SPL 250 U joint	Kropp Shop		1.0	\$0.00	\$0.00											
4	✓ crossmember bolt ontop of transmission yoke to the right loose	\$0.00	\$0.00	\$0.00												
5	✓ dpf outlet clamp loose? Exhaust leak? Black around the ring	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	No leaks, only black marks															
6	✓ Front diff breather tube broke off	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	X1 new breather tube															
7	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00												

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 2234

Everett Twin

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	7,361 hr & 818,794 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 26, 2025	Nov 26, 2025		Nov 26, 2025 4:37 PM	Nov 26, 2025 4:39 PM

Line	Task	Parts	Labor	Total		
1	✓ 12 drives	\$0.00	\$0.00	\$0.00		
2	✓ Left steer	\$0.00	\$0.00	\$0.00		
3	✓ Left top work light	\$0.00	\$0.00	\$0.00		
4	✓ Def line	\$0.00	\$0.00	\$0.00		
5	✓ New coolant hose clamp	\$0.00	\$0.00	\$0.00		
6	✓ Tightened work light	\$0.00	\$0.00	\$0.00		
7	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
8	✓ Drive tires (set of 12)	\$0.00	\$0.00	\$0.00		
9	✓ Rh drag link	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	346-574 - RH drag link T800	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	7,384 hr & 819,776 km

Type	Scheduled	Due	Started	Closed
	Dec 1, 2025		Dec 1, 2025 5:46 PM	Dec 1, 2025 5:46 PM

Line	Task	Parts	Labor	Total		
1	✓ Air Lines	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	tp1 supply line leak					
2	✓ Belts and Hoses	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	coolant leaks					
3	✓ Exhaust	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	def injector code					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	5578983RX - Doser	Kropp Shop	EKW	1.0	\$0.00	\$0.00
4	✓ Mirrors	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	rh west coast nfg					
5	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 2346

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	7,478 hr & 824,319 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 8, 2025	Dec 8, 2025		Dec 9, 2025 9:59 PM	Dec 9, 2025 9:59 PM

Line	Task	Parts	Labor	Total
1	✓ block heater cord end	\$0.00	\$0.00	\$0.00
2	✓ plugged blending valve back in	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	7,563 hr & 827,275 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 13, 2025	Dec 13, 2025		Dec 13, 2025 12:08 PM	Dec 13, 2025 12:16 PM

Line	Task	Parts	Labor	Total		
1	✓ ABS codes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	wire wore, connected back together					
	lh rear wss code					
2	✓ Air Lines	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	lh front drive chaffed lines					
3	✓ Belts and Hoses	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	lower rad hose 45 degree nfg					
4	✓ Brake Accessories	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	middle lh drive brake pot nfg					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ Check all fluid levels	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	power steering level low					
6	✓ Driveline	\$0.00	\$0.00	\$0.00		

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Notes

inspect first u joint

7	✓ Engine	\$0.00	\$0.00	\$0.00
---	----------	--------	--------	--------

Notes

egr pipe leaking exhaust

8	✓ Exhaust	\$0.00	\$0.00	\$0.00
---	-----------	--------	--------	--------

Notes

bellows pipe cracked

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
EBPB11861 - Bellows kit	Kropp Shop		1.0	\$0.00	\$0.00

9	✓ Front Axle	\$0.00	\$0.00	\$0.00
---	--------------	--------	--------	--------

Notes

LH drag king castle nut loose to pitman arm backed off and cleaned threads and re installed checked play and is all good

loose steering 1/8" turn slop

10	✓ Lights - All	\$0.00	\$0.00	\$0.00
----	----------------	--------	--------	--------

Notes

skirt light marker out, skirt lh signal out

11	✓ Mirrors	\$0.00	\$0.00	\$0.00
----	-----------	--------	--------	--------

Notes

tighten rh mirror

12	✓ Tire Chains	\$0.00	\$0.00	\$0.00
----	---------------	--------	--------	--------

Notes

lh mudflap hanger bracket hitting tire

13	✓ Transmission	\$0.00	\$0.00	\$0.00
----	----------------	--------	--------	--------

Notes

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 2357
Sam Hawksley, Terren Page
CLOSED

top up transmission oil

14	✓ Windows	\$0.00	\$0.00	\$0.00
----	-----------	--------	--------	--------

Notes

RH windshield cracked

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 2361

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	7,563 hr & 827,275 km

Type	Scheduled	Due	Started	Closed
	Dec 13, 2025		Dec 13, 2025 1:56 PM	Dec 13, 2025 1:56 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 2403

Terren Page, Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	7,714 hr & 831,533 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 26, 2025	Dec 26, 2025		Jan 1, 2026 6:00 PM	Jan 1, 2026 6:00 PM

Line	Task	Parts	Labor	Total
1	✓ Fan won't turn off	\$0.00	\$0.00	\$0.00
2	✓ Intake pressure sensor shorted	\$0.00	\$0.00	\$0.00
3	✓ LH fuel cap mia	\$0.00	\$0.00	\$0.00
4	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 2411

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	7,714 hr & 831,533 km

Type	Scheduled	Due	Started	Closed
	Jan 2, 2026		Jan 2, 2026 7:38 PM	Jan 2, 2026 7:38 PM

Line	Task	Parts	Labor	Total
1	✓ Breakdown: steady bearing failure drive out and repair	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 2457

Aiden Kenny

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	7,898 hr & 840,472 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 16, 2026	Jan 16, 2026		Jan 16, 2026 5:37 PM	Jan 16, 2026 5:37 PM

Line	Task	Parts	Labor	Total
1	✓ Tranny leak questionable	\$0.00	\$0.00	\$0.00
2	✓ Tie up air lines on #4lh axel	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	7,898 hr & 840,472 km

Type	Scheduled	Due	Started	Closed
	Jan 17, 2026		Jan 17, 2026 6:43 AM	Jan 17, 2026 6:43 AM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	8,075 hr & 849,271 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 1, 2026	Feb 1, 2026		Feb 1, 2026 2:37 PM	Feb 1, 2026 2:37 PM

Line	Task	Parts	Labor	Total																								
1	✓ Mirrors	\$0.00	\$0.00	\$0.00																								
	<u>Notes</u>																											
	all mirrors NFG, mirror heat not working																											
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>Convex mirror t800</td><td>Kropp Shop</td><td></td><td>2.0</td><td>\$0.00</td><td>\$0.00</td></tr><tr><td>T800 west coast mirror</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr><tr><td>T800 west coast mirror</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	Convex mirror t800	Kropp Shop		2.0	\$0.00	\$0.00	T800 west coast mirror	Kropp Shop		1.0	\$0.00	\$0.00	T800 west coast mirror	Kropp Shop		1.0	\$0.00	\$0.00			
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost																							
Convex mirror t800	Kropp Shop		2.0	\$0.00	\$0.00																							
T800 west coast mirror	Kropp Shop		1.0	\$0.00	\$0.00																							
T800 west coast mirror	Kropp Shop		1.0	\$0.00	\$0.00																							
2	✓ Other	\$0.00	\$0.00	\$0.00																								
	<u>Notes</u>																											
	rear leveling valve loose																											
3	✓ Radiator	\$0.00	\$0.00	\$0.00																								
	<u>Notes</u>																											
	1" coolant hose NFG, 5/8" hose back of head NFG, lower rad hose leak																											
4	✓ Steering System	\$0.00	\$0.00	\$0.00																								
	<u>Notes</u>																											
	power steering pump																											
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>Sp33126 - TRP power steering pump Cummins</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	Sp33126 - TRP power steering pump Cummins	Kropp Shop		1.0	\$0.00	\$0.00															
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost																							
Sp33126 - TRP power steering pump Cummins	Kropp Shop		1.0	\$0.00	\$0.00																							
5	✓ Wheels & Rims	\$0.00	\$0.00	\$0.00																								

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Notes

FRHO drive rim cracked

6	✓ Windows	\$0.00	\$0.00	\$0.00
---	-----------	--------	--------	--------

Notes

LH windshield cracked

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Windshield LH	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 2518

Sam Hawksley

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	8,086 hr & 849,670 km

Type	Scheduled	Due	Started	Closed
	Feb 5, 2026		Feb 5, 2026 2:56 PM	Feb 5, 2026 2:56 PM

Line	Task	Parts	Labor	Total		
1	✓ Transmission aux bearing broke out cap	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	RTLO-18918B - Transmission	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	8,188 hr & 854,825 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 15, 2026	Feb 15, 2026		Feb 15, 2026 2:59 PM	Feb 16, 2026 9:03 AM

Line	Task	Parts	Labor	Total		
1	✓ ABS codes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	lh rear wss code					
2	✓ Belts and Hoses	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Tranny cooler coolant lines need changed					
3	✓ Check all fluid levels	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	coolant level low					
4	✓ Front Axle	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	tie rod bar bent					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	347-205 - t800 tie rod bar	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ Lights - All	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	rear skirt light wires hanging and lights not on					
6	✓ Tires	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 2556
Trent Court, Aiden Kenny
CLOSED

LH steer tire inside wore

7	✓ lower LH step bolt MIA- replaced	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	8,313 hr & 859,719 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 26, 2026	Feb 26, 2026		Feb 26, 2026 8:04 PM	Feb 26, 2026 9:01 PM

Line	Task	Parts	Labor	Total		
1	✓ Air Lines	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Service and supply ripped off back left axle					
2	✓ Brake Accessories	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Brake pots missing rubber plug					
3	✓ Engine	\$0.00	\$0.00	\$0.00		
4	✓ Exhaust	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Exhaust clamp loose x2 from turbo to can					
5	✓ Mirrors	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Drivers mirror missing					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	T800 west coast mirror	Kropp Shop		1.0	\$0.00	\$0.00
6	✓ Transmission	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Oil leak					
7	✓ LH steer shock bushing	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 2591

Sam Hawksley

CLOSED

0391246000 - steer shock bushing kit

Kropp Shop

1.0

\$0.00

\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	8,313 hr & 859,719 km

Type	Scheduled	Due	Started	Closed
	Feb 27, 2026		Feb 27, 2026 9:52 AM	Feb 27, 2026 9:52 AM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	oil 15w-40	Kropp Shop		42.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	8,419 hr & 868,383 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 31, 2026	Mar 31, 2026		Apr 1, 2026 7:27 AM	Apr 1, 2026 2:05 PM

Line	Task	Parts	Labor	Total
1	✓ Differential pressure code	\$0.00	\$0.00	\$0.00
2	✓ Fan hub air line leaking	\$0.00	\$0.00	\$0.00
3	✓ turbo downpipe exhaust leaks	\$0.00	\$0.00	\$0.00

Notes

Took out exhusst and replaced 3 gaskets and two clamps

4	✓ Def pressure code			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	5509448RX - DEF pump t880	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ Transmission 4th gear MIA			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	RTLO-18918B - Transmission	Kropp Shop		1.0	\$0.00	\$0.00
6	✓ Fixed leak on the rad side of top rad hose, changed clamp			\$0.00	\$0.00	\$0.00
7	✓ Tightened clamp on engine side of top rad hose			\$0.00	\$0.00	\$0.00
8	✓ Tightened hose clamp on coolant hose on coolant filter housing			\$0.00	\$0.00	\$0.00
9	✓ Replaced shifter boot in cab			\$0.00	\$0.00	\$0.00

Kropp Contracting
Shop

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

Work Order 2660

Trent Court

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	8,565 hr & 871,834 km

Type	Created	Scheduled	Due	Started	Closed
	Apr 6, 2026	Apr 6, 2026		Apr 13, 2026 6:18 PM	Apr 13, 2026 6:18 PM

Line	Task	Parts	Labor	Total
1	✓ De rate ambient air temperature sensor inaccurate	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0KR951080	E68682	8,578 hr & 872,473 km

Type	Created	Scheduled	Due	Started	Closed
	Apr 14, 2026	Apr 14, 2026		Jun 17, 2026 7:20 AM	Jul 2, 2026 10:27 AM

Line	Task	Parts	Labor	Total
1	✓ Transmission noises	\$0.00	\$0.00	\$0.00
Notes				
Auxiliary drive gear broken, splitter shift collar sheared off				
Removed and replaced auxiliary				
2	✓ Steering wheel out to the left	\$0.00	\$0.00	\$0.00
3	✓ ABS codes	\$0.00	\$0.00	\$0.00
4	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
5	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
6	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
7	✓ rh mirror replace	\$0.00	\$0.00	\$0.00
8	✓ Air discharge line p clips broken	\$0.00	\$0.00	\$0.00
9	✓ Loose steering shaft	\$0.00	\$0.00	\$0.00
10	✓ Rh step bent as well as bracket	\$0.00	\$0.00	\$0.00
11	✓ DEF codes	\$0.00	\$0.00	\$0.00
12	✓ Ac compressor toast	\$0.00	\$0.00	\$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Ac compressor	Kropp Shop		1.0	\$0.00	\$0.00

875 - 2019 Kenworth t800

Parent: T42 - 2016 Gerrys

CLOSED

13	✓ Air leak on truck somewhere, drains to 0	\$0.00	\$0.00	\$0.00
14	✓ Clutch sticking	\$0.00	\$0.00	\$0.00
15	✓ no cruise control	\$0.00	\$0.00	\$0.00

Notes

Brake pedal sticking

16	✓ change belts	\$0.00	\$0.00	\$0.00
17	✓ lh rear drive brake falling apart	\$0.00	\$0.00	\$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Es2 shoe kit	Kropp Shop		1.0	\$0.00	\$0.00
Brake Drum	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00