

WINDREM



Work Order

Vehicle Code: 105

Work Order #: 32845
 Issued: 2025-07-17 10:54 AM
 Status: Completed
 Date: 2025-07-22
 Employee: CODY
 Name: FRY
 Page #: 1

Year: 2017
 Make: WESTERN STAR
 Model: 4900
 License No: BL 94788
 VIN #: 5KJJALD16HPJC3759
 Meter: 1: 1345954 2: 0
 Meter Type: Kilom Hours
 Transmission: DD16
 Engine: Detroit DD16
 Engine Serial #:

Alt. Vehicle ID:
 WO Type:
 Est. Downtime:
 Hour Estimate:
 Reference No:
 Requested By:
 Reason:
 Delay Code:

Work Order Notes:

Code for crankcase breather oil seperator speed low

DATE COMPLETED

RELEASED BY - (SIGNATURE REQUIRED)

Replaced crankcase breather

Services Performed

Service Code	Description	Technician	Actual Hours	Hours	Cost
5024AF	ENGINE - AIR FILT	CODY		0.50	\$0.00
	COMMENT				
Total Service				0.50	\$0.00

Parts Used

Part Number	Part Description	Service Code	Quantity	Cost (each)	Total
DDE.EA4720108262	BREATHER ASSEMBLY		1.00	\$559.28	\$559.28
DDE.A4720180780	CRANKCASE GASKET		1.00	\$10.88	\$10.88
Total Parts					\$570.16
Total Parts and Service					\$570.16

WINDREM

Vehicle Code: 105



Work Order

Year: 2017
 Make: WESTERN STAR
 Model: 4900
 License No: BL 94788
 VIN #: 5KJJALD16HPJC3759
 Meter: 1: 1155488 2: 0
 Meter Type: Kilom Hours
 Transmission:
 Engine: Detroit DD16
 Engine Serial #:

Alt. Vehicle ID:
 WO Type: ANNUAL INSPECTION
 Est. Downtime:
 Hour Estimate:
 Reference No:
 Requested By:
 Reason:
 Delay Code:

Work Order #: 32962
 Issued: 2025-07-21 8:31 AM
 Status: Completed
 Date: 2025-07-23
 Employee: SHAWN
 Name: MAITLAND
 Page #: 1

Work Order Notes:

- Removed all wheels to check brakes
- Replaced all brakes and rotors
- Replaced wheel beagin
- Replaced all spring pin bushings and spring wear shoes
- Replaced all pads
- Replaced both steer axel wheel sensors
- Replaced all wheel seals

DATE COMPLETED

RELEASED BY - (SIGNATURE REQUIRED)

Services Performed

Service Code	Description	Technician	Actual Hours	Hours	Cost
0021	ANNUAL INSPECTION SAFETY	SHAWN		30.00	\$0.00
	COMMENT				
Total Service				30.00	\$0.00

Parts Used

Part Number	Part Description	Service Code	Quantity	Cost (each)	Total
TMSET406	BEARING SET	7007	2.00	\$32.32	\$64.64
TMSET413	BEARING SET	7007	2.00	\$49.87	\$99.73
CR47691XT	SEAL,WHEEL	7007	6.00	\$59.99	\$359.94
ZCP3303024	Gasket-H	7007	1.00	\$3.14	\$3.14
16-16456-000	SPRING SHIM	6009	4.00	\$17.49	\$69.96
16-16456-001	SPRING SHIM	6009	4.00	\$17.49	\$69.96
16-22080-000	BUSHING, SPRING, RR	6009	2.00	\$96.45	\$192.90
16-22080-000	BUSHING, SPRING, RR	6009	2.00	\$101.96	\$203.92
76620G	BRAKE ROTOR,FREIGHTLINER	2500	6.00	\$399.99	\$2,399.94
SAFXA351ALP	PLATE S,5TH WHEEL	6027	1.00	\$1,899.99	\$1,899.99
WAB4410309172	SENSOR, ABS	6027	1.00	\$79.06	\$79.06
CR35066	SEAL,WHEEL	2511	2.00	\$43.99	\$87.98
BW1369ZNRS	BRAKE PADS	2511	3.00	\$179.99	\$539.97
Total Parts					\$6,071.14
Total Parts and Service					\$6,071.14

WINDREM

Vehicle Code: 105

Year: 2017
 Make: WESTERN STAR
 Model: 4900
 License No: BL 94788
 VIN #: 5KJJALD16HPJC3759
 Meter: 1: 951 2: 0
 Meter Type: Kilom Hours
 Transmission: Detroit DD16
 Engine:
 Engine Serial #:

Alt. Vehicle ID:
 WO Type:
 Est. Downtime:
 Hour Estimate:
 Reference No:
 Requested By:
 Reason:
 Delay Code:



Work Order

Work Order #: 33303
 Issued: 2025-09-30 8:35 AM
 Status: Completed
 Date: 2025-10-06
 Employee: CODY
 Name: FRY
 Page #: 1

Work Order Notes:
Needs trans and PTO

Removed and replace trans
Get lash on new PTO
replaced exhaust flex pipe

DATE COMPLETED

RELEASED BY - (SIGNATURE REQUIRED)

Services Performed

Service Code	Description	Technician	Actual Hours	Hours	Cost
	DRIVE TRAIN - TRANS MISC	CODY		10.00	\$0.00
	COMMENT				
	CHASSIS - PTO PUMP	CODY		8.00	\$0.00
	COMMENT				
Total Service				18.00	\$0.00

Parts Used

Number	Part Description	Service Code	Quantity	Cost (each)	Total
	PIPE, 5" FLEX	5020	4.00	\$22.95	\$91.80
0PLS	CLAMP, EXHAUST, 5"SS	5023	2.00	\$18.99	\$37.98
0PLS	CLAMP, EXHAUST, 5"SS	5023	1.00	\$18.99	\$18.99
0PLS	CLAMP, EXHAUST, 5"SS	5023	1.00	\$19.99	\$19.99
019959702	Clamp Kit	5023	1.00	\$59.03	\$59.03
9-001	CROSS SHAFT CLUTCH	5023	1.00	\$82.67	\$82.67
-001	CLUTCH RELEASE SHAFT	5023	1.00	\$54.42	\$54.42
8	SENSOR, SPEED, TRANS	2000	1.00	\$79.99	\$79.99
	FILTER	2000	1.00	\$7.28	\$7.28
ELDING	WELDING SUPPLIES	0022	1.00	\$20.00	\$20.00
001M	ROD BARE M8-1.25X1M	0022	1.00	\$6.93	\$6.93
8918BP	TRANSMISSION	0022	1.00	\$4,395.00	\$4,395.00
4.3401	INSULATOR	0022	4.00	\$7.28	\$29.12
4.3402	UPPER ENGINE MOUNT	0022	2.00	\$13.77	\$27.54
	SAE 50, FULL SYNTH, TRANS	2000	1.00	\$239.99	\$239.99
Total Parts					\$5,170.73
Total Parts and Service					\$5,170.73

WINDREM



Work Order

Vehicle Code: 105

Year: 2017
 Make: WESTERN STAR
 Model: 4900
 License No: BL 94788
 VIN #: 5KJJALD16HPJC3759
 Meter: 1: 56307 2: 0
 Meter Type: Kilom Hours
 Transmission:
 Engine: Detroit DD16
 Engine Serial #:

Alt. Vehicle ID:
 WO Type:
 Est. Downtime:
 Hour Estimate:
 Reference No:
 Requested By:
 Reason:
 Delay Code:

Work Order #: 33650
 Issued: 2026-02-09 8:07 AM
 Status: Completed
 Date: 2026-02-09
 Employee: ROB
 Name: POST
 Page #: 1

Work Order Notes:
 No start

DATE COMPLETED

RELEASED BY - (SIGNATURE REQUIRED)

Replaced 4 batteries

Services Performed

Service Code	Description	Technician	Actual Hours	Hours	Cost
4006	ELEC - BATTERY REPLACE	ROB		2.00	\$130.00
	COMMENT				
Total Service				2.00	\$130.00

Parts Used

Part Number	Part Description	Service Code	Quantity	Cost (each)	Total
FLTBTGA31SS	BATTERY, SCREW TOP, GRP31S		2.00	\$139.99	\$279.98
FLTBTGA31SS	BATTERY, SCREW TOP, GRP31S		2.00	\$139.99	\$279.98
Total Parts					\$559.96
Total Parts and Service					\$689.96

WINDREM

Work Order

Vehicle Code: 105

Work Order #: 33579
 Issued: 2026-01-06 8:41 AM
 Status: Completed
 Date: 2026-01-06
 Employee:
 Name:
 Page #: 1

Vendor: METRO
 Name: METRO TRUCK GROU
 Address:
 City/State: Ayr ON

Year: 2017 Alt. Vehicle ID:
 Make: WESTERN STAR WO Type:
 Model: 4900 Est. Downtime:
 License No: BL 94788 Hour Estimate:
 VIN #: 5KJJALD16HPJC3759 Reference No:
 Meter: 1: 56307 2: 0 Requested By:
 Meter Type: Kilom Hours Reason:
 Transmission: Delay Code:
 Engine: Detroit DD16
 Engine Serial #:

Work Order Notes:

Truck shut off on the highway due to loss of power, possibly an electrical issue
 Towed unit inside, hooked up to laptop to check for faults, was not able to connect
 to any power train ECU's found 5 amp fuse blown for the ignition circuit. Replaced
 fuse and unit did not have any codes. Started unit and unit started up but would not
 shut off with the key. Would take anywhere from 2-15 minutes for the unit to shut itself off .
 Programmed a test CPC and unit still had the same issue. Unit would not shut off. Disconnected
 CPC and removed ignition relay and 5 amp fuse for power trains ECU;s and unit kept running.
 Started to look at working, Moved multiple harnesses and notice when the ACM harness was
 moved the truck shut off without th key even in the ignition. Moved the harness again and could
 hear modules waking up. Opened up ACM harness and found the wires have internally rubbed
 through inside the loom. Found 3 broken wires and one rubbed through wire. Repaired all wires
 and truck now starts and shuts off with no coeds. Quoted out ACM harness for repair an called the
 customer. Customer asked to not do the ACM harness at the time and just leave the temp repair
 on the wiring. Wrapped up harness with abrasion tape and loom. Took unit on a road test and
 unit frove fine. Unit did not throw any codes

DATE COMPLETED

RELEASED BY - (SIGNATURE REQUIRED)

Parts Used

Part Number	Part Description	Service Code	Quantity	Cost (each)	Total
OUTSIDE SERVICE	ROADSIDE SERVICE CALL REPAIR		1.00	\$644.76	\$644.76
Total Parts					\$644.76
Total Parts and Service					\$644.76