

**WINDREM**



**Vehicle Code: 105**

Year: 2017  
 Make: WESTERN STAR  
 Model: 4900  
 License No: BL 94788  
 VIN #: 5KJJALD16HPJC3759  
 Meter: 1: 1334892 2: 0  
 Meter Type: Kilom Hours  
 Transmission:  
 Engine: Detroit DD16  
 Engine Serial #:

Alt. Vehicle ID:  
 WO Type:  
 Est. Downtime:  
 Hour Estimate:  
 Reference No:  
 Requested By:  
 Reason:  
 Delay Code:

Work Order #: 32689  
 Issued: 2025-06-03 8:28 AM  
 Status: Completed  
 Date: 2025-06-03  
 Employee:  
 Name:  
 Page #: 1

Vendor: INLAND  
 Name: INLAND TRUCK AND T  
 Address: PO BOX 671  
 City/State: NIAGRA FALLS ON

**Work Order Notes:**

Labour  
 Check reported "brake leaking"  
 Found 3rd axel left side brake chamber faulty  
 Replace faulty chamber and plumb  
 Re check leaks and operation - All ok

DATE COMPLETED \_\_\_\_\_ RELEASED BY - (SIGNATURE REQUIRED) \_\_\_\_\_

**Parts Used**

Part Number	Part Description	Service Code	Quantity	Cost (each)	Total
OUTSIDE SERVICE	INLAND TRUCK AND TRAILER REPAIR		1.00	\$379.25	\$379.25
<b>Total Parts</b>					\$379.25
<b>Total Parts and Service</b>					\$379.25

WINDREM

Vehicle Code: 105

Year: 2017  
 Make: WESTERN STAR  
 Model: 4900  
 License No: BL 94788  
 VIN #: 5KJJALD16HPJC3759  
 Meter: 1: 1248419 2: 0  
 Meter Type: Kilom Hours  
 Transmission: Detroit DD16  
 Engine: Detroit DD16  
 Engine Serial #:

Alt. Vehicle ID:  
 WO Type:  
 Est. Downtime:  
 Hour Estimate:  
 Reference No:  
 Requested By:  
 Reason:  
 Delay Code:



### Work Order

Work Order #: 31530  
 Issued: 2024-10-28 9:51 AM  
 Status: Completed  
 Date: 2024-10-30  
 Employee: CODY  
 Name: FRY  
 Page #: 1

DATE COMPLETED

RELEASED BY - (SIGNATURE REQUIRED)

Work Order Notes:  
DRIVE SHAFTS

REPAIR:  
 REPLACED YOKE AT TRANS  
 REPLACED YOKE AT HANGER AND REPLACED HANGER BEARING  
 REPLACED YOKE AT 1RST DIFF AND SEAL  
 REPLACED ALL U JOINTS BETWEEN TRANS AND 1RST DIFF

### Services Performed

Service Code	Description	Technician	Actual Hours	Hours	Cost
007	DRIVE TRAIN - DRIVELINE	CODY		2.00	\$100.00
	COMMENT				
006	DRIVE TRAIN - U JOINT	CODY		2.00	\$100.00
	COMMENT				
008	DRIVE TRAIN - YOKE	CODY		6.00	\$300.00
	COMMENT				
<b>Total Service</b>				<b>10.00</b>	<b>\$500.00</b>

### Parts Used

Part Number	Part Description	Service Code	Quantity	Cost (each)	Total
03326	HANGER BEARING	2007	1.00	\$149.99	\$149.99
25RPLS1	U JOINT	2006	1.00	\$249.99	\$249.99
A.CP25RPLS1	U JOINT KIT	2006	1.00	\$225.42	\$225.42
A.CP25RPLS1	U JOINT KIT	2006	1.00	\$225.42	\$225.42
A.KIT2826	NUT & WASHER	2007	1.00	\$39.78	\$39.78
A.A1.1205X2728	SEAL	2007	1.00	\$82.99	\$82.99
0115C1	NUT	2007	1.00	\$38.26	\$38.26
VYS45	YOKE, END	2008	1.00	\$698.77	\$698.77
VYSC3811	END YOKE	2006	1.00	\$487.44	\$487.44
VYS3813A	END YOKE	2008	1.00	\$423.88	\$423.88
22	HEX NUT	0120	1.00	\$30.99	\$30.99


Total Parts

\$2,652.93

Total Parts and Service

\$3,152.93

**WINDREM**



**Vehicle Code: 105**

Year: 2017  
 Make: WESTERN STAR  
 Model: 4900  
 License No: BL 94788  
 VIN #: 5KJJALD16HPJC3759  
 Meter: 1: 1248419 2: 0  
 Meter Type: Kilom Hours  
 Transmission:  
 Engine: Detroit DD16  
 Engine Serial #:

Alt. Vehicle ID:  
 WO Type:  
 Est. Downtime:  
 Hour Estimate:  
 Reference No:  
 Requested By:  
 Reason:  
 Delay Code:

Work Order #: 31530  
 Issued: 2024-10-28 9:51 AM  
 Status: Completed  
 Date: 2024-10-30  
 Employee: CODY FRY  
 Name: CODY FRY  
 Page #: 1

Work Order Notes: DRIVE SHAFTS  
 DATE COMPLETED \_\_\_\_\_ RELEASED BY - (SIGNATURE REQUIRED) \_\_\_\_\_

REPAIR:  
 REPLACED YOKE AT TRANS  
 REPLACED YOKE AT HANGER AND REPLACED HANGER BEARING  
 REPLACED YOKE AT 1RST DIFF AND SEAL  
 REPLACED ALL U JOINTS BETWEEN TRANS AND 1RST DIFF

**Services Performed**

Service Code	Description	Technician	Actual Hours	Hours	Cost
2007	DRIVE TRAIN - DRIVELINE	CODY		2.00	\$100.00
	COMMENT				
2006	DRIVE TRAIN - U JOINT	CODY		2.00	\$100.00
	COMMENT				
2008	DRIVE TRAIN - YOKE	CODY		6.00	\$300.00
	COMMENT				
<b>Total Service</b>				<b>10.00</b>	<b>\$500.00</b>

**Parts Used**

Part Number	Part Description	Service Code	Quantity	Cost (each)	Total
5003326	HANGER BEARING	2007	1.00	\$149.99	\$149.99
CP25RPLS1	U JOINT	2006	1.00	\$249.99	\$249.99
TDA.CP25RPLS1	U JOINT KIT	2006	1.00	\$225.42	\$225.42
TDA.CP25RPLS1	U JOINT KIT	2006	1.00	\$225.42	\$225.42
TDA.KIT2826	NUT & WASHER	2007	1.00	\$39.78	\$39.78
TDA.A1.1205X2728	SEAL	2007	1.00	\$82.99	\$82.99
2500115C1	NUT	2007	1.00	\$38.26	\$38.26
25WYS45	YOKE, END	2008	1.00	\$698.77	\$698.77
25WYSC3811	END YOKE	2006	1.00	\$487.44	\$487.44
25WYS3813A	END YOKE	2008	1.00	\$423.88	\$423.88
K4122	HEX NUT	0120	1.00	\$30.99	\$30.99
<b>Total Parts</b>					<b>\$2,652.93</b>
<b>Total Parts and Service</b>					<b>\$3,152.93</b>

WINDREM



Work Order

Vehicle Code: 105

Work Order #: 33345  
Issued: 2025-10-23 9:24 AM

WINDREM



Work Order

Vehicle Code: 105

Work Order #: 31369  
Issued: 2024-10-01 3:46 PM  
Status: Completed  
Date: 2024-10-01  
Employee:  
Name:  
Page #: 1

Year: 2017  
Make: WESTERN STAR  
Model: 4900  
License No: BL 94788  
VIN #: 5KJJALD16HPJC3759  
Meter: 1: 767168 2: 0 Hours  
Meter Type: Kilom  
Transmission:  
Engine: Detroit DD16  
Engine Serial #:

Alt. Vehicle ID:  
WO Type:  
Est. Downtime:  
Hour Estimate:  
Reference No:  
Requested By:  
Reason:  
Delay Code:

Vendor: INLAND  
Name: INLAND TRUCK AND T  
Address: PO BOX 671  
City/State: NIAGRA FALLS ON

DATE COMPLETED

RELEASED BY - (SIGNATURE REQUIRED)

Work Order Notes:

REPAIR:  
SERVICE CALL TO VINELAND SCALES H 600.00  
CHECK REPORTED "SPEEDO SENSOR BROKEN"  
DIAGNOSE SPEEDO SENSOR BROKEN  
CHISEL OUT BROKEN SENSOR  
CLEAN OUT RUST JACKING IN SENSOR BORE  
AND SEAT  
INSTALL NEW SENSOR  
RUN AND TEST  
HOOK UP TO COMPUTER AND READ CODES  
CLEAR CODES - ALL OK

Services Performed		Technician	Actual Hours	Hours	Cost
Service Code 2012	Description DRIVE TRAIN - WHEEL SENSR			1.00	\$0.00
	COMMENT				
Total Service				1.00	\$0.00

Parts Used		Service Code	Quantity	Cost (each)	Total
Part Number OUTSIDE SERVICE	Part Description ROADSIDE SERVICE	2012	1.00	\$852.48	\$852.48
Total Parts					\$852.48
Total Parts and Service					\$852.48

# WINDREM



# Work Order

**Vehicle Code: 105**

Year: 2017  
 Make: WESTERN STAR  
 Model: 4900  
 License No: BL 94788  
 VIN #: 5KJJALD16HPJC3759  
 Meter: 1: 1378159 2: 0  
 Meter Type: Kilom Hours  
 Transmission:  
 Engine: Detroit DD16  
 Engine Serial #:

Alt. Vehicle ID:  
 WO Type:  
 Est. Downtime:  
 Hour Estimate:  
 Reference No:  
 Requested By:  
 Reason:  
 Delay Code:

Work Order #: 33345  
 Issued: 2025-10-23 9:24 AM  
 Status: Completed  
 Date: 2025-10-23  
 Employee: HAYDN  
 Name: MARKLAND  
 Page #: 1

**Work Order Notes:**

Replaced CPC under dash - core returned

DATE COMPLETED

RELEASED BY - (SIGNATURE REQUIRED)

### Services Performed

Service Code	Description	Technician	Actual Hours	Hours	Cost
0100	MISC REPAIRS	HAYDN		0.50	\$0.00
COMMENT					
<b>Total Service</b>				<b>0.50</b>	<b>\$0.00</b>

### Parts Used

Part Number	Part Description	Service Code	Quantity	Cost (each)	Total
dde.ra0064463402	REMAN ECU		1.00	\$2,006.14	\$2,006.14
<b>Total Parts</b>					<b>\$2,006.14</b>
<b>Total Parts and Service</b>					<b>\$2,006.14</b>