

ADAPT-A-LIFT GROUP PTY LTD

Service History Listing Active Units

Date: 19/06/2026

Time: 11:06:53AM

For Equipment Code From: H12510 To: H12510

For Customer Code From: All To: All

For Date Posted From: All To: All

For Branch Code From: All To: All

Don't Show Cost

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H12510		Description: HYSTER H2.5TX					
Make: HYSTER		Model: H2.5TX		Serial No.: D466R01916N			
1823107	advertise online - used	DDEJESUS	5/05/2026	Internal	4785.0	\$0.00	Carry out Inspection and Diagnosis of Electrical System Remove ancillary items and Repair Wiring as necessary, Refit ancillary items, Carry out equipment condition assessment digging machine troubleshooting machine dosent start taking photo advertise online repair wiring and forktrack
48913	Pre Hire Inspection	201WORKSHOP	11/11/2025	Inspection	4999.0	\$0.00	
1740014	READY - Scheduled Service - KM IC 500hr SM - 6500hrs .0500 Hour Service	MLALLY	16/09/2025	Internal	4738.0	\$0.00	Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. traveel to site remove and replace engine oil filter and replace engine oil grease unit lube chain check coolant check trans oil check chians blow out brakes test drive blow out air filter and radiator Travel to and from job site. Replace unit worn out seat and repair wiring to seat. Remove and replace both inner and outer lift chains
1705144	FW from 1694330 - lift chains require replacing. Requires new seat belt.	201SUBC-DUBB002	26/03/2025	Internal	4572.0	\$0.00	Travel to and from job site. Carry out unit 2000hr service. Replace unit engine oil and filter. Replace hydraulic oil and filter. Replace unit air filter and spark plugs. Grease and lube unit. Test all functions lights and alarms. Adjust fan belt. Adjust brakes. Replace trans oil and filter. Replace diff
1705141	FW from 1694330 - Replace Steer Tyres 6.00-9 Solid with Split Wheel	SUBC-RNT20102	26/03/2025	Internal	4545.0	\$0.00	oil. Inspect unit and steering. Blow down unit and radiator. Found unit lift chains require replacing. Requires new seat belt. Requires new steer Tyres.
1694330	Scheduled Service - KM IC 2000hr SM - 6000hrs .2000 Hour Service	201SUBC-DUBB002	25/03/2025	Internal	4455.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H12510		Description: HYSTER H2.5TX					
Make: HYSTER		Model: H2.5TX		Serial No.: D466R01916N			
1648756	Scheduled Service - KM IC 500hr SM - 5500hrs .0500 Hour Service	201SUBC-DUBB002	6/09/2024	Internal	4205.0	\$0.00	Carry out unit B service 500hr. Replace engine oil and filter. Test all functions lights and alarms. Adjust fan belt and brakes. Blow down unit. Grease and lube mast. Jack and inspect unit steering. Grease steering. Perform service checks. Top up coolant level. Top up hyd oil leve
1645378	Seat belt not working properly. Cannot extend the seat belt enough to put it on. Etkt 828340	201SUBC-DUBB002	2/08/2024	Internal	126993.0	\$0.00	Travel to and from job site. Locate unit and found seat belt faulty. Remove and replace seat belt. Rewire seat belt buck wiring and test. Grease and lube unit. Blow down.
1627764	3G Sunset - Replace FM1 Kit for VAM kit. Etkt 763680	201SUBC-DUBB002	28/05/2024	Internal	4114.0	\$0.00	Travel to and from job site. Sign in and locate unit. Carry out VAM upgrade. Could not swap data so had to contact Geoff from AALG to complete each upgrade
1580794	Scheduled Service - KM IC 1000hr SM - 5000hrs .1000 Hour Service	201SUBC-DUBB002	22/03/2024	Internal	4062.0	\$0.00	Travel to and from job site. Carry out unit 1000hr service. Grease and lube unit. Test all functions lights and alarms. Replace engine oil and filter. Replace air filter. Replace spark plugs. Blow down unit and radiator. Unit has one spark plug faulty thread. Jack and inspect steering. Grease steering. Adjust fan belt and adjust brakes. Check all fluid levels. Tension wheel nuts.
1535192	Scheduled Service - KM IC 500hr SM - 4500hrs .0500 Hour Service	201SUBC-DUBB002	11/06/2023	Internal	3590.0	\$0.00	Travel to and from site. Carry out 500 Hr service. Test all functions, lights and alarms. Grease unit and lube mast. Replace air filter. Replace engine oil and filter. Inspect steering, adjust brakes. Tension fan belt. Blow down unit.
1517927	Faulty seatbelt	201SUBC-DUBB002	2/03/2023	Internal	3407.0	\$0.00	
1452634	Scheduled Service - KM 4000hr SM - 4000hrs .4000 Hour Service	MMcNAIR	13/12/2022	Internal	3407.0	\$0.00	Travel to and from site. Sign in and locate unit. Carry out unit 4000Hr service. Replace engine oil and Filter. Replace blocked air filter. Replace spark plugs Replace trans oil and filter. Replace diff oil. Replace Fan belt. Replace brake fluid and coolant. Adjust brakes and grease unit. Check steering. Test all functions lights and alarms.

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H12510		Description: HYSTER H2.5TX					
Make: HYSTER		Model: H2.5TX		Serial No.: D466R01916N			
1391162	Scheduled Service - NT 500 hrs service .0500 Hour Service	MMcNAIR	30/07/2021	Internal	2878.0	\$0.00	Travel to and from job site. Sign in and locate unit. Carry out unit 500hr service. Replace engine oil and Filter. Grease unit. Jack and inspect steering. Lube Maste. Test all functions lights and alarms. Adjust Belts. Adjust brakes. Blow down unit and radiator. Return unit to work.
1352319	Unit has gone flat. Battery possibly needs to be replaced. Requesting ETA	MMcNAIR	18/01/2021	Internal	2611.0	\$0.00	Travel to site and sign in Locate unit and inspect no start Inspect battery and test found battery dropped cell. Remove battery and left site Pick up new battery and return to site Install battery and start unit Test alternator charge All good - return unit
1344462	Scheduled Service - 0500HR .0500 Hour Service	MMcNAIR	9/12/2020	Internal	2570.0	\$0.00	Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. Travel to site and locate unit carry out 500 hr service grease and lube machine and mast test all functions lights and alarms replace engine oil and filter replace air filter wash machine adjust brakes and grease and check steering
1314471	Supply and Replace Seat	MMcNAIR	17/07/2020	External	2366.0	\$565.95	Replace Seat, Locate unit and position inwork area Remove old seat as was broken mounting and suspension bracket Install new seat repair wiring and fit new deutz plug test unit and return unit to customer
1310285	Scheduled Service - 1000HR .1000 Hour Service	MMcNAIR	30/06/2020	Internal	2343.0	\$0.00	1000hr Service Locate unit and carry out machine 1000hr service grease and lube maste jack steering and inspect pins bushes and bearings grease steering and all machine grease points Drain and replace engine oil and filter test all light alarms and maschine functions adjust fan belt replace air filter and check all fluid levels check plugs and return machine to customer Unit seat front bracket that mounts to hood broken and cracked
1255359	Scheduled Service - 0500hr 0500hr. 0500 Hour Service	MMcNAIR	14/11/2019	Internal	2109.0	\$0.00	Travel to site, Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. travel to and crom site locate mavhine carry out machine service grease and lube test all functions lights and alarms blow out radiator and engine bay adjust brakes test

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H12510		Description: HYSTER H2.5TX					
Make: HYSTER		Model: H2.5TX		Serial No.: D466R01916N			
1208195	Scheduled Service - 2000 Hour (Service HD1.5-3.5TX). 2000 Hour Service	MMcNAIR	17/05/2019	Internal	1829.0	\$0.00	Scheduled Service - 2000hr Service carry out machine 2000hr service eng trans and dii fluid and filter changes grease and lube test all functions adjust brakes and lift chains blow out radiator check fluid levels lights and guages Scheduled Service -
1162569	Scheduled Service - 0500 Hour (Service HD1.5-3.5TX). 0500 Hour Service	MMcNAIR	11/11/2018	Internal	1544.0	\$0.00	Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. travel to site locate unitcarry out machine service grease and lube test all functions
1111416	service Level B Service	202SUBC	15/05/2018	Internal	1147.0	\$0.00	Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.
1055207	service	SPHILLIPS	16/10/2017	Internal	809.0	\$0.00	
1038192	repair/replace seat	SPLUMMER	9/08/2017	Internal	677.0	\$0.00	Travel to site, Replace Seat, Travel to site, sign in, locate unit and move to service area. Inspect seat assembly and found suspension has collasped due to centre rod coming adrift. Replaced seat assembly and wire in seat belt switch wiring. Function tested unit.
1006506	service	SPLUMMER	4/04/2017	Internal	462.0	\$0.00	Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. Perform PM service as er instruction, clean, lube and full function tested.
1005911	OIL LEAK ROBERT - 0428 798 226	SPLUMMER	31/03/2017	Internal	462.0	\$0.00	OIL LEAK ROBERT - 0428 798 226 Travel to site, Refit Hydraulic Hose/s and ancillary items, Travel to site from Bathurst. Check and found sideshift cylinder hose fitting loose. Tigthened fitting, check oil level and wash down. Function tested.

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H12510		Description: HYSTER H2.5TX					
Make: HYSTER		Model: H2.5TX		Serial No.: D466R01916N			
983954	ERROR CODE 100	Griffsub1	9/01/2017	Internal	367.0	\$0.00	<p>Travel to site,</p> <p>Carry out Inspection and Diagnosis of Attachment</p> <p>travel to site inspect unit and diagnose call for info on unit to pin point fault contact manager as unable to access unit software no software and cables . travel to bathurst</p> <p>Remove ancillary items and Traction card from unit. Repair Traction card as necessary and Refit to unit, Refit ancillary items,</p> <p>Travel to site. Retrieve error code using scan tool supplied. Call technical support to get code meaning. Erase all codes and function tested. Travel back to bathurst.</p>
960771	SERVICE	JDAVIES	10/10/2016	Internal	237.0	\$0.00	<p>Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.</p> <p>Travel to site,</p>
934182	fork track not working	SPLUMMER	6/07/2016	Internal	157.0	\$0.00	<p>250hr Service Repair Fleet Management System as required,</p> <p>Travel 2 hrs to site, diagnose and repair FM1 system on 3 units as per instruction by Rod McCormack from Speedsheild. Function tested and travel back to Bathurst</p>
898106	Return Credit Required	201WORKSHOP	26/02/2016	Internal	5.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
---------	-------------	----------	------	----------	----------	--------	-------

Owner: ADAP001

Equip. Code: H12510

Description: HYSTER H2.5TX

Make: HYSTER

Model: H2.5TX

Serial No.: D466R01916N

858302	Prep for Rental - Lienert Aust	CGITTOES	29/09/2015	Cap Prep	5.0	\$0.00	<p>Please note that line two for three new units is for your Forbes site in NSW</p> <p>Rate per week (per unit) excludes replacement tyres for the duration hire</p> <p>Pre Delivery Inspection - 0 - 5.5 Ton</p> <p>Fork Track</p> <p>Delivery to site</p> <p>Frame and shackle for bin tipper chain</p> <p>Supply and fit relay to speed limit</p> <p>H2.5TX - LPG Forklift (EL Engine)</p> <p>Nominal Capacity-2500 kg</p> <p>Basic Light With LH Shift Lever - RH Light Switch</p> <p>LED Rear Combination Lights</p> <p>LED Strobe Light</p> <p>Hyd. Control Valve - 3 Fun - Lever With Interlock</p> <p>Forks - CL2 STD 40x122x1070</p> <p>Load Backrest - CL2 1020x1070</p> <p>Drive Tire: 7.00-12 - Solid With Split Wheel</p> <p>6.00-9 - Solid With Split Wheel</p> <p>Sequential Seat Belt Interlock</p> <p>Cyclone Type Pre-Cleaner</p> <p>Mast - 3 Stg FFL 2205 / 4800 (BOF) *</p> <p>Lexan Top Covers For Rain Protection</p> <p>Monotrol - Foot Directional Control</p> <p>ISS Carriage Including HTU - E Mast</p> <p>Rear Drive Handle with Horn Button</p> <p>Return to vertical tilt</p> <p>EFI Engine Upgrade</p> <p>Prepare equipment for hire to requested specification</p> <p>Fit Fleet Management System as required,</p> <p>Check/Inspect/Diagnose Fleet Management System and test operation,</p>
--------	--------------------------------	----------	------------	----------	-----	--------	---

Equipment Total:	\$565.95
Customer Total:	\$565.95