

# ADAPT-A-LIFT GROUP PTY LTD

## Service History Listing Active Units

Date: 19/06/2026

Time: 11:10:20AM

For Equipment Code From: H12748 To: H12748

For Customer Code From: All To: All

For Date Posted From: All To: All

For Branch Code From: All To: All

Don't Show Cost

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H12748		<b>Description:</b> HYSTER H2.5XT LPG Forklift + 360 rotator**SEE NOTES**					
<b>Make:</b> HYSTER		<b>Model:</b> H2.5XT		<b>Serial No.:</b> D466R02769P			
1771324	NOT COMPLETED - Scheduled Service - BB IC 1000HR SM .1000 Hour Service	NMORAN	28/01/2026	Internal	7071.0	\$0.00	Labour Carry out equipment condition assessment travel to parts, collect parts to return to 7h travel to parts in 7h, fill out return forms, inform mitch, was told to plac on return shelf. took photos and sent to coordinator. Carry out equipment condition assessment
1779615	DEHIRE - Replace damaged seat belt. Clean, repair hood & side cover, prepare & touch up paint. Replace broken vent cover, tyne pins & left rear light with cover.	901QUOTE SENT02	20/01/2026	External	7910.0	\$375.00	seat belt damaged,tyres worn,paint worn and scratches 3hrs,vent cover broken,tyne pins damaged,hood damaged,left cover under hood damaged,rear left light broken and cover damaged,cleaning 4 hrs, Carry out equipment condition assessment
1779526	Condition Report	MJHORMOZ	20/01/2026	Internal	7909.0	\$0.00	checking machine,photo,quote for parts. Labour Travel to site, Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. travel to parts to collect service kit travel to site loacte unit find safe space to work carry out 500hr scheduled maintenance as per tick sheet travel to PK to dispose of rubbish travel to site
1739486	Scheduled Service - KM IC 500hr SM - 8500hrs .0500 Hour Service	NMORAN	9/09/2025	Internal	7071.0	\$0.00	
1730718	Hydraulic hose behind the rotator has snapped off - Ptk 1158856	SUBC-RTL20101	7/07/2025	Internal	6021.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H12748		<b>Description:</b> HYSTER H2.5XT LPG Forklift + 360 rotator**SEE NOTES**					
<b>Make:</b> HYSTER		<b>Model:</b> H2.5XT		<b>Serial No.:</b> D466R02769P			
1715927	fit rotator for Cleanaway	ODEMERIN	8/05/2025	Internal	6021.0	\$0.00	<p>Carry out equipment condition assessment</p> <p>Fit Attachment and ancillary items,</p> <p>Repair Attachment as necessary,</p> <p>Refit Hydraulic Hose/s and ancillary items,</p> <p>Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items,</p> <p>Grease All Points on Unit,</p> <p>Removed load guard and tynes. Removed attachment from H12752 and fit to this machine. Repaired attachment and tynes lock. Weld lock for attachment mounting to secure movement both side of carriage. Removed hyd. hoses attachment from H12752 and transfer to this machine. Cleaned the attachment. Grease the grease point. Request new load rating plate for this machine.</p> <p>Note: waiting new load plate.</p> <p>Steam clean equipment as necessary.</p> <p>Remove ancillary items, prepare and Paint unit as required,</p> <p>Install Hard Labels,</p> <p>Cleaned the machine and touch up paint. Installed new load rating plate. Test all function and prep for hire.</p>

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H12748		<b>Description:</b> HYSTER H2.5XT LPG Forklift + 360 rotator**SEE NOTES**					
<b>Make:</b> HYSTER		<b>Model:</b> H2.5XT		<b>Serial No.:</b> D466R02769P			
1712843	Green tag inspection	SMALONISIO	24/04/2025	Internal	6019.0	\$0.00	Carry out equipment condition assessment Carry out Inspection and Diagnosis of Electrical System Repair Light Circuit as required, Repair Wet Weather Gear as necessary, Steam clean equipment as necessary. Repair Traction Battery Prepare For Hire - Workshop

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H12748		<b>Description:</b> HYSTER H2.5XT LPG Forklift + 360 rotator**SEE NOTES**					
<b>Make:</b> HYSTER		<b>Model:</b> H2.5XT		<b>Serial No.:</b> D466R02769P			
1700200	Scheduled Service Job. Hyster D466_4000Hr SvKit_LPG_Nis_H2.0-3.5XT. 4000 Hour Service	ODEMERIN	13/03/2025	Internal	6015.0	\$0.00	Change Engine Oil as required,  Replace Engine Oil Filter,  Replace Ignition Spark Plugs as required,  Replace Transmission Oil as Required  Replace Transmission Filter,  Grease All Points on Unit,  Drain and refill differential oil,  Bleed Brake System  Remove ancillary items and Hydraulic Filter and Replace, Refit Hydraulic Filter and ancillary items,  Replace Hydraulic Oil as Required  Note; Waiting for gas plate.  Flush and Replace Cooling System Coolant  Replace Fan Belt,  Remove and Replace Air filter,  Install Hard Labels,  Replaced engine oil, oil filter, spark plug, air filter,tansmission oil and transmission oil filter. Replaced hyd. oil, suction filter, return filter, diff. oil, coolant, fan belt, and brake fluid. Installed gas plate (missed). Repaired seat switch wiring. Grease the grease point and lubricate the chain. Cleaned the machine and test all function.

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H12748		<b>Description:</b> HYSTER H2.5XT LPG Forklift + 360 rotator**SEE NOTES**					
<b>Make:</b> HYSTER		<b>Model:</b> H2.5XT		<b>Serial No.:</b> D466R02769P			
1700198	green tag	ODEMERIN	6/03/2025	Internal	6013.0	\$0.00	<p>Carry out equipment condition assessment</p> <p>Steam clean equipment as necessary.</p> <p>Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items,</p> <p>Replace Lift Chain,</p> <p>Adjust Lift Chain to correct specification,</p> <p>Carry out machine condition assessment.</p> <p>Installed handle (missing.</p> <p>Replaced free lift chain both side and adjust the chain and hoses tension over the mast.</p> <p>Cleaned the machine.</p> <p>Carry out equipment condition assessment</p>
1700022	Dehire Inspection - Check for damages	SMALONISIO	5/03/2025	Internal	6014.0	\$0.00	<p>Carry out Inspection and Diagnosis of Electrical System</p> <p>Install Light/s</p> <p>100Hr Service</p>
1694650	Green tag inspection	RLE	13/02/2025	Internal	6001.0	\$0.00	<p>Grease the whole unit.Installed the blue light.Check lights and operations.</p> <p>Check/Inspect/Diagnose Hydraulic Oil Leak and test operation,</p> <p>Carried out diagnosis on oil leak and found oil coming from the gearbox, suspect its the rear main seal. This unit is a temporary stand in. Spoke to Naomi to get this unit swapped out ASAP.</p>
1692760	leaking oil, tech to assess. etkt # 1011575	DPhangnalay	7/02/2025	Internal	5966.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H12748		<b>Description:</b> HYSTER H2.5XT LPG Forklift + 360 rotator**SEE NOTES**					
<b>Make:</b> HYSTER		<b>Model:</b> H2.5XT		<b>Serial No.:</b> D466R02769P			
1686514	Prep for STR	EURFANO	15/01/2025	Internal	5963.0	\$0.00	<p>Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items,</p> <p>Refit Load Guard and ancillary items,</p> <p>Refit Forks/Tynes and ancillary items,</p> <p>Remove ancillary items and Remove Drive Wheel from unit,</p> <p>installed load guard took to used machine  installed tynes took to used machine  font and rear tyres swap to used machine  snap screw suplied screw to cylinder bracket</p> <p>Refit Wheel/s and ancillary items,</p> <p>Remove Fleet Management System as required,</p> <p>Prepare For Sale - Workshop</p> <p>removed and changed front and rear tyre  cleaned machine  Removed forktrack and harnesses  installed missing strobe light  Note: some parts are took to the used machine = Load guard, front and rear tyres, strobe light,  Prep for hire</p>

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H12748		<b>Description:</b> HYSTER H2.5XT LPG Forklift + 360 rotator**SEE NOTES**					
<b>Make:</b> HYSTER		<b>Model:</b> H2.5XT		<b>Serial No.:</b> D466R02769P			
1685840	Scheduled Service Job. KM IC 1000hr SM - 7000hrs/7yrs. 1000 Hour Service	EURFANO	15/01/2025	Internal	5963.0	\$0.00	Carry out equipment condition assessment  Prepare For Hire - Workshop  Grease All Points on Unit,  Replace Ignition Spark Plugs as required,  Change Engine Oil as required,  1000hr Service  Removed and replaced spark plug replaced transmission oil replaced transmission oil filter replaced air filter oil changed replaced oil filter lubricated all lifting chain greased all greasing point Checked all control and function checked all lights and horn cleaned machine  prep for hire
1685841	Scheduled Service Job. Hyster D466_0500Hr SvKit_LPG_Nis_H2.0-3.5XT. 0500 Hour Service		13/01/2025	Internal	5960.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H12748		<b>Description:</b> HYSTER H2.5XT LPG Forklift + 360 rotator**SEE NOTES**					
<b>Make:</b> HYSTER		<b>Model:</b> H2.5XT		<b>Serial No.:</b> D466R02769P			
1671142	Prep for STR - M3 Logistics	EURFANO	7/11/2024	Internal	5960.0	\$0.00	<p>Carry out equipment condition assessment</p> <p>Remove Fleet Management System as required,</p> <p>Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items,</p> <p>Remove ancillary items and Load Guard, inspect and report,</p> <p>Remove ancillary items and Forks/Tynes, Inspect and report,</p> <p>Remove ancillary items and Attachment, Strip, Inspect and report,</p> <p>Carried out 50 points checked  removed load guard  removed attachment  remove tyres  checked all control and function  removed hydraulic hose ans seal hoses  report all missing parts  report damaged parts  report not working parts  checked all fluids and oil  prep for sale machine  Steam clean equipment as necessary.</p>
1668657	Asses unit condition	NMAISTRY	29/10/2024	Internal	5959.0	\$0.00	<p>Repair Light Circuit as required,</p> <p>unit required additional cleaning, grease and oil all on the top of the drivers cab. unit was blocked in wash bay. speed limit was set to 10km/ph.</p> <p>Carry out Inspection and Diagnosis of Attachment</p> <p>unit is covered in webs, has some random stickers and is generally dirty. needs to be cleaned. there are scuffs and scratches on the body of the unit. touch up paint is recommended. wiring for lights is untidy. tires require regrooving, left hand front tire has a crack in the side wall. Adaptalift sticker phoe number is out of date, needs eplacing. entire unit needs lubrication. attachment is rusted with minor damage, attachment requires cleaning and lubrication before testing full range of function. engine requires cleaning. beacon light was damaged and removed, needs to be replaced.</p>

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H12748		<b>Description:</b> HYSTER H2.5XT LPG Forklift + 360 rotator**SEE NOTES**					
<b>Make:</b> HYSTER		<b>Model:</b> H2.5XT		<b>Serial No.:</b> D466R02769P			
1603920	STR Dehire Inspection	201WORKSHOP	27/02/2024	Internal	5882.0	\$0.00	
1584756	Replace broken off Strobe light	ALLOCATE	5/12/2023	External	5882.0	\$0.00	
1555498	Scheduled Service - KM IC 500hr SM - 6500hrs .0500 Hour Service	AGUTIERREZ	1/12/2023	Internal	5882.0	\$0.00	Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. Service 500hr, Carry out preventive maintainance service and safety inspection in the line with agreed scope of work. Report on condition of equipment and additional work requirements. Lubricate all grease point mast and chain. Replace Engine oil , washer and filter. Test all function. ok Found broken off Strobe lighth Please Qoute.
1523249	Gas problem	CZARIS	24/03/2023	Internal	5678.0	\$0.00	Repair LPG Converter as necessary, Unit has no power , check unit and found gas converter full off wax , strip gas converter , clean and fit converter, test unit
1483408	Scheduled Service - KM IC 2000hr SM - 6000hrs .2000 Hour Service	CZARIS	24/03/2023	Internal	5678.0	\$0.00	Travel to site,  2000hr Service
1511895	Quote to replace Tynes,	901QUOTE SENT01	6/02/2023	Internal	5513.0	\$0.00	travel to site carry out 2000 service
1460429	Replace Tynes, Mirror, Strobe Light - 1070	901QUOTE SENT01	6/07/2022	Internal	5513.0	\$0.00	No response from Customer to damage quote, to be reviewed again at end of hire

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H12748		<b>Description:</b> HYSTER H2.5XT LPG Forklift + 360 rotator**SEE NOTES**					
<b>Make:</b> HYSTER		<b>Model:</b> H2.5XT		<b>Serial No.:</b> D466R02769P			
1431218	KIT ORDERED AL - Scheduled Service - 1000Hr Service .1000 Hour Service	ALI	21/06/2022	Internal	5513.0	\$0.00	<p>Travel to site, to site. wait for finding unit(20mins). wrong address. then to 16 kangroo av. talk to cusstomer . says busy because this is only one &amp; the other one with slip is oil leaking( being tagged out).ring stacey.wait for job.</p> <p>Carry out equipment condition assessment to site. talk to Paul. says no access because h15204 is still not working. check, no grab on slip. ring Stacey.</p> <p>Labour</p> <p>wait for job s to tablet. to base. drops off waste.</p> <p>1000hr Service</p> <p>Repair Attachment as necessary,</p> <p>to site. locate unit. unsafe: need replace 2 over stretched freelif chains(BL634 *10 ft, 4 links); need replace 2 worn out tynes(1070mm). broken off 2 mirrors. broken off a rotating strobe. worn out 2 steering tyres. Pls quote a.s.a.p. H3367N is having astuck twiin pallet handler, lubricate handler as requested, test ok. complaint:none.cause:SM.correction:report.</p>
1441859	The unit won't turn on. Tagged Out.	DPhangnalay	30/03/2022	Internal	5425.0	\$0.00	<p>Travel to site,</p> <p>Carry out Inspection and Diagnosis of Electrical System</p> <p>Carried out diagnosis on no start. Unit started first go. Adjusted fuel ratio and return to service.</p> <p>Repair Attachment as necessary,</p>
1440972	Slip sheet not operational. SF EMAIL via Stas	DPhangnalay	29/03/2022	Internal	5747.0	\$0.00	<p>Carried out inspection on unit. Customer complained that the sheet is sagging under load. Sheet is sagging because fork tynes havent been fitted underneath the sheet. Carried Carried out repair and fitted fork tynes.</p>
1432002	Attach slip sheet	DPhangnalay	15/02/2022	External	5419.0	\$522.07	<p>Travel to site,</p> <p>Fit Attachment and ancillary items,</p> <p>Labour</p> <p>Waited for attachment to arrive to site. Carried fitting as required. Unit need fitings to connect to hydraulic system. Travelled to pirtek. Site closed need to return tomorrow morning. `</p> <p>Continued fitting attachment. Test check function ok.</p>

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H12748		<b>Description:</b> HYSTER H2.5XT LPG Forklift + 360 rotator**SEE NOTES**					
<b>Make:</b> HYSTER		<b>Model:</b> H2.5XT		<b>Serial No.:</b> D466R02769P			
1431169	Hydraulic hose on mast has snapped - spraying oil. Unit non operational	201SUBC	10/02/2022	Internal	4367.0	\$0.00	ATTEND URGENT CALL OUT. FOUND SIDE SHIFT HOSE HAD BLOWN OFF FITTING AND HUGDE OIL SPILL LEAKING EVERYWHERE. USE ABSORB MATERIAL AND PADS AROUND MACHINE TO SOAK UP OIL SPILL. REMOVE UNIT AND REPLACE THE LIFT HOSE ASSEMBLY, CLEAN DOWN MACHINE AND TOP UP HYDRAULIC OIL AND TEST. TESTED GOOD AND WASHED AND DEGREASED THE MACHINE AS REQUESTED.
1396890	Replace Seat Belt	901QUOTE SENT01	19/08/2021	External	4367.0	\$0.00	
1394179	Seat belt does not click in, Mirror has broken - Tech to assess as Rosemary was not aware	DPhangnalay	5/08/2021	Internal	4367.0	\$0.00	Travel to site,  Repair Hydraulic Hose/s as necessary,  Carry out equipment condition assessment  Hose came off sheave on unit H12749, carried out repair. Unit H1101 has the broken seat belt. Customer damage see photos for refs.
1393342	Speed Limit To 8km	ALLOCATE	3/08/2021	External	4353.0	\$0.00	Please quote customer for a new seat belt buckle.
1376105	Scheduled Service - 500hr SM - 4500hrs .0500 Hour Service	ALI	29/06/2021	Internal	4353.0	\$0.00	Labour  Travel to site,  pick uup in DP for jobs. to site. locate unit.  Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.  Repair Revolving/Flashing/Strobe light as required,  Replace Lift Chain,  locate unit. repair strobe light. no show on forktrack screen. need replacing worn out 40*120*1070 tynes. missing a step on hand grip. need replacing stretched BL634 free lift chains(rp3402*1, rp3405*4). damaged a load guard mounting bolt. see photos. fill sheet. complaint::none.cause:SM.correction:report.

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H12748		<b>Description:</b> HYSTER H2.5XT LPG Forklift + 360 rotator**SEE NOTES**					
<b>Make:</b> HYSTER		<b>Model:</b> H2.5XT		<b>Serial No.:</b> D466R02769P			
1369527	Brakes are not working. Tagged out. Requesting ETA	GSINGH	15/04/2021	Internal	4180.0	\$0.00	<p>Travel to site,</p> <p>Carry out equipment condition assessment</p> <p>Carry out Inspection and Diagnosis of Brake System</p> <p>travel to site, create safe work area, access truck, concern - brakes, cause - remove hubs and inspect brakes,shoes low and need replacment, order parts, inform customer,</p> <p>Labour</p> <p>Remove wheel/s, Remove Brake drum/s,</p> <p>Replace brake shoe/s,</p> <p>Replace Brake Wheel Cylinders,</p> <p>travel to site, found stock piled around truck, request customer to create safe work space,access truck to safe work area, remove both side hubs and brakes, replace with new brake shoes a d wheel cylindres, assy hubs, bleed and adjust, operate and check ok.</p>
1368367	Unit not starting.	GSINGH	7/04/2021	Internal	4171.0	\$0.00	<p>Carry out Inspection and Diagnosis of Electrical System</p> <p>access truck, concern - wont start, cause - check and diagnose battery, order new,</p> <p>Labour</p> <p>Travel to site,</p> <p>Replace Battery,</p> <p>Adjust Transmission Control Valve to correct specification ,</p> <p>Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items,</p> <p>pickup parts, travel to site, access truck, remove and replace battery, adjust inching, blow clean unit, operate and check ok,</p>
1364512	FW 1363786 - Replace Tynes - CL2 1070x120x40	901QUOTE SENT01	16/03/2021	External	4085.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H12748		<b>Description:</b> HYSTER H2.5XT LPG Forklift + 360 rotator**SEE NOTES**					
<b>Make:</b> HYSTER		<b>Model:</b> H2.5XT		<b>Serial No.:</b> D466R02769P			
1363786	Unit is leaking gas from the gas bottle connection. Urgent. Requesting ETA	GBANKS	12/03/2021	Internal	4085.0	\$0.00	Travel to site, Remove ancillary items and Repair Gas Leak as necessary, Refit ancillary items, Replace Forks/Tynes, TRAVEL TO SITE,FOUND UNIT.DIAGNOSIS UNIT WITH A GAS LEAK AND NOT STARTING.REPAIR GAS COULPER AND FIT.UNIT STARTING OK.CHECK UNIT FOUND TYNES WORN OUT.STAND UNIT DOWN TAKE PHOTOS.GB12/3/21.
1361723	horn not working, hub cap missing - no cust damage	DPhangnalay	3/03/2021	Internal	4033.0	\$0.00	Replace Horn  Labour  Reseal Hub/s as necessary,  Carried out inspection on horn, Test check power no power. Found blown fuse. Replace fuse but horn still did not work. Replaced horn and test ok. Found hub cap missing. Picked up part from workshop. Fitted hub cap as rerquied.
1345647	Unit is leaking oil and struggling to run. Tagged out at door 15. Requesting ETA	DPhangnalay	9/12/2020	Internal	3788.0	\$0.00	Travel to site,  Carry out Inspection and Diagnosis of Electrical System  Check/Inspect/Diagnose Cylinder  Labour  Replace Battery,  Carried out inspection on unit. Found unit not starting up at all. Checked fuses ok, Checked battery voltage 2volts. Jump started unit and checked alternator ok. Carried out inspection on hydraulic leak. No leaks found  Complaint - Unit leaking oil and struggling to run Cause - No leaks found, Unit wouldnt start up cause flat battery, Unit did run abit sluggish. Correction - Replaced battery and turn up fuel on carburettor so unit caould idle. Idle srcew was turn all the way in causing rough idle.

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H12748		<b>Description:</b> HYSTER H2.5XT LPG Forklift + 360 rotator**SEE NOTES**					
<b>Make:</b> HYSTER		<b>Model:</b> H2.5XT		<b>Serial No.:</b> D466R02769P			
1343881	Steering Orbital Leaking	TRAZ	1/12/2020	Internal	3788.0	\$0.00	<p>Repair Steering Box as necessary,</p> <p>Steering orbitrol oil leaking. Repair hydraulic oil leak.</p> <p>Overhaul Steering as required,</p> <p>Refit Steering Box and ancillary items,</p> <p>Refit Hydraulic Hose/s and ancillary items,</p> <p>Refit Dashboard and ancillary items,</p> <p>Remove ancillary items and Repair Wiring as necessary, Refit ancillary items, 4000hr Service,</p>
1343187	Scheduled Service Job. Hyster B466_4000 Hour Service Kit_ Diesel. 4000 Hour Service	APATRIMONIO	30/11/2020	Internal	3564.0	\$0.00	<p>Performed machine 4000hrs servicing. Carry out equipment condition assessment</p>
1343183	Fleet Inpsection/ Prep for hire	TRAZ	27/11/2020	Internal	3653.0	\$0.00	<p>Steam clean equipment as necessary.</p> <p>Remove ancillary items and Remove Drive Wheel from unit,</p> <p>Remove ancillary items and Hydraulic Hose/s, inspect and report,</p> <p>Refit Hydraulic Hose/s and ancillary items,</p> <p>Replace Seat,</p> <p>Remove ancillary items and Wheel/s, Inspect and report,</p> <p>Refit Wheel/s and ancillary items,</p> <p>Remove ancillary items and Dashboard, inspect and report,</p> <p>Overhaul Steering as required,</p> <p>Remove ancillary items and Steering Pump, Strip, Inspect and report,</p> <p>Refit Steering Pump and ancillary items,</p> <p>Repair King Pins,</p>

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H12748		<b>Description:</b> HYSTER H2.5XT LPG Forklift + 360 rotator**SEE NOTES**					
<b>Make:</b> HYSTER		<b>Model:</b> H2.5XT		<b>Serial No.:</b> D466R02769P			
1321098	Inspection	MLUMAY	18/08/2020	Internal	3652.0	\$0.00	Replace Battery, Repair Light/s Replace Revolving/Flashing/Strobe light, Prepare For Hire - Workshop Grease All Points on Unit,

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H12748		<b>Description:</b> HYSTER H2.5XT LPG Forklift + 360 rotator**SEE NOTES**					
<b>Make:</b> HYSTER		<b>Model:</b> H2.5XT		<b>Serial No.:</b> D466R02769P			
1266989	Carry out inspection report and quote for str	JMASSARA	3/01/2020	Internal	3578.0	\$0.00	<p>Prepare For Hire - Workshop</p> <p>Steam clean equipment as necessary.</p> <p>Grease All Points on Unit,</p> <p>CARRIED OUT PRE-HIRE INSPECTION, STEAM CLEANED ENTIRE UNIT &amp; CLEANED,GREASED ENTIRE UNIT,GREASED MAST &amp; CHAINS</p> <p>Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items,</p> <p>Replace Revolving/Flashing/Strobe light,</p> <p>Replaced over head gaurd drain tube &amp; plug, replaced rotating light</p> <p>Replace Tie Rod End/s,</p> <p>Regroove tyres as necessary.</p> <p>Replace Mast Wear Strips,</p> <p>Replace Ignition Switch as required,</p> <p>Repair Revolving/Flashing/Strobe light as required,</p> <p>Remove ancillary items, prepare and Paint unit as required,</p> <p>Replace Load Guard,</p> <p>Replaced rotating light re-routed wiring &amp; secured,re-grooved rear tyres,replaced steer pins &amp; bushes,removed attachment &amp; replaced upper &amp; lower wear strips &amp; lubed attachment, replaced ignition switch,cleaned &amp; masked tynes &amp; painted,located load gaurd &amp; fitted,cleaned &amp; masked lower section of unit &amp; painted</p>
1259908	DEHIRE & TYRE INSPECTIO	BIG TRUCK VIC	2/12/2019	External	3578.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H12748		<b>Description:</b> HYSTER H2.5XT LPG Forklift + 360 rotator**SEE NOTES**					
<b>Make:</b> HYSTER		<b>Model:</b> H2.5XT		<b>Serial No.:</b> D466R02769P			
1236095	Scheduled Service - 0500 Hour (Service HD1.5-3.5TX). 0500 Hour Service	311 Planning F	12/09/2019	Internal	3349.0	\$0.00	Travel to site,  Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.  Performed PMS 500,retigthening the hydraulic hose of sidershift.
1220851	Not Starting	BIG TRUCK VIC	2/07/2019	Internal	3113.0	\$0.00	
1217158	TECHNICIAN INITIATED JOB	RWALKER	18/06/2019	Internal	3082.0	\$0.00	
1190550	Scheduled Service - 1000 Hour (Service HD1.5-3.5TX). 1000 Hour Service	311 Planning F	12/06/2019	Internal	2852.0	\$0.00	Scheduled Service -
1186360	Replace Tyres Full Set - Fair Wear	BIG TRUCK VIC	19/02/2019	Internal	2818.0	\$0.00	Replace Tyres Full Set - Fair Wear
1161844	Oil Leak	JKOLARITSCH	15/11/2018	Internal	2562.0	\$0.00	Remove ancillary items and Repair Hydraulic Oil Leak as necessary. Refit ancillary items,  Inspect oil leak found loose quick release coupling tighten and clean oil mess test return unit to service Scheduled Service -
1146375	Scheduled Service - 0500 Hour (Service HD1.5-3.5TX). 0500 Hour Service	311 Planning F	12/10/2018	Internal	2389.0	\$0.00	15/10/2018 - Dave from APS picked up Hydraulic Leak on attachment
1124145	Hydraulic Leak on attachment	RMIFSUD	27/06/2018	Internal	2227.0	\$0.00	Check/Inspect/Diagnose Hydraulic Oil Leak and test operation,  oil leak attachment sreel pipe snapped , spoke to paul from northwest will be headingg there in the morning
1104387	Quote to replace Tines	AFOX	19/04/2018	External	2206.0	\$419.19	Labour Quote to replace Tines  Repair Attachment as necessary,  Fit new tynes.

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H12748		<b>Description:</b> HYSTER H2.5XT LPG Forklift + 360 rotator**SEE NOTES**					
<b>Make:</b> HYSTER		<b>Model:</b> H2.5XT		<b>Serial No.:</b> D466R02769P			
1100681	Scheduled Service- 2000hr service II 2000hr type LPG Level D Service	311 Planning B	9/04/2018	Internal	2066.0	\$0.00	Scheduled Service- 2000hr service II 2000hr type LPG  Labour  Travel to site,  Wait at trug while service kit is being picked travel to site customer asked to swap over spare tynes for unit h12751  2000hr Service  Carry out service unit needs tines replaced rear tyres low orded new grab handle replace when recived intermittent issues with seatbelt
1100530	intermittent issues with seatbelt	JKOLARITSCH	6/04/2018	Internal	2060.0	\$0.00	Remove ancillary items and Repair Wiring as necessary, Refit ancillary items,  Replace left hand head light globe inspect unit for seat belt sequence error inspect loom and found pin in seat switch plug not seated repair and test return unit to service Travel to site,
1076825	Not Operational - Error Code C28 - Peter 0417 545 850	BIG TRUCK VIC	9/01/2018	Internal	1800.0	\$0.00	Travel to site,  Carry out Inspection and Diagnosis of Electrical System  Remove ancillary items and Repair Wiring as necessary, Refit ancillary items,  locate unit unit.check seat/ seat belt interlock wires/ok. check fuel supply/no gas at carby. gas solenoid not opening/ no power at solenoid, chase wire and find break,repair wire.test unit all ok

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H12748		<b>Description:</b> HYSTER H2.5XT LPG Forklift + 360 rotator**SEE NOTES**					
<b>Make:</b> HYSTER		<b>Model:</b> H2.5XT		<b>Serial No.:</b> D466R02769P			
1061092	Scheduled Service - 1500hr service II 500hr type	BNORTON	19/12/2017	Internal	1750.0	\$0.00	Scheduled Service - 1500hr service II 500hr type  22/11/2017 - Drop pointed to Ryan Walker  24/11/2017 - Will looking for service, advised sent to Ryan Walker on 22/11/2017  27/12//2017 - Another set of parts drop pointed to Frank L, due to service losing previous parts  Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.  Labour
1030684	Forktrack issues	DWILSON	11/07/2017	Internal	1094.0	\$0.00	
1026841	Scheduled Service - 1000hr LPG	311 Planning C	6/07/2017	Internal	1094.0	\$0.00	Scheduled Service - 1000hr LPG  1000hr Service  Carry out service Telemetry stopped reporting 18/02/2017  - diagnose and report on telemetry not reporting  Remove ancillary items and Repair Wiring as necessary, Refit ancillary items,  Carry out test with speedsheild order new seat belt buckle fit when recived  Travel to site,  Repair Fleet Management System as required,  fit new seat belt and canbus adapter disconnect bypass return unit to service
1026828	Telemetry stopped reporting 18/02/2017	311 Planning C	6/07/2017	Internal	1219.0	\$0.00	Remove ancillary items and Repair Wiring as necessary, Refit ancillary items,  Carry out test with speedsheild order new seat belt buckle fit when recived  Travel to site,  Repair Fleet Management System as required,  fit new seat belt and canbus adapter disconnect bypass return unit to service
1026394	Hour meter not working - Peter S	DHOLT	26/06/2017	Internal	1041.0	\$0.00	Remove ancillary items and Repair Wiring as necessary, Refit ancillary items,  Inspect hour meter, check wiring and function, all working. Broken exhaust  Repair Exhaust pipe as required,  removed broken muffler. took it to trug workshop and repaired. drove back to site and fitted muffler
1013624	Broken exhaust	NMOORE	5/05/2017	Internal	801.0	\$0.00	removed broken muffler. took it to trug workshop and repaired. drove back to site and fitted muffler

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H12748		<b>Description:</b> HYSTER H2.5XT LPG Forklift + 360 rotator**SEE NOTES**					
<b>Make:</b> HYSTER		<b>Model:</b> H2.5XT		<b>Serial No.:</b> D466R02769P			
997332	WK11 Scheduled 500hr Service -	DWILSON	28/02/2017	Internal	623.0	\$0.00	WK11 Scheduled 500hr Service -  Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.
995155	Scheduled Service -	ACHENOWETH	20/02/2017	Internal	575.0	\$0.00	service unit, grease & lube unit & mast, clean out radiator. Scheduled Service -  Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.
986939	Won't start Peter 0417 545 850	DHOANG	18/01/2017	Internal	466.0	\$0.00	Carry out 500 hr service. Replace 1 headlamp globe. Won't start Peter 0417 545 850  Carry out Inspection and Diagnosis of Telemetry System  inspect unit diagnose no start no crank and monitor not lighting at forktrek tested power fuses all ok tested wiring loom ok diagnose module faulty remove send to speed shield for repair.  Repair Fleet Management System as required,  refitted repair module refitted bypass plug found still not working suspect assories curcuit faulty waiting on scott braker .  helped david refit the forktrack module still not working. needs to e further inspected. Unit is not operating.
983426	Unit is not operating.	AMCLAREN	5/01/2017	Internal	408.0	\$0.00	Adjust LPG Convertor to correct specification,  test for not starting reconnect hose to carby and secure with clamp test all okay replace headlight globe Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items,  Replace Load Guard,  - Remove and replace load guard . - - Fit fire extinguisher .  Fit rating plates
960126	Rating Plates, Cut Down Load Guards & fit Fire Extinguisher	301WORKSHOP	7/10/2016	Cap Prep	83.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H12748		<b>Description:</b> HYSTER H2.5XT LPG Forklift + 360 rotator**SEE NOTES**					
<b>Make:</b> HYSTER		<b>Model:</b> H2.5XT		<b>Serial No.:</b> D466R02769P			
911682	Prep for Rental - Qube Altona	PBURCH	18/08/2016	Cap Prep	1.0	\$0.00	Labour Hours: 10.00  Pre Delivery Inspection - 0 - 5.5 Ton  Rating Plate for Non Factory Ordered Attachments (Rating plate and plumb to suit owned attachments)  Drive in racking mods delivery to engineer Forktrack Hyster 3 Year Warranty - Standard XT  Fit Fleet Management System as required,  Carry out New Equipment Predelivery to correct specification.  Started a PD check over .  Prepare equipment for hire to requested specification  Check/Inspect/Diagnose Frame, Body or Chassis and test operation,
						<b>Equipment Total:</b>	<u><b>\$1,316.26</b></u>
						<b>Customer Total:</b>	<u><b>\$1,316.26</b></u>