## **ADAPT-A-LIFT GROUP PTY LTD**

## **Service History Listing Active Units**

For Equipment Code From: H18034 To: H18034

For Date Posted From: All To: All

Don't Show Cost

For Customer Code From: All To: All For Branch Code From: All To: All

Date: 13/06/2025 Time: 9:47:06AM

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: A	ADAP001						
Equip.	Code: H18034 Descripti	on: CUSHMAN 800E					
Make	: CUSHMAN	Model: 800E		Serial No.: 3	574679		
1675400	Transport to Ritchie Bros Auction	601WORKSHOP	22/11/2024	Cap Prep	1.0	\$0.00	
1589411	Scheduled Service - KM BE 1000hr SM - 1000hrs/1Yr .1000 Hour Service ( Cushman)	621SUBC	21/01/2024	Internal	1.0	\$0.00	
1583134	The unit requires a first aid kit-ETKT-598769 via John Smit	621WORKSHOP	28/11/2023	Internal	1.0	\$0.00	
1552151	Solid Filling in Tyes - ETCK 463563	SUBC-RTL60101	27/07/2023	Internal	2.0	\$0.00	
1543825	Scheduled Service - KM BE 500hr SM - 500hrs .0500 Hour Service	GSUMMERS	26/07/2023	Internal	2.0	\$0.00	Travel to site,
							Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.
							Travel to site, sign in locate truck
							perform 500hr service
							fit adaptalift stickers
1546070	Remove tilt tray release handle. Etkt 460290	RBERGIN	30/06/2023	Internal	3.0	\$0.00	Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items,
							Modify tray handles to suit
1537190	Carry out seat switch modification	RBERGIN	25/05/2023	Internal	3.0	\$0.00	Repair Seat Switch Wiring,
							Repair Switch/es
							Remove seat cushion and fit seat pad switch refit and wire into system
							Reposition tow go switch
1534540	fit flag	RBERGIN	12/05/2023	Internal	10.0	\$0.00	Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items,
							Fit brackets and flags to entire fleet of Cushmans at Albermarle.
							Travel to site,
							loxate trucks and fit flags drive roubd site to where trucks are and assist ross

Database: Adaptalift

Job No.	Description		Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: A	DAP001							
Equip. 0	Code: H18034	Description	on: CUSHMAN 800E					
Make	: CUSHMAN		Model: 800E		Serial No.: 3	574679		
1532681 Fi	Fix Wiring		RBERGIN	5/05/2023	Internal	3.0	\$0.00	Repair Seat Switch Wiring,
								Repair Fleet Management System as required,
								Travel to site,
								Unit driving wihtout the set belt fastened. Check wiring and components. Adjust parameters. Travel back to base. Job completed
								Concern : unit driving without the seat belt fastened Cause : factory parameters were set to off correction : Adjust parameters
								Job completed
								Carry out Inspection and Diagnosis of Electrical System
								Labour
								Carry out Inspection and Diagnosis of Telemetry System
								Attempt to modify seat switch wiring through forktrak unable to do so will require new seat pad switches.
1532455	Quote to supply and i custom brackets	nstal flags and	ALLOCATE	5/05/2023	External	1.0	\$620.28	
1516240			SUBC-RNT60101	23/02/2023	External	1.0	\$2,176.51	

Report ID : 493 (reports) Database: Adaptalift Page 2 of 3

Job No. Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001	a ariation. OHOUMAN COOF					
	scription: CUSHMAN 800E					
Make: CUSHMAN	Model: 800E		Serial No.: 35	74679		
1387217 Prep for Rental – Albermarle	SWIJESINGH	2/12/2022	Cap Prep	1.0	\$0.00	- Check over (should already be PD'd) - Forktrack and impact camera - Front and rear blue spot lights - speed limit 20km/h and swipe card activated - LED work lights front and rear - seat belt fitted according to AS 2664 - Windscree wiper front - reverse beeper - orange flashing beacon -lockable battery isolator - wheel nut indicators - sign/ vehicle ID fleet stickers - Albermarle numbers - Reflect striping - 1kg fire ext, - Safety triangle - Sideview mirrors - canopy storage net - glove box door - grab handle kit - tie down Dloops x 4 - radio clip - seat cover - mesh cargo net tray cover - mirrors sit outside doors  Fit Fleet Management System as required,
						Remove ancillary items and Repair Wiring as necessary Refit ancillary items,
						Fit Full Camera Kit,
						Installed fork track and impact camara kit and card reader. Installed switch seat belt and charge the battery ,clean and test drove and check speed .(10km/hr)
			Equipment	Total:	\$2,796.79	

Report ID : 493 (reports) Database: Adaptalift Page 3 of 3