

## Field Inspection Report

**Client:**  
**Force in Motion Fluid Power Inc.**  
 960C Alsgard St. Kelowna, BC V1X 7J2

**File Number:** CAM-776  
**Date:** October 10, 2025  
**PO:**  
**Location:** Force in Motion Kelowna

**Attention:** Bob Betts




<b>Make:</b> Palfinger		<b>Model:</b> PK7501		<b>Serial No:</b> 0922235		<b>Unit No:</b>	
<b>Year:</b>	<b>Hour Meter:</b>		<b>Load Chart</b> Yes <input checked="" type="checkbox"/>		<b>Logbook/Manual</b> Yes		
<b>Capacity:</b>		<b>Decal Issued:</b> October 10, 2025		<b>Equipment Owner:</b>			
<b>Type of Equipment Inspected:</b> Articulating Crane				<b>Mechanical:</b> <input checked="" type="checkbox"/> Force in Motion-Bob			
				<b>Stability Test:</b> <input checked="" type="checkbox"/> Greuter Eng. GE-3187-			

**Applicable Specification:**  
 ASME B30.22-2005 “Articulating Boom Cranes”  
 Occupational Health and Safety Regulations

**Type of Inspection Performed:** Visual Inspections  Magnetic Particle Inspections

Component:	Accept	Reject	Comments
1. Outriggers (2x)	<b>X</b>		
2. Mainframe	<b>X</b>		
3. Turret	<b>X</b>		
4. Main Boom Section	<b>X</b>		
5. Articulating Boom Section	<b>X</b>		
6. First Hydraulic Boom Section	<b>X</b>		<b>See Repair Note Below</b>
7. Second Hydraulic Boom Section	<b>X</b>		
8. Third Hydraulic Boom Section	<b>X</b>		
9. Hydraulic Boom Tip Section	<b>X</b>		
10. Swivel Load Hook	<b>X</b>		



	
<p align="center"><b>Equipment at Time of Inspection</b></p>	<p align="center"><b>Identification Tag</b></p>
<p><b>Repair:</b> Repair was performed by Force in Motion personnel. Missing wear pad was replaced with original equipment manufacturers (OEM) or equivalent component on October 10, 2025. Inspection of repair revealed no further defects.</p>	
<p><b>Consumables Used:</b> A/C Yoke: Parker B300 s/n 32398 // Magnaflux #1 Grey 20D010</p>	
<p><b>Inspection Plan No.:</b> CNIL2</p>	
<p><b>Inspection Personnel</b>  Evan Nebone // CWB Level 2 No. 12630 // CAN/CGSB No. 19267</p>	

# GREUTER ENGINEERING LTD.

## INSPECTION | NON-DESTRUCTIVE TESTING | CERTIFICATION

### Certification Report

October 22, 2025

File: GE-3187-36

Ref: CAM-776

Force In Motion Fluid Power Inc.  
960C Alsgard Street  
Kelowna, BC V1X 7J2

Attention: Bob Betts

**Re: Certification of a Palfinger Articulating Crane**

**Model: PK7501**

**Serial: 0922235**

**Unit: N/A**

**Owner**

#### **Structural Inspection**

Visual inspection and magnetic particle testing were performed on the accessible structural components of the above-described equipment by Camber NDT Inspections personnel. Reference Camber NDT Inspections file CAM-776 dated October 10, 2025 for complete structural inspection findings.

#### **Structural Repairs**

All structural repairs were performed by Force In Motion Fluid Power personnel. This missing wear pad was replaced with original equipment manufacturers (OEM) components. Inspection of repairs revealed no further defects.

#### **Mechanical and Controls Inspection**

The mechanical and control systems were inspected by Force In Motion Fluid Power personnel. Reference inspection report dated October 10, 2025 for complete mechanical/controls inspection findings. Greuter Engineering has received the inspection documentation and judged it acceptable.


#### **Certification**

Annual inspections were performed in accordance with *ASME B30.22-2005 "Articulating Boom Cranes"* and the applicable occupational health and safety regulations. Based on the inspection findings **the equipment is judged to be safe for use**. Stability testing documentation by Greuter Engineering, reference file no. GE-3187-35.

The equipment shall be inspected, operated, and maintained in accordance with the manufacturer's instructions, applicable codes and standards, and occupational health and safety regulations. All structural repairs or modifications to the equipment must be approved in writing by Greuter Engineering prior to the work being performed. Any unauthorized repairs or modifications, or the equipment being involved in a misadventure will immediately void this certification.

**Next Inspection Due: October 10, 2026**

Greuter Engineering Ltd. (EGBC Permit No. 1002364)



Nick Greuter, P.Eng.  
CWB Visual 3 (11740)  
CGSB MT 2 | PT 2 (17490)