



CO9-1

Low Stage Work Order Inspection

Inspection Date:	09-17-2025	Unit Number:	LHS-88
Approval Status:	Requires Approval	Approved Date:	
Inspected By:	Brent Willey	Approved By:	
Signature:		Approved Signature:	

Received Checklist from Operations? No

EVALUATIONS

Building

	Good / Service Needed	Comments
Building Clean in/out		
Roof Hatch in place		
Belly Doors & Latches		
Vents		
Windows and Screens		
Main door condition including latches		
D Rings returned with unit? Put S in comments		
Change overs returned with unit		

Decals

	Good / Service Needed	Comments
Danger		
2924		
Methanol		
Manway		
Propane		
Hearing Protection		
Misc Stickers		
Unit #		
Exterior/Skid Paint		
Interior Paint		

Low Stage Work Order Inspection

	Good / Service Needed	Comments
3" Dirty Side Drain Valve (dwg 65)		
3" Dirty Side Drain Valve (dwg 65)		
3" Dirty Side Circumvent Valve (dwg 67)		
3" Clean Side Drain Valve (dwg 65)		
3" Water Bypass/Oil Box Drain/Dirty Side Blow Down (dwg 69)		
3" Water Drain Valve (dwg 610)		
3" Water Out Valve (dwg 610)		
3" Condensate Out Valve (dwg 612)		
3" Bypass Water to Condensate Valve (dwg 613)		
3" Water Leg Upstream of Y-Strainer Valve (dwg 614)		
3" Condensate Leg Upstream of Y-Strainer Valve (dwg 615)		
Condensate Leg V-Ball Valve (dwg 620)		
Condensate Leg V-Ball Valve (dwg 621)		
3" Downstream of Turbine, Condensate Leg (dwg 622)		
3" Downstream of Turbine, Water Leg (dwg 623)		
3" Condensate Bypass Valve (dwg 624)		
3" Water Bypass Valve (dwg 625)		
4" Gas Out Upstream of V-Cone Valve (dwg 626)		
2" Gas Out Upstream of V-Cone Valve		
4" Gas Valve (dwg 631)		
2" Dirty Side Spargo Valve (dwg 634)		
2" Clean Side Spargo Valve (dwg 635)		

Manways - Vessel Interior

	Good / Service Needed	Comments
Manway Dirty Side Platform		
Manway Clean Side Platform		
Visual of Spargo		
Visual of Steam Line		
Visual of Vent		

Additional Notes:

Tank has been worked. No offfield solids or liquids in vessel.