



# **Rebel NDT** Inspections Ltd.

BONNYVILLE - COLD LAKE -ST. PAUL - ATHABASCA - LAC LA BICHE

· Having Access to:

- •Non-Destructive Testing UT MPI LPI
- ·Wall Thickness Testing
- \*Hardness Testing \*Materials Consulting
- Crane and Picker Certification
- Manlift Certification Corrosion
- Monitoring
- Failure Analysis Quality Control
- ·Weld Procedures (WPS,PQR)
- · Predictive Maintenance
- · Computer Generated Drawings(CAD)

Box 7282

Bonnyville AB T9N 2H6

PHONE 780-826-9387

email: JReid@RebelNDT.com

Consigned to Edge Energy Logistics

Date 25-Sep-25

Address Box 1230

Workorder 1012703

Lac La Biche AB TOA 2C0

Location Lac La Biche AB

Purchase Order#

Customer Edge Energy Logistics R-04

## Eng Certification - Visual - Dry Magnetic Particle

Date	是於學科	Description of charge	Hours	Rate	Price
25-Sep-25		Equipment for a Eng Certification - Visual - Dry Magnetic pection of 1 TELESCOPIC BOOM TRUCK S/N 3W56353-1 for Edge Energy Logistics R-04			\$689.00
		Travel - mileage	130.00	\$1.35	\$175.50
Were you			Line Item S	ub Total	\$864.50
satisfied with	Yes		Enviro	Charge	\$15.00
our service?	■ No		Su	b Total	\$879.50
			GS	T @ 5%	\$43.98
				Total	\$923.48

Inspected By: Jeff Reid #22576 Eddy Rondeau

Received by:



# Rebel NDT Inspections Ltd.

BONNYVILLE - COLD LAKE -ST. PAUL - ATHABASCA - LAC LA BICHE

· Having Access to:

- · Non-Destructive Testing · UT MPI LPI
- ·Wall Thickness Testing
- Hardness Testing Materials Consulting
- · Crane and Picker Certification Manlift Certification • Corrosion
- Monitoring
- Failure Analysis Quality Control
- · Weld Procedures (WPS,PQR) Predictive Maintenance
- Computer Generated Drawings(CAD)

Box 7282

Bonnyville AB T9N 2H6

PHONE 780-826-9387

email: JReid@RebelNDT.com

Date 25-Sep-25

Address Box 1230

Consigned to Edge Energy Logistics

Location Lac La Biche AB

Workorder 1012703

Lac La Biche AB TOA 2CO

Purchase Order#

Customer Edge Energy Logistics R-04

#### Eng Certification - Visual - Dry Magnetic Particle

Contact Name:			Phone #:	
Item:   Telescopic Boom Truck   Location:   La		Lac La Biche AB		
			Model:	WHL45TC100
Make:		Weldco-Beales MFG.	Unit:	R-04
Serial Numbe	r:	3W56353-1	Capacity:	80000 lbs

# Field Report

### **RESULTS OF INSPECTION IN ALL ACCESSIBLE AREAS:**

Rebel NDT Inspections Ltd. performed a Visual and Dry Magnetic Particle inspection on the above mentioned Telescopic Boom Truck.

Above equipment was cleaned of dirt, oil and grease prior to inspection.

- 1. Deficiency (Must be rectified for certification) Driver side front outrigger box has two cracks noted. Material must be mild steel & NOT cyclically loaded. Cracks must be gouged 100% and re-welded by a journeyman welder using 7018-1 rod or equivalent wire feed. Remove any stress risers. Customer to visually reinspect work 24 hrs. post-repair.
- 2. Deficiency (Must be rectified for certification) -One crack were noted on passenger side front outrigger box. Material must be mild steel & NOT cyclically loaded. Cracks must be gouged 100% and re-welded by a journeyman welder using 7018-1 rod or equivalent wire feed. Remove any stress risers. Customer to visually reinspect work 24 hrs. post-repair.

Upon completion of repairs, and review and approval by our professional engineer (P.Eng.) the inspected equipment will be recommended for certification.

Calibrated Equipment Used Yokes: YC-65-10 Yokes: YC-64-10

Workorder#: 1012703 Date: 25-Sep-25 Edge Energy Logistics



# Rebel NDT Inspections Ltd.

BONNYVILLE - COLD LAKE -ST. PAUL - ATHABASCA - LAC LA BICHE

· Having Access to:

- •Non-Destructive Testing UT MPI LPI
- •Wall Thickness Testing
- · Hardness Testing · Materials Consulting
- •Crane and Picker Certification
  •Manlift Certification •Corrosion
- Monitoring Corrosic
- •Failure Analysis •Quality Control
- •Weld Procedures (WPS,PQR) •Predictive Maintenance
- •Computer Generated Drawings(CAD)

Box 7282

Bonnyville AB T9N 2H6

PHONE 780-826-9387

email: JReid@RebelNDT.com

## Required Repair Summary

If more than one repair option was noted, please specify which option was used All welding to be done to CSA W59-03

Please fill out the details of who completed the repairs, and have them initial the items they repaired along with date of the repair

CON	1PANY			NAME		TICKET N	IUMBER (i	e JOURNE	YMAN)	WC	)	
Α												
В												
С												
Item	Telescopic Boom Truck				Year Boom Dismantled:							
Make	Weldco-E	Weldco-Beales MFG.				Re-Cert Period: 1 Year						
Serial Number	3W56353-1				Inspection Location: lac la biche							
Mode	WHL45T	WHL45TC100 Year Manufactured:										
Unit	R-04	R-04 hrs / miles / km:										
Capacity	80000 lb	S			Colour:							
□ вс 🛂 ав	□ ѕк	□мв	□ ON	☐ QC	□ ив	☐ PEI	□ NS	□ NL	□ үк	□ nwt	□ NV	

#### **Comments**

Rebel NDT Inspections Ltd. performed a Visual and Dry Magnetic Particle inspection on the above mentioned Telescopic Boom Truck.

Above equipment was cleaned of dirt, oil and grease prior to inspection.

- 1. Deficiency (Must be rectified for certification) Driver side front outrigger box has two cracks noted.

  Material must be mild steel & NOT cyclically loaded. Cracks must be gouged 100% and re-welded by a journeyman welder using 7018-1 rod or equivalent wire feed. Remove any stress risers. Customer to visually reinspect work 24 hrs. post-repair.
- 2. Deficiency (Must be rectified for certification) -One crack were noted on passenger side front outrigger box.

  Material must be mild steel & NOT cyclically loaded. Cracks must be gouged 100% and re-welded by a journeyman welder using 7018-1 rod or equivalent wire feed. Remove any stress risers. Customer to visually reinspect work 24 hrs. post-repair.

Upon completion of repairs, and review and approval by our professional engineer (P.Eng.) the inspected equipment will be recommended for certification.

Outrigger		Inspection types	FIX	Repair Date	Initials	Comment #
Outrigger Boxes	/ Base Frame	Visual & MPI	х			1,2

Page 1