



BRITISH
COLUMBIA

Ministry of Transportation
and Infrastructure

Inspection Identifier: MV1058_20250730_1250

W56-9

Page 1 of 3

VEHICLE INSPECTION REPORT / NOTICE and ORDER

Vehicle(s) inspected this 30 of JUL YR 2025 at 12:50 (24hr Clock) on HIGHWAY 16 at or near Tete Jaune Cache
INSPECTION LEVEL: 1 - Driver and Vehicle (NAS) CAMPAIGN: CVSA Violation Ticket #:AJ26644048

INSPECTION RESULT: Out of Service

OUT OF SERVICE BY: MOTOR VEHICLE ACT / REGS UNTIL HIGHLIGHTED ITEMS BELOW ARE REPAIRED.

INSPECTION ITEMS NOTED BELOW TO BE REPAIRED: PRIOR TO NEXT DISPATCH

SEND PROOF OF REPAIRS TO: PO Box 490 Hwy 16 East Valemount V0E 2Z0 /FAX:250-566-4663

Power Unit: <u>Out of Service</u>		CVSA decal:
Owner:	OPEN SEA TRUCK LINES INC.	
Address:	OPEN SEA TRUCK LINES INC.	
City:	EDMONTON	Prov: AB Postal Code: T6T 1P3
Registration:	NSC #: 2530194	Jur: AB
Plate #:	0EL239	Year: 2019 Make: KENWORTH
Body Style:		VIN: 1XKYDP9X1KJ999973
GVW:	46500	Odometer: 896605 KM
CVIP decal:		CVIP Jur:
Cargo Seal #:		UN: DG Type:

Trailer #1: <u>Out of Service</u>		CVSA decal:
Registration:	Plate #: 6KJ958	Jur: AB
VIN:	1RND48A2XDR02906	Year: 2013 Make: REITNOUER
CVIP decal:	CVIP Jur:	
Cargo Seal #:	UN: 1072	DG Type: SMOC

Driver: <u>INDERPAL SINGH</u>		
D.L.# 163372675	D.O.B.:05-OCT-1987	Jur: AB

INSPECTION RESULTS				
INSPECTION ITEMS	#	PU	T1	COMMENTS
Braking System	44	O		RUBBER AIR LINE AT REAR OF CAB GOING TO TRAILER GLADHAND IS WORN THROUGH THE
	44	N		REINFORCEMENT PLY FROM CHAFFING ON ELECTRICAL PLUG COVER.
	44	O		AXLE 3, RIGHT: ABSENCE OF EFFECTIVE BRAKE ACTION UPON APPLICATION OF SERVICE
	44	N		BRAKES.
	44	O		AXLE 5, LEFT: DEFECTIVE BRAKE. MISSING CLEVIS PIN IN SLACK ADJUSTER.
	44	O		AXLE 5, RIGHT: DEFECTIVE BRAKE. VOID IN UPPER BRAKE LINING EXCEEDING 1/16".
	44	X		Axle 4, left: audible air leak upon brake application from proper connection
	44	X		of air line to service chamber at the fitting.
	44	X		Audible air leak from engine block; source indeterminable.
Brake Adjustment	45	O		AXLE 2, LEFT: EXCESSIVE PUSHROD TRAVEL.
	45	N		BRAKE COMPONENTS MUST BE MECHANICALLY INSPECTED PRIOR TO RELOADING.
Suspension	46	X		Axle 4: black air line to suspension worn to 2nd colour from chaffing on air
	46	N		line to axle 4, left, service chamber.
Miscellaneous	55	X		Fail to carry valid CVIP Report in vehicle.
	55	X		Fail to carry valid registration in vehicle.
	55	N		Vehicle plate has been replaced; digital copy displayed on Drivers mobile.
	55	X		Fail to carry valid registration & CVIP Report.
	55	C		Left & right jockey boxes closed w/ bungee cords & tie down winch.

BRAKE INFORMATION							
Unit	Axle #	Brake Type	Chamber Type	Chamber Size	Slack Type	Left	Right
PU	1	Air	Clamp	24XL	Automatic	1	1 1/8

Peace Officer (Inspector): K.ZEILINGER

Number: MV1058

Signature:

PO Box 490 Hwy 16 East Valemount V0E 2Z0

Assist:

I HEREBY ACKNOWLEDGE RECEIPT OF A COPY OF THIS INSPECTION REPORT.

DRIVER SIGNATURE:

SEE REVERSE FOR DETAILS REGARDING COMPLIANCE.

The information on this form is collected under the authority of the Motor Vehicle Act, Section 217. The information will be used to process your vehicle inspection and/or Notice and Order. If you have any questions please contact the issuing Officer or call CVSE at (250) 952-0577. Visit www.cvse.ca