

R14-19
SEP



Test and Inspection Report in Accordance with CSA B620

Facility Name:	Total Inspection Services Inc.	Work Order Number:	5362
Address:	7018 Stanley Drive PO Box 974 Dawson Creek BC V1G 4H9	Date:	MAY 9 2026
Telephone:	250-784-7966	Transport Canada Facility Registration #:	25-0847
Tank Owner:	DRIVE LOGISTICS	Tank TCRN/MDIN:	12986
Address:	PO BOX 7813 STN MAIN PEACE RIVER AB T8S 1T3	Unit #:	SB160B
Telephone:	1 780-618-8572		

Tank Serial #:	13124	Tank Spec:	TC / DOT 407
Manufacturer:	TREMCAR USA	Mfr. Date:	01/2014
Special Service:	N/A	Lined:	Yes ☐ No ☒
MAWP/Design Pressure:	172 KPA	Insulated:	Yes ☐ No ☒
Min Shell Thickness:	5.842 MM	Min Head Thickness:	7.163 MM

Gauge Calibration Checked: Yes ☒ No ☐ Gauge #: D1

Cert. Date: 01/2014 Assembler: TREMCAR USA

Capacity: ☐ Total US gals ☒ Total Litres ☐ Total Imp gals

Compartments: 1. 28370 2. 3. 4.

TEST PERFORMED ☒ V – shall signify external inspection ☒ I – shall signify internal inspection
☒ K – shall signify leakage test

EXTERNAL VISUAL INSPECTION "V"

	Complies	Reject	N/A	Complies on Retest
Data plate, present and legible	☒	☐	☐	☐
Shell & Heads, corrosion, abrasion, dents, overlay patches, leaks etc.	☒	☐	☐	☐
Structural members, outriggers, cross members, etc.	☒	☐	☐	☐
Piping and valves for leakage, damage, corrosion	☒	☐	☐	☐
Remote closures, emergency shut off decals, thermal devices	☐	☒	☐	☒
Hoses for defects, identification and test dates	☒	☐	☐	☐
Gaskets on full opening rear heads for damage or cuts	☐	☐	☒	☐



7018 Stanley Dr, PO Box 974
Dawson Creek BC V1G 4H9
Phone: 250-784-7966
E-mail: tis@pris.ca

HOSE TEST CERTIFICATE

Customer DRIVE LOGISTICS

Unit # SB160A

Invoice # WO# 5353

**THIS CERTIFICATE IS PROOF THAT ALL ASSEMBLIES LISTED BELOW HAVE BEEN TESTED
HYDROSTATICALLY**

ASSEMBLY	SERIAL #	TEST PRESSURE	WORKING PRESSURE	HOLD TIME	EXTERNAL INSPECTION
FLUID HOSE	1644	180 PSI	150 PSI	5 MIN	PASSED

STEWART SKAFTE

Tested By

Signature

MAY 8 2026

Date Tested



7018 Stanley Dr, PO Box 974
Dawson Creek BC V1G 4H9
Phone: 250-784-7966
E-mail: tis@pris.ca

HOSE TEST CERTIFICATE

Customer	<u>DRIVE LOGISTICS</u>
Unit #	<u>SB160B</u>
Invoice #	<u>WO# 5362</u>

**THIS CERTIFICATE IS PROOF THAT ALL ASSEMBLIES LISTED BELOW HAVE BEEN TESTED
HYDROSTATICALLY**

ASSEMBLY	SERIAL #	TEST PRESSURE	WORKING PRESSURE	HOLD TIME	EXTERNAL INSPECTION
FLUID HOSE	1645	180 PSI	150 PSI	5 MIN	PASSED

STEWART SKAFTE

Tested By

Signature

MAY 8 2026

Date Tested



7018 Stanley Dr, PO Box 974
Dawson Creek BC V1G 4H9
Phone: 250-784-7966
E-mail: tis@pris.ca

HOSE TEST CERTIFICATE

Customer	<u>DRIVE LOGISTICS</u>
Unit #	<u>SB160B</u>
Invoice #	<u>WO# 5362</u>

THIS CERTIFICATE IS PROOF THAT ALL ASSEMBLIES LISTED BELOW HAVE BEEN TESTED
HYDROSTATICALLY

ASSEMBLY	SERIAL #	TEST PRESSURE	WORKING PRESSURE	HOLD TIME	EXTERNAL INSPECTION
FLUID HOSE	1646	180 PSI	150 PSI	5 MIN	PASSED

STEWART SKAFTE

Tested By

Signature

MAY 8 2026

Date Tested



Test and Inspection Report in Accordance with CSA B620

Facility Name:	Total Inspection Services Inc.	Work Order Number:	5353
Address:	7018 Stanley Drive PO Box 974 Dawson Creek BC V1G 4H9	Date:	MAY 9 2026
Telephone:	250-784-7966	Transport Canada Facility Registration #:	25-0847
Tank Owner:	DRIVE LOGISTICS	Tank TCRN/MDIN:	12958
Address:	PO BOX 7813 STN MAIN PEACE RIVER AB T8S 1T3	Unit #:	SB160A
Telephone:	1 780-618-8572		

Tank Serial #:	13123	Tank Spec:	TC / DOT 407
Manufacturer:	TREMCAR USA	Mfr. Date:	01/2014
Special Service:	N/A	Lined:	Yes ☐ No ☒
MAWP/Design Pressure:	172 KPA	Insulated:	Yes ☐ No ☒
Min Shell Thickness:	5.969 MM	Min Head Thickness:	7.163 MM

Gauge Calibration Checked: Yes ☒ No ☐ Gauge #: D1

Cert. Date: 01/2014 Assembler: TREMCAR USA

Capacity: ☐ Total US gals ☒ Total Litres ☐ Total Imp gals

Compartment: 1. 28370 2. 3. 4.

TEST PERFORMED ☒ V – shall signify external inspection ☒ I – shall signify internal inspection
☒ K – shall signify leakage test

EXTERNAL VISUAL INSPECTION "V"

	Complies	Reject	N/A	Complies on Retest
Data plate, present and legible	☒	☐	☐	☐
Shell & Heads, corrosion, abrasion, dents, overlay patches, leaks etc.	☒	☐	☐	☐
Structural members, outriggers, cross members, etc.	☐	☒	☐	☒
Piping and valves for leakage, damage, corrosion	☒	☐	☐	☐
Remote closures, emergency shut off decals, thermal devices	☐	☒	☐	☒
Hoses for defects, identification and test dates	☒	☐	☐	☐
Gaskets on full opening rear heads for damage or cuts	☐	☐	☒	☐

Tank attachments to frame or running gear	☒	☐	☐	☐
Ladders, walkways, etc.	☒	☐	☐	☐
Fill covers, manways and closure devices	☒	☐	☐	☐
Relief valves and vents (replace or test if tank in service where lading corrosive to relieve device)	☒	☐	☐	☐
Accident damage protection	☒	☐	☐	☐

INTERNAL VISUAL INSPECTION "I"

	Complies	Reject	N/A	Complies on Retest
Interior surface, corrosion, distortion, overlay patches, cracking etc.	☒	☐	☐	☐
Interior welds for defects, cracking, etc.	☒	☐	☐	☐
Internal supports and attachments	☒	☐	☐	☐
Internal valves, piping and vents for leakage, damage, etc.	☒	☐	☐	☐

Note: Rejection Criteria for Visual Inspections

Any of the following conditions shall cause the tank to be rejected:

- Less than minimum material thickness under any cut, dig or gouge.
- Any dent with a depth greater than 1/2" where it includes a weld.
- Any dent with a depth greater than 10% of the length of the dent.
- Any weld defect including a crack, pinhole, or incomplete fusion of the weld.
- Any repairs made using overlay patches.
- Defective, unidentified or out of test Hose Assemblies.

LEAKAGE TEST "K"

Test Pressure: 137.6 KPA (80% of MAWP Min.) Test Medium: AIR Hold Time: 5 MINS

Item Tested				Item Tested			
	Pass	Fail	Complies on Retest		Pass	Fail	Complies on Retest
Compartment # 1	☒	☐	☐	Compartment # 1 Piping	☒	☐	☐
Compartment # 2	☐	☐	☐	Compartment # 2 Piping	☐	☐	☐
Compartment # 3	☐	☐	☐	Compartment # 3 Piping	☐	☐	☐
Compartment # 4	☐	☐	☐	Compartment # 4 Piping	☐	☐	☐

Tank attachments to frame or running gear	☒	☐	☐	☐
Ladders, walkways, etc.	☒	☐	☐	☐
Fill covers, manways and closure devices	☒	☐	☐	☐
Relief valves and vents (replace or test if tank in service where lading corrosive to relieve device)	☐	☒	☐	☒
Accident damage protection	☒	☐	☐	☐

INTERNAL VISUAL INSPECTION "I"

	Complies	Reject	N/A	Complies on Retest
Interior surface, corrosion, distortion, overlay patches, cracking etc.	☒	☐	☐	☐
Interior welds for defects, cracking, etc.	☒	☐	☐	☐
Internal supports and attachments	☒	☐	☐	☐
Internal valves, piping and vents for leakage, damage, etc.	☒	☐	☐	☐

Note: Rejection Criteria for Visual Inspections

Any of the following conditions shall cause the tank to be rejected:

- Less than minimum material thickness under any cut, dig or gouge.
- Any dent with a depth greater than $\frac{1}{8}$ " where it includes a weld.
- Any dent with a depth greater than 10% of the length of the dent.
- Any weld defect including a crack, pinhole, or incomplete fusion of the weld.
- Any repairs made using overlay patches.
- Defective, unidentified or out of test Hose Assemblies.

LEAKAGE TEST "K"

Test Pressure: 137.6 KPA (80% of MAWP Min.)

Test Medium: AIR

Hold Time: 5 MINS

Item Tested				Item Tested			
	Pass	Fail	Complies on Retest		Pass	Fail	Complies on Retest
Compartment # 1	☒	☐	☐	Compartment # 1 Piping	☒	☐	☐
Compartment # 2	☐	☐	☐	Compartment # 2 Piping	☐	☐	☐
Compartment # 3	☐	☐	☐	Compartment # 3 Piping	☐	☐	☐
Compartment # 4	☐	☐	☐	Compartment # 4 Piping	☐	☐	☐

Defects found, location and corrective action *(use additional sheets if necessary)*

RESEAL PRV
LABEL ESD

Defects corrected and released
Tank successfully retested after repair

☒ Yes
☒ Yes

☐ No
☐ No

Tank Disposition:

- ☐ Returned to service as no defects or damage was discovered
☒ Returned to service after retest
☐ Removed from service

Tank Marking: 05 26 VIK 847

Month, year and service symbol (MMYY XXXXXX 000) after all defects are corrected.

Tank markings applied

☒ Yes

☐ No

Tank Tester Name:

Stewart Skafte

Signature:



Date: MAY 9 2026



7018 Stanley Dr, PO Box 974
Dawson Creek BC V1G 4H9
Phone: 250-784-7966
E-mail: tis@pris.ca

HOSE TEST CERTIFICATE

Customer DRIVE LOGISTICS

Unit # SB160A

Invoice # WO# 5353

**THIS CERTIFICATE IS PROOF THAT ALL ASSEMBLIES LISTED BELOW HAVE BEEN TESTED
HYDROSTATICALLY**

ASSEMBLY	SERIAL #	TEST PRESSURE	WORKING PRESSURE	HOLD TIME	EXTERNAL INSPECTION
FLUID HOSE	1643	180 PSI	150 PSI	5 MIN	PASSED

STEWART SKAFTE

Tested By

Signature

MAY 8 2026

Date Tested

Defects found, location and corrective action (use additional sheets if necessary)

CRACK RHS RAIL
CRACK RHS BY PUMPBOX
LABEL ESD

Defects corrected and released
Tank successfully retested after repair

☒ Yes

☐ No

☒ Yes

☐ No

Tank Disposition:

☐ Returned to service as no defects or damage was discovered

☒ Returned to service after retest

☐ Removed from service

Tank Marking: 05 26 VIK 847

Month, year and service symbol (MMYY XXXXXX 000) after all defects are corrected.

Tank markings applied

☒ Yes

☐ No

Tank Tester Name: Stewart Skafte

Signature:



Date: MAY 9 2026