

Prespatou Truck Repair Ltd.

Box 296
Prespatou, British Columbia V0C 2S0
Canada

Phone: (250) 630-2101 or (250) 262-6461

Email: prespatoutruckrepair@yahoo.ca

INVOICE

Invoice No.: 20367
Date: May 05, 2026
Ship Date:
Page: 2
Re: Order No.

Sold to:

Sage Creek Oilfield Services

Ship to:

Sage Creek Oilfield Services

Business No.: 800169351

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
			Subtotal:			23,762.29
			Freight	GP		399.50
			GP - GST 5%, PST 7% on sales - not Included			1,208.12
			GST			1,691.35
			PS			

Shipped By:

Tracking Number:

Comment: Unit# 20201



Job# 2166

Sold By:

WE NOW ACCEPT E-TRANSFERS VIA EMAIL

Total Amount 27,061.26

Amount Paid 0.00

Amount Owning 27,061.26

Prespatou Truck Repair Ltd.

Box 296
 Prespatou, British Columbia V0C 2S0
 Canada

Phone: (250) 630-2101 or (250) 262-6461

Email: prespatoutruckrepair@yahoo.ca

INVOICE

Invoice No.: 20367
 Date: May 05, 2026
 Ship Date:
 Page: 1
 Re: Order No.

J01-1

Sold to:
 Sage Creek Oilfield Services

Ship to:
 Sage Creek Oilfield Services

Business No.: 800169351

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
ISX123113	Each	1.0	PAI overhaul kit with 150mm liners and fractured rod bearings	GP	5,370.75	5,370.75
5394198	Each	1.0	cylinder head	GP	5,220.95	5,220.95
IDISXHBK	Each	1.0	head bolt kit	GP	595.00	595.00
3690406	Each	1.0	engine camshaft	GP	1,395.00	1,395.00
4059410	Each	3.0	front exhaust rocker lever	GP	169.00	507.00
4059411	Each	3.0	rear exhaust rocker lever	GP	169.00	507.00
4059412	Each	3.0	front intake rocker lever	GP	169.00	507.00
4059413	Each	3.0	rear intake rocker lever	GP	169.00	507.00
5658098CUM	Each	2.0	air compressor intake line o-ring	GP	4.00	8.00
6303173CUM	Each	1.0	ISX front engine cover strip (3687007CUM)	GP	74.57	74.57
89440DYC	Each	1.0	fan belt tensioner	GP	274.54	274.54
4966454CUM	Each	1.0	doser/turbo output clamp	GP	96.47	96.47
D84-1000-612231	Each	1.0	belt	GP	141.39	141.39
0						
D84-1000-606162	Each	1.0	ISX air conditioning 6 rib belt	GP	73.39	73.39
0						
996813502-002	Each	1.0	fan blade	GP	361.36	361.36
3163075	Each	1.0	ISX paint	GP	50.12	50.12
LF14000NNFLG	Each	1.0	ISX engine oil filler + eco fee	GP	61.30	61.30
ET10	Each	2.0	hose clamp	GP	3.52	7.04
5526-075	Inch	14.0	3/4" heater hose (NL4875075)	GP	0.70	9.80
3HD-1	Inch	38.0	1" good year rad hose	GP	0.92	34.96
ET16	Each	2.0	3/4 - 1 1/2" hose clamp	GP	3.91	7.82
134A	Pounds	4.3	Freon	GP	20.40	87.72
488100PBD	Ounce	0.5	Pag Oil 100 with dye	GP	3.43	1.72
257004-428C	Each	2.0	15/40 chevron oil + eco fee	GP	111.82	223.64
257004-464C	Jug	3.0	jug 15/40 chevron oil + eco fee	GP	25.38	76.14
EC7501	Jug	14.0	50/50 extended life antifreeze + eco fee	GP	14.74	206.36
4110	hr.	55.0	labor	GP	125.00	6,875.00
4112	Each	6,875.0	Shop supplies 7 % of labor	GP	0.07	481.25
			diagnose engine complaint for excessive blow by, took engine apart, found #5 piston ring broken, found camshaft lobes wore, complete inframe rebuild, replace cylinder head, camshaft, and rocker levers, test drive truck			
			KM: 535,154 HRS: 13,101 202 KW VIN: 968833 ESN: 80249670			

Comment: Unit# 20201

Continue...

WE NOW ACCEPT E-TRANSFERS VIA EMAIL