

Tio-\
Repair Order
Invoice

Page

Activity Sub-Total:

98.8000

One EA

1/2

1,250.05

98.80

Invoice To:

LARRY GAULTIER

Box 474

Grovedale AB T0H1X0

Canada

Shop Supplies

Shop Supplies

Tel: 587-343-2575

Bank Mechanical Ltd.

10803 - 99 Street

Clairmont, AB T8X 5B4

Tel: (780) 567 2990

Canada

reception@bankmechanical.ca

Invoice Date	Invoice	A/C	Customer PO	Payment Te	rm	Customer Tax #	
Sep 15, 2025	WI019364	LG		CASH			
RO WO019814	Owner LARRY GAULTIER		Repair Loc. Bank	Repair Loc. Bank Mechanical Ltd.		. Repair Sep 15, 2025	
	MESONA,		License	of.	Last Cert. ()		
			"Allegai		Er	ngine	
Activity Descript Part Number	tion Part Desc	ription		Quantity	Charge	Total	
1. Repair Rear D/	S fender			1.50 HR	152.0000	228.00	
Try to tighten a	nd no luck. Installed nev	w bar, drilled and mounted.					
M11-388	Fender bra	ıket		1.00 EA	155.9880	155.99	
				Ad	tivity Sub-Tota	l: 383.99	
2. Inspect trailer				5.00 HR	152.0000	760.00	
		and protection valve on air tank s ew bags and replaced valve.	tuck closed. Torched off #1 P/S				
MHSK458	MOUNTING	G KIT		2.00 EA	14.8070	29.61	
101-B	1/4NPT FE	MALE TEE		1.00 EA	8.6320	8.63	
4485-122C	HEX NIPPI	LE		1.00 EA	2.9640	2.96	
1469-6C	#6 X 3/8NF	PT AB 90 ELBOW		2.00 EA	11.2580	22.52	
MER-EAS8050	AIR SPRIN	IG		2.00 EA	193.2320	386.46	
140280	VALVE			1.00 EA	39.8720	39.87	

Authorized



Repair Order Invoice

Invoice To:

LARRY GAULTIER

Box 474

Grovedale AB T0H1X0

Canada

Tel: 587-343-2575

Bank Mechanical Ltd.

10803 - 99 Street

Clairmont, AB T8X 5B4

Tel: (780) 567 2990

Canada

reception@bankmechanical.ca

Page

2/2

Invoice Date	Invoice	A/C	Customer PO	Payment Term	Customer Tax #
Sep 15, 2025	WI019364	LG		CASH	

Total Labor:

988.00

Total Parts: Shop Supplies: 646.04

Enviromental Fee:

98.80 12.92

Sub Total:

1,745.76

GST:

86.64

Invoice Total: \$

1,832.40

DISCLAIMER REGARDING ESTIMATES:

TERMS OF SERVICE:

REPAIR NEEDS.

Please note that all repair estimates provided by BANK MECHANICAL are estimates based on the information available at the time of assessment. While we make every effort to ensure the accuracy of our estimates, unforeseen circumstances may arise during the repair process, leading to adjustments in cost and timelines. We strive to keep our customers informed during the repair process and will notify you promptly of any changes to the initial estimate. Your understanding and cooperation in such situations are greatly appreciated.

For your safety, any work requiring wheel removal must be re-torque within 100km of driving. Failure to re-

WE THANK YOU FOR CHOOSING BANK MECHANICAL FOR YOUR TRUCK, TRAILER AND AUTOMOTIVE

torqued may result in wheel loosening, which can lead to serious damage or accidents.***

Signature	
-----------	--