

Service Job	Invoice No	Date	Customer Id	Customer Name	Cost Cent	Prob	Type of Call	Equip ID	Hrs	Kms	Job Description	Work Done	Labor Cost	Material Cost	Subcontra ctor Cost	Other Cost	Total Cost
97533	116868	09/10/2026	1HM103HBG	ID - EARTHMOVING	184G	R	Sundries	1MX891	11030.000	0	CHECK OVER	CARRIED OUT PREDISPOSAL AS REQUIRED	126	20	0	20	146
96411		08/24/2026	1HM103HBG	ID - EARTHMOVING	184G	R	Hydraulic	1MX891	11750.000	0	REPLACE BLOWN HITCH HOSE		126	0	0	0	126
94930	115685	07/28/2026	1HM103HBG	ID - EARTHMOVING	184G	R	Bodywork	1MX891	11750.000	0	SUPPLY PARTS ONLY - DAMAGED MIRRORS	SUPPLY PARTS ONLY - DAMAGED MIRRORS	0	324.5	0	0	324.5
85157	102021	02/10/2026	1HM103HBG	ID - EARTHMOVING	182G	R	Sundries	1MX891	11750.000	0	REPAIR BENT HANDRAIL		432	50	0	50	482
84452	101871	01/28/2026	1HM103HBG	ID - EARTHMOVING	186G	S	Service EarthmovingC	1MX891	11750.000	0	1000HR SERVICE	CARRY OUT SERVICE AND VEHICLE INSPECTION. CHECK ALL LIGHTS, CHECK FLUID LEVELS. CHECK SUSPENSION, BRAKES AND TYRES - REPLACED BROKEN GREASE NIPPLES - REPAIRED OIL LEAK ON BOOM	768	434.96	0	92	1254.96
84265	104742	01/23/2026	1HM103HBG	ID - EARTHMOVING	186G	R	Chassis	1MX891	11750.000	0	PMI INSPECTION AND REPAIRS AS PER LIST	•Marguard Screen to come off and have a label fitted to it •Remove all the breath safe system •Replace the rear camera and covers •Rear handrail repair •Door Repair (not closing) •Remove GPS Pole on rear of machine and all of the GPS components cables •Replace Fitting on hitch hose block at base of dipper arm •Hose loose on dipper arm •Clamp on top of bucket cylinder •Work light missing on top of cab •Remove side window cab guard (next to boom) •Toolbox under cab door needs cleaning out •Panel under door needs to be repaired •1mb1238 Needs a new cutting edge •Hight sensor needs to be removed from the boom CARRY OUT REPAIRS PER JOB LIST - REMOVE BREATHE SAFE SYSTEM - REMOVE HEIGHT LIMITER SYSTEM, ISSUE WITH FINDING CIRCUIT TO CUT OFF BOOM UP HYDRAULICS - PANELS ORDERED TO REPALCE BREATHE SAFE - FIT PANELS AND CAB FILTER - CLEAN CAB OUT	5988	3002.31	0	200	8990.31

77506	95915	09/08/2025	1HM103HBG ID - EARTHMOVING	184G	R	Sundries	1MX891	11750.000 0 0	CHECK OUT HEATER FAULT	INVESTIGATED REPORTED HEATER ISSUE/S - COULD NOT FAULT AT TIME OF TESTING	111	0	0	0	111
76243	94855	08/15/2025	1HM103HBG ID - EARTHMOVING	184G	R	Hydraulic	1MX891	0.0000 0	HYDRAULIC LEAK	TRAVELLED TO LKW REPAIRED OIL LEAK FROM RH SIDE BLADE HOSE RAN UP & TESTED FOR FURTHER LEAKS - NONE FOUND, ALL OK PACKED UP& RETURNED TO SERVICE	700	1686.51	0	340	2686.51
75276	91162	07/30/2025	1HM103HBG ID - EARTHMOVING	183G	R	Electrical	1MX891	11750.000 0 0	REPAIR ELECTRICAL CONCERNS	ATTEND TO ELECTRICAL CONCERNS: - IGNITION SWITCH U/S: REMOVED & REPLACED - HORN INOPERATIVE: FOUND & REPLACED BLOWN FUSE - HEADLIGHTS INOPERATIVE: FOUND PLUG FOR SWITCH UNPLUGGED - RECONNECTED (FIXED ONE HEADLIGHT) CHECKED WIRING TO OTHER HEADLIGHT, FOUND LED ASSEMBLY TO HAVE BEEN WIRED BACK TO FRONT - REPAIRED AS REQUIRED	168	20	0	20	188
75244	91586	07/29/2025	1HM103HBG ID - EARTHMOVING	182G	R	Sundries	1MX891	11750.000 0 0	REPAIR HANDRAIL	REPAIR CRACKS IN HANDRAIL MAKE TEMPLATE FOR MISSING SECTION COLLECT AND DELIVER STEEL TO BE ROLLED INTO SHAPE FAB NEW SECTION AND WELD HAND RAIL	2502	595.6	0	250	3097.6
75088	90323	07/28/2025	1HM103HBG ID - EARTHMOVING	186G	R	Lathe	1MX891	11750.000 0 0	Hitch repair	REPAIR HITCH AS REQUESTED HITCH NOW FITTED TO DIGGER	444	30	0	30	474

74892	91149	07/23/2025	1HM450HBG ID - CIVIL CONTRACTING	186G	R	Bodywork	1MX891	5424.0000	0	1MX891 - Damage Repair Ex LKW	REMOVE HAND RAIL TO HAVE REPAIRED REPLACE BROKEN LH TOP MIRROR AND RH MIRROR REPLACE WIPER ARM ASSY REMOVE MARGUARD SCREEN REPLACE TOP WORK LIGHTS AND REPAIR WIRING REPAIR/REFIT FRONT PANNEL UNDER WINDSCREEN REPLACE FINAL DRIVE OILS FIT UP QUICK HITCH REPAIR HYDRAULIC BLOCK FOR QUICK HITCH AND TILT CYLINDER HOSES REMOVE AND MAKE NEW HOSE FROM REAR OF MAIN BOOM DOWN TO END OF DIPPER MAKE NEW QUICK HITCH HOSES RESECURE HOSES ON BOOM AND DIPPER MAKE NEW CLAMPS FOR DIPPER HOSES REPLACE E-STOP	2050	2525.45	0	224	4599.45
74654	90956	07/17/2025	1HM103HBG ID - EARTHMOVING	184G	S	Service EarthmovingA	1MX891	10784.0000	0	CARRY OUT 250HR SERVICE		100	161.06	0	15	261.06
74552	90696	07/16/2025	1HM103HBG ID - EARTHMOVING	186G	R	Engine	1MX891	10760.0000	0	ENGINE REPAIR	REMOVE COUNTER WEIGHT TO CARRY OUT DIAGNOSTICS ON FUEL SYSTEM DRAIN AND INSPECT TANK REMOVE ALL FUEL LINES, CLEAN AND INSPECT REPLACE FUEL FILTERS REMOVE AND INSPECT PRESURE RELEIF IN COMMON RAIL REASSEMBLE ALL REMOVED LINES, REPLACE ALL WASHERS, REFILL TANK AND TAKE TO WASH BAY AND STEAM CLEAN ENGINE BAY REFIT COUNTER WEIGHT, CARRY OUT MULTIPLE TESTS IN OPERATION ALL OK	2542	209.09	0	150	2751.09
72974	88058	06/17/2025	1HM103HBG ID - EARTHMOVING	184G	R	Engine	1MX891	11250.0000	0	Derating Fault	ATTEND TO DERATING FAULT ATTEMPT TO REPAIR FAULT INCLUDING REPLACING FUEL FILTER AND RE BLEEDING SYSTEM FOUND OT BE STILL DERATING UNABLE OT CARRY OUT COMPLETE DIAGNOSTICS ON SITE, MACHINE WILL NEED TO BE REUTRNRD TO WORKSHOP	1116.5	5.56	0	0	1122.06
71963	87895	05/29/2025	1HM103HBG ID - EARTHMOVING	182G	R	Sundries	1MX891	11250.0000	0	CHANGE DOOR SCREEN / REPAIR BENT MARGUARD SCREEN		912	0	0	75	987

71213	87153	05/15/2025	1HM103HBG ID - EARTHMOVING	186G	S	Service EarthmovingA	1MX891	11250.000	0	0	Carry out 250H Service	144	32	0	0	176	
70932	87691	05/09/2025	1HM103HBG ID - EARTHMOVING	186G	R	Chassis	1MX891	0.0000	0	0	Equipment Fault Repair	REPAIR AND MAKE HOSES ON DIPPER ARM REPLACE TOP CYLINDER PIN REPLACE MIRRORS REPLACE FUEL TANK SENDER SPLIT TRACKS READY FOR KOMATSU TO REPLACE LINKS UNER WARRANTY REPLACE WIPER ARM ASSEMBLY SET/CHECK PRESSURES FOR TILT AND QUICK HITCH	4512.75	606.98	0	142.78	5262.51
70568	85517	05/02/2025	1HM103HBG ID - EARTHMOVING	182G	R	Sundries	1MX891	10533.000	0	0	FAB SCREEN FOR DOOR / REPAIRS	1013	0	0	350	1363	
69568	85838	04/09/2025	1HM450HBG ID - CIVIL CONTRACTING	184G	A	Bodywork	1MX891	10533.000	0	0	REPLACE DAMAGED DOOR	434	8118.42	0	0	8552.42	
68539	85806	03/21/2025	1HM103HBG ID - EARTHMOVING	184G	R	Electrical	1MX891	10533.000	0	0	Fuel gauge not working and elc faults	DIAGNOSE FAULTY SENDER MACHINE TAKEN TO WORKSHOP FOR REPAIRS	549.76	370.5	0	0	920.26
66454	86405	02/13/2025	1HM103HBG ID - EARTHMOVING	182G	R	Sundries	1MX891	10533.000	0	0	REPAIR DAMAGED PANELS / HANDRAIL	4530.44	2439.63	0	250	7220.07	

66384	80639	02/12/2025	1HM103HBG ID - EARTHMOVING	186G	S	Service EarthmovingB	1MX891	10359.000 0 0	500hr SERVICE + REPAIR OPERATORS DOOR / REPLACE EXTERIOR MIRRORS	WASH DOWN MACHINE BEFORE BOUGHT INTO WORKSHOP CARRY OUT 500 HOUR SERVICE AND INSPECTION - REMOVE TRACKS, REMOVE X3 GROUSERS EACH SIDE, ONCE FOUND MASTER LINK USE TRACK PRESS TO PUSH PIN OUT - REMOVE TRACKS, ROLL UP AND PUT ON PALLETTE - REMOVE X2 BROKEN ROLLER GUARDS AND REPLACE WITH NEW - REMOVE CARRIER ROLLERS , CHECK IDLETS AND CORRECT OPERATION - REMOV RADIATORS AND CLEAN OUT DEBRIS - REMOVE COVERS/BRACKETS TO REMVE AND CLEAN - REMOVE SPROCKETS AND CLEAN PINAL DRIVE SURFACE REASY FOR NEW - FOUND BREATH SAFE SYSTEM NOT WORKING, FOUND PLUGS UNPLUGGED. RECONNECT AND TEST - DOOR NOT SLIDING CORRECTLY, REMOVE AND REPLACE DOOR ROLLERS AND ADJUST - BOOM CREEPING, REMOVE PANELS AROUND CONTROL VALVES AND INSPECT ALL OK - CONDUCT CREEP TEST 5MM OVER 8 MINUTES REMOVE TOP CON SENSORS AND WIRING - SENSORS AND WIRING COMPLETELY DAMAGED - FASTEN DIPPER ARM HOSES TO BOOM - BREAKER HOSE HARD LINE HAS BEEN SWAPPED	7130.36	1973.39	0	342	9445.75
66394	81015	02/12/2025	1HM103HBG ID - EARTHMOVING	121G	INT-R	Tracks	1MX891	10533.000 0 0	REPLACE TRACK ASSEMBLIES		2468.74	9777.39	0	100	12346.13
66295	79668	02/11/2025	1HM103HBG ID - EARTHMOVING	184G	R	Chassis	1MX891	10359.000 0 0	Mud guard removal		186.56	0	0	0	186.56
65897	79875	02/03/2025	1HM103HBG ID - EARTHMOVING	184G	S	Service EarthmovingC	1MX891	10359.000 0 0	Supply 2x filter kits - LKW		0	1356.54	0	0	1356.54
65744	78440	01/31/2025	1HM103HBG ID - EARTHMOVING	186G	R	Sundries	1MX891	10359.000 0 0	PMI inspection	CARRY OUT PMI INSPECTION	93.28	0	0	15	108.28
61130	76998	11/11/2024	1HM103HBG ID - EARTHMOVING	184G	R	Sundries	1MX891	10359.000 0 0	Repairs after Tunnel Damage	LIST GIVEN TO KEVI OF REQUIRED REPAIRS REPAIRS TO MACHINE AFTER ROCKS FALLING ON IT IN TUNNEL	932.8	1676.07	0	0	2608.87
60771	73398	11/04/2024	1HM103HBG ID - EARTHMOVING	184G	R	Electrical	1MX891	10359.000 0 0	4G Tracker		186.56	319	0	52.5	558.06

60077	72355	10/21/2024	1HM103HBG ID - EARTHMOVING	184G	S	Service EarthmovingA	1MX891	10359.000	0	A Service - 10,250 hours & HANDRAIL REPAIRS	CARRY OUT SAMPE SERVICE AND WELD BROKEN HANDRAIL AROUND COUNTER WEIGHT X2 NOTES: BLADE RAM CYLINDER GUARD MIA	483.36	32	0	310	825.36
58887	72268	09/27/2024	1HM103HBG ID - EARTHMOVING	184G	R	Sundries	1MX891	10050.000	0	REPLACE GLASS - HOBART AUTO GLASS		0	405.45	0	0	405.45
58646	71193	09/23/2024	1HM103HBG ID - EARTHMOVING	184G	R	Engine	1MX891	10050.000	0	ADJUST BELTS		93.28	0	0	125	218.28
58648	71937	09/23/2024	1HM103HBG ID - EARTHMOVING	184G	R	Hydraulic	1MX891	10050.000	0	SET UP ROCK BREAKER	SETUP ROCK BREAKER FOR TUNNEL AND FIT UP SCREEN	956.12	0	0	660	1616.12
58552	70019	09/19/2024	1HM103HBG ID - EARTHMOVING	182G	INT-R	Lathe	1MX891	0.0000	0	MACHINE 4 NEW WINDOW ROLLERS AS PER SAMPLE	MACHINE 4 NEW WINDOW ROLLERS AS PER SAMPLE	180.2	0	0	20	200.2
58335	71025	09/16/2024	1HM103HBG ID - EARTHMOVING	184G	R	Sundries	1MX891	0.0000	0	ROCK SCREEN	ATTEMPT TO FIT WRONG SCREEN X3 TAK EPHOTOS ETC TO SEND TO MANUFACTURER	1772.32	28.38	0	300	2100.7
56935	68347	08/19/2024	1HM103HBG ID - EARTHMOVING	184G	R	Chassis	1MX891	10050.000	0	MACHINE INSPECTION	GREASE MACHINE CARRY OUT PRESTART FOUND AIR FILTER BLOCKED, CLEAN OUT AND TE4ST OK	323.3	0	0	20	343.3
55742	67302	07/26/2024	1HM450HBG ID - CIVIL CONTRACTING	121G	F	Bodywork	1MX891	0.0000	0	HINGED DEMO GUARD		0	4965	0	0	4965
55467	66791	07/22/2024	1HM103HBG ID - EARTHMOVING	184G	R	Sundries	1MX891	10050.000	0	Re-Fit LHS Track		326.48	0	0	125	451.48
55478	67217	07/22/2024	1HM103HBG ID - EARTHMOVING	184G	R	Sundries	1MX891	10000.000	0	Replace Lower front glass		254.93	396.74	0	50	701.67
55197	69983	07/17/2024	1HM103HBG ID - EARTHMOVING	184G	R	Sundries	1MX891	0.0000	0	REPAIR CAB LEAK	INSPECTED LEAK - USED SMOKE BOMB TO IDENTIFY REMOVED PANELLING, FOUND SOURCE OF LEAK UNABLE TO REPAIR ON DAY, REQUIRED FOAM & SEALANT SOURCED EXPANSION FOAM & APPLIED AS REQUIRED RECHECKED FOR LEAKS, NONE FOUND, ALL OK	569.75	17.26	0	30	617.01

54820	67198	07/10/2024	1HM103HBG ID - EARTHMOVING	184G	S	Service EarthmovingD	1MX891	10000.0000	0	D Service 10,000 hours	CARRY OUT SERVICE AND VEHICLE INSPECTION. CHECK ALL LIGHTS, CHECK FLUID LEVELS. CHECK SUSPENSION, BRAKES AND TYRES	1667.65	799.35	0	110	2577
											NOTES: REAR MAIN LEAKING					
54515	67220	07/04/2024	1HM103HBG ID - EARTHMOVING	184G	R	Hydraulic	1MX891	9807.0000	0	SUPPLY ONLY ELBOW FOR Q/HITCH REPAIR		0	48.11	0	0	48.11
53382	64067	06/12/2024	1HM103HBG ID - EARTHMOVING	184G	R	Sundries	1MX891	9807.0000	0	REPLACED QUICK HITCH HOSES & FITTING IN MANIFOLD - 1MX891 - LAKE KING WILLIAM		0	0	785	0	785
51935	65077	05/13/2024	1HM103HBG ID - EARTHMOVING	184G	R	Electrical	1MX891	9807.0000	0	Repair breathe safe system	INSPECT AIR SYSTEM FOR AIR TIGHT RELSEAE SMOKE BOMB AND CHECKED ALL OK	93.28	71.16	0	0	164.44
51568	61073	05/06/2024	1HM103HBG ID - EARTHMOVING	184G	R	Tracks	1MX891	0.0000	0	Re-Fir track	REFIT TRACK TO DIGGER AT LKW OUTLET SLACK OFF IDLER AND REFIT TRACK RETENSION TRACK AND TEST ALL OK	373.12	0	0	15	388.12
45390	55388	01/18/2024	1HM103HBG ID - EARTHMOVING	184G	R	Sundries	1MX891	9807.0000	0	Replace broken mirror	REPLACED BROKEN MIRROR. REMOVED BROKEN BOLTS ON WINDOW SECURITY MESH. FITTED NEW GAL BOLTS AND WASHERS. FITTED NEW BROWSER PLATE BOLTS TO REACKS. FITTED NEW DRIVERS DOOR SECURITY MESH.	474	155.65	0	25	654.65
45309	55381	01/17/2024	1HM103HBG ID - EARTHMOVING	184G	R	Hydraulic	1MX891	9807.0000	0	REPAIR OIL LEAK	CHECKED OIL LEAKS ANDREPLACED SPOOLS ON HEIGHT LIMITER CIRCUIT.	660	962.1	0	30	1652.1
45260	56537	01/16/2024	1HM103HBG ID - EARTHMOVING	182G	R	Sundries	1MX891	9807.0000	0	REPAIR BROKEN HANDRAIL	REPAIR BROKEN HANDRAIL SETUP GEAR, COVER AREA BELOW HANDRAIL WITH LEATHER BLANKET, GRIND & PREP, WELD HANDRAIL, PAINT & CLEANUP	85	0	0	20	105

45153	55871	01/15/2024	1HM103HBG ID - EARTHMOVING	184G	F	Sundries	1MX891	9807.0000	0	Fit up breathe safe system	FITTED NEW BREATHE SAFE SYSTEM TO MACHINE AND CHECKED OPERATIONS. ALL OK.	1871.75	230.51	0	90	2192.26
44031	53334	12/11/2023	1HM103HBG ID - EARTHMOVING	184G	R	Sundries	1MX891	9807.0000	0	Wash and PMI	CARRIED OUT CLEANING AND INSPECTION OF MACHINE INSIDE OF DOORS. FOLLOW UP: AIR FILTERS, MIRRORS, ORDERED FOR NEXT VISIT	220	435.58	0	10	665.58
43199	51509	11/23/2023	1HM103HBG ID - EARTHMOVING	192G	S	Service EarthmovingA	1MX891	9807.0000	0	250HR SERVICE	HRS: 9807 SERVICE CARRIED OUT AS PER SERVICE SHEET FOLLOW UP ADJ TRACKS TOP UP HYD OIL	154	32	0	57.75	243.75
41426	49389	10/18/2023	1HM103HBG ID - EARTHMOVING	482G	R	Sundries	1MX891	9556.0000	0	Replace adaptor for quick hitch		0	157.36	0	0	157.36
40664	50774	10/03/2023	1HM103HBG ID - EARTHMOVING	192G	R	Electrical	1MX891	0.0000	0	Code EOE-DA22KK Present	HRS: 9657 CODE - TRAVEL INSPECT & TEST FOUND ALTERNATOR U/S REMOVE CONTACTED NAPA PICK UP PARTS - FIT CHARGING BUT BATTERY LIGHT STAYING ON AFTER MARKETS - GENINIE CIRCUIT - ORDERED COLLECTED REMOVE & REPLACE ALL OK	1258.75	826.78	0	195	2280.53
39684	46163	09/14/2023	1HM103HBG ID - EARTHMOVING	192G	R	Hydraulic	1MX891	9556.0000	0	Hydraulic Leak (Enzed Sublet)	ARRANGE SUBLET	0	314.73	0	5	319.73

39140	45811	09/04/2023	1HM103HBG ID - EARTHMOVING	192G	R	Hydraulic	1MX891	9556.0000	0	List Of Works	TRAVEL TO CASINO, INSPECT OIL LEAKS, REMOVE CRACKED FITTING ON HITCH HOSE BLOCK, TRAVEL FOR REPLACEMENT (COULDNT OPERATE UNIT DUE TO OIL SPRAY), RETURN TO JOB, FIT FITTING & HOSE, START UNIT, REMOVE BUCKET, REMOVE DAMAGED HOSE, REMOVE BROKEN BOLTS FROM GPS SENSOR ON HITCH, FOUND BROKEN E STOP, TRAVEL FOR PARTS, RETURN & FIT HOSE, NEW E STOP & SENSOR COVER, FILL HYD OIL, CHECK OVER UNIT & OTHER COMPLAINTS, RETURN TRAVEL.	889.5	932.6	0	228.47	2050.57
38583	44821	08/23/2023	1HM103HBG ID - EARTHMOVING	192G	R	Electrical	1MX891	0.0000	0	New UHF (Missing) & Change Bucket Teeth	HRS: 9504 TRAVEL TO CASINO JOB FIT UHF INTO EXCAVATOR TEST - ALL OK CHANGED BUCKET TEETH ON DRENCHING BUCKET BUCKET PINS WERE SIEZED SOLID HAD TO CUT TEETH OFF & OXY CUT PINS OUT ONCED REMOVED CLEANED BUCKET TEETH ADAPTORS UP FITTED NEW TEETH SUPPLIED BY OPERATOR	317.5	340	0	115.9	773.4
38492	45009	08/21/2023	1HM103HBG ID - EARTHMOVING	182G	R	Sundries	1MX891	9495.0000	0	REPAIR BROKEN HANDRAIL	REPAIR BROKEN HANDRAIL - WELD PREP & WELD UP 3 CRACKS IN HANDRAIL, CLEANUP WELDS & PAINT	382.5	0	0	50	432.5
38415	44781	08/18/2023	1HM103HBG ID - EARTHMOVING	186G	INT-S	Service EarthmovingB	1MX891	9495.0000	0	500 HR SERVICE	CARRY OUT SERVICE AND VEHICLE INSPECTION. CHECK ALL LIGHTS, CHECK FLUID LEVELS. CHECK SUSPENSION, BRAKES AND TYRES REMOVE BELLT PLATE PLACE IN PRESS AND WASH DRAIN AND REPLACE FIANL DRIVE OILS SAMPLE SLEW AND HYDRAULIC - HYDRAULIC OIL WAS LOW FOUND SLEW MOTOR TO ALSO BE LOW ON OIL HYDRAULIC LEAK ON CONTROL DCV, DREAGEASED AND WASHED FIT LED LIGHT TO ROOF AND WIRE IN	972	516.97	0	50	1538.97
37696	46794	08/04/2023	1HM103HBG ID - EARTHMOVING	184G	R	Tracks	1MX891	0.0000	0	FIT SECOND HAND TRACKS	REPLACE TRACKERS WITH 2ND HAND UNITS REPLACE TOP ROLLER REPLACE TRACKS WITH 2ND HAND	1087	204.66	0	50	1341.66

36168	42417	07/07/2023	1HM103HBG ID - EARTHMOVING	184G	R	Tracks	1MX891	9405.0000	0	REFIT TRACK	TRAVELLED TO SOUTH HOBART FOUND THROWN TRACK FOR EXCAVATOR DOWN A BANK RELEASED TRACK ADJUSTER, RETRACTED & FIT TRACK TIGHTENED & GREASED ADJUSTER & CHECKED OPERATION - ALL OK AT TIME OF TESTING PACKED UP & RETURNED TO SERVICE	402.5	44.76	0	60	507.26
31172	36595	04/20/2023	1HM103HBG ID - EARTHMOVING	184G	R	Trimming	1MX891	0.0000	9301	TOPCON SENSOR BRAKET	INSPECTED U/S TOP CON SENSOR MOUNT & ORDERED NEW PARTS AS REQUIRED. REPLACED BRACKET, REFIT SENSOR & COVER. ALL OK	214.08	0	0	25	239.08
27790	32633	02/28/2023	1HM103HBG ID - EARTHMOVING	184G	S	Service EarthmovingA	1MX891	0.0000	0	SAMPLE SERVICE		225.63	64	0	75	364.63
24628	28887	01/11/2023	1HM103HBG ID - EARTHMOVING	192G	INT-R	Engine	1MX891	9124.0000	9124	Air Con Issue	TRAVELLED TO GEORGE TOWN SIGNED INTO SITE OFFICE TRAVELLED TO MACHINE ON SITE INPECTED TRAVELLED TO WB	180.08	0	0	79.09	259.17
22403	26682	11/14/2022	1HM103HBG ID - EARTHMOVING	182G	R	Tracks	1MX891	9045.0000	0	REPAIR BENT TRACK ROLLER	REPAIR BENT TRACK ROLLER - UNBOLT RUBBER TRACK PLATES & GROUSERS, PRESS TRACK CHAIN APART, PORTA POWER ROLLER PLATE STRAIGHT, REPLACE REMOVED GUSSET, REASSEMBLE TRACK TOGETHER, REFIT GROUSER & RUBBER PAD	2836.46	174.21	0	100	3110.67
22192	25983	11/07/2022	1HM103HBG ID - EARTHMOVING	184G	R	Engine	1MX891	0.0000	0	REPLACE LEAKING REMOTE ENGINE OIL FILTER HOSES	REMOVE AND REPLACE LEAKING REMOTE OIL FILTER HOSES WORK CARRIED OUT BY PIRTEK AT BRYN ESTYN	0	0	590.76	0	590.76

21985	26517	11/02/2022	1HM103HBG ID - EARTHMOVING	184G	R	Tracks	1MX891	9045.0000	0	REFIT THROWN TRACK / INSPECT DOOR SHUTTING ISSUE	RE FIT AND RE TENTION CHECK OVER DOOR THAT WONT SHUT REPLACED DOOR ROLLERS AND ADJUSTED	513.79	300.2	0	200	1013.99
21528	25513	10/24/2022	1HM103HBG ID - EARTHMOVING	184G	R	Electrical	1MX891	0.0000	0	INSPECT TILT HITCH AND THROTTLE ISSUES	REMOVE AND REPLACE THROTTLE POTENTIOMETRE AND KNOB TO REPAIR THROTTLE CODE ISSUE REMOVE AND REPLACE RIGHT HAND JOY STICK TO REPAIR HORN ISSUE TRAVEL BRYN ESTYN AND RETURN 9020 HRS	391.31	314.89	0	90	796.2
21317	25309	10/17/2022	1HM103HBG ID - EARTHMOVING	184G	S	Service EarthmovingC	1MX891	0.0000	0	CARRY OUT S1 C SERVICE	CARRY OUT S1 C SERVICE AS PER SERVICE SHEET TRAVEL BRYN ESTYN AND RETURN 9020 HRS	685.04	776.54	0	110	1571.58
18547	23534	08/18/2022	1HM103HBG ID - EARTHMOVING	192G	R	Sundries	1MX891	0.0000	0	CHARGE OUT BATTERY S MISSED ON SERVICE CALL 14575		0	298.18	0	0	298.18
17671	20869	08/01/2022	1HM103HBG ID - EARTHMOVING	184G	R	Tracks	1MX891	8874.0000	0	REFIT TRACK	REFIT RIGHT HAND TRACK AND CHECK CARRIER ROLLERS RUNNING STRAIGHT TRAVEL HOWRAH AND RETURN	299.71	0	0	85	384.71
17541	21610	07/28/2022	1HM103HBG ID - EARTHMOVING	184G	R	Tracks	1MX891	0.0000	8861	REFIT TRACK	REFIT RIGHT HAND TRACK TWICE IN TWO DAYS REMOVE CARRIER ROLLER FROM 1MX1045 AND FIT TO 1MX891 INCASE SLIGHTLY BENT SHAFT ON ROLLER CAUSING TRACK TO ROLL OFF TRAVEL HOWRAH AND RETURN TWICE	599.41	183	0	145	927.41

17065	21576	07/18/2022	1HM103HBG ID - EARTHMOVING	184G	S	Service EarthmovingA	1MX891	8808.0000	0	CARRY OUT S1 SAMPLE SERVICE	CARRY OUT S1 SAMPLE SERVICE AS PER SERVICE SHEET REPLACE MISSING BREAKER TAP BOLTS TRAVEL HOWRAH	171.26	32	0	65	268.26
16478	19042	07/05/2022	1HM103HBG ID - EARTHMOVING	184G	R	Electrical	1MX891	8716.0000	0	REPAIR TILT HITCH OPERATION	INSPECT TILT HITCH ISSUE, TRACE TO FAULTY RELAYS IN CONTACTS. REPLACED RELAYS AND UNIT TESTED OK WORK COMPLETED BY SPECIALIST AUTO ELECTRICS	0	0	343.23	0	343.23
14865	16958	05/30/2022	1HM103HBG ID - EARTHMOVING	192G	S	Engine	1MX891	7577.0000	0	SERVICE- -500HR	HRS: 8562 COMPLETE SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. GREASE ALL LUBRICATION POINTS. CHANGE ENGINE OIL AND FILTER. CHANGE AIR FILTER. CHANGE FUEL FILTER. CHECK ALL OTHER FLUID LEVELS.	213.55	47.9	0	74.7	336.15
14557	17415	05/23/2022	1HM103HBG ID - EARTHMOVING	192G	R	Sundries	1MX891	0.0000	0	REPAIRS AFTER BEING BROKEN INTO	HRS: 8536 REMOVED IGNITION BARREL FROM 1MX1011 WAS PARKED IN CROSSROADS YARD NOT BEING USED TRAVELED TO AIRPORT JOB FOUND IGNITION BARREL HAD A SCREWFRIVER BASHED INTO IT	469.81	325.73	0	139.5	935.04
14575	18683	05/23/2022	1HM103HBG ID - EARTHMOVING	192G	INT-R	Sundries	1MX891	0.0000	0	REPLACE BATTEERIES	TRAVEL TO AIRPORT JOB FITTED NEW BATTERY'STARTED OK	170.84	0	0	112	282.84
13843	16290	05/09/2022	1HM103HBG ID - EARTHMOVING	192G	R	Engine	1MX891	7577.0000	0	REPLACE BELTS	HRS: 7,577 REPLACE BELTS	256.26	236.59	0	49.1	541.95

12386	15480	03/30/2022	1HM103HBG ID - EARTHMOVING	192G	S	Service EarthmovingA	1MX891	7577.0000	0	250HR SERVICE	HRS: 8273 COMPLETE SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. GREASE ALL LUBRICATION POINTS. CHANGE ENGINE OIL AND FILTER. CHANGE AIR FILTER. CHANGE FUEL FILTER. CHECK ALL OTHER FLUID LEVELS.	256.26	99.02	0	111.6	466.88
12045	13297	03/22/2022	1HM103HBG ID - EARTHMOVING	192G	INT-S	Service EarthmovingB	1MX891	7577.0000	0	B - 500 HR SERVICE & INSPECTION		0	0	963.16	0	963.16
11718	14597	03/15/2022	1HM103HBG ID - EARTHMOVING	121G	R	Sundries	1MX891	0.0000	0	POOR SATELLITES TRACKING - POSITINO PARTNERS	POOR SATELLITES TRACKING ON BOTH GPS BOARDS CHECKED MACHINE & FOUND SYSTEM USING 4 GLONASS SATELLITES ON BOTH BOARDS (NO GPS SATELLITES AT ALL) TESTED ANTENNAS, ROVER BOX & CONTROL BOX NO ISSUES FOUND SET UP TOPCON ROVER & CHECKED SATELLITE TRACKING FOUND POOR SATELLITE RECEPTION CHECKED EASTERN END OF THE JOB FOUND TOPCON EXCAVATOR, TOPCON ROVER & THE TRIMBLE ROVER DROPPED ALL SATELLITES NO FAULT WITH THE EQUIPMENT ON SITE	0	0	145	0	145
10248	11252	02/10/2022	1HM103HBG ID - EARTHMOVING	192G	R	Air Con	1MX891	7815.0000	0	BLOCKED ENGINE COOLERS AC CONDENSOR	HRS: 7957 ENG OVERHEATING AIR CON NOT WORKING REMOVED & CLEANED SCREENS BLOW OUT EXCESSIVE BUILD UP OF DEBRIS COOLER RE FITTED TESTED OK	135.97	0	0	63.8	199.77

10105	12770	02/08/2022	1HM103HBG ID - EARTHMOVING	192G	S	Service EarthmovingD	1MX891	7815.0000	0	CARRY OUT 2000HR SERVICE	HRS: 7983	555.23	626.07	0	91.55	1272.85
											COMPLETE SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. GREASE ALL LUBRICATION POINTS. CHANGE ENGINE OIL AND FILTER. CHANGE AIR FILTER. CHANGE FUEL FILTER. CHECK ALL OTHER FLUID LEVELS.					
9262	10383	01/19/2022	1HM103HBG ID - EARTHMOVING	192G	R	Bodywork	1MX891	7815.0000	0	NOISE FROM HEATER FAN AREA	1MX891 HRS: 7,815	384.39	0	0	19.2	403.59
8132	9480	12/14/2021	1HM103HBG ID - EARTHMOVING	192G	S	Bodywork	1MX891	7760.0000	0	SAMPLE SERVICE	NOISE FROM HEATER FAN AREA 1MX891 HRS: 7,760.00	93.26	32.01	0	34	159.27
											COMPLETE SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. GREASE ALL LUBRICATION POINTS. CHANGE ENGINE OIL AND FILTER. CHANGE AIR FILTER. CHANGE FUEL FILTER. CHECK ALL OTHER FLUID LEVELS.					
7547	8262	12/01/2021	1HM103HBG ID - EARTHMOVING	192G	R	Sundries	1MX891	7091.0000	0	Adjust fan belts	1MX891 HRS: 7679	170.84	0	0	37.5	208.34
											ADJUST FAN BELT BELTS SQUEELING BELT LOOSE TENSIONED UP BELT TESTED OK					
6394	6726	11/03/2021	1HM103HBG ID - EARTHMOVING	192G	R	Electrical	1MX891	7091.0000	0	JUMPSTART AND CHECK CHARGE RATE	1MX891	427.1	0	0	35.8	462.9
5968	6393	10/21/2021	1HM103HBG ID - EARTHMOVING	192G	R	Electrical	1MX891	7091.0000	0	supply hyd oil and look at tilt function	JUMP START & CHECK CHARGE RATE 1MX891 HRS: 7091.00	340.22	82.4	0	45.95	468.57
5453	5918	10/07/2021	1HM103HBG ID - EARTHMOVING	192G	R	Engine	1MX891	7091.0000	0	INSPECT ENGINE BAY NOISE	SUPPLY HYD OIL & LOOK AT TILT FUNCTION 1MX891 HRS: 7,091.00	351.77	0	0	36.9	388.67
5209	5319	10/01/2021	1HM103HBG ID - EARTHMOVING	192G	R	Hydraulic	1MX891	7091.0000	0	HOSE FAILURE TO ROCK BREAKER	INSPECT ENGINE BAY NOISE 1MX891 HOSE FAILURE TO ROCK BREAHER	41.25	0	605.09	0	646.34

4617	4425	09/17/2021	1HM103HBG	ID - EARTHMOVING	192G	S	Service EarthmovingA	1MX891	7091.0000	0	S1A SAMPLE SERVICE	1MX891 OD:7281 S1A SAMPLE SERVICE	215.88	0	0	111.76	327.64
1657	2698	07/07/2021	1HM103HBG	ID - EARTHMOVING	192G	R	Electrical	1MX891	7091.0000	0	HITCH FAULTS	HITCH OPERATING ONE WAY BUT INTERMITENT THE OTHER WAY. INSPECT SPOOLS AND RELAYS. ATTENDS STEP 3 SITE ON WEST TAMAR, PERFORMED DIAGNOSTIC TEST TO TILT PROBLEM - WOULD NOT FAULT. STAYED AND WATCHED MACHINE GET OPERATED TO SEE FAULT. FOUND FAULT WITH RELAY NOT WORKING. SWAPPED RELAY TO SEE FAULT CHANGE SIDES - YES COLLECTED RELAY FROM ASHDOWN - WENT TO TOLL SITE AND INSTALLED - TESTED ALL OK	1025.04	0	0	166	1191.04
1094	1333	06/24/2021	1HM103HBG	ID - EARTHMOVING	192G	R	Electrical	1MX891	7073.3000	0	joystick fault		752.22	0	0	37.62	789.84
574	1753	06/11/2021	1HM103HBG	ID - EARTHMOVING	192G	S	Service EarthmovingC	1MX891	7032.5000	0	Service		699.99	521.05	0	333.7	1554.74
210524-0110	SVC00264 812	06/04/2021	1H0103	ID - EARTHMOVING	192_INT	R	Electrical	1MX891			REPLACE UHF HAND PIECE		39.45	45.9	0	0	85.35
210513-0045	SVC00264 244	05/28/2021	1H0103	ID - EARTHMOVING	192_INT	R	Hydraulic	1MX891			FIT XROAD BREAKER TO UNIT	FIT XROAD BREAKER TO UNIT - SUBLET TO PIRTEK PIRTEK INVOICE LC-T00013893 ATTEND SITE AT BEACONSFIELD TO SUPPLY AND FIT ADAPTORS TO CONNECT ROCK BREAKER AND REPLACE DAMAGED HYDRAULIC HOSE TO QUICK HITCH AS REQUESTED.	36.35	0	467.15	1.82	505.32
210419-0127	SVC00262 977	04/30/2021	1H0103	ID - EARTHMOVING	192_INT	S	Service	1MX891			S1 A SERVICE	S1 A SERVICE CARRY OUT SERVICE AS PER SHEET, TRAVEL TO AND FROM EXETER	122.55	245.71	0	45.5	413.76
210113-0062	SVC00257 261	02/15/2021	1H0103	ID - EARTHMOVING	192_INT	S	Service	1MX891			S1B SERVICE	TRAVEL TO EXETER, CARRY OUT S1B SERVICE	393.9	1011.01	0	50	1454.91

201217-0060	SVC00257418	01/07/2021	1H0103	ID - EARTHMOVING	192_INT	R	Engine	1MX891	6434	TIGHTEN FAN BELTS	TRAVEL TO EXETER. DIAGNOSE BELT SQUEAL. FOUND ALT BELT LOOSE. REMOVE ACCESS PANEL AND ADJUST BELT. FOUND WASHER ON WRONG SIDE OF YOKE FOR ADJUSTMENT BOLT. RECTIFY AND TIGHTEN. REFIT ACCESS PANEL. START AND RUN MACHINE. TURN A/C ON OFF, LOAD UP HYDS AND INCREASE TO MAX RPM. NOT SQUEALING NOW. BOTH BELTS IN GOOD CONDITION.	276.95	33.28	609.21	75	994.44
201002-0028	SVC00253539	10/23/2020	1H0103	ID - EARTHMOVING	192_INT	R	Bodywork	1MX891		FIT ROPS	FOUND PARTS TO FIT ROP, LIFTED ROP UP ON TOP OF CAB MEASURED UP RIGHT LENGTH BOLTS AND SOURCE NEW BOLTS, BOLTED DOWN ROP AND RESECURED FLASHING LIGHT BRACKET, PREP AND WELD UP BROKEN HANDRAIL ON REAR EXCAVATOR, WASHED EXCAVATOR AS REQUIRED, PAINTED HAND RAIL AND TOUCH UP PAINT BAD SCRATCHES	797.18	104.56	0	40	941.74
200825-0056	SVC00251341	09/16/2020	1H0103	ID - EARTHMOVING	192_INT	R	Bodywork	1MX891	6273 HRS	FIT NEW MIRROR	TRAVE TO SITE AT GODERICH ST, FIT NEW MIRROR TO UNIT	67.58	125.56	0	25	218.14
200825-0023	SVC00251314	08/31/2020	1H0103	ID - EARTHMOVING	192_INT	S	Service	1MX891		S1A SAMPLE SERVICE	CARRIED OUT S1A SAMPLE SERVICE	145.4	30.78	0	0	176.18
200612-0077	SVC00246716	08/26/2020	1H0103	ID - EARTHMOVING	192_INT	R	Electrical	1MX891	6117	Flashing light	TRAVEL TO INVERMAY, INSPECT FLASHING LIGHT, REMOVE LIGHT CAGE AND REMOVE CAB MOUNTING PLATE, FIT NEW LIGHT ASSY AND WIRE IN, REFIT PLATE AND CAGE, TEST LIGHT ALL OK	148.5	0	0	40	188.5
200612-0077	SVC00248432	08/26/2020	1H0103	ID - EARTHMOVING	192_INT	R	Electrical	1MX891	6117	Flashing light	Repair flashing light on site in Foster street	109.05	200	0	0	309.05
200727-0047	SVC00249807	08/18/2020	1H0103	ID - EARTHMOVING	192_INT	R	Bodywork	1MX891		INSPECT BROKEN WIPER	Arranged the required part for the wiper assembly. Once the part arrived it was fitted,	145.4	170.19	0	10	325.59

200714-0031	SVC00249 180	07/22/2020	1H0103	ID - EARTHMOVING	192_INT	R	Booms	1MX891	6179	REPLACE BROKEN CYLINDER PIN	INSPECT MACHINE AND WORK OUT WHAT PIN SIZE WAS NEEDED, COLLECT NEW PIN FROM KOMATSU, CLEANED UP HOLES AND PIN AND KNOCKED IN NEW PIN, GREASED UP PIN	139.88	374.64	0	0	514.52
200528-0034	SVC00246 677	06/03/2020	1H0103	ID - EARTHMOVING	192_INT	R	Engine	1MX891	6074	FAN BELTS SLIPPING	TRAVEL TO INVERMAY, INSPECT NOISE COMING FROM BELTS, ADJUST A/C BELT TENSION, TEST RUN AND CHECK OK	145.4	0	0	25	170.4
200507-0065	SVC00245 418	05/25/2020	1H0103	ID - EARTHMOVING	192_INT	R	Trays/Buckets	1MX891		SUPPLY MOLY GREASE AS PER D.H	PICK UP NEW GREASE CARTRIDGES AND TRAVEL TO INVERMAY CONSTRUCTION SITE, PUT GREASE CARTRIDGES IN CONTAINER.	109.05	164.51	0	20	293.56
200430-0005	SVC00245 851	05/14/2020	1H0103	ID - EARTHMOVING	181_INT	R	Booms	1MX891	6013 HRS	PAINT DIPPER AFTER WELDING REP	PAINT DIPPER AFTER WELDING REPAIRS WERE CARRIED OUT FIT NEW SWL DECALS TO DIPPER DECALS SUPPLIED BY EYE SPY.	399.85	114.21	45	90	649.06
200416-0054	SVC00244 239	05/12/2020	1H0103	ID - EARTHMOVING	184_INT	S	Service	1MX891	6013 HRS	S1 D SERVICE	S1 D SERVICE AS PER SERVICE SHEET REPLACE FAULTY REVOLVING LIGHT	531.05	686.02	0	27	1244.07
200512-0054	SVC00245 667	05/12/2020	1H0103	ID - EARTHMOVING	121_INT	R	Sundries	1MX891		SUPPLY BOLT ON RUBBER PADS	SUPPLY BOLT ON RUBBER PADS	0	4128.6	0	0	4128.6
200427-0095	SVC00245 077	05/06/2020	1H0103	ID - EARTHMOVING	184_INT	R	Booms	1MX891	6013 HR	REPAIR CRACKS IN DIPPER ARM	REPAIR CRACKS IN DIPPER ARM WASH MACHINE READY FOR REPAIRS, REMOVE HOSES AND PIPES FROM DIPPER ARM AND TO BOOM. REMOVE DIPPER ARM FOR WELDING REPAIRS CUT AND WELD FISH PLATES TO DIPPER ARM AS PER KOMATSU DRAWINGS, HAVE DIPPER ARM PAINTED. REFIT DIPPER ARM TO MACHINE AND REFIT ALL PLUMBING, TEST OPERATION AND CHECK FOR LEAKS.	3078.75	155	0	50	3283.75

200501-0010	SVC00245 078	05/06/2020	1H0103	ID - EARTHMOVING	184_INT	R	Tyres	1MX891	6013 HR	FIT NEW RUBBER OVERLAYS	CLEAN MATERIAL FROM TRACK PLATES AND FIT NEW RUBBER OVERLAYS AS REQUESTED	857.85	0	0	42	899.85
200407-0047	SVC00243 888	04/22/2020	1H0103	ID - EARTHMOVING	184_INT	R	Booms	1MX891	5928 HR	REPAIR CRACKS ON DIPPER ARM	REPAIR CRACKS ON DIPPER ARM INSPECT CRACKS IN DIPPER ARM, GOUGE OUT AND REWELD CRACKS IN DIPPER ARM TRAVEL CAMBRIDGE AND RETURN	464.35	49.29	0	98	611.64
200129-0087	SVC00239 976	02/06/2020	1H0103	ID - EARTHMOVING	184_INT	R	Air Con	1MX891	5618 HRS	CHECK AIR CON SYSTEM	CHECK AIR CON SYSTEM NOT WORKING, CLEANED A/C FILTERS AND COOLERS AND UNIT TESTED OK TRAVEL CAMBRIDGE TO LA	122.55	0	0	37.25	159.8
191212-0013	SVC00237 743	01/22/2020	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1MX891	5470 HR	REPLACE REVOLVING LIGHT	REPLACE REVOLVING LIGHT REMOVE AND REPLACE FAULTY REVOLVING LIGHT TRAVEL CAMBRIDGE	89.2	140.72	0	25	254.92
200106-0058	SVC00239 136	01/15/2020	1H0103	ID - EARTHMOVING	184_INT	R	Suspension/UC	1MX891	5549 HRS	REPLACE LEFT HAND CARRIER ROLL	REPLACE LEFT HAND CARRIER ROLLER TRAVEL TO CAMBRIDGE JOB SITE	85.45	158	0	37.5	280.95
200102-0029	SVC00238 473	01/07/2020	1H0103	ID - EARTHMOVING	184_INT	S	Service	1MX891	5514 HRS	S1B SERVICE	CARRIED OUT THE REQUIRED SERVICE AND SAFETY INSPECTIONS AS PER SERVICE SHEET. BLOW OUT RADIATOR AND COOLER CORES TRAVEL TO CAMBRIDGE AND RETURN	326.8	309.04	0	78.5	714.34
191125-0029	SVC00236 651	12/04/2019	1H0103	ID - EARTHMOVING	184_INT	R	Booms	1MX891	5390 hrs	REPAIR CRACKS ON DIPPER ARM	REPAIR CRACKS AROUND BUSHES IN DIPPER ARM. TRAVEL TO BENDERS DRIVE AND RETURN TWICE	368.55	0	0	36.75	405.3

190927-0036	SVC00233 645	10/15/2019	1H0103	ID - EARTHMOVING	192_INT	R	Electrical	1MX891		SUBLET TO CARSWELLS	SUBCONTRACTOR CARSWELL TO CHECK AND REPAIR TILT OPERATION	36.35	122	0	0	158.35
191004-0044	SVC00234 048	10/08/2019	1H0103	ID - EARTHMOVING	192_INT	S	Service	1MX891	5277 HRS	SAMPLE SERVICE	TRAVELLED TO RAEBURN, CARRY OUT SAMPLE SERVICE	227.1	39.04	0	75	341.14
190828-0032	SVC00231 938	08/29/2019	1H0103	ID - EARTHMOVING	184_INT	R	Sundries	1MX891	4949	CHECK & REPAIR SLEW FAULT	CHECK & REPAIR SLEW FAULT, TRAVEL TO UTAS JOB AND INSPECT SWING BRAKE NOT RELEASING, FOUND SWING BRAKE SWITCH ON, CHECKED FAULT WITH SWING LIMIT FUNCTION COMING ON INTERMINTENT, CHECKED WIRING AND FOUND CONNECTIONS TO SOLENOIDS LOOSE AND FULL OF DIRT, CLEANED COMPONENTS AND RE-INSTALLED, RETURNED TO SITE AND CARRY OUT FURHTER TESTS, FOUND SOLENOID POST TO BE U/S, RECONNECT HOSES TO BYPASS SWING LIMIT FUNCTION.	0	0	677.73	0	677.73
190813-0039	SVC00231 110	08/20/2019	1H0103	ID - EARTHMOVING	192_INT	S	Service	1MX891	5015	5000hr service	CARRIED OUT 5000HR SERVICE AS PER SCHEDULE	463.83	543.7	0	25	1032.53
190711-0029	SVC00229 302	07/31/2019	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1MX891		REPLACE BROKEN ALTERNATOR BELT	1MX891-4887 HRS BROKEN ALTERNATOR BELT & BUCKET ANGLE SENSOR BRACKET. TRAVEL TO CAMBRIDGE AND PICK UP NEW ALTERNATOR BELT. TRAVEL WITH BELT TO BOTHWELL TO MEET OPERATOR FROM CATTLE HILL WORK SITE. TRAVEL BACK TO WORKSHOP. MECHANIC ON SITE FITTED NEW BELT. REMOVE COVERS AND BROKEN ALTERNATOR ADJUSTER BOLT ASSY. REPAIR ADJUSTER BOLT ASSY AND FIT NEW BELT. REFIT COVERS. REPAIRED BUCKET ANGLE SENSOR BRACKET.	898.7	134.24	0	260	1292.94
190624-0080	SVC00228 236	07/30/2019	1H0103	ID - EARTHMOVING	184_INT	S	Service	1MX891		S1 A SAMPLE SERVICE	CARRIED OUT S1 A SAMPLE SERVICE ONLY AS PER SERVICE SHEET	167.15	31.93	0	5	204.08

190517-0060	SVC00227 076	06/04/2019	1H0103	ID - EARTHMOVING	186_INT	R	Electrical	1MX891	4519hrs	REPLACE HARNESS	Replaced supplied harness. Removed faulty harness and bracket, fitted new, secured as required.	72.7	0	0	0	72.7
190520-0026	SVC00226 148	05/23/2019	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1MX891		REPAIR LIGHTS	REPAIR LIGHTS REPLACE MISSING LIGHT ON TOP OF CAB REPLACE BROKEN MOUNTING BOLTS THAT SECURE GPS SENSOR COVER TIGHTEN GPS POLE MOUNTING BOLTS	204.25	0	0	10	214.25
190508-0024	SVC00225 346	05/15/2019	1H0103	ID - EARTHMOVING	184_INT	S	Service	1MX891		S1 B SERVICE	CARRIED OUT S1 B SERVICE AS PER SERVICE SHEET. ADJUST BELT TENSION. CHANGE FINAL DRIVE OILS	385.68	437.97	0	24	847.65
190314-0035	SVC00222 310	03/27/2019	1H0103	ID - EARTHMOVING	184_INT	S	Service	1MX891		S1 SAMPLE SERVICE	S1 SAMPLE SERVICE AS PER SERVICE SHEET TRAVEL YORK PLAINS	297.2	31.06	0	77.5	405.76
190207-0084	SVC00220 131	02/22/2019	1H0103	ID - EARTHMOVING	184_INT	R	Sundries	1MX891		CHECK LOCKUP FAULT WITH LEFT	CHECK LOCKUP FAULT WITH LEFT HAND CONSOLE, FOUND RADIO TO BE STUCK UNDER CONSOLE NOT LETTING IT RELEASE. MOVED RADIO AND TESTED OK TRAVEL YORK PLAINS	199.75	0	0	125	324.75
190215-0044	SVC00220 545	02/19/2019	1H0103	ID - EARTHMOVING	184_INT	R	Sundries	1MX891		REPLACE GREASE NIPPLES IN H LI	REPLACE GREASE NIPPLES IN H LINK REMOVE BROKEN GREASE NIPPLES AND REMOVE DIRT FROM GREASE TRACKS. FIT NEW GREASE NIPPLES AND GREASE MACHINE TRAVEL YORK PLAINS	122.55	0	0	68.5	191.05

190201-0067	SVC00220 333	02/13/2019	1H0103	ID - EARTHMOVING	184_INT	R	Sundries	1MX891	4106 HRS	REPAIR QUICK HITCH FAULT	REPAIR QUICK HITCH FAULT, CHECK ELECTRICS AND FOUND TO BE OK. CHECK HYDRAULIC OPERATION AND FOUND FAULT TO BE IN CYLINDER REMOVED CYLINDER AND FOUND FAULTY CHECK VALVE . REPLACE CHECK VALVE AND REFIT CYLINDER. TESTED OK TRAVEL YORK PLAINS AND RETURN TWICE SUPPLY HYD OIL TO OPERATOR 10129	817	332.22	0	290	1439.22
190118-0036	SVC00217 864	01/30/2019	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1MX891		CHECK TILT HEAD FAULT	CHECK TILT HEAD NOT WORKING INTERMITTANTLY. FOUND BROKEN WIRING IN JOYSTICK, REMOVE AND REPAIR WIRING LOOM . REASSEMBLE AND TESTED OK TRAVEL YORK PLAINS	285.95	0	0	140	425.95
190107-0061	SVC00218 289	01/16/2019	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1MX891		CHECK FAULT WITH RIGHT HAND J	CHECK FAULT WITH RIGHT HAND JOY STICK, CHECKED AND FOUND RELAYS TO BE FAULTY. REPLACED RELAYS AND TESTED OK TRAVEL YORK PLANS	245.1	32.52	0	125	402.62
181207-0020	SVC00216 913	12/21/2018	1H0103	ID - EARTHMOVING	184_INT	S	Service	1MX891	3980 hrs	S1 D SERVICE	TRAVEL YORK PLAINS. CARRIED OUT S1 D SERVICE AS PER SERVICE SHEET.	488.03	532.52	0	154	1174.55
181112-0035	SVC00215 298	11/20/2018	1H0103	ID - EARTHMOVING	184_INT	R	Trays/Buckets	1MX891	3840 HRS	TIGHTEN CUTTING EDGE BOLTS	TRAVELLED TO YORK PLAINS, TIGHTEN LOOSE CUTTING EDGE BOLTS, REMOVE GPS SENSOR COVER AND REPLACE BROKEN STUDS, REFIT COVER AND SECURE IN PLACE.	245.1	0	0	74.5	319.6
181023-0066	SVC00214 166	10/30/2018	1H0103	ID - EARTHMOVING	184_INT	S	Service	1MX891		S1 SAMPLE SERVICE	S1 SAMPLE SERVICE AS PER SERVICE SHEET TRAVEL YORK PLAINS	423.5	31.83	0	138.75	594.08
181023-0081	SVC00214 183	10/30/2018	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1MX891	3787 hrs	CHECK FAULT CODE ON DISPLAY	CHECK FAULT CODE ON DISPLAY, FOUND SLEW LOCK SWITCH STUCK IN BETWEEN ON AND OFF. TURN SWITCH TO OFF POSITION AND CLEARED CODE TIGHTEN NOISY FAN BELTS TRAVEL YORK PLAINS AND RETURN	326.8	0	0	250	576.8

181021-0026	SVC00213 967	10/22/2018	1H0103	ID - EARTHMOVING	184_INT	R	Sundries	1MX891	3764	REPLACED U/S GREASE NIPPLES	TRAVELLED TO YORK PLAINS, REPLACED BROKEN GREASE NIPPLES	81.7	0	0	42.5	124.2
180927-0011	SVC00212 637	10/03/2018	1H0103	ID - EARTHMOVING	184_INT	R	Sundries	1MX891	3690 hrs	REPAIR TRIMBLE SENSOR BRACKET	TRAVELLED TO ANTILL PONDS, REPLACE TRIMBLE COVER RETAINING BOLTS AND REFIT COVER.	122.55	0	0	25	147.55
180921-0046	SVC00212 262	09/21/2018	1H0103	ID - EARTHMOVING	121_INT	R	Engine	1MX891		SUPPLY ENGINE & HYDRAULIC OILS	SUPPLY ENGINE & HYDRAULIC OILS PLUS COOLANT TO KERRY SCOTT	0	338.04	0	0	338.04
180824-0019	SVC00210 624	08/28/2018	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1MX891	3546 HRS	CHECK FAN BELTS	CHECK FAN BELTS AND ADJUST TO SUIT TRAVEL ANTILL PONDS	81.7	0	0	25	106.7
180815-0048	SVC00210 167	08/21/2018	1H0103	ID - EARTHMOVING	181_INT	R	Sundries	1MX891		PREP AND PAINT OLD ROCK BREAKER	PREP AND PAINT OLD ROCK BREAKER SCREENS	181.75	37.98	0	20	239.73
180801-0026	SVC00210 113	08/15/2018	1H0103	ID - EARTHMOVING	184_INT	S	Service	1MX891	3472 HRS	S1 B SERVICE	TRAVELLED TO TUNBRIDGE, CARRIED OUT S1 B SERVICE AS PER SERVICE SHEET, TIGHTENED DRIVE BELTS	275.3	180.58	0	94	549.88
180813-0040	SVC00209 939	08/13/2018	1H0103	ID - EARTHMOVING	184_INT	R	Sundries	1MX891	NA	REPLACE GREASE NIPPLES ON TLT	TRAVELLED TO OATLANDS, REPLACED GREASE NIPPLES ON TILT A HEAD	122.55	0	0	25	147.55
180522-0039	SVC00205 217	05/28/2018	1H0103	ID - EARTHMOVING	184_INT	S	Service	1MX891	3279	S1 A SERVICE	CARRIED OUT THE REQUIRED SAMPLE SERVICE AND SAFETY INSPECTIONS	80.35	31.55	0	5	116.9
180528-0028	SVC00205 531	05/28/2018	1H0103	ID - EARTHMOVING	184_INT	R	Sundries	1MX891	3279 HRS	FIT BREAKER SCREENS	FIT BREAKER SCREENS TO FRONT OF MACHINE, RELOCATE THE WORK LIGHTS TO SUIT	160.7	0	0	8	168.7
180503-0004	SVC00204 897	05/16/2018	1H0103	ID - EARTHMOVING	184_INT	R	Bodywork	1MX891	NOT PROVIDED	REPLACE L/HAND CAB MIRROR	REMOVE AND REPLACE BROKEN LEFT HAND CAB MIRROR	40.18	86.12	0	0	126.3
180201-0006	SVC00199 600	02/26/2018	1H0103	ID - EARTHMOVING	184_INT	S	Service	1MX891	2985 HRS	S1 C SERVICE	CARRIED OUT S1 C SERVICE AS PER SERVICE SHEET, CLEANED IN CAB AIR CON FILTER SCREEN AND REPLACED INTAKE FILTER, REPLACED WIPER BLADE AND UNBLOCKED WASHER JET, REMOVED COOLER SCREENS AND CLEANED, CLEAN COOLER CORE AND REFIT SCREEN, REMOVE COVERS AND ADJUST ENGINE BELTS, WELD BROKEN RAIL ON COUNTER WEIGHT	398.63	599.05	0	20	1017.68
180129-0107	SVC00199 264	02/13/2018	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1MX891	2900 hrs	TIGHTEN LOOSE FAN BELTS	TRAVELLED TO CAMBRIDGE, TIGHTEN LOOSE FAN BELTS AS REQUESTED	80.35	0	0	25	105.35

180122-0010	SVC00199 616	02/06/2018	1H0103	ID - EARTHMOVING	186_INT	R	Sundries	1MX891	2803HRS	CHECK FOR NOISE IN CAB	CHECK FOR NOISE IN CAB. FOUND SCREWDRIVER JAMMED BETWEEN THE REAR OF THE CAB AND BODY PANNEL COULD NOT TRACE OWNER OF THE SCREWDRIVER. CARRIED OUT BY KOMATSU.	0	0	450.8	0	450.8
180112-0042	SVC00198 517	01/17/2018	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1MX891	2826 HRS	REPLACE UHF ANTENNA BASE	TRAVELLED TO CAMBRIDGE PARK, REMOVED INTERIOR PANELS AND RUN NEW ANTENNA BASE AND CABLE , REFIT PANELS AND TEST OPERATION ALL OK.	160.7	20	0	58	238.7
171214-0041	SVC00197 410	12/20/2017	1H0103	ID - EARTHMOVING	184_INT	S	Service	1MX891		S1 SAMPLE SERVICE	TRAVELLED TO CAMBRIDGE, CARRIED OUT S1 SAMPLE SERVICE AS PER SERVICE SHEET	160.7	30.92	0	58	249.62
171117-0055	SVC00196 532	11/28/2017	1H0103	ID - EARTHMOVING	184FIELDS	R	Sundries	1MX891	2663 HRS	CHECK NOISE BEHIND CAB AND AD	TRAVELLED TO CAMBRIDGE, CHECK NOISE BEHIND CAB AND ADJUST FAN BELTS, CHECK AND ADJUST ENGINE BELTS TO STOP SLIPPING, REMOVE COVER AND CHECK NOISE AT BACK OF CAB , CHECK CAB MOUNTS ETC TO CHECK FOR MOVEMENT , FOUND ALL OK, REFIT COVERS	160.7	0	0	45.5	206.2
171018-0027	SVC00194 554	10/24/2017	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1MX891	2515 Hrs	SWAP OVER TILT HEAD HOSES	SWAP OVER TILT HEAD HOSES CHECK TILT HEAD OPERATION, FOUND UNIT TO OPERATE OPPOSITE TO JOY STICK OPERATION. TRACE HOSES BACK TO CHANGE OVER SOLINOID AND SWAP HOSES OVER. TEST OPERATE AND TESTED OK TRAVEL CAMBRIDGE	80.35	0	0	30	110.35
170915-0064	SVC00192 629	10/11/2017	1H0103	ID - EARTHMOVING	184_INT	S	Service	1MX891	2479 HRS	S1 B SERVICE	CARRIED OUT S1 B SERVICE AS PER SCHEDULE	369.08	133.24	0	23.5	525.82
170721-0050	SVC00190 011	07/31/2017	1H0103	ID - EARTHMOVING	184_INT	S	Service	1MX891	2274 HRS	S1 SAMPLE SERVICE	TRAVELLED TO RHH, CARRIED OUT S1 SAMPLE SERVICE ONLY	120.53	29.04	0	30	179.57

170529-0073	SVC00187 048	06/30/2017	1H0103	ID - EARTHMOVING	186_INT	R	Hydraulic	1MX891	NA	SET UP FOR ROTARY CUTTER	SET UP FOR ROTARY CUTTER . WIRE IN RELAY AND SWITCH AS REQUIRED. WIRED IN DIN PLUG AND COIL.TESTED OK MAKE MOUNTING PLATES FOR 6 WAY VALVE ANDCROSS OVER RELIEF VALVES , PAINT PLATES AND FIT TO UNIT. MOUNT VALVES AND MAKE UP AND FIT FLEXIBLE AND STEEL HOSES AND PIPES. RUN WIRING AND FIT SWITCHES FOR CROSS OVER RELIEF VALVE . TOP UP HYDRAULIC OIL AND ADJUST FLOWS AND PRESSURES CLEAN UP WORK AREA AFTER REPAIRS.	3747.83	1343.49	0	10	5101.32
170515-0020	SVC00186 247	05/17/2017	1H0103	ID - EARTHMOVING	184_INT	R	Trays/Buckets	1MX891	NA	CHECK HEAD PLATE FITMENT	TRAVELLED TO OLD BEACH, CHECK HEAD PLATE FITMENT, FOUND HEAD PLATE NON COMPATIBLE WITH QUICK HITCH ON MACHINE, MEASURED PIN CENTRES FOR ALTERATIONS TO BE CARRIED OUT, RETURN TRAVEL	321.4	0	0	78.5	399.9
170505-0057	SVC00185 752	05/10/2017	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1MX891	2054 hrs	REMOVE SPARK ARRESTER	REMOVE SPARK ARRESTER AND FIT NEW ELBOW ON MUFFLER OUTLET PIPE SUPPLY OPERATOR WITH 2 X HYD ADAPTORS FOR BREAKER CIRCUIT TO GO FROM 13 TON TO 8 TON ATTACHMENT	80.35	43.3	0	0	123.65
170405-0062	SVC00184 522	04/10/2017	1H0103	ID - EARTHMOVING	186_INT	R	Sundries	1MX891	1971 HRS	REPAIR NED KELLY LOCK	REPAIR NED KELLY LOCK ON FUEL TANK, REPLACE MISSING BOLT FROM TRACK MOTOR COVER PLATE REMOVE AND REPLACE BROKEN MIRROR	110.13	151.96	0	0	262.09
170309-0015	SVC00183 490	03/21/2017	1H0103	ID - EARTHMOVING	186_INT	R	Electrical	1MX891	1865 hrs	JUMP START AND CHECK OVER	TRAVEL SELFS POINT AND JUMP START UNIT, CHECK HOW UNIT WIRED FOR TRIMBLE SYSTEM. RETURN LA	115.34	0	0	0	115.34

170310-0025	SVC00183 464	03/21/2017	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1MX891	1870 HRS	REWIRE TRIMBLE SYSTEM	TRAVELLED TO CALTEX, REWIRE TRIMBLE SYSTEM FROM 12 VOLT TO 24 VOLT OFF BATTERY ISOLATOR DUE TO DISCHARGING ONE BATTERY DURING OPERATION	160.7	0	0	20.5	181.2
170216-0049	SVC00181 679	02/23/2017	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1MX891	1770 HRS	JUMP START, REPLACE FAULTY BAT	JUMP START, REPLACE FAULTY BATTERY, BATTERY REPLACED UNDER PARTS WARRANTY	200.88	0	0	25	225.88
170119-0059	SVC00180 653	01/24/2017	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1MX891	1681 HRS	Replace batteries	TRAVELLED TO IMPACT, CHECK AND JUMP START UNIT, REMOVE AND REPLACE FAULTY BATTERIES	200.88	242.33	0	28.75	471.96
161017-0021	SVC00176 162	10/25/2016	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1MX891		SUPPLY TOP UP OIL	SUPPLY TOP UP OIL	0	40.58	0	0	40.58
160719-0023	SVC00171 860	08/02/2016	1H0103	ID - EARTHMOVING	186_INT	R	Engine	1MX891	1054 HRS	FIT SPARK ARRESTOR TO UNIT	FIT SPARK ARRESTOR TO UNIT PARK UNIT IN WORKSHOP CUT MUFFLER OUTLET PIPE BEFORE BEND ,WELD OUTLET BEND TO SPARK ARRESTER AND FIT ARRESTER TO UNIT DISCONNECT STROBE LIGHT AND PARK UNIT BACK ON WASH BAY	238.88	32.26	0	12	283.14
160630-0037	SVC00170 456	07/04/2016	1H0103	ID - EARTHMOVING	184_INT	R	Booms	1MX891	944hrs	REPLACE GREASE NIPPLES IN QUIC	CUT OFF GREASE NIPPLE PROTECTORS ON H LINK, REMOVED BROKEN GREASE NIPPLES AND FIT PLUGS TO STOP DIRT ENTRY	157.5	0	0	8	165.5
151102-0021	SVC00158 952	05/17/2016	1H0103	ID - EARTHMOVING	182_INT	F	Sundries	1MX891		FIT UP AS PER SHEET	FIT UP AS PER SHEET. Rod protectors, Front screen. kelly lock.	2712.69	984.29	0	0	3696.98
160516-0066	SVC00168 071	05/16/2016	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1MX891	706	TIDY UP TRIMBLE WIRING	RESECURED TRIMBLE WIRING AND TAPED UP CUT IN OTHER CABLE COVERING.	118.13	0	0	6	124.13

151019-0034	SVC00159133	11/19/2015	1H0103	ID - EARTHMOVING	181_INT	F	Sundries	1MX891	FIT HB DECALS TO MACHINE	FIT HB DECALS TO MACHINE PAINT KELLY BOX ON DIESEL LOCK ASSIST TOPCON WITH WELDING WHILE FITTING UP GPS UNIT	750.78	42.83	147	35	975.61
-------------	-------------	------------	--------	------------------	---------	---	----------	--------	--------------------------	---	--------	-------	-----	----	--------

Applied filters:
Posted_Date is on or after 01/01/1900
Equipment_ID is 1MX891