



EQUIPMENT SALES & SERVICE LIMITED

Tel: 416-249-8141 Fax: 416-249-8912
Toll Free: 800-268-0679 www.essltd.com

MANAGED COMPANIES
Platinum member

WORK SAFE

Ship to: Drainville Ltd

Invoice to: Drainville Ltd
1 Hickory Tree Road
Suite #1510
York ON M9N 3W4

Branch Toronto		
Date 04/05/21	Time 12:15:35 (O)	Page 03
Account No. DRAIN010	Phone No. 4169386824	Work Order No. W36847
Ship Via PICK UP	Purchase Order DENIS	
Hours to Complete		
Date	Salesperson APA	

SERVICE WORK ORDER

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
007537		80040066		
EXCAVATOR	1			
TXC225LC-2	2			
CORRECTION:				
Cut off the damaged pedestal weldment, ground surfaces flat then a new pedestal was manufactured and welded in place.				
SUBLETL		CARRIER ROLLER	1	780.00
				LABOR 881.60
				SUBLET 780.00
11040001	21015001		SEGMENT TOTAL==>	1661.60

SEGMENT# 4 5 INTER .	01/05/21	01/05/21	01/29/21	
Recoil Springs Broken				6.00
CORRECTION:				
Recoil springs are broken, extract and replace both the idler and recoil spring assemblies.				
K1038864		RECOIL ASSY	2 N	1810.00
				PARTS 3620.00
				LABOR 410.35
11040001			SEGMENT TOTAL==>	4030.35

SEGMENT# 5 5 INTER .	01/05/21	01/05/21	01/29/21	
Check Final Drive Levels/Leakage				4.00
COMPLAINT:				
Customer requested that we check the final drive oil level and oil condition				
CORRECTION:				
Found the LH final drive oil very low and the remaining oil is discolored, very viscous and contaminated. The RH final drive oil level is also low. Drained both final drive compartments. Refilled with T010 powertrain oil. Powered the final drives free-wheeled with no load to flush contamination and debris from the compartment. Drained and				

CONTINUED ON PAGE 04

CONFIRMATION OF WORK PERFORMED Correction:

Customer Signature: _____

Details describing the cause and correction as well as all other related charges for labour, mileage, sundries and taxes will be included on the Service Invoice. If nobody is available for signature, this report will be emailed or faxed to the customer. E & O E