

**Registration** 97620C  
**VIN** RYUNDG91T00010391  
**Model** 2021 Hitachi Loader ZW150PL-5B  
**Call Sign ID** HWL3

**EXP:** 10/08/2026

**COI EXPIRY:** N/A

Date	Repairer	Job Card if known	Odometer/Hours	Work carried out
21.05.21	Hitachi		0	Purchase new Loader ZW150PL-5B_9
7.10.21	Hitachi - Brodie Peter Holland	Report 321320	253	250 hour service
3.12.21	Hitachi	WO00133837		500 hour service
27.2.22	Hitachi		700	750 hour service
6.6.22	Hitachi			Propeller shafts and oil leak on dif fixed
21.6.22	Hitachi			1000 hour service
31.08.22	Hitachi			New cutting edges
31.10.22	Hitachi		1274	1250 hour service
8.1.23	Hitachi		1422	1500 hour service
8.5.23	Hitachi		1804	1750 hour service
31.5.23	Hitachi			2000 hour service
23.06.23	Hitachi			Fuel dilution in Engine oil
18.7.23	Hitachi			Slow Hydraulics issue
28.7.23	Hitachi			Intermittent Transmission Drive Fault
11.1.24	Hitachi			2500 hour service
21.2.24	Hitachi			Oil leak and filters supplied and fixed
5.11.24	Hitachi - Brodie Peter Holland	Report 832267	2962	3000 hour service
26.11.24	Hitachi - Reece	Report 843499	3013	Machine has had reported water in the hydraulic oil as per sample. Drained out old oil replaced filters and topped back up oil to level. Checked machine for water entry points. Found the breather being most likely. As it was wet. Carried out injector cutout test looking for abnormalities. All was ok. Over fuelling was due to excessive idle time.
12.2.25	Morgan North	Job card 0001	3115	Remove and replace cutting edges, new bolts, grease
9.8.25	Hitachi - Brodie Peter Holland	Report 976189	3443	3500 hour service and fit new gasket and cover, torque bolts with loctite according to sequence required. Fit brake line and breather, bleed brakes and test machine.