



Work Order: 11786

EBID-151

Description: Inspections, Replace L/F Idler, and Repairs	4018 Hours	Date Started: 2020-12-21
Equipment: E633 John Deere 350GLC Excavator w/ Thumb	RD-2020-358 Insheet RD-2021-101 Outsheet	
Serial#: 1FF350GXPHD811881		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
41	01/05/21	AP	Vendor: 10132 Gregg Distributors LP 059-336964 Line: 2		EA	5.000	3.16	15.80
50	01/04/21	AP	Vendor: 21172 SMS Equipment Inc. PSI/71076869 Line: 1		LS	0.000	0.00	995.35
51	01/05/21	AP	Vendor: 21172 SMS Equipment Inc. PSI/71076875 Line: 1		LS	0.000	0.00	-33.44
59	01/08/21	AP	Vendor: 10132 Gregg Distributors LP 059-337874 Line: 1		EA	2.000	10.44	20.88
6	01/05/21	EMParts	T210839 Yoke-Idler		EA	1.000	214.33	214.33
11	01/05/21	EMParts	24505 Lock-Out Lever Kit		EA	1.000	19.78	19.78
12	01/05/21	EMParts	2484 Master Disconnect Switch		EA	1.000	70.09	70.09
13	01/05/21	EMParts	T210811 Pin-Track Master		EA	1.000	86.91	86.91
43	01/07/21	EMParts	30080B Switch-Toggle (SPST On-Off 20A		EA	1.000	4.40	4.40
44	01/07/21	EMParts	FXB00000979 Cover-Window Latch		EA	1.000	21.58	21.58
45	01/07/21	EMParts	J850412 Screw		EA	1.000	0.51	0.51
472	01/19/21	EMParts	Zink Free Multitool 5w20 Zink-Free Hydraul		EA	10.000	5.46	54.61

Labour Total 0.00

Parts Total 1,470.80

Miscellaneous Total 0.00

Segment: 2 Insheet Inspections

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1583	12/22/20	PR	Employee: 1575 Paul Nixon		HRS	1.500		

Labour Total 1.50

Parts Total 0.00

Miscellaneous Total 0.00

Segment: 3 Wash and Clean Cab

Cab very dirty.

Wash unit and clean cab. Unit was very greasy and the cab had lots of garbage and mud in it. -Paul

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
327	01/07/21	PR	Employee: 1575 Paul Nixon		HRS	6.500		
330	01/08/21	PR	Employee: 1575 Paul Nixon		HRS	1.000		



Work Order: 11786

Labour Total	7.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Replace L/H Idler and Yoke

Bring unit into shop, release track tension, split track. Remove damaged idler and yoke. Install new idler and yoke. Reconnect track with new pin. Install track pads, set track tension.-Paul

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
316	01/04/21	PR	Employee: 1575 Paul Nixon		HRS	2.000		
320	01/05/21	PR	Employee: 1575 Paul Nixon		HRS	2.000		

Labour Total	4.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Decal unit

Remove Renters Decals

Peel off renter decals. -Paul

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
317	01/04/21	PR	Employee: 1575 Paul Nixon		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 Check, adjust fluid levels and filters

*Top up washer fluid, check ether bottle and top up hyd. fluid.
Re-index crankcase breather.
Tighten primary fuel filter and bowl.
Fuel tank lid not venting.*

*Topped up wiper fluid, checked ether bottle (ok), topped up hyd oil level.
Re-indexed CC breather so it vents below lower house panels and not into engine bay.
Tightened primary fuel filter and bowl, they were both loose.
Check/inspect fuel tank lid. Seemed ok, looked into correct operation for that type of cap, it was working as intended.-Paul*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
324	01/06/21	PR	Employee: 1575 Paul Nixon		HRS	1.500		



Work Order: 11786

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 Repair radar and camera mounting

Rear camera/radar held on with tape and zip ties.
R/H radar mounts broken held on with zip ties.
Radar wires in cab not routed properly.

Removed all broken rubber radar mounts for both radars, mounted solid to brackets.
Straighten bent brackets, install missing bolts. Install p-clamp on wires in cab. -Paul

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
318	01/04/21	PR	Employee: 1575 Paul Nixon		HRS	1.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 8 Repair panels, window and doors

Screw missing on front slider window and cab door little cover broken.
F/R track step is bent up.
Rops top hatch not held down and rattles.
Fire Ext. bracket behind cab broken.
Tape on back window.

Replace missing/broken parts on front slider window on cab door.
Straighten bent track frame step.
Put rubber in between ROPS and hatch. Install new rubber hatch hold down bungees.
Remove and discard broken fire ext. bracket as there was another one in air filter compartment.
Remove all left over tape on cab back window from previous window replacement. -Paul

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
321	01/05/21	PR	Employee: 1575 Paul Nixon		HRS	0.500		
325	01/06/21	PR	Employee: 1575 Paul Nixon		HRS	1.000		
328	01/07/21	PR	Employee: 1575 Paul Nixon		HRS	0.500		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 9 Repair hyd. couplers, case drain and harness



Work Order: 11786

Valve in air filter compartment missing locks and handle.
 No couplers on aux. valves.
 Case drain on R/H side of boom only zip tied on and not clamped.
 Electrical harness on L/H side falling off and getting damaged.

Lock plate for valve in air filter compartment correct, but not installed correctly. Reinstalled properly and secured.
 Install new couplers and fittings onto aux. lines on stick.
 Install proper clamps and reposition case drain hose on RH side of stick/boom.
 Repair damaged harness on LH side of stick. Feed harness thru a hydraulic hose and secured hose. -Paul

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
319	01/04/21	PR	Employee: 1575 Paul Nixon		HRS	1.500		
322	01/05/21	PR	Employee: 1575 Paul Nixon		HRS	1.000		
326	01/06/21	PR	Employee: 1575 Paul Nixon		HRS	3.000		
						Labour Total	5.50	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 10 Repair P.A.S.S.

PAS not working. Check connections and battery power, ok. Found PAS to be stiff. Removed and free up, reinstall.
 Found PAS switch to be faulty in cab. Replace switch and test, working fine now. -Paul

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
323	01/06/21	PR	Employee: 1575 Paul Nixon		HRS	3.000		
						Labour Total	3.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 11 Install master disconnect switch

Unit did not have a battery lock out switch. Mount and install new switch, connect cables.-Paul

Segment: 12 Outsheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
329	01/08/21	PR	Employee: 2471 Greg Royer		HRS	3.500		
						Labour Total	3.50	
						Parts Total	0.00	
						Miscellaneous Total	0.00	



Work Order: 11786

Labour Total	30.50
Parts Total	1,470.80
Miscellaneous Total	0.00

Description: Buff and Paint Counterweight **Date Started:** 2021-04-30
Equipment: E633 John Deere 350GLC Excavator w/ Thumb
Serial#: 1FF350GXPHD811881

Segment: 1 Parts and Service

Segment: 2 Buff and Paint Counterweight

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
381	05/03/21	PR	Employee: 2623 Brenton Woolman		HRS	3.500		
1960	04/30/21	PR	Employee: 2623 Brenton Woolman		HRS	3.500		

Labour Total	7.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
382	05/04/21	PR	Employee: 2623 Brenton Woolman		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	7.50
Parts Total	0.00
Miscellaneous Total	0.00

Description: Inspections and Repairs **4030 Hours** **Date Started:** 2021-07-16
Equipment: E633 John Deere 350GLC Excavator w/ Thumb **RD-2021-226 Insheet&Outsheet**
Serial#: 1FF350GXPHD811881 **GRO#8744**

Segment: 1 Parts and Service

2 - "6m Back" Sticker

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
-------	-------------	--------	---------	--------	----	-------	-------	------------



Work Order: 12277

582 07/22/21 EMParts Dyed Diesel Dyed Diesel EA 427.750 0.87 374.24

Labour Total	0.00
Parts Total	374.24
Miscellaneous Total	0.00

Segment: 2 Inspections and Repairs

Cleaned Battery Terminals.
Grease Unit.
Cut off Corks.
Re-Position Track Steps.
Fuel.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
508	07/16/21	PR	Employee: 2395 Nickolas Schou		HRS	6.000		

Labour Total	6.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash undercarriage/machine

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
506	07/14/21	PR	Employee: 2623 Brenton Woolman		HRS	2.000		
507	07/15/21	PR	Employee: 2623 Brenton Woolman		HRS	7.000		
509	07/16/21	PR	Employee: 2623 Brenton Woolman		HRS	2.000		

Labour Total	11.00
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	17.00
Parts Total	374.24
Miscellaneous Total	0.00

Description: Inspections, 4000 Hour Service and Repairs	5293 Hours	Date Started: 2022-04-08
Equipment: E633 John Deere 350GLC Excavator w/ Thumb	RD-2022-146 Insheet	
Serial#: 1FF350GXPHD811881		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
489	04/19/23	AP	Vendor: 10321 Union Tractor Ltd. 040-228301 Line: 1		EA	2.000	55.28	110.56
490	04/19/23	AP	Vendor: 10321 Union Tractor Ltd. 040-228301 Line: 2		EA	-2.000	55.28	-110.56



Work Order: 12987

491	04/19/23	AP	Vendor: 10321 Union Tractor Ltd. 040-228301 Line: 3	EA	2.000	303.50	606.99
561	04/24/23	AP	Vendor: 10132 Gregg Distributors LP 059-539863 Line: 4	EA	2.000	9.75	19.50
565	05/04/23	AP	Vendor: 10321 Union Tractor Ltd. 040-228477 Line: 1	LS	0.000	0.00	-86.40
605	05/11/23	AP	Vendor: 10321 Union Tractor Ltd. 240-102152 Line: 1	LS	0.000	0.00	12,108.81
1357	04/27/23	AP	Vendor: 10321 Union Tractor Ltd. 040-228376 Line: 1	LS	0.000	0.00	8,705.80
1932	04/24/23	AP	Vendor: 10132 Gregg Distributors LP 059-539863 Line: 6	EA	-2.000	9.75	-19.50
1933	04/24/23	AP	Vendor: 10132 Gregg Distributors LP 059-539863 Line: 8	EA	2.000	9.75	19.50
1934	04/19/23	AP	Vendor: 10321 Union Tractor Ltd. 040-228301 Line: 4	EA	-2.000	55.28	-110.56
1935	04/19/23	AP	Vendor: 10321 Union Tractor Ltd. 040-228301 Line: 5	EA	2.000	55.28	110.56
1936	04/19/23	AP	Vendor: 10321 Union Tractor Ltd. 040-228301 Line: 6	EA	-2.000	303.50	-606.99
1937	04/19/23	AP	Vendor: 10321 Union Tractor Ltd. 040-228301 Line: 7	EA	2.000	55.28	110.56
1938	04/19/23	AP	Vendor: 10321 Union Tractor Ltd. 040-228301 Line: 8	EA	-2.000	55.28	-110.56
1939	04/19/23	AP	Vendor: 10321 Union Tractor Ltd. 040-228301 Line: 9	EA	2.000	303.50	606.99
1940	04/27/23	AP	Vendor: 10321 Union Tractor Ltd. 040-228376 Line: 2	LS	0.000	0.00	-8,705.80
1941	04/27/23	AP	Vendor: 10321 Union Tractor Ltd. 040-228376 Line: 3	LS	0.000	0.00	8,705.80
2131	05/29/23	AP	Vendor: 10401 RBC Avion Visa May 23_L Dahl Line: 1	LS	0.000	0.00	60.92
2186	05/04/23	AP	Vendor: 10321 Union Tractor Ltd. 040-228477 Line: 2	LS	0.000	0.00	86.40
2187	05/04/23	AP	Vendor: 10321 Union Tractor Ltd. 040-228477 Line: 3	LS	0.000	0.00	-86.40
2188	05/11/23	AP	Vendor: 10321 Union Tractor Ltd. 240-102152 Line: 2	LS	0.000	0.00	-12,108.81
2189	05/11/23	AP	Vendor: 10321 Union Tractor Ltd. 240-102152 Line: 3	LS	0.000	0.00	12,108.81
29	07/04/23	EMParts	51M7042 o-ring	EA	3.000	0.00	0.00
30	07/04/23	EMParts	T77857 Seal-O-Ring Face -8	EA	3.000	4.91	14.74
122	06/06/23	EMParts	4189839 Shim-101mm ID x 165mm OD x 1.2	EA	2.000	10.68	21.37
246	10/16/23	EMParts	Zinc Free Multiloil 5w20 Zink-Free Hydraulic	EA	194.000	7.90	1,532.81
259	10/16/23	EMParts	75W90 Certop SN 75W90 Gear Lube	EA	18.500	10.27	189.95
372	06/20/23	EMParts	4630525 Filter-Hydraulic Pilot	EA	1.000	43.65	43.65
373	06/20/23	EMParts	4632689 Filter-Cab Air(4S00686)	EA	1.000	68.65	68.65
374	06/20/23	EMParts	9755978 Step	EA	1.000	261.48	261.48
375	06/20/23	EMParts	AL153660 Wiper Blade-19.5" Steel Frame	EA	1.000	66.32	66.32
376	06/20/23	EMParts	AT330978 Filter-Air Primary	EA	1.000	57.08	57.08
377	06/20/23	EMParts	AT330980 Filter-Air Secondary	EA	1.000	240.92	240.92
378	06/20/23	EMParts	AT381935 Tank-Coolant	EA	1.000	384.08	384.08
379	06/20/23	EMParts	AT387542 Housing-Fuel Filter W/Primer	EA	1.000	612.95	612.95
380	06/20/23	EMParts	FYA00001490 Filter-Cab Air	EA	1.000	26.00	26.00
381	06/20/23	EMParts	FYA00003014 Vent Louver-Round	EA	1.000	38.75	38.75
382	06/20/23	EMParts	FYA00033065 Filter-Hydraulic Tank	EA	1.000	204.90	204.90
383	06/20/23	EMParts	T377531 Cover-Air Filter	EA	1.000	66.40	66.40
384	06/20/23	EMParts	TH100679 Seal-O-Ring	EA	1.000	21.41	21.41
385	06/20/23	EMParts	TH105684 Seal-O-Ring	EA	2.000	10.64	21.28
398	04/19/23	EMParts	19M8889 Bolt	EA	1.000	12.36	12.36
399	04/19/23	EMParts	4346770 Pulley-Tensioner	EA	1.000	226.76	226.76
400	04/19/23	EMParts	FF502547 V-Belt-A/C	EA	1.000	52.85	52.85
401	04/19/23	EMParts	RE542195 Seal-Front Main	EA	1.000	34.55	34.55
402	04/19/23	EMParts	RE548027 Tensioner-Belt	EA	1.000	193.81	193.81
403	04/19/23	EMParts	T428691 V-Belt	EA	1.000	67.12	67.12
406	04/19/23	EMParts	K32J2048 12-14 X 1-1/2 Hex head tec	EA	1.000	0.20	0.20
432	04/20/23	EMParts	14M7025 Nut-Wing (M10x1.5)	EA	1.000	8.26	8.26
1035	07/27/23	EMParts	4134370 Shim	EA	1.000	37.49	37.49
1036	07/27/23	EMParts	4469095 Shim-Plastic	EA	1.000	34.75	34.75
1039	07/27/23	EMParts	4189839 Shim-101mm ID x 165mm OD x 1.2mm Thk	EA	-1.000	10.68	-10.68

Labour Total	0.00
Parts Total	25,945.83
Miscellaneous Total	0.00

Segment: 2 Inspections



Work Order: 12987

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
690	04/08/22	PR	Employee: 2471 Greg Royer		HRS	2.500		
1871	06/27/23	PR	Employee: 3103 Dallas Wood		HRS	2.500		
						Labour Total		5.00
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 3 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1870	06/26/23	PR	Employee: 2623 Brenton Woolman		HRS	9.500		
						Labour Total		9.50
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 4 T/S and Repair Leaks

*R/F Pump Mounting Leaking.
 Engine Oil pan/Front Cover leaking (Clean and verify).
 Engine oil cooler seeping around mount.
 Coolant reservoir leaking at lower tube and small tubes at top.
 Fuel Filter wet all over of fuel(Clean and verify leak)
 Wiper spray doesn't function fill and test.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
793	06/20/23	PR	Employee: 3108 Zachary Dean		HRS	4.000		
795	06/21/23	PR	Employee: 3108 Zachary Dean		HRS	7.000		
1661	04/18/23	PR	Employee: 3110 Callum Deditch		HRS	2.000		
1662	04/19/23	PR	Employee: 3110 Callum Deditch		HRS	10.000		
						Labour Total		23.00
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 5 Check and Adjust pressure's

Pressure are high 40mpa

Segment: 6 Check and Repair Pins and Bushings

*Arm to Boom pins and bushings look sloppy.
 Q/A to Arm pins and bushings look sloppy.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
-------	-------------	--------	---------	--------	----	-------	-------	------------



Work Order: 12987

796	06/21/23	PR	Employee: 3103 Dallas Wood	HRS	1.500
797	06/21/23	PR	Employee: 3108 Zachary Dean	HRS	2.500

Labour Total	4.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 Check and Adjust tracks/Replace U/C

*Remove tracks to be sent out and pad swapped.
 Remove and replace all undercarriage except for RH idler.
 Had to extract one broken bolt for front RH carrier roller.
 Torque all hardware to spec.
 Install new tracks and tighten.
 -Paul*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
800	06/23/23	PR	Employee: 3108 Zachary Dean		HRS	1.500		
2565	05/03/23	PR	Employee: 1575 Paul Nixon		HRS	8.500		
2566	05/04/23	PR	Employee: 1575 Paul Nixon		HRS	5.000		
2567	05/08/23	PR	Employee: 1575 Paul Nixon		HRS	1.000		

Labour Total	16.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 8 4000 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
798	06/22/23	PR	Employee: 3108 Zachary Dean		HRS	7.500		

Labour Total	7.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 9 Repair panels, fix broken bolts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
794	06/20/23	PR	Employee: 3108 Zachary Dean		HRS	5.500		
799	06/22/23	PR	Employee: 3108 Zachary Dean		HRS	2.000		
801	06/23/23	PR	Employee: 3108 Zachary Dean		HRS	4.000		



Work Order: 12987

Labour Total	11.50
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	76.50
Parts Total	25,945.83
Miscellaneous Total	0.00

Description: Rental Return Emsco	5293 Hours	Date Started: 2022-04-08
Equipment: E633 John Deere 350GLC Excavator w/ Thumb	RD-2022-146 Insheet	
Serial#: 1FF350GXPHD811881		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
134	04/08/22	EMParts	Dyed Diesel Dyed Diesel		EA	49.980	1.34	66.80
887	05/31/22	EMParts	9755978 Step		EA	3.000	141.19	423.57
888	05/31/22	EMParts	FF513253 Cover-Bottom		EA	1.000	395.90	395.90
889	05/31/22	EMParts	FYA00003014 Vent Louver-Round		EA	1.000	35.53	35.53

Labour Total	0.00
Parts Total	921.80
Miscellaneous Total	0.00

Segment: 2 Wash and Clean Cab

Replace Stay back stickers after painting counter weight.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
301	07/08/22	PR	Employee: 2623 Brenton Woolman		HRS	1.500		
792	06/23/23	PR	Employee: 2623 Brenton Woolman		HRS	3.000		
870	07/11/22	PR	Employee: 2623 Brenton Woolman		HRS	9.500		
871	07/12/22	PR	Employee: 2623 Brenton Woolman		HRS	9.500		
872	07/13/22	PR	Employee: 2623 Brenton Woolman		HRS	5.500		

Labour Total	29.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Repair Panels, steps and Doors



Work Order: 12988

Belly Pans very bent and ripped through.
 Mechanic's wire tied up on comp. door to hold tarp.
 L/R Heater vent broken.
 3 Step extension missing and R/F Bent.
 Rear Compartment door's are dented.
 Upper Panel above swing missing and broken bolts.
 Broken bracket on valve below washer fluid reservoir.
 Roof cage latch broken/not latched.
 P.A.S.S switch loose.
 Camera display visor broken corner.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
791	06/19/23	PR	Employee: 3108 Zachary Dean		HRS	5.000		
1659	04/20/23	PR	Employee: 3110 Callum Deditch		HRS	9.000		
1660	04/21/23	PR	Employee: 3110 Callum Deditch		HRS	4.000		

Labour Total	18.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Remove Customer Decals

Labour Total	47.00
Parts Total	921.80
Miscellaneous Total	0.00

Description: Repair back up alarm	Date Started: 2023-09-01
Equipment: E633 John Deere 350GLC Excavator w/ Thumb	
Serial#: 1FF350GXPHD811881	

Segment: 1 Parts

Segment: 2 Repair backup alarm

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1527	08/29/23	PR	Employee: 3110 Callum Deditch		HRS	1.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00



Work Order: 14297

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Description: Inspection and Repairs	5629 Hours	Date Started: 2023-10-19
Equipment: E633 John Deere 350GLC Excavator w/ Thumb	RD-2023-277 Insheet RD-2023-313 Outsheet	
Serial#: 1FF350GXPHD811881		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
200	11/02/23	AP	Vendor: 10321 Union Tractor Ltd. 040-230393 Line: 1		EA	1.000	331.25	331.25
201	11/02/23	AP	Vendor: 10321 Union Tractor Ltd. 040-230393 Line: 2		EA	1.000	55.28	55.28
202	11/02/23	AP	Vendor: 10321 Union Tractor Ltd. 040-230393 Line: 3		EA	-1.000	55.28	-55.28
176	11/09/23	EMParts	DZ115246 Actuator		EA	1.000	1,725.51	1,725.51
204	11/14/23	EMParts	4649874 Hydraulic xy		EA	1.000	1,021.93	1,021.93
1052	11/28/23	EMParts	5P8249 Washer-7/8" Hard		EA	4.000	1.50	6.00
1053	11/28/23	EMParts	9253782 Roller		EA	1.000	303.50	303.50
1054	11/28/23	EMParts	J932202 Bolt		EA	4.000	15.61	62.44

Labour Total	0.00
Parts Total	3,450.63
Miscellaneous Total	0.00

Segment: 2 Inspections

Outsheet unit, checkover, found front left bottom roller failed, replaced.
-Paul

Segment: 3 Wash/Paint counterweight

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1588	10/27/23	PR	Employee: 2623 Brenton Woolman		HRS	4.500		
2535	10/30/23	PR	Employee: 2623 Brenton Woolman		HRS	5.000		

Labour Total	9.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 T/S and Repair Codes

Active code-ECU-641-12

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
489	11/02/23	PR	Employee: 3131 Shawn Rowe		HRS	3.000		
493	11/07/23	PR	Employee: 3131 Shawn Rowe		HRS	3.000		



Work Order: 14412

2536 10/31/23 PR Employee: 3131 Shawn Rowe HRS 1.000

Labour Total	7.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Repair leaks

*R/H final drive oil leaking from behind motor cover.
Arm cylinder barrel end hose leaking at base of boom crimp.
Rear Battery leaking acid a lot.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
490	11/02/23	PR	Employee: 3131 Shawn Rowe		HRS	6.000		
492	11/03/23	PR	Employee: 3131 Shawn Rowe		HRS	4.500		
494	11/07/23	PR	Employee: 3131 Shawn Rowe		HRS	3.000		
495	11/08/23	PR	Employee: 3131 Shawn Rowe		HRS	2.500		

Labour Total	16.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 Repair lights, A/C, Air Filter cover and wiper

*R/H boom light out.
A/C feels weak.
Engine air filter cover not seating properly.
Wiper fluid empty.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
491	11/02/23	PR	Employee: 3131 Shawn Rowe		HRS	0.500		
496	11/08/23	PR	Employee: 3131 Shawn Rowe		HRS	0.500		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	33.50
Parts Total	3,450.63
Miscellaneous Total	0.00

Description: Rental Return Legacy	5629 Hours	Date Started: 2023-10-19
Equipment: E633 John Deere 350GLC Excavator w/ Thumb	RD-2023-277 Insheet RD-2023-312 Outsheets	
Serial#: 1FF350GXPHD811881		

Segment: 1 Parts



Work Order: 14413

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
642	11/16/23	EMParts	5W40 Spectra 5W40		I	29.000	7.70	223.35
643	11/16/23	EMParts	Zinc Free Multoil 5w20 Zink-Free Hydraul		EA	18.500	7.20	133.19
1138	10/31/23	EMParts	4632689 Filter-Cab Air(4S00686)		EA	1.000	77.52	77.52
1139	10/31/23	EMParts	AT330978 Filter-Air Primary		EA	1.000	57.08	57.08
1140	10/31/23	EMParts	AT365869 Filter-Fuel / Water Separator		EA	1.000	91.65	91.65
1141	10/31/23	EMParts	DZ118283 Filter-Oil		EA	1.000	35.19	35.19
1142	10/31/23	EMParts	FYA00001490 Filter-Cab Air		EA	1.000	51.55	51.55
1143	10/31/23	EMParts	FYA00070858 Strainer-Fuel		EA	1.000	112.63	112.63
1144	10/31/23	EMParts	RE525523 Filter Kit-Fuel		EA	1.000	133.05	133.05

Labour Total	0.00
Parts Total	915.21
Miscellaneous Total	0.00

Segment: 2 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1585	10/24/23	PR	Employee: 2623 Brenton Woolman		HRS	5.000		
1586	10/25/23	PR	Employee: 2623 Brenton Woolman		HRS	9.500		
1587	10/26/23	PR	Employee: 2623 Brenton Woolman		HRS	9.500		
1589	10/27/23	PR	Employee: 2623 Brenton Woolman		HRS	5.000		

Labour Total	29.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 350 Hour Service and top up fluids

*Cab air filters very dirty, due for service.
No fuel screen.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
486	11/01/23	PR	Employee: 3131 Shawn Rowe		HRS	3.500		
488	11/08/23	PR	Employee: 3131 Shawn Rowe		HRS	0.500		

Labour Total	4.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Repair Panels, handle, mirror and remove decals

*Several bent belly pans.
Adjust mirrors.
hydraulic compartment door handle bent.
Remove renter's decals.*



Work Order: 14413

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
487	11/01/23	PR	Employee: 3131 Shawn Rowe		HRS	6.000		

Labour Total	6.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	39.00
Parts Total	915.21
Miscellaneous Total	0.00

Description: Reg Maintennace	GRO11780	Date Started: 2024-07-05
Equipment: E633 John Deere 350GLC Excavator w/ Thumb	5634 hours	
Serial#: 1FF350GXPHD811881		

Segment: 1 parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
455	11/21/24	AP	Vendor: 10132 Gregg Distributors LP 059-697563 Line: 1		EA	1.000	1.81	1.81

Labour Total	0.00
Parts Total	1.81
Miscellaneous Total	0.00

Segment: 2 Complete In/Out sheet

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
129	07/04/24	PR	Employee: 3119 Shawn Dittmer		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 wash

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
648	07/11/24	PR	Employee: 22 Garrett Nelson		HRS	6.000		
649	07/16/24	PR	Employee: 22 Garrett Nelson		HRS	1.000		



Work Order: 14945

Labour Total	7.00
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	9.00
Parts Total	1.81
Miscellaneous Total	0.00

Description: Repair Leaks	Unit at BlackRod Job#702	Date Started: 2024-07-22
Equipment: E633 John Deere 350GLC Excavator w/ Thumb	Hours: 5641	
	Next service hours:5881	
Serial#: 1FF350GXPHD811881	GRO# 10247	

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
311	07/22/24	EMParts	4033725 Ring-Backup		EA	2.000	3.60	7.20
312	07/22/24	EMParts	4506418 Seal-O-Ring		EA	1.000	3.57	3.57
313	07/22/24	EMParts	TH101926 Seal-O-Ring		EA	2.000	8.51	17.02
826	07/26/24	EMParts	Zinc Free Spectra MV 5W20 Zinc-Free Hydr		EA	19.000	7.20	136.79

Labour Total	0.00
Parts Total	164.58
Miscellaneous Total	0.00

Segment: 2 Repair Leaks

Replaced o-ring on final relief valve
-Zac 07/19/24

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
650	07/19/24	PR	Employee: 3108 Zachary Dean		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	2.00
Parts Total	164.58
Miscellaneous Total	0.00

Description: Repair Leaks	Hours:5747	Date Started: 2024-08-13
Equipment: E633 John Deere 350GLC Excavator w/ Thumb	Next Service hours:5881	
	GRO#10288	
Serial#: 1FF350GXPHD811881		



Work Order: 15012

Segment: 1 Parts

Segment: 2 Repair leaks on boom

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
448	08/07/24	PR	Employee: 3103 Dallas Wood		HRS	1.000		

Labour Total 1.00

Parts Total 0.00

Miscellaneous Total 0.00

Labour Total 1.00

Parts Total 0.00

Miscellaneous Total 0.00

Description: 350 Hour Service	Unit at BlackRod	Date Started: 2024-08-27
Equipment: E633 John Deere 350GLC Excavator w/ Thumb	Hours:5895	
Serial#: 1FF350GXPHD811881	Next Service:6195	
	GRO#10345	

Segment: 1 Parts

4 X Grease
-Zac

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
53	09/04/24	EMParts	5W40 Spectra Xtreme 5W40 (CK-4)		I	22.000	7.94	174.66
597	08/27/24	EMParts	4632689 Filter-Cab Air(4S00686)		EA	1.000	72.96	72.96
598	08/27/24	EMParts	AT330978 Filter-Air Primary		EA	1.000	91.72	91.72
599	08/27/24	EMParts	AT365869 Filter-Fuel / Water Separator		EA	1.000	94.78	94.78
600	08/27/24	EMParts	FYA00001490 Filter-Cab Air		EA	1.000	27.62	27.62
601	08/27/24	EMParts	RE521420 Filter-Oil		EA	1.000	33.96	33.96
602	08/27/24	EMParts	RE525523 Filter Kit-Fuel		EA	1.000	122.14	122.14
603	08/27/24	EMParts	RS5430 Air-Filter		EA	1.000	0.00	0.00

Labour Total 0.00

Parts Total 617.84

Miscellaneous Total 0.00

Segment: 2 350 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1334	08/29/24	PR	Employee: 3108 Zachary Dean		HRS	2.500		



Work Order: 15039

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Repair Leaks

Labour Total	2.50
Parts Total	617.84
Miscellaneous Total	0.00

Description: Repair Pump Drive Leak	Unit at BlackRod site.	Date Started: 2024-09-06
Equipment: E633 John Deere 350GLC Excavator w/ Thumb	Hours:5961	
Serial#: 1FF350GXPHD811881	Next service hours: 6195	
	GRO#10354	

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
75	09/06/24	EMParts	FYB00000680 Breather-Pump Drive		EA	1.000	103.41	103.41
76	09/06/24	EMParts	FYB00001128 Bearing-Pump Drive		EA	1.000	67.29	67.29
77	09/06/24	EMParts	FYB00001129 Bearing-Pump Drive		EA	1.000	94.94	94.94
78	09/09/24	EMParts	TH105684 Seal-O-Ring		EA	2.000	10.58	21.15
84	09/09/24	EMParts	9742779 Gasket		EA	1.000	27.51	27.51
85	09/09/24	EMParts	CH11570 Seal-O-Ring		EA	1.000	5.26	5.26
156	09/12/24	EMParts	966993 Seal-O-Ring		EA	2.000	3.08	6.15
157	09/12/24	EMParts	AT264339 Seal-O-Ring		EA	1.000	14.55	14.55
158	09/12/24	EMParts	TH109453 Seal-Lip Type		EA	1.000	80.31	80.31
159	09/12/24	EMParts	TH105684 Seal-O-Ring		EA	1.000	10.58	10.58
160	09/12/24	EMParts	5W40 Spectra Xtreme 5W40 (CK-4)		I	2.500	7.94	19.85
161	09/12/24	EMParts	Zinc Free Spectra MV 5W20 Zinc-Free Hydr		EA	20.000	7.20	143.99

Labour Total	0.00
Parts Total	594.99
Miscellaneous Total	0.00

Segment: 2 Repair Pump Drive Leak

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
406	09/06/24	PR	Employee: 3103 Dallas Wood		HRS	4.500		
407	09/09/24	PR	Employee: 3103 Dallas Wood		HRS	7.000		
408	09/10/24	PR	Employee: 3103 Dallas Wood		HRS	4.500		

Labour Total	16.00
Parts Total	0.00
Miscellaneous Total	0.00



Work Order: 15064

Labour Total	16.00
Parts Total	594.99
Miscellaneous Total	0.00

Description: Inspections, 1000 Hour Service and Repairs	6244 Hours	Date Started: 2024-11-21
Equipment: E633 John Deere 350GLC Excavator w/ Thumb	RD-2024-226 Insheet	
Serial#: 1FF350GXPHD811881		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
56	04/08/25	EMParts	1237106 Bushing-Boom Cylinder(350)		EA	2.000	279.05	558.10
57	04/08/25	EMParts	7N0296 Ether Cyinder-18oz		EA	1.000	111.93	111.93
58	04/08/25	EMParts	FYA00007743 Seal Kit-Boom Cylinder(350)		EA	2.000	798.05	1,596.10
73	04/09/25	EMParts	R522690 Gasket-Fan Pump to Engine Cove		EA	1.000	18.86	18.86
74	04/09/25	EMParts	R531534 Gasket-Auxiliary Drive		EA	1.000	18.82	18.82
129	04/14/25	EMParts	4346770 Pulley-Tensioner		EA	1.000	351.50	351.50
130	04/14/25	EMParts	FF502547 V-Belt-A/C		EA	1.000	83.74	83.74
462	04/29/25	EMParts	TRV208871 Monitor-7" Camera and Radar (O		EA	1.000	1,665.00	1,665.00
791	11/28/24	EMParts	4630525 Filter-Hydraulic Pilot		EA	1.000	45.47	45.47
792	11/28/24	EMParts	4632689 Filter-Cab Air(4S00686)		EA	1.000	67.72	67.72
793	11/28/24	EMParts	AT330978 Filter-Air Primary		EA	1.000	91.72	91.72
794	11/28/24	EMParts	AT330980 Filter-Air Secondary		EA	1.000	240.92	240.92
795	11/28/24	EMParts	AT365869 Filter-Fuel / Water Seperator		EA	1.000	170.60	170.60
796	11/28/24	EMParts	FYA00001490 Filter-Cab Air		EA	1.000	40.38	40.38
797	11/28/24	EMParts	FYA00003014 Vent Louver-Round		EA	1.000	44.23	44.23
798	11/28/24	EMParts	FYA00033065 Filter-Hydraulic Tank		EA	1.000	200.61	200.61
799	11/28/24	EMParts	FYA00070858 Strainer-Fuel		EA	1.000	128.90	128.90
800	11/28/24	EMParts	RE521420 Filter-Oil		EA	1.000	33.96	33.96
801	11/28/24	EMParts	RE541746 Filter-Fuel Kit		EA	1.000	117.46	117.46
817	11/29/24	EMParts	TH100679 Seal-O-Ring		EA	1.000	20.95	20.95

Labour Total	0.00
Parts Total	5,606.97
Miscellaneous Total	0.00

Segment: 2 Inspections

Segment: 3 Wash and clean cab, paint

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
153	06/02/25	PR	Employee: 3087 Bogdan (Dan) Korchinskii		HRS	3.000		
281	04/01/25	PR	Employee: 2623 Brenton Woolman		HRS	9.500		
282	04/02/25	PR	Employee: 2623 Brenton Woolman		HRS	9.500		
283	04/03/25	PR	Employee: 2623 Brenton Woolman		HRS	9.500		
1198	03/31/25	PR	Employee: 2623 Brenton Woolman		HRS	9.500		



Work Order: 15162

Labour Total	41.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 1000 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
284	04/08/25	PR	Employee: 3108 Zachary Dean		HRS	8.500		

Labour Total	8.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Repair Louvers, Monitor, Rops,

Segment: 6 Repair leaks

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
285	04/10/25	PR	Employee: 3103 Dallas Wood		HRS	1.500		
286	04/10/25	PR	Employee: 3108 Zachary Dean		HRS	8.000		
287	04/11/25	PR	Employee: 3108 Zachary Dean		HRS	9.500		
591	04/14/25	PR	Employee: 3108 Zachary Dean		HRS	7.000		

Labour Total	26.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 Repair Power boost

Labour Total	75.50
Parts Total	5,606.97
Miscellaneous Total	0.00