



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #785
Invoice Number:
PO Number:









WORK ORDER
























WORK ORDER DETAILS




















EE25-2

















Issue Date:	Mon, Oct 3, 2022 9:48 AM	#30 2016 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X2GR983194
Actual Start Date:	Thu, Sep 29, 2022 7:00 AM	License Plate:	
Expected Completion Date:		Operator:	Heinz Zier
Actual Completion Date:	Fri, Oct 7, 2022 4:37 PM	Type:	Tandem
Duration:	8 days 9 hrs 37 mins	Group:	
Repair Priority Class:	Non-Scheduled	Odometer:	716,703km (voided meter)
Status:	Completed	Secondary Meter:	18,854hr
Issued By:			
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$6.09	\$0.00	\$6.09
 MICHAEL ABLOG (Contact) 	0.21 hrs \$29.00		\$6.09
 Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$6.02	\$6.16	\$12.18
 Rickylynn Peters (Contact)	0.28 hrs \$21.50		\$6.02
 MXFPSC30 (Part) - Main (Archived) GREASE PRECISION TUBE	1 tube \$6.16		\$6.16
 Truck Preventative Maintenance Inspection	\$28.50	\$0.00	\$28.50
 Ross Cowell (Contact)	1 hr \$28.50		\$28.50

Item	Labor	Parts	Subtotal
	\$5.99	\$0.00	\$5.99
Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.			
 Ross Cowell (Contact)	0.21 hrs \$28.50		\$5.99
 Check Diff and Trans Oil	\$5.99	\$0.00	\$5.99
 Ross Cowell (Contact)	0.21 hrs \$28.50		\$5.99
 Torque Wheels Verify wheels are properly torqued	\$5.99	\$0.00	\$5.99
 Ross Cowell (Contact)	0.21 hrs \$28.50		\$5.99
 Walk Around Inspection	\$11.60	\$0.00	\$11.60
 MICHAEL ABLOG (Contact) 	0.4 hrs \$29.00		\$11.60
 Tire Condition and Pressure Inspection Check all tires  -Need New Drive Tires	\$86.00	\$0.00	\$86.00
 Rickylynn Peters (Contact)	4 hrs \$21.50		\$86.00
 gear pump sideplugs leaking	\$5.99	\$0.00	\$5.99
 Ross Cowell (Contact)  taped	0.21 hrs \$28.50		\$5.99
 a2 output yoke loose	\$14.79	\$24.55	\$39.34
 MICHAEL ABLOG (Contact)  replaced nut	0.51 hrs \$29.00		\$14.79
 FGRKIT2637 (Part) · Main ROCKWELL DIFF OUTPUT,	1 ea \$24.55		\$24.55
 Engine Oil & Filter Replacement	\$22.50	\$234.66	\$257.16
 JOE NEMEC (Contact)	0.25 hrs \$90.00		\$22.50
 MXF15W40 (Part) ENGINE OIL, 15W40 BUL	50 L \$3.84		\$192.00
 BALBD50000 (Part) · Main (Archived) OIL FILTER	1 ea \$42.66		\$42.66

Item	Labor	Parts	Subtotal
 Engine Rebuild  Engine pressuring up cooling system. Tore down engine found cracked cylinder head. Liner heights were all around 0.009". Removed cylinders and cut counterbores. Installed new liners with shims to bring height to 0.012". Installed new pistons and rod bearings. Installed new cylinder head with all new gaskets and seals. Replaced front gear housing and all gaskets.	\$4,740.00	\$11,643.88	\$16,383.88
 JOE NEMEC (Contact) 40 hrs \$90.00			\$3,600.00
 Ross Cowell (Contact) 40 hrs \$28.50			\$1,140.00
 GWK1135304 (Part) · Main (Archived) ORING OIL COOLER COOL 1 ea \$26.24			\$26.24
 GWK4966454CUM (Part) · Main CLAMP TURBO> BELLOWS 1 ea \$61.02			\$61.02
 GWK5298564 (Part) · Main SHIM 6 ea \$65.82			\$394.92
 TTD2264659 (Part) · Main MAHLE CYLINDER SLEEVE 6 ea \$150.00			\$900.00
 GWK3411881CUM (Part) · Main INTERNAL SNAP RING, O 1 ea \$7.16			\$7.16
 TTDX2881879 (Part) · Main (Archived) ISX PISTON KIT 6 ea \$551.03			\$3,306.18
 GWK1135304 (Part) · Main (Archived) ORING OIL COOLER COOL 1 ea \$26.24			\$26.24
 GWK4952631 (Part) · Main THERMOSTAT OIL DELETE 1 ea \$133.11			\$133.11
 GWK4955831CUM (Part) · Main OIL COOLER KIT 1 ea \$582.10			\$582.10
 GWK4357177CUM (Part) · Main PRESSURE RELIEF VALVE 1 ea \$16.93			\$16.93
 FGR3483682 (Part) · Main OIL COOLER GASKET KIT 1 ea \$123.90			\$123.90
 GWK5440813 (Part) · Main AIR COMPRESSOR GASKET 1 ea \$16.07			\$16.07
 GWK4988280 (Part) · Main GASKET POWER STEERING 1 ea \$4.10			\$4.10
 GWK5414049 (Part) · Main FUEL PUMP GASKET 1 ea \$27.14			\$27.14
 GWK3685173CUM (Part) · Main CRANK SEAL FRONT CUMM 1 ea \$80.70			\$80.70

Item		Labor	Parts	Subtotal
 GWK4318947CUM (Part) · Main THERMOSTAT WATER 180	1 ea \$87.93			\$87.93
 GWK186780 (Part) · Main SEAL 2 1/8"	1 ea \$2.22			\$2.22
 GWK3678724 (Part) · Main WATER PUMP-BLOCK O-RI	1 ea \$3.93			\$3.93
 GWK4059172 (Part) · Main WATER PUMP INLET O-RI	1 ea \$7.99			\$7.99
 GWK3685556 (Part) · Main FRONT COVER GASKET-AD	1 ea \$12.96			\$12.96
 GWK5060640 (Part) · Main A/C BELT	1 ea \$22.73			\$22.73
 GWK5120910 (Part) · Main (Archived) FAN BELT W900	1 ea \$83.43			\$83.43
 GWK3164273 (Part) · Main ELECTRICAL CONNECTOR,	1 ea \$15.89			\$15.89
 GWK2866337CUM (Part) · Main EXHAUST GASKET 5" CIR	1 ea \$16.70			\$16.70
 GWK90-0012 (Part) · Main V BAND CLAMP	1 ea \$15.05			\$15.05
 GWKK028-2490-1 (Part) STANDOFF BRACKET	1 ea \$19.00			\$19.00
 NTXP550830 (Part) · Main POWER STEERING FILTER S/AS PT9354-MPG	1 ea \$13.40			\$13.40
 GWK4026684 (Part) · Main OIL PAN GASKET CUMM	1 ea \$283.28			\$283.28
 GWK5468170 (Part) · Main GEAR HOUSING FRONT ST	1 ea \$1,032.07			\$1,032.07
 TTDFP2881767 (Part) UPPER ENGINE GASKET K	1 ea \$899.71			\$899.71
 GWK3691253RX (Part) · Main (Archived) CYLINDER HEAD ISX & X	1 ea \$3,421.78			\$3,421.78

DESCRIPTION

SUMMARY

Subtotal	\$16,848.71
Labor	\$4,939.46
Parts	\$11,909.25
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$16,848.71



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #2845
Invoice Number:
PO Number:




















WORK ORDER






WORK ORDER DETAILS





















Issue Date:	Thu, Oct 12, 2023 8:01 AM	#30 2016 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X2GR983194
Actual Start Date:	Wed, Oct 11, 2023 8:01 AM	License Plate:	
Expected Completion Date:		Operator:	Heinz Zier
Actual Completion Date:	Mon, Oct 16, 2023	Type:	Tandem
Duration:	5 days	Group:	
Repair Priority Class:	Scheduled	Odometer:	853,305km
Status:	Completed	Secondary Meter:	21,938hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 A1 Dust Shields	\$3.80	\$0.00	\$3.80
 Ross Cowell (Contact)	0.1 hrs		\$3.80
 Replaced missing bolts	\$38.00		
 Power Steering Leak	\$3.80	\$0.00	\$3.80
 Ross Cowell (Contact)	0.1 hrs		\$3.80
 Tightened clamps	\$38.00		
 Truck Preventative Maintenance Inspection	\$38.00	\$0.00	\$38.00
 Ross Cowell (Contact)	1 hr		\$38.00
	\$38.00		
 air to air bushing rh side	\$7.60	\$0.00	\$7.60
 Ross Cowell (Contact)	0.2 hrs		\$7.60
	\$38.00		
 Transmission Replacement	\$608.00	\$7,442.76	\$8,050.76

Item		Labor	Parts	Subtotal
 Ross Cowell (Contact)				\$608.00
 Swapped transmission, replaced rear main seal, installed new clutch. Replaced linkage bearings and found pto and gear pump worn so replaced them as well.				
		16 hrs \$38.00		
 A1DRTL018918REBUILT (Part) · Main TRANSMISSION REBUILD	1 ea \$4,350.00			\$4,350.00
 FGR127760 (Part) · Main CLUTCH BRAKE 1 PIECE	1 ea \$59.30			\$59.30
 GWK4965569 (Part) · Main REAR CRANK SEAL CUMM	1 ea \$135.61			\$135.61
 GWK308925-25 (Part) · Main CLUTCH 15.5 2050 TORQ	1 ea \$1,246.00			\$1,246.00
 HVEFLY_WHEEL (Part) · Main FLYWHEEL RESURFACE	1 ea \$139.95			\$139.95
 FGR462ESK4022 (Part) · Main CLUTCH ROD END RH S/A	1 ea \$47.55			\$47.55
 FGR462ESK4021 (Part) · Main CLUTCH ROD END LH, S/	1 ea \$49.05			\$49.05
 GWKSPF6S (Part) · Main CLUTCH ROD END RH 3/8	2 ea \$11.45			\$22.90
 GWK1R812 (Part) · Main INNER RACE / CLUTCH	2 ea \$29.62			\$59.24
 GWKHJ122012 (Part) · Main NEEDLE BEARING / CLUT	2 ea \$27.70			\$55.40
 DPIPL12702BPBB (Part) · Main (Archived) MUNCIE GEAR PUMP, 27	1 ea \$984.90			\$984.90
 FGR35P8 (Part) · Main PTO FORK COVER GASKET	1 ea \$2.15			\$2.15
 GWK2866337CUM (Part) · Main EXHAUST GASKET 5" CIR	3 ea \$18.41			\$55.23
 FGRSW50A3 (Part) · Main EXHAUST CLAMP 5" SS	2 ea \$21.80			\$43.60
 MXFCD50 (Part) · Main TRANSMISSION OIL	18 L \$10.66			\$191.88
 Hydraulic Filter Replacement		\$7.60	\$116.03	\$123.63
 Ross Cowell (Contact)	0.2 hrs \$38.00			\$7.60

Item		Labor	Parts	Subtotal
 BALPT9187 (Part) · Main	1 ea			\$31.25
HYDRAULIC COOLER FILT S/AS FGR350001	\$31.25			
 MXFMV32 (Part) · Main (Archived)	18 L			\$84.78
HYDRAULIC OIL	\$4.71			
 Rebuild PTO		\$72.00	\$1,181.67	\$1,253.67
 Ernesto Ablog (Contact)	2 hrs			\$72.00
	\$36.00			
 FGR28P216 (Part) · Main	1 ea			\$19.30
PTO SEAL	\$19.30			
 FGR3P282X (Part) · Main	1 ea			\$169.42
OUTPUT PTO SHAFT 7/8	\$169.42			
 FGR22P1272 (Part) · Main	4 ea			\$4.40
PTO BEARING CAP GASKE	\$1.10			
 FGR22P1273 (Part) · Main	1 ea			\$2.35
PTO BEARING CAP GASKE	\$2.35			
 FGR2P778 (Part) · Main	1 ea			\$297.45
PTO OUTPUT GEAR, 680	\$297.45			
 FGR35P152 (Part) · Main	1 ea			\$2.14
PTO GASKET 8 BOLT .02	\$2.14			
 FGR35P8 (Part) · Main	1 ea			\$2.15
PTO FORK COVER GASKET	\$2.15			
 FGR550439 (Part) · Main	1 ea			\$46.56
PTO CLUSTER GEAR BEAR S/AS 21075T	\$46.56			
 FGR5P1246 (Part) · Main	1 ea			\$511.65
PTO CLUSTER, INPUT GEAR	\$511.65			
 FGR550532 (Part) · Main	1 ea			\$33.15
PTO BEARING REAR OUTP	\$33.15			
 FGR550221 (Part) · Main	2 ea			\$25.60
PTO BEARING RACE S/AS 15245T	\$12.80			
 FGR550397 (Part) · Main	1 ea			\$33.15
PTO BEARING #15126	\$33.15			
 FGR9P60 (Part) · Main	1 ea			\$34.35
PTO IDLER SHAFT. 680	\$34.35			
 Engine Oil & Filter Replacement		\$9.50	\$234.24	\$243.74
 Ross Cowell (Contact)	0.25 hrs			\$9.50
	\$38.00			
 NXTDBL7900 (Part) · Main	1 ea			\$55.60
OIL FILTER HIGH EFFICIENCY S/AS BD50000	\$55.60			

Item	Labor	Parts	Subtotal
 MXF15W40 (Part) · Main ENGINE OIL, 15W40 BUL			\$178.64
	44 L \$4.06		
 Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$7.60	\$0.00	\$7.60
 Ross Cowell (Contact)	0.2 hrs \$38.00		\$7.60
 Check Diff and Trans Oil	\$7.60	\$10.35	\$17.95
 Ross Cowell (Contact)  Changed a3 breather	0.2 hrs \$38.00		\$7.60
 FGRKIT2902 (Part) · Main BREATHING & TUBE KIT,	1 ea \$10.35		\$10.35
 Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$2.40	\$0.00	\$2.40
 Rickylynn Peters (Contact)	0.1 hrs \$24.00		\$2.40
 Tire Condition and Pressure Inspection Check all tires	\$131.40	\$3,472.00	\$3,603.40
 Rickylynn Peters (Contact)	0.1 hrs \$24.00		\$2.40
 Rickylynn Peters (Contact)  Replaced drives	2 hrs \$24.00		\$48.00
 Allan Bates (Contact)  Replaced drives	3 hrs \$27.00		\$81.00
 KALDT890 (Part) · Main ROAD X DRIVE TIRES 11R 245	8 ea \$434.00		\$3,472.00
 Torque Wheels Verify wheels are properly torqued	\$2.40	\$0.00	\$2.40
 Rickylynn Peters (Contact)	0.1 hrs \$24.00		\$2.40
 Walk Around Inspection	\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact)	0.25 hrs \$90.00		\$22.50

Item	Labor	Parts	Subtotal
↳ Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$7.60	\$0.00	\$7.60
👤 Ross Cowell (Contact)	0.2 hrs \$38.00		\$7.60

DESCRIPTION

SUMMARY

Subtotal	\$13,388.85
Labor	\$931.80
Parts	\$12,457.05
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$13,388.85

RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
#5611 From 0 on the peavine to stop sign at the junction 750 meets the 88 , I stop for traffic to go by and that was it all I had was 4 gear when to plains Nipisi and then home Reported Oct 9, 2023 by Heinz Zier		
#5601 Heard funny noise coming from the clutch we thought, but was told to just keep going by Luc and joe Reported Oct 8, 2023 by Heinz Zier		
#5669 [Inspection] Splines worn Reported almost 2 years ago by Ross Cowell • Truck Preventative Maintenance Checklist by Ross Cowell Generated by the failed inspection item "Hydraulic Motor" on the "Truck Preventative Maintenance Checklist" form submitted by Ross Cowell on Oct 13, 2023 at 10:20 AM MDT		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #3392
Invoice Number:
PO Number:


WORK ORDER














WORK ORDER DETAILS

Issue Date:	Tue, Jan 23, 2024 11:22 AM	#30 2016 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X2GR983194
Actual Start Date:	Tue, Jan 23, 2024 11:23 AM	License Plate:	
Expected Completion Date:		Operator:	Heinz Zier
Actual Completion Date:	Fri, Jan 26, 2024	Type:	Tandem
Duration:	3 days	Group:	
Repair Priority Class:	Scheduled	Odometer:	900,168km
Status:	Completed	Secondary Meter:	23,038hr
Issued By:			
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
Truck Preventative Maintenance Inspection	\$37.00	\$0.00	\$37.00
Roper Gorgichuk (Contact)	1 hr \$37.00		\$37.00
Oil Leak, Hydraulic Pump and Pto	\$37.00	\$19.30	\$56.30
Roper Gorgichuk (Contact)	1 hr \$37.00		\$37.00
FGR28P216 (Part) · Main PTO SEAL	1 ea \$19.30		\$19.30
#6770 · [Inspection] Pto or hydraulic pump is leaking out Generated by the failed inspection item "Hydraulic Motor" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Jan 23, 2024 at 1:26 PM MST			
Product Pump u joint and Yoke	\$3.70	\$0.00	\$3.70
Roper Gorgichuk (Contact)	0.1 hrs \$37.00		\$3.70

Item	Labor	Parts	Subtotal
#6771 · [Inspection] U- Joint yoke loose on the shaft Generated by the failed inspection item "Product Pump" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Jan 23, 2024 at 1:26 PM MST			
 Light Repair Repair Lights	\$7.40	\$49.95	\$57.35
 Roper Gorgichuk (Contact)	0.2 hrs \$37.00		\$7.40
 FGR94707 (Part) · Main LED SURESEAL PLUG ASS	1 ea \$4.55		\$4.55
 FGR60275Y (Part) · Main AMBER OVAL MODEL 60 L	1 ea \$45.40		\$45.40
#6773 · [Inspection] LHs bumper Signal light no maker Generated by the failed inspection item "Clearance Lights" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Jan 23, 2024 at 1:26 PM MST			
 air to air bushings rh	\$19.00	\$73.10	\$92.10
 Joseph Pitney (Contact)	0.5 hrs \$38.00		\$19.00
 FGRM203076 (Part) · Main AIR-AIR MOUNTING KIT	1 ea \$73.10		\$73.10
#6769 · [Inspection] Air to air bushings Generated by the failed inspection item "Air to Air Mounts" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Jan 23, 2024 at 1:26 PM MST			
 leaking shocks	\$38.00	\$76.05	\$114.05
 Joseph Pitney (Contact)	1 hr \$38.00		\$38.00
 FGR85937 (Part) · Main SHOCK DRIVE 8 BAG SUS	1 ea \$76.05		\$76.05
#6768 · [Inspection] A3 rhs shock leaking and a1 lhs shock bushing is pushed out Generated by the failed inspection item "Shocks" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Jan 23, 2024 at 1:26 PM MST			
 Clutch linkage arm loose on cross shaft	\$7.77	\$0.00	\$7.77
 Roper Gorgichuk (Contact)	0.21 hrs \$37.00		\$7.77
 7 Wire Repair	\$5.40	\$0.00	\$5.40
 Allan Bates (Contact)	0.2 hrs \$27.00		\$5.40
#6772 · [Inspection] 7 wire harness wire greened out at connector Generated by the failed inspection item "Trailer Cord and Pins" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Jan 23, 2024 at 1:26 PM MST			

Item	Labor	Parts	Subtotal
 A1 LHS hub	\$37.00	\$651.03	\$688.03
 Roper Gorgichuk (Contact)	1 hr		\$37.00
 Replaced hub. Hub cap bolts broke off	\$37.00		
 GWKCM10082209 (Part) · Main	1 ea		\$651.03
HUB ASSEMBLY	\$651.03		
 #6766 · [Inspection] A1 Lhs hub milky Generated by the failed inspection item "Front Hub Oil Level" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Jan 23, 2024 at 1:26 PM MST			
↳ Engine Oil & Filter Replacement	\$9.25	\$352.37	\$361.62
 Roper Gorgichuk (Contact)	0.25 hrs		\$9.25
	\$37.00		
 NXTDBL7900 (Part) · Main	1 ea		\$55.85
OIL FILTER HIGH EFFICIENCY S/AS BD50000	\$55.85		
 MXF5W40 (Part) · Main	42 L		\$296.52
ENGINE OIL 5W40 BULK	\$7.06		
↳ Air System Leaks	\$18.00	\$0.00	\$18.00
Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.			
 JOE NEMEC (Contact)	0.2 hrs		\$18.00
	\$90.00		
↳ Check Diff and Trans Oil	\$18.00	\$0.00	\$18.00
 JOE NEMEC (Contact)	0.2 hrs		\$18.00
	\$90.00		
↳ Inspect and Service Trailer Hitch	\$9.25	\$0.00	\$9.25
Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.			
 Roper Gorgichuk (Contact)	0.25 hrs		\$9.25
	\$37.00		
↳ Tire Condition and Pressure Inspection	\$5.40	\$0.00	\$5.40
Check all tires			
 Allan Bates (Contact)	0.2 hrs		\$5.40
	\$27.00		
↳ Torque Wheels	\$5.40	\$0.00	\$5.40
Verify wheels are properly torqued			
 Allan Bates (Contact)	0.2 hrs		\$5.40
	\$27.00		

Item	Labor	Parts	Subtotal
↳ Walk Around Inspection	\$18.00	\$0.00	\$18.00
👤 JOE NEMEC (Contact)	0.2 hrs \$90.00		\$18.00
↳ Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$19.00	\$6.90	\$25.90
👤 Joseph Pitney (Contact)	0.5 hrs \$38.00		\$19.00
🔧 MXFPSC30 (Part) - Main (Archived) GREASE PRECISION TUBE	1 tube \$6.90		\$6.90

DESCRIPTION

SUMMARY

Subtotal	\$1,523.27
Labor	\$294.57
Parts	\$1,228.70
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$1,523.27

RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
#6704 Scales on pup going on and off , not fixed Reported Jan 18, 2024 by Heinz Zier		
#6767 [Inspection] Coolant leaking from the rad area Reported over 1 year ago by Roper Gorgichuk • Truck Preventative Maintenance Checklist by Roper Gorgichuk Generated by the failed inspection item "Coolant Level" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Jan 23, 2024 at 1:26 PM MST		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245










Work Order Number: #3718
Invoice Number:
PO Number:












WORK ORDER

WORK ORDER DETAILS

Issue Date:	Tue, Mar 26, 2024 2:28 PM	#30 2016 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X2GR983194
Actual Start Date:	Tue, Mar 26, 2024 2:28 PM	License Plate:	
Expected Completion Date:		Operator:	Heinz Zier
Actual Completion Date:	Thu, Mar 28, 2024	Type:	Tandem
Duration:	2 days	Group:	
Repair Priority Class:	Scheduled	Odometer:	935,541km
Status:	Completed	Secondary Meter:	23,722hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 engine heater repair Diagnosis and repair engine heater.	\$74.00	\$25.98	\$99.98
 Roper Gorgichuk (Contact)  Rebuilt engine heater with a different fan	2 hrs \$37.00		\$74.00
 PWR20.1820.99.0001.0A (Part) · Main ESPAR FAN GASKET	1 ea \$25.98		\$25.98
 Truck Preventative Maintenance Inspection	\$13.75	\$0.00	\$13.75
 Chad Caouette (Contact)	0.5 hrs \$27.50		\$13.75
 Engine Oil & Filter Replacement	\$7.60	\$360.98	\$368.58
 Ross Cowell (Contact)	0.2 hrs \$38.00		\$7.60
 NXTDBL7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000	1 ea \$57.40		\$57.40

Item		Labor	Parts	Subtotal
 MXF5W40 (Part) - Main ENGINE OIL 5W40 BULK	43 L \$7.06			\$303.58
↳ Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.		\$3.80	\$0.00	\$3.80
 Ross Cowell (Contact)	0.1 hrs \$38.00			\$3.80
↳ Check Diff and Trans Oil		\$7.60	\$0.00	\$7.60
 Ross Cowell (Contact)	0.2 hrs \$38.00			\$7.60
↳ Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.		\$82.50	\$631.75	\$714.25
 Chad Caouette (Contact)  rebuilt fifthwheel jaws	3 hrs \$27.50			\$82.50
 SAFRK351AL (Part) - Main JAW KIT	1 ea \$631.75			\$631.75
↳ Tire Condition and Pressure Inspection Check all tires		\$6.75	\$0.00	\$6.75
 Allan Bates (Contact)	0.25 hrs \$27.00			\$6.75
↳ Torque Wheels Verify wheels are properly torqued		\$6.88	\$0.00	\$6.88
 Chad Caouette (Contact) 	0.25 hrs \$27.50			\$6.88
↳ Walk Around Inspection		\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact)	0.25 hrs \$90.00			\$22.50
↳ Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.		\$3.80	\$0.00	\$3.80
 Ross Cowell (Contact)	0.1 hrs \$38.00			\$3.80

DESCRIPTION

SUMMARY

Subtotal	\$1,247.89
Labor	\$229.18
Parts	\$1,018.71
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$1,247.89

RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
#7409 Pro heater not working shows F 30 on the screen Reported Mar 25, 2024 by Heinz Zier		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245











Work Order Number: #3984
Invoice Number:
PO Number:






















WORK ORDER





















WORK ORDER DETAILS















Issue Date:	Tue, May 7, 2024 10:36 AM	#30 2016 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X2GR983194
Actual Start Date:	Tue, May 7, 2024 10:37 AM	License Plate:	
Expected Completion Date:		Operator:	Heinz Zier
Actual Completion Date:	Wed, May 8, 2024	Type:	Tandem
Duration:	1 day	Group:	
Repair Priority Class:	Scheduled	Odometer:	960,155km
Status:	Completed	Secondary Meter:	24,140hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Air Leak at Air Dryer	\$18.50	\$16.58	\$35.08
 Roper Gorgichuk (Contact)	0.5 hrs \$37.00		\$18.50
 GWK5009233BXW (Part) · Main KIT-BOLT AD-IS AIR DRYER	1 ea \$16.58		\$16.58
 Steer Tire Replacement	\$27.00	\$700.00	\$727.00
 Allan Bates (Contact)	1 hr \$27.00		\$27.00
 CXEXZE2 (Part) · Main STEER TIRES 11R 24.5	2 ea \$350.00		\$700.00
 drivers side stack bushing	\$9.00	\$59.79	\$68.79
 Ernesto Ablog (Contact)  Replaced bushings	0.25 hrs \$36.00		\$9.00
 GWKEM75-69000HTATR (Part) · Main EXHAUST MOUNT BUSHING	1 ea \$38.64		\$38.64

Item		Labor	Parts	Subtotal
 FGRM13109 (Part) · Main EXHAUST MOUNT BUSHING				\$21.15
	1 ea			\$21.15
 Drive Axle Brakes		\$92.00	\$843.20	\$935.20
 Chad Caouette (Contact)	2 hrs			\$55.00
 removed and replaced drive axel brakes	\$27.50			
 Roper Gorgichuk (Contact)	1 hr			\$37.00
	\$37.00			
 FGRXSS504709E2K (Part) · Main BRAKE SHOE DRIVE16.5X	4 ea			\$263.20
	\$65.80			
 GWKDB1657B (Part) · Main BRAKE DRUM 16.5 X 7 S/AS GWK16792X	4 ea			\$580.00
	\$145.00			
 PS windshield		\$45.00	\$54.95	\$99.95
 JOE NEMEC (Contact)	0.5 hrs			\$45.00
	\$90.00			
 GWKDW1163-30 (Part) · Main WINDSHIELD , PS	1 ea			\$54.95
	\$54.95			
 A2 Torque Rods		\$82.50	\$167.00	\$249.50
 Chad Caouette (Contact)	3 hrs			\$82.50
 replaced torque rod bushings	\$27.50			
 FGRTRB6825 (Part) · Main V-ROD BUSHING TORQUE	4 ea			\$167.00
	\$41.75			
 Fuel Pump Gasket		\$133.00	\$83.66	\$216.66
 MICHAEL ABLOG (Contact)				\$133.00
 removed fuel pump to inspect and clean. installed fuel pump and torqued bolts to 60lbs and bracket bolts to 45lbs. replaced fuel pump gasket, sealing washers and power steering gasket.				
	3.5 hrs			
	\$38.00			
 GWK5414049 (Part) · Main FUEL PUMP GASKET	1 ea			\$35.81
	\$35.81			
 GWK4988280 (Part) · Main GASKET POWER STEERING	1 ea			\$5.33
	\$5.33			
 GWK3963991CUM (Part) · Main RUBBER LINED WASHER	2 ea			\$14.76
	\$7.38			
 GWK3963990CUM (Part) · Main WASHER RUBBER LINED	2 ea			\$9.04
	\$4.52			

Item		Labor	Parts	Subtotal
 GWK3963988 (Part) - Main WASHER RUBBER LINED	4 ea \$4.68			\$18.72
 Truck Preventative Maintenance Inspection		\$63.00	\$0.00	\$63.00
 JOE NEMEC (Contact)	0.7 hrs \$90.00			\$63.00
 CVIP		\$90.00	\$0.00	\$90.00
 JOE NEMEC (Contact)	1 hr \$90.00			\$90.00
 Engine Oil & Filter Replacement		\$9.00	\$229.59	\$238.59
 Kurt Kerekanich (Contact)	0.25 hrs \$36.00			\$9.00
 NXTDBL7900 (Part) - Main OIL FILTER HIGH EFFICIENCY S/AS BD50000	1 ea \$58.65			\$58.65
 MXF15W40 (Part) - Main ENGINE OIL 15W40 BUL	42 L \$4.07			\$170.94
 Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.		\$6.88	\$0.00	\$6.88
 Chad Caouette (Contact) 	0.25 hrs \$27.50			\$6.88
 Check Diff and Trans Oil		\$6.88	\$0.00	\$6.88
 Chad Caouette (Contact) 	0.25 hrs \$27.50			\$6.88
 Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.		\$6.88	\$0.00	\$6.88
 Chad Caouette (Contact)	0.25 hrs \$27.50			\$6.88
 Tire Condition and Pressure Inspection Check all tires		\$6.75	\$0.00	\$6.75
 Allan Bates (Contact)	0.25 hrs \$27.00			\$6.75
 Torque Wheels Verify wheels are properly torqued		\$22.50	\$0.00	\$22.50

Item		Labor	Parts	Subtotal
 JOE NEMEC (Contact)	0.25 hrs \$90.00			\$22.50
 Walk Around Inspection		\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact)	0.25 hrs \$90.00			\$22.50
 Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.		\$6.88	\$6.90	\$13.78
 Chad Caouette (Contact)	0.25 hrs \$27.50			\$6.88
 MXFPSC30 (Part) - Main (Archived) GREASE PRECISION TUBE	1 tube \$6.90			\$6.90
 airtank straps  Straps billed direct to unit		\$137.50	\$0.00	\$137.50
 Chad Caouette (Contact)  all four airtank straps are rusted and broken and pin are seized in bracket had to cut pins out and weld bracket replaced all four straps and rubber	5 hrs \$27.50			\$137.50
 teflone plate on 5 th wheel		\$34.38	\$366.90	\$401.28
 Chad Caouette (Contact)  replaced wear plate	1.25 hrs \$27.50			\$34.38
 SAFRK3311 (Part) - Main TEFLON PLATE KIT	1 ea \$366.90			\$366.90

DESCRIPTION

SUMMARY

Subtotal	\$3,348.72
Labor	\$820.15
Parts	\$2,528.57
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$3,348.72

Issue

Assigned Due

#7835 [Inspection] Cab Air Filter

Reported over 1 year ago by JOE NEMEC • Truck Preventative Maintenance Checklist by JOE NEMEC
Generated by the failed inspection item "Cab Air Filter" on the "Truck Preventative Maintenance Checklist" form submitted by JOE NEMEC on May 7, 2024 at 11:26 AM MDT



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245









Work Order Number: #4747
Invoice Number:
PO Number:























WORK ORDER





















WORK ORDER DETAILS






Issue Date:	Tue, Sep 10, 2024 10:20 AM	#30 2016 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X2GR983194
Actual Start Date:	Tue, Sep 10, 2024 10:21 AM	License Plate:	
Expected Completion Date:		Operator:	Heinz Zier
Actual Completion Date:	Thu, Sep 12, 2024	Type:	Tandem
Duration:	2 days	Group:	
Repair Priority Class:	Scheduled	Odometer:	1,024,661km
Status:	Completed	Secondary Meter:	25,331hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 diff breather replacement A3 diff breather	\$9.25	\$11.30	\$20.55
 Roper Gorgichuk (Contact)	0.25 hrs \$37.00		\$9.25
 FGRKIT2902 (Part) · Main BREATHER & TUBE KIT,	1 ea \$11.30		\$11.30
 Truck Preventative Maintenance Inspection	\$37.00	\$0.00	\$37.00
 Roper Gorgichuk (Contact)	1 hr \$37.00		\$37.00
 Install Dash Camera	\$18.50	\$544.40	\$562.90
 Roper Gorgichuk (Contact)	0.5 hrs \$37.00		\$18.50
 010-02619-00 (Part) · Main Garmin Dash Cam Live	1 ea \$539.99		\$539.99

Item		Labor	Parts	Subtotal
 VPSPB3922-11 (Part) · Main	1 ea			\$4.41
ADAPTER PLUG 12V FEMA	\$4.41			
 Power Steering Leak Repair		\$6.75	\$12.62	\$19.37
 Allan Bates (Contact)	0.25 hrs			\$6.75
 Replaced line	\$27.00			
 HPTG643-075 (Part) · Main	2 in			\$12.62
HYDRAULIC HOSE, 3/4	\$6.31			
 #9349 · [Inspection] Return line on power steering pump leaking				
Generated by the failed inspection item "Power Steering Level" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Sep 10, 2024 at 2:44 PM MDT				
 A3 Input U-Joints		\$9.25	\$0.00	\$9.25
 Roper Gorgichuk (Contact)	0.25 hrs			\$9.25
 Pinged the strap with lock tite	\$37.00			
 #9350 · [Inspection] A3 input u-joint cap sipping in the drive shaft yoke				
Generated by the failed inspection item "Driveline and Steady Bearing" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Sep 10, 2024 at 2:44 PM MDT				
 A1 LHS Shock		\$6.75	\$76.45	\$83.20
 Allan Bates (Contact)	0.25 hrs			\$6.75
	\$27.00			
 MON65405 (Part) · Main	1 ea			\$76.45
SHOCK STEER W900 S/AS	\$76.45			
 Exhaust Leak Repair		\$37.00	\$38.78	\$75.78
 Roper Gorgichuk (Contact)				\$37.00
 Replaced gaskets on elbow going from the down pipe to the dpf can				
	1 hr			
	\$37.00			
 GWK2866337CUM (Part) · Main	1 ea			\$18.67
EXHAUST GASKET 5" CIR	\$18.67			
 FGRJ0090056 (Part) · Main (Archived)	1 ea			\$1.00
CLAMP 2" FORMED EXHAU	\$1.00			
 GWK2866636CUM (Part) · Main	1 ea			\$19.11
EXHAUST GASKET 4"	\$19.11			
 Engine Oil & Filter Replacement		\$6.75	\$229.59	\$236.34
 Allan Bates (Contact)	0.25 hrs			\$6.75
	\$27.00			
 NXTDBL7900 (Part) · Main	1 ea			\$58.65
OIL FILTER HIGH EFFICIENCY S/AS BD50000	\$58.65			

Item	Labor	Parts	Subtotal
 MXF15W40 (Part) · Main ENGINE OIL, 15W40 BUL	42 L \$4.07		\$170.94
 Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$9.25	\$0.00	\$9.25
 Roper Gorgichuk (Contact)	0.25 hrs \$37.00		\$9.25
 Check Diff and Trans Oil	\$6.75	\$0.00	\$6.75
 Allan Bates (Contact)	0.25 hrs \$27.00		\$6.75
 Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$9.25	\$0.00	\$9.25
 Roper Gorgichuk (Contact)	0.25 hrs \$37.00		\$9.25
 Tire Condition and Pressure Inspection Check all tires	\$6.75	\$0.00	\$6.75
 Allan Bates (Contact)	0.25 hrs \$27.00		\$6.75
 #9339 · Needs drive tires			
 #9246 · Needs drive tires			
 Torque Wheels Verify wheels are properly torqued	\$6.75	\$0.00	\$6.75
 Allan Bates (Contact)	0.25 hrs \$27.00		\$6.75
 Walk Around Inspection	\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact)	0.25 hrs \$90.00		\$22.50
 Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$6.75	\$0.00	\$6.75
 Allan Bates (Contact)	0.25 hrs \$27.00		\$6.75
 ABS Repair	\$46.25	\$0.00	\$46.25
 Roper Gorgichuk (Contact)  Fixed wiring issue	1.25 hrs \$37.00		\$46.25

Item	Labor	Parts	Subtotal
 #9190 · ABS warning light on for truck and trailer			
 replace shifter boot	\$9.25	\$129.88	\$139.13
 Roper Gorgichuk (Contact)	0.25 hrs \$37.00		\$9.25
 GWKK042-79 (Part) · Main SHIFTER BOOT UPPER	1 ea \$129.88		\$129.88
 #9191 · Rubber boot for the bottom of shifter			

DESCRIPTION

SUMMARY

Subtotal	\$1,297.77
Labor	\$254.75
Parts	\$1,043.02
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$1,297.77



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #4837
Invoice Number:
PO Number:






















WORK ORDER








WORK ORDER DETAILS

Issue Date:	Mon, Sep 30, 2024 3:43 PM	#30 2016 Kenworth W900	
Scheduled Start Date:	Mon, Sep 30, 2024 3:44 PM	VIN/SN: 1XKWD40X2GR983194	
		License Plate:	
Actual Start Date:	Mon, Sep 30, 2024 3:45 PM	Operator: Heinz Zier	
		Type: Tandem	
		Group:	
Expected Completion Date:			
Actual Completion Date:	Tue, Oct 1, 2024	Odometer: 1,035,224km	
Duration:	1 day	Secondary Meter: 25,519hr	
Repair Priority Class:	Scheduled		
Status:	Completed		
Issued By:	Ernesto Ablog		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Install Dash Camera	\$0.00	\$539.99	\$539.99
 Roper Gorgichuk (Contact)	0 hrs		\$0.00
 S/N 779004492	\$37.00		
 010-02619-00 (Part) · Main	1 ea		\$539.99
Garmin Dash Cam Live	\$539.99		
 Truck Preventative Maintenance Inspection	\$27.00	\$7.14	\$34.14
 Ernesto Ablog (Contact)	0.75 hrs		\$27.00
	\$36.00		
 MNACHV255675-448 (Part) · Main	2 L		\$7.14
AW32 HYDRAULIC OIL	\$3.57		
 Winter Front Clip Lhs	\$36.00	\$25.53	\$61.53
 Kurt Kerekanich (Contact)	1 hr		\$36.00
	\$36.00		

Item		Labor	Parts	Subtotal
 GWK75700AU0 (Part) · Main WINTERFRONT TWIST BUT	1 Pac \$25.53			\$25.53
 Top up hydraulic oil		\$5.55	\$0.00	\$5.55
 Roper Gorgichuk (Contact)	0.15 hrs \$37.00			\$5.55
 Exhaust Clamp Between Stack		\$9.00	\$0.00	\$9.00
 Kurt Kerekanich (Contact)  Tightened clamps	0.25 hrs \$36.00			\$9.00
 fuel filters replacement		\$18.00	\$108.27	\$126.27
 Ernesto Ablog (Contact)	0.5 hrs \$36.00			\$18.00
 BALPF46081 (Part) · Main BALDWIN FUEL FILTER	1 ea \$43.96			\$43.96
 NTXDBF6776 (Part) · Main FUEL FILTER SPIN ON S/AS BF46129	1 ea \$64.31			\$64.31
 ac and fan belt worn out		\$9.00	\$140.90	\$149.90
 Ernesto Ablog (Contact)	0.25 hrs \$36.00			\$9.00
 GWK5060640 (Part) · Main A/C BELT	1 ea \$42.73			\$42.73
 VPS4120910X (Part) · Main CONTINENTAL XTREME HD BELT	1 ea \$98.17			\$98.17
 Engine Oil & Filter Replacement		\$9.00	\$241.80	\$250.80
 Ernesto Ablog (Contact)	0.25 hrs \$36.00			\$9.00
 NXTDBL7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000	1 ea \$58.65			\$58.65
 MXF15W40 (Part) · Main ENGINE OIL, 15W40 BUL	45 L \$4.07			\$183.15
 Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.		\$9.25	\$0.00	\$9.25
 Roper Gorgichuk (Contact)	0.25 hrs \$37.00			\$9.25
 Check Diff and Trans Oil		\$9.00	\$0.00	\$9.00

Item		Labor	Parts	Subtotal
 Kurt Kerekanich (Contact)	0.25 hrs \$36.00			\$9.00
↳ Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.		\$7.20	\$0.00	\$7.20
 Ernesto Ablog (Contact)	0.2 hrs \$36.00			\$7.20
↳ Tire Condition and Pressure Inspection Check all tires		\$13.50	\$0.00	\$13.50
 Allan Bates (Contact)	0.5 hrs \$27.00			\$13.50
↳ Torque Wheels Verify wheels are properly torqued		\$9.00	\$0.00	\$9.00
 Ernesto Ablog (Contact)	0.25 hrs \$36.00			\$9.00
↳ Walk Around Inspection		\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact)	0.25 hrs \$90.00			\$22.50
↳ Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.		\$6.00	\$4.67	\$10.67
 Rickylynn Peters (Contact)	0.25 hrs \$24.00			\$6.00
 MNACHV259118-652 (Part) · Main STARPLEX EP2 TUBE Summer Grease	1 ea \$4.67			\$4.67

DESCRIPTION

SUMMARY

Subtotal	\$1,258.30
Labor	\$190.00
Parts	\$1,068.30
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$1,258.30

Issue	Assigned	Due
#9340 Phone booster Reported Sep 9, 2024 by Heinz Zier		
#9432 No power to the touch screen or am fm radio Reported Sep 17, 2024 by Heinz Zier		
#9192 Need a phone booster Reported Aug 28, 2024 by Heinz Zier		
#9547 Driver side windshield took a rock Reported Sep 23, 2024 by Heinz Zier		
#9638 [Inspection] Winter Front Clips Reported 10 months ago by Ernesto Ablog - Truck Preventative Maintenance Checklist by Ernesto Ablog Generated by the failed inspection item "Winter Front Clips" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Sep 30, 2024 at 4:16 PM MDT		
#9637 [Inspection] A2 both shocks leaking Reported 10 months ago by Ernesto Ablog - Truck Preventative Maintenance Checklist by Ernesto Ablog Generated by the failed inspection item "Shocks" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Sep 30, 2024 at 4:16 PM MDT		
#9636 [Inspection] Hydraulic Oil Level Reported 10 months ago by Ernesto Ablog - Truck Preventative Maintenance Checklist by Ernesto Ablog Generated by the failed inspection item "Hydraulic Oil Level" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Sep 30, 2024 at 4:16 PM MDT		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #5127
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Tue, Nov 12, 2024 7:11 AM	#30 2016 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X2GR983194
Actual Start Date:	Tue, Nov 12, 2024 7:11 AM	License Plate:	
Expected Completion Date:		Operator:	Heinz Zier
Actual Completion Date:	Thu, Nov 14, 2024	Type:	Tandem
Duration:	2 days	Group:	
Repair Priority Class:	Scheduled	Odometer:	1,056,128km
Status:	Completed	Secondary Meter:	25,904hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Clutch Brake Replacement	\$47.50	\$37.00	\$84.50
 MICHAEL ABLOG (Contact)	1.25 hrs		\$47.50
 replaced with 2pc clutch brake	\$38.00		
 FGRMAFB201 (Part) · Main	1 ea		\$37.00
CLUTCH BRAKE 2 PIECE	\$37.00		
 #10139 · [Inspection] 1 piece clutch brake worn out Generated by the failed inspection item "Clutch Brake Condition" on the "Truck Preventative Maintenance Checklist" form submitted by MICHAEL ABLOG on Nov 12, 2024 at 7:48 AM MST			
 Truck Preventative Maintenance Inspection	\$19.00	\$0.00	\$19.00
 MICHAEL ABLOG (Contact)	0.5 hrs		\$19.00
	\$38.00		
 Air Filters Replacement	\$19.00	\$208.76	\$227.76
 MICHAEL ABLOG (Contact)	0.5 hrs		\$19.00
	\$38.00		

Item		Labor	Parts	Subtotal
<div> <div></div> <div>NTXP625128 (Part) · Main</div> <div>AIR FILTER W900</div> </div>	<div>2 ea</div> <div>\$104.38</div>			\$208.76
<div> <div></div> <div>Coolant Leaks Repair</div> </div>		\$19.00	\$13.08	\$32.08
<div> <div></div> <div>Joseph Pitney (Contact)</div> </div>	<div>0.5 hrs</div> <div>\$38.00</div>			\$19.00
<div> <div></div> <div>GWKCT300LTRP (Part) · Main</div> <div>CONSTANT TORQUE CLAMP</div> </div>	<div>1 ea</div> <div>\$13.08</div>			\$13.08
<div> <div></div> <div>Back Up Alarm Repair</div> </div>		\$9.50	\$40.90	\$50.40
<div> <div></div> <div>Joseph Pitney (Contact)</div> </div>	<div>0.25 hrs</div> <div>\$38.00</div>			\$9.50
<div> <div></div> <div>FGR73090 (Part) · Main</div> <div>BACK UP ALARM 107DB S/AS FGR575</div> </div>	<div>1 ea</div> <div>\$40.90</div>			\$40.90
<div> <div></div> <div>#10140 · [Inspection] Back up alarm</div> <div>Generated by the failed inspection item "Back up alarm" on the "Truck Preventative Maintenance Checklist" form submitted by MICHAEL ABLOG on Nov 12, 2024 at 7:48 AM MST</div> </div>				
<div> <div></div> <div>Ziptie Wires & Air lines</div> </div>		\$9.50	\$0.00	\$9.50
<div> <div></div> <div>MICHAEL ABLOG (Contact)</div> </div>	<div>0.25 hrs</div> <div>\$38.00</div>			\$9.50
<div> <div></div> <div>Engine Oil & Filter Replacement</div> </div>		\$9.50	\$379.05	\$388.55
<div> <div></div> <div>MICHAEL ABLOG (Contact)</div> </div>	<div>0.25 hrs</div> <div>\$38.00</div>			\$9.50
<div> <div></div> <div>MXF5W40 (Part) · Main</div> <div>ENGINE OIL 5W40 BULK</div> </div>	<div>45 L</div> <div>\$7.12</div>			\$320.40
<div> <div></div> <div>NXTDBL7900 (Part) · Main</div> <div>OIL FILTER HIGH EFFICIENCY S/AS BD50000</div> </div>	<div>1 ea</div> <div>\$58.65</div>			\$58.65
<div> <div></div> <div>Air System Leaks</div> <div>Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.</div> </div>		\$9.50	\$0.00	\$9.50
<div> <div></div> <div>MICHAEL ABLOG (Contact)</div> </div>	<div>0.25 hrs</div> <div>\$38.00</div>			\$9.50
<div> <div></div> <div>Check Diff and Trans Oil</div> </div>		\$9.50	\$0.00	\$9.50
<div> <div></div> <div>Joseph Pitney (Contact)</div> </div>	<div>0.25 hrs</div> <div>\$38.00</div>			\$9.50

Item	Labor	Parts	Subtotal
↳ Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$9.50	\$0.00	\$9.50
👤 MICHAEL ABLOG (Contact) 0.25 hrs \$38.00			\$9.50
↳ Tire Condition and Pressure Inspection Check all tires	\$84.00	\$3,472.00	\$3,556.00
👤 Jayden Binet (Contact) 3.5 hrs \$24.00			\$84.00
🔧 KALDT890 (Part) · Main ROAD X DRIVE TIRES 11R 245 8 ea \$434.00			\$3,472.00
↳ Torque Wheels Verify wheels are properly torqued	\$9.50	\$0.00	\$9.50
👤 Joseph Pitney (Contact) 0.25 hrs \$38.00			\$9.50
↳ Walk Around Inspection	\$9.50	\$0.00	\$9.50
👤 MICHAEL ABLOG (Contact) 0.25 hrs \$38.00			\$9.50
↳ Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$19.00	\$0.00	\$19.00
👤 Joseph Pitney (Contact) 0.5 hrs \$38.00			\$19.00

DESCRIPTION

SUMMARY

Subtotal	\$4,434.29
Labor	\$283.50
Parts	\$4,150.79
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$4,434.29

Issue	Assigned	Due
#10133 Anti-freeze leak Reported Nov 11, 2024 by Heinz Zier		
#10135 There is a vibration on the front end , starts to shake and then stops as fast as it starts Reported Nov 11, 2024 by Heinz Zier		
#10134 Hydraulic leak Reported Nov 11, 2024 by Heinz Zier		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245













Work Order Number: #5285
Invoice Number:
PO Number:
























WORK ORDER

WORK ORDER DETAILS

Issue Date:	Mon, Dec 2, 2024 3:15 PM	#30 2016 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X2GR983194
Actual Start Date:	Mon, Dec 2, 2024 3:15 PM	License Plate:	
Expected Completion Date:		Operator:	Heinz Zier
Actual Completion Date:	Tue, Dec 3, 2024	Type:	Tandem
Duration:	1 day	Group:	
Repair Priority Class:	Scheduled	Odometer:	1,066,044km
Status:	Completed	Secondary Meter:	26,176hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 ABS Repair	\$57.00	\$190.70	\$247.70
 A3LH			
 Ernesto Ablog (Contact)	1.5 hrs		\$57.00
 Replaced both abs sensor A3	\$38.00		
 FGR4410309102 (Part) · Main	2 ea		\$190.70
ABS SENSOR KIT, 90 DE	\$95.35		
 #10370 · Abs warning lights on truck and trailer			
 Truck Preventative Maintenance Inspection	\$19.00	\$0.00	\$19.00
 MICHAEL ABLOG (Contact)	0.5 hrs		\$19.00
	\$38.00		
 Fuel Tank Breather Repair	\$6.25	\$0.00	\$6.25
 Rickylynn Peters (Contact)	0.25 hrs		\$6.25
 Cleaned breather hose on both sides.	\$25.00		
 #10371 · Vent line frozen or plugged on fuel tanks			

Item	Labor	Parts	Subtotal
 Air Dryer Purge Valve Replacement	\$25.00	\$147.74	\$172.74
<div> <div></div> <div>Rickylynn Peters (Contact)</div> </div> <div> <div></div> <div>Part # K022105</div> </div> <div> <div></div> <div>1 hr</div> </div> <div> <div></div> <div>\$25.00</div> </div>			\$25.00
<div> <div></div> <div>BENK022105 (Part) · Main</div> </div> <div> <div></div> <div>AD-IP VALVE PURGE</div> </div> <div> <div></div> <div>1 ea</div> </div> <div> <div></div> <div>\$147.74</div> </div>			\$147.74
<div> <div></div> <div> #10397 · [Inspection] Air dryer purge valve Generated by the failed inspection item "Air Dryer Condition" on the "Truck Preventative Maintenance Checklist" form submitted by MICHAEL ABLOG on Dec 2, 2024 at 4:02 PM MST </div> </div>			
 Battery 2 wing nut missing	\$3.80	\$69.56	\$73.36
<div> <div></div> <div>MICHAEL ABLOG (Contact)</div> </div> <div> <div></div> <div>0.1 hrs</div> </div> <div> <div></div> <div>\$38.00</div> </div>			\$3.80
<div> <div></div> <div>GWKHWC09341 (Part) · Main</div> </div> <div> <div></div> <div>WINGED STUD, BATTERY</div> </div> <div> <div></div> <div>2 ea</div> </div> <div> <div></div> <div>\$21.66</div> </div>			\$43.32
<div> <div></div> <div>FGRM593674 (Part) · Main</div> </div> <div> <div></div> <div>BATTERY BOX WASHER</div> </div> <div> <div></div> <div>2 ea</div> </div> <div> <div></div> <div>\$13.12</div> </div>			\$26.24
 Engine shutdown not working	\$19.00	\$90.28	\$109.28
<div> <div></div> <div>Ernesto Ablog (Contact)</div> </div> <div> <div></div> <div>Replaced solenoid</div> </div> <div> <div></div> <div>0.5 hrs</div> </div> <div> <div></div> <div>\$38.00</div> </div>			\$19.00
<div> <div></div> <div>GWKBA12450 (Part) · Main</div> </div> <div> <div></div> <div>VALVE SOLENOID ENG SH</div> </div> <div> <div></div> <div>1 ea</div> </div> <div> <div></div> <div>\$90.28</div> </div>			\$90.28
 Engine Oil & Filter Replacement	\$9.50	\$379.05	\$388.55
<div> <div></div> <div>MICHAEL ABLOG (Contact)</div> </div> <div> <div></div> <div>45Ltrs. 5w40, 7900</div> </div> <div> <div></div> <div>0.25 hrs</div> </div> <div> <div></div> <div>\$38.00</div> </div>			\$9.50
<div> <div></div> <div>NXTDBL7900 (Part) · Main</div> </div> <div> <div></div> <div>OIL FILTER HIGH EFFICIENCY S/AS BD50000</div> </div> <div> <div></div> <div>1 ea</div> </div> <div> <div></div> <div>\$58.65</div> </div>			\$58.65
<div> <div></div> <div>MXF5W40 (Part) · Main</div> </div> <div> <div></div> <div>ENGINE OIL 5W40 BULK</div> </div> <div> <div></div> <div>45 L</div> </div> <div> <div></div> <div>\$7.12</div> </div>			\$320.40
 Air System Leaks	\$12.50	\$40.79	\$53.29
Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.			
<div> <div></div> <div>Rickylynn Peters (Contact)</div> </div> <div> <div></div> <div>G50-4064-04-016 replaced main line from compressor.</div> </div> <div> <div></div> <div>0.5 hrs</div> </div> <div> <div></div> <div>\$25.00</div> </div>			\$12.50
<div> <div></div> <div>GWKG50-1064-04-016 (Part) · Main</div> </div> <div> <div></div> <div>UNLOADER HOSE ASSEMBLY S/AS K342-255-016</div> </div> <div> <div></div> <div>1 ea</div> </div> <div> <div></div> <div>\$40.79</div> </div>			\$40.79
 Check Diff and Trans Oil	\$6.25	\$11.30	\$17.55

Item		Labor	Parts	Subtotal
👤 Rickylynn Peters (Contact)	0.25 hrs			\$6.25
📦 Installed new diff breather on A2 Part # 2902	\$25.00			
📦 FGRKIT2902 (Part) · Main	1 ea			\$11.30
BREATHER & TUBE KIT,	\$11.30			
↳ Inspect and Service Trailer Hitch		\$9.50	\$0.00	\$9.50
Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.				
👤 MICHAEL ABLOG (Contact)	0.25 hrs			\$9.50
	\$38.00			
↳ Tire Condition and Pressure Inspection		\$7.25	\$0.00	\$7.25
Check all tires				
👤 Allan Bates (Contact)	0.25 hrs			\$7.25
	\$29.00			
↳ Torque Wheels		\$7.25	\$0.00	\$7.25
Verify wheels are properly torqued				
👤 Allan Bates (Contact)	0.25 hrs			\$7.25
	\$29.00			
↳ Walk Around Inspection		\$9.50	\$0.00	\$9.50
👤 MICHAEL ABLOG (Contact)	0.25 hrs			\$9.50
	\$38.00			
↳ Grease Unit		\$6.25	\$0.00	\$6.25
Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.				
👤 Rickylynn Peters (Contact)	0.25 hrs			\$6.25
	\$25.00			

DESCRIPTION

SUMMARY

Subtotal	\$1,127.47
Labor	\$198.05
Parts	\$929.42
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+ \$0.00 (0.0%)
Total	\$1,127.47

RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
#10239 P/S windshield took a rock Reported Nov 21, 2024 by Heinz Zier		
#10238 D/S windshield has crack, Reported Nov 21, 2024 by Heinz Zier		