



CX Energy Services  
PO Box 3450, 74028 RR 174, 74028 RR 174  
High Prairie, AB, T0G 1E0  
CA  
7805230245

Work Order Number: #2406  
Invoice Number:  
PO Number:













# WORK ORDER

## WORK ORDER DETAILS


















EE25-4






















Issue Date:	Wed, Aug 23, 2023 3:35 PM	#66 2019 Kenworth W900
Scheduled Start Date:		VIN/SN: 1XKWD40X4KJ959986
Actual Start Date:	Wed, Aug 23, 2023 3:37 PM	License Plate:
Expected Completion Date:		Operator: Stephen Trimble
Actual Completion Date:	Thu, Aug 31, 2023	Type: Semi Truck
Duration:	8 days	Group:
Repair Priority Class:	Scheduled	Odometer: 599,521km
Status:	Completed	Secondary Meter: 12,187hr
Issued By:	Ernesto Ablog	
Assigned to:		
Vendor:		
Labels:		














## LINE ITEMS


Item	Labor	Parts	Subtotal
 AC Repair	\$17.00	\$150.73	\$167.73
 Roper Gorgichuk (Contact)	0.5 hrs		\$17.00
 Recharged ac system	\$34.00		
 GWK1000841496BSM (Part) · Main	1 ea		\$150.73
HARDLINE-SUCTION	\$150.73		
 Drag Link Replacement	\$17.00	\$482.74	\$499.74
 Drag Link Worn Out			
 Roper Gorgichuk (Contact)	0.5 hrs		\$17.00
	\$34.00		
 GWKL24VU8036B11 (Part) · Main (Archived)	1 ea		\$482.74
DRAG LINK KENWORTH	\$482.74		
 Exhaust Bellows Bracket Loose	\$17.50	\$0.00	\$17.50
 Ernesto Ablog (Contact)	0.5 hrs		\$17.50
 Re-enforced bracket	\$35.00		
 Replace Female Wing Nut	\$8.75	\$109.65	\$118.40

Item		Labor	Parts	Subtotal
<div> <div></div> <div>Ernesto Ablog (Contact)</div> </div> <div> <div></div> <div>Replaced wing nut</div> </div>	0.25 hrs \$35.00			\$8.75
<div> <div></div> <div>DIX10WF10B (Part) · Main</div> </div> <div> <div></div> <div>WING COUPLER 1 1/4 S/AS FB20114NPTF5</div> </div>	1 ea \$109.65			\$109.65
<div> <div></div> <div>Engine Rebuild</div> </div> <div> <div></div> <div>Truck had excessive blow by and was pushing some oil out blow by tube. Tore down engine and found cylinder liners washed out and egr cooler failed. Checked liner heights and they were all 0.009" to 0.010". Cut counter bores to receive 0.020" shim and new liners to achieve 0.012" liner heights. Installed Cummins overhaul kit as well as a reman cylinder head. Oil cooler element was replaced as well as a new oil thermostat. Front crankshaft seal was also replaced and a new vibration dampener installed.</div> </div>		\$3,352.00	\$22,316.36	\$25,668.36
<div> <div></div> <div>JOE NEMEC (Contact)</div> </div>	26 hrs \$90.00			\$2,340.00
<div> <div></div> <div>MICHAEL ABLOG (Contact)</div> </div>	8 hrs \$29.00			\$232.00
<div> <div></div> <div>Ross Cowell (Contact)</div> </div>	8 hrs \$38.00			\$304.00
<div> <div></div> <div>Roper Gorgichuk (Contact)</div> </div>	14 hrs \$34.00			\$476.00
<div> <div></div> <div>GWK3689755CUM (Part) · Main</div> </div> <div> <div></div> <div>GASKET, LUB OIL COOLER HOUSING</div> </div>	1 ea \$119.81			\$119.81
<div> <div></div> <div>GWK4955831CUM (Part) · Main</div> </div> <div> <div></div> <div>OIL COOLER KIT</div> </div>	1 ea \$629.74			\$629.74
<div> <div></div> <div>GWK2894829CUM (Part) · Main</div> </div> <div> <div></div> <div>INJECTOR CONNECTOR, CROSS TUBE</div> </div>	6 ea \$125.22			\$751.32
<div> <div></div> <div>GWK4965698CUM (Part) · Main</div> </div> <div> <div></div> <div>MANIFOLD MOUNTING BOL</div> </div>	12 ea \$8.89			\$106.68
<div> <div></div> <div>GWK5298564 (Part) · Main</div> </div> <div> <div></div> <div>SHIM</div> </div>	6 ea \$73.57			\$441.42
<div> <div></div> <div>GWK4386527 (Part) · Main</div> </div> <div> <div></div> <div>THERMOSTAT OIL X15 21</div> </div>	1 ea \$127.42			\$127.42
<div> <div></div> <div>GWKS16255 (Part) · Main</div> </div> <div> <div></div> <div>SNAP RING OIL THREMOS</div> </div>	1 ea \$8.11			\$8.11
<div> <div></div> <div>GWK3336204 (Part) · Main</div> </div> <div> <div></div> <div>OIL THERMOSTAT O-RING</div> </div>	1 ea \$13.14			\$13.14
<div> <div></div> <div>GWK5120910 (Part) · Main (Archived)</div> </div> <div> <div></div> <div>FAN BELT W900</div> </div>	1 ea \$90.08			\$90.08

Item		Labor	Parts	Subtotal
 GWK3678506CUM (Part) · Main (Archived)	22 ea			\$630.30
HEAD BOLT, SHORT	\$28.65			
 GWK5693831CUM (Part) · Main (Archived)	1 ea			\$10,235.44
KIT, EPA 17X15 OVER	\$10,235.44			
 GWK5658203RXCUM (Part) · Main (Archived)	1 ea			\$8,004.38
HEAD, CYLINDER	\$8,004.38			
 GWK4101884CUM (Part) · Main	1 ea			\$1,069.83
VIBRATION DAMPER	\$1,069.83			
 GWK3685173CUM (Part) · Main	1 ea			\$88.69
CRANK SEAL FRONT CUMM	\$88.69			
 Clutch Gap Adjustment		\$8.75	\$0.00	\$8.75
 Ernesto Ablog (Contact)	0.25 hrs			\$8.75
	\$35.00			
 clutch brake replacement		\$17.50	\$35.00	\$52.50
 Ernesto Ablog (Contact)	0.5 hrs			\$17.50
 Replaced clutch brake	\$35.00			
 FGRMAFB201 (Part) · Main	1 ea			\$35.00
CLUTCH BRAKE 2 PIECE	\$35.00			
 A2Rh Abs Sensor		\$29.00	\$85.40	\$114.40
 MICHAEL ABLOG (Contact)				\$29.00
 Diagnosed as bad sensor on A2RH wheel end. Pulled wheels and replaced sensor. Tested operation and fault lamp goes out after self test now.				
	1 hr			
	\$29.00			
 FGR4410309102 (Part) · Main	1 ea			\$85.40
ABS SENSOR KIT, 90 DE	\$85.40			
 change air filter		\$17.00	\$192.88	\$209.88
 Kurt Kerekanich (Contact)	0.5 hrs			\$17.00
	\$34.00			
 NTPP625128 (Part) · Main	2 ea			\$192.88
AIR FILTER W900	\$96.44			
 change hydraulic filter		\$17.00	\$12.94	\$29.94
 Kurt Kerekanich (Contact)	0.5 hrs			\$17.00
	\$34.00			
 BALBT8443 (Part) · Main	1 ea			\$12.94
HYDRAULIC FILTER GARD S/AS P565059	\$12.94			
 Truck Preventative Maintenance Inspection		\$26.25	\$0.00	\$26.25

Item		Labor	Parts	Subtotal
 Ernesto Ablog (Contact)	0.75 hrs \$35.00			\$26.25
 After-treatment System Delete		\$486.00	\$1,524.87	\$2,010.87
 Roper Gorgichuk (Contact)	3 hrs \$34.00			\$102.00
 Removed emissions system and def tank. Welded new piping				
 JOE NEMEC (Contact)				\$270.00
 Grabbed parts for delete, did programing with triple threat diesel. Built new coolant feed line for turbo.	3 hrs \$90.00			
 Ross Cowell (Contact)				\$114.00
 Installed coolant pipes to replace egr cooler, helped with exhaust and installed pyro.	3 hrs \$38.00			
 FGR41968L (Part) · Main	2 ea \$78.80			\$157.60
5" MARMON FLANGE				
 GWK90-0013 (Part) · Main	1 ea \$16.70			\$16.70
CLAMP -VBAND 5"				
 FGRJ000203 (Part) · Main	2 ea \$10.15			\$20.30
5" ACCUSEAL EXHAUST CLAMP S/AS FGR35228				
 GWKR605-10 (Part) · Main	1 ea \$339.62			\$339.62
PYROMETER KIT				
 TTDPLATE-32 (Part) · Main	1 ea \$35.00			\$35.00
2 HOLE ROUND W/EARS THICK				
 TTD190772-6 (Part) · Main	1 ea \$57.91			\$57.91
#6 FSAE-#6 TEFLON 90				
 TTDS-6TW (Part) · Main	1 ea \$7.84			\$7.84
#6 TEFLON HIGH TEMP HOSE				
 GWK5575183 (Part) · Main	1 ea \$224.06			\$224.06
COOLANT TRANSFER TUBE				
 GWK4367122 (Part) · Main (Archived)	1 ea \$308.30			\$308.30
COOLANT TRANFER TUBE				
 GWK3683870 (Part) · Main	1 ea \$236.04			\$236.04
Rear exhaust manifold elbow.				
 FGRL5901212A (Part) · Main	1 ea \$52.30			\$52.30
EXHAUST ELBOW 12" ALU				
 FGRL5901818A (Part) · Main	1 ea \$69.20			\$69.20
EHAUST ELBOW 18" ALUM				
 Engine Oil & Filter Replacement		\$9.50	\$239.52	\$249.02

Item		Labor	Parts	Subtotal
 Ross Cowell (Contact)	0.25 hrs \$38.00			\$9.50
 BALBD50000 (Part) · Main (Archived) OIL FILTER	1 ea \$44.64			\$44.64
 MXF15W40 (Part) · Main ENGINE OIL, 15W40 BUL	48 L \$4.06			\$194.88
↳ Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.		\$21.50	\$34.75	\$56.25
 Rickylynn Peters (Contact)  Replaced air fitting on leveling valve, 1/2 union on front air tank.	1 hr \$21.50			\$21.50
 FGRPC146212 (Part) · Main 3/4" UNION COUPLING	1 ea \$29.15			\$29.15
 FGRPC14696B (Part) · Main 1/4"X3/8" PUSH TO CON	1 ea \$5.60			\$5.60
↳ Check Diff and Trans Oil		\$4.30	\$0.00	\$4.30
 Rickylynn Peters (Contact)	0.2 hrs \$21.50			\$4.30
↳ Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.		\$3.80	\$0.00	\$3.80
 Ross Cowell (Contact)	0.1 hrs \$38.00			\$3.80
↳ Tire Condition and Pressure Inspection Check all tires		\$5.00	\$0.00	\$5.00
 Allan Bates (Contact)	0.2 hrs \$25.00			\$5.00
↳ Torque Wheels Verify wheels are properly torqued		\$2.15	\$0.00	\$2.15
 Rickylynn Peters (Contact)  ✓	0.1 hrs \$21.50			\$2.15
↳ Walk Around Inspection		\$9.50	\$0.00	\$9.50
 Ross Cowell (Contact)	0.25 hrs \$38.00			\$9.50
↳ Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.		\$9.50	\$0.00	\$9.50

Item	Labor	Parts	Subtotal
 Ross Cowell (Contact)	0.25 hrs \$38.00		\$9.50

## DESCRIPTION

## SUMMARY

Subtotal	\$29,263.84
Labor	\$4,079.00
Parts	\$25,184.84
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+ \$0.00 (0.0%)
<b>Total</b>	<b>\$29,263.84</b>

## RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
<b>#5168</b> [Inspection] Clutch Brake Condition Reported almost 2 years ago by Ernesto Ablog • Truck Preventative Maintenance Checklist by Ernesto Ablog Generated by the failed inspection item "Clutch Brake Condition" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Aug 23, 2023 at 4:03 PM MDT		
<b>#5169</b> [Inspection] Drag Link Reported almost 2 years ago by Ernesto Ablog • Truck Preventative Maintenance Checklist by Ernesto Ablog Generated by the failed inspection item "Drag Link" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Aug 23, 2023 at 4:03 PM MDT		
<b>#5156</b> Seat swop Reported Aug 22, 2023 by Stephen Trimble Replace drivers seat with used spare in shop		
<b>#5157</b> Crank seal Reported Aug 22, 2023 by Stephen Trimble Oil leak and blow by		
<b>#5153</b> Truck and trailer ABS Reported Aug 22, 2023 by Stephen Trimble ABS Lights on		



CX Energy Services  
PO Box 3450, 74028 RR 174, 74028 RR 174  
High Prairie, AB, T0G 1E0  
CA  
7805230245

Work Order Number: #3817  
Invoice Number:  
PO Number:

# WORK ORDER





















## WORK ORDER DETAILS

Issue Date:	Tue, Apr 9, 2024 5:16 PM	#66 2019 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X4KJ959986
Actual Start Date:	Tue, Apr 9, 2024 5:16 PM	License Plate:	
Expected Completion Date:		Operator:	Stephen Trimble
Actual Completion Date:	Fri, Apr 12, 2024	Type:	Semi Truck
Duration:	3 days	Group:	
Repair Priority Class:	Scheduled	Odometer:	726,546km
Status:	Completed	Secondary Meter:	14,816hr
Issued By:			
Assigned to:			
Vendor:			
Labels:			

## LINE ITEMS

Item	Labor	Parts	Subtotal
Truck Preventative Maintenance Inspection	\$37.00	\$731.80	\$768.80
Roper Gorgichuk (Contact)	1 hr \$37.00		\$37.00
GWKP27-1284-111EXCH (Part) · Main BATTERY-DUAL PURPOSE PACCAR	4 ea \$182.95		\$731.80
Fan Hub Fitting Leaking	\$9.29	\$9.85	\$19.14
Roper Gorgichuk (Contact)	0.25 hrs \$37.00		\$9.29
FGRPC14694A (Part) · Main ELBOW 90 1/4X1/8	1 ea \$4.25		\$4.25
FGRPC14624 (Part) · Main UNION COUP DOT,1/4	1 ea \$5.60		\$5.60

#7566 · [Inspection] Air fitting leaking on fan hub  
Generated by the failed inspection item "Fan Hub and Blades" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Apr 10, 2024 at 8:09 AM MDT

Item		Labor	Parts	Subtotal
 air filters due		\$15.20	\$208.76	\$223.96
 Ross Cowell (Contact)		0.4 hrs \$38.00		\$15.20
 NTP625128 (Part) · Main AIR FILTER W900		2 ea \$104.38		\$208.76
 engine heater repair Diagnosis and repair engine heater.		\$37.00	\$0.00	\$37.00
 Roper Gorgichuk (Contact)  Disassembled water pump and cleaned out the scum. Reassemble and tested heater		1 hr \$37.00		\$37.00
 Engine Fan Belt Replacement		\$7.77	\$90.08	\$97.85
 Roper Gorgichuk (Contact)		0.21 hrs \$37.00		\$7.77
 GWK5120910 (Part) · Main (Archived) FAN BELT W900		1 ea \$90.08		\$90.08
 #7565 · [Inspection] Replace fan belt Generated by the failed inspection item "Belt Tension and Condition" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Apr 10, 2024 at 8:09 AM MDT				
 Engine Oil & Filter Replacement		\$9.25	\$355.17	\$364.42
 Roper Gorgichuk (Contact)		0.25 hrs \$37.00		\$9.25
 NXTDBL7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000		1 ea \$58.65		\$58.65
 MXF5W40 (Part) · Main ENGINE OIL 5W40 BULK		42 L \$7.06		\$296.52
 Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.		\$6.88	\$0.00	\$6.88
 Chad Caouette (Contact) 		0.25 hrs \$27.50		\$6.88
 Check Diff and Trans Oil		\$6.88	\$0.00	\$6.88
 Chad Caouette (Contact) 		0.25 hrs \$27.50		\$6.88



Item	Labor	Parts	Subtotal
↳ <b>Inspect and Service Trailer Hitch</b> Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$6.88	\$0.00	\$6.88
<div> <div></div> <div>Chad Caouette (Contact)</div> </div> <div> <div></div> <div>0.25 hrs</div> </div> <div> <div></div> <div>\$27.50</div> </div>			\$6.88
↳ <b>Tire Condition and Pressure Inspection</b> Check all tires	\$6.00	\$0.00	\$6.00
<div> <div></div> <div>Rickylynn Peters (Contact)</div> </div> <div> <div></div> <div>0.25 hrs</div> </div> <div> <div></div> <div>\$24.00</div> </div>			\$6.00
↳ <b>Torque Wheels</b> Verify wheels are properly torqued	\$9.25	\$0.00	\$9.25
<div> <div></div> <div>Roper Gorgichuk (Contact)</div> </div> <div> <div></div> <div>0.25 hrs</div> </div> <div> <div></div> <div>\$37.00</div> </div>			\$9.25
↳ <b>Walk Around Inspection</b>	\$22.50	\$0.00	\$22.50
<div> <div></div> <div>JOE NEMEC (Contact)</div> </div> <div> <div></div> <div>0.25 hrs</div> </div> <div> <div></div> <div>\$90.00</div> </div>			\$22.50
↳ <b>Grease Unit</b> Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$7.77	\$0.00	\$7.77
<div> <div></div> <div>Roper Gorgichuk (Contact)</div> </div> <div> <div></div> <div>0.21 hrs</div> </div> <div> <div></div> <div>\$37.00</div> </div>			\$7.77

#### DESCRIPTION

#### SUMMARY

Subtotal	\$1,577.33
Labor	\$181.67
Parts	\$1,395.66
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
<b>Total</b>	<b>\$1,577.33</b>

Issue	Assigned	Due
#7550 Slight odour of battery Reported Apr 9, 2024 by Stephen Trimble Odour of battery by battery box. Wing nuts too tight to open to investigate		



CX Energy Services  
PO Box 3450, 74028 RR 174, 74028 RR 174  
High Prairie, AB, T0G 1E0  
CA  
7805230245

Work Order Number: #4313  
Invoice Number:  
PO Number:



















# WORK ORDER

## WORK ORDER DETAILS

Issue Date:	Thu, Jul 4, 2024 7:35 AM	#66 2019 Kenworth W900	
Scheduled Start Date:	Thu, Jul 4, 2024 7:36 AM	VIN/SN: 1XKWD40X4KJ959986 License Plate:	
Actual Start Date:	Thu, Jul 4, 2024 7:36 AM	Operator: Stephen Trimble Type: Semi Truck Group:	
Expected Completion Date:			
Actual Completion Date:	Thu, Jul 4, 2024 7:36 AM	Odometer: 780,590km Secondary Meter: 15,779hr	
Duration:			
Repair Priority Class:	Scheduled		
Status:	Completed		
Issued By:	Rickylynn Peters		
Assigned to:			
Vendor:			
Labels:			

## LINE ITEMS

Item	Labor	Parts	Subtotal
Wash Out Rad	\$112.00	\$0.00	\$112.00
MICHAEL ABLOG (Contact)	2 hrs		\$76.00
removed rad and washed it out in the wash bay	\$38.00		
Ernesto Ablog (Contact)	1 hr		\$36.00
	\$36.00		
#8464 · Engine running hot Defluffed as must as possible in the field and still running hot,			
Engine fan Replacement	\$19.00	\$321.13	\$340.13
MICHAEL ABLOG (Contact)	0.5 hrs		\$19.00
	\$38.00		
GWK996813502-002 (Part) · Main FAN BLADE T800 W900	1 ea		\$321.13
	\$321.13		

Item	Labor	Parts	Subtotal
<b>#8519 · [Inspection] Fan Hub and Blades</b> Generated by the failed inspection item "Fan Hub and Blades" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Jul 4, 2024 at 8:32 AM MDT			
 Fuel Filter Replacement	\$9.00	\$108.27	\$117.27
 Ernesto Ablog (Contact) <div>0.25 hrs \$36.00</div>			\$9.00
 BALPF46081 (Part) · Main BALDWIN FUEL FILTER <div>1 ea \$43.96</div>			\$43.96
 NTXDBF6776 (Part) · Main FUEL FILTER SPIN ON S/AS BF46129 <div>1 ea \$64.31</div>			\$64.31
 Truck Preventative Maintenance Inspection	\$27.00	\$0.00	\$27.00
 Ernesto Ablog (Contact) <div>0.75 hrs \$36.00</div>			\$27.00
 A2 RH tires flat	\$40.50	\$0.00	\$40.50
 Allan Bates (Contact) <div>1.5 hrs \$27.00</div>			\$40.50
 A3Lhs Brake Pot Spring Broken	\$24.00	\$148.90	\$172.90
 Rickylynn Peters (Contact) <div>1 hr \$24.00</div>			\$24.00
 FGRLCP3030 (Part) · Main LIFESEAL 2.5, BRAKE P <div>1 ea \$148.90</div>			\$148.90
<b>#8518 · [Inspection] Brake Pot Condition</b> Generated by the failed inspection item "Brake Pot Condition" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Jul 4, 2024 at 8:32 AM MDT			
 Hood Crack Repair	\$38.00	\$0.00	\$38.00
 MICHAEL ABLOG (Contact) <div>1 hr \$38.00</div>  buffed up area that was cracked and put epoxy over it.			\$38.00
 Engine Oil & Filter Replacement	\$19.00	\$225.52	\$244.52
 Joseph Pitney (Contact) <div>0.5 hrs \$38.00</div>			\$19.00
 NXTDBL7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000 <div>1 ea \$58.65</div>			\$58.65
 MXF15W40 (Part) · Main ENGINE OIL, 15W40 BUL <div>41 L \$4.07</div>			\$166.87

Item		Labor	Parts	Subtotal
↳ <b>Air System Leaks</b>		\$12.00	\$0.00	\$12.00
	Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.			
👤 Rickylynn Peters (Contact)		0.5 hrs		\$12.00
🗑 Deleted chain up leveling valve.		\$24.00		
↳ <b>Check Diff and Trans Oil</b>		\$6.00	\$0.00	\$6.00
👤 Rickylynn Peters (Contact)		0.25 hrs		\$6.00
		\$24.00		
↳ <b>Inspect and Service Trailer Hitch</b>		\$9.50	\$0.00	\$9.50
	Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.			
👤 MICHAEL ABLOG (Contact)		0.25 hrs		\$9.50
		\$38.00		
↳ <b>Tire Condition and Pressure Inspection</b>		\$6.00	\$0.00	\$6.00
	Check all tires			
👤 Rickylynn Peters (Contact)		0.25 hrs		\$6.00
🗑		\$24.00		
↳ <b>Torque Wheels</b>		\$13.50	\$0.00	\$13.50
	Verify wheels are properly torqued			
👤 Allan Bates (Contact)		0.5 hrs		\$13.50
		\$27.00		
↳ <b>Walk Around Inspection</b>		\$22.50	\$0.00	\$22.50
👤 JOE NEMEC (Contact)		0.25 hrs		\$22.50
		\$90.00		
↳ <b>Grease Unit</b>		\$6.00	\$6.90	\$12.90
	Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.			
👤 Rickylynn Peters (Contact)		0.25 hrs		\$6.00
		\$24.00		
🔧 MXFPSC30 (Part) · Main (Archived)		1 tube		\$6.90
	GREASE PRECISION TUBE	\$6.90		

## DESCRIPTION

## SUMMARY

---

Subtotal	\$1,174.72
Labor	\$364.00
Parts	\$810.72
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$1,174.72



CX Energy Services  
PO Box 3450, 74028 RR 174, 74028 RR 174  
High Prairie, AB, T0G 1E0  
CA  
7805230245











Work Order Number: #4644  
Invoice Number:  
PO Number:

# WORK ORDER

## WORK ORDER DETAILS

Issue Date:	Thu, Aug 29, 2024 4:34 PM	#66 2019 Kenworth W900	
Scheduled Start Date:	Thu, Aug 29, 2024 4:35 PM	VIN/SN: 1XKWD40X4KJ959986 License Plate:	
Actual Start Date:	Thu, Aug 29, 2024 4:35 PM	Operator: Stephen Trimble Type: Semi Truck Group:	
Expected Completion Date:			
Actual Completion Date:	Tue, Sep 3, 2024 8:49 AM	Odometer: 825,332km Secondary Meter: 16,534hr	
Duration:	4 days 16 hrs 14 mins		
Repair Priority Class:	Non-Scheduled		
Status:	Completed		
Issued By:			
Assigned to:			
Vendor:			
Labels:			

## LINE ITEMS

Item	Labor	Parts	Subtotal
 Air Compressor Stainless line	\$38.00	\$104.24	\$142.24
 MICHAEL ABLOG (Contact)  replaced line	1 hr \$38.00		\$38.00
 GWKD9022-6050 (Part) - Main HOSE ASSY	1 ea \$104.24		\$104.24
 Service truck	\$55.00	\$0.00	\$55.00
 Kurt Kerekanich (Contact)  Greased truck Checked diffs	1 hr \$36.00		\$36.00
 MICHAEL ABLOG (Contact)  Changed oil	0.5 hrs \$38.00		\$19.00
 Clutch Assembly Replacement	\$720.00	\$7,980.17	\$8,700.17

Item		Labor	Parts	Subtotal
👤 Kurt Kerekanich (Contact)				\$720.00
🔧	Removed exhaust, pto, driveline and transmission. Found springs in clutch had broke and damaged friction plates and took a chunk out of flywheel. Installed resurfaced flywheel in good condition billed unit for new flywheel. Installed rebuilt transmission and re-installed PTO with new gaskets. Filled with new oil. Re-installed driveline and exhaust with all new gaskets.	20 hrs \$36.00		
🔧 GWKK042-79 (Part) · Main	1 ea \$129.88			\$129.88
SHIFTER BOOT UPPER				
🔧 GWKK042-080 (Part) · Main	1 ea \$51.80			\$51.80
BOOT-LOWER SHIFT				
🔧 FGR33225 (Part) · Main	2 ea \$12.20			\$24.40
5" TORCTITE SS CLAMP				
🔧 SPI2507018X (Part) · Main	2 ea \$22.80			\$45.60
SPL250-BEARING RETAIN				
🔧 GWK2866337CUM (Part) · Main	1 ea \$18.67			\$18.67
EXHAUST GASKET 5" CIR				
🔧 GWK90-0013 (Part) · Main	1 ea \$16.72			\$16.72
CLAMP -V BAND 5"				
🔧 A1DRTL018918REBUILT (Part) · Main	1 ea \$4,049.55			\$4,049.55
TRANSMISSION REBUILD				
🔧 GWK308925-25 (Part) · Main	1 ea \$1,209.47			\$1,209.47
CLUTCH 15.5 2050 TORQ				
🔧 GWK4965569 (Part) · Main	1 ea \$135.94			\$135.94
REAR CRANK SEAL CUMM				
🔧 GWK3680922CUM (Part) · Main (Archived)	1 ea \$2,298.14			\$2,298.14
FLYWHEEL				
🔧 Front Gear Housing Replacement		\$2,560.00	\$2,029.15	\$4,589.15
🔧	Front gear housing leaking between housing and engine block Removed front gears and housing cleaned up block surface and installed new housing with new gasket.			
👤 MICHAEL ABLOG (Contact)	20 hrs \$38.00			\$760.00
👤 JOE NEMEC (Contact)	20 hrs \$90.00			\$1,800.00
🔧 GWK351-0415 (Part) · Main	1 ea \$63.82			\$63.82
OIL PAN HEATER				
🔧 5575513CUM (Part) · Main	1 ea \$11.06			\$11.06
SCREW, HEX FLANGE HEAD CAP S/AS GWK3678882				



Item		Labor	Parts	Subtotal
☞ GWK3687007 (Part) · Main	1 ea			\$56.98
FRONT COVER SEAL RECT	\$56.98			
☞ GWK3688113 (Part) · Main	1 ea			\$18.68
ENGINE COVER PLUG S/AS X-12-1207	\$18.68			
☞ GWK5658098CUM (Part) · Main	4 ea			\$16.64
SEAL, O-RING	\$4.16			
☞ GWK3104392 (Part) · Main	1 ea			\$81.13
VALVE COVER GASKET IS	\$81.13			
☞ GWK3691032CUM (Part) · Main	1 ea			\$50.28
TUBE, LUBE OIL DRAIN	\$50.28			
☞ NAP3600015 (Part) · Main	1 ea			\$44.33
BLOCK HEATER CORD, 4'	\$44.33			
☞ GWK4026684 (Part) · Main	1 ea			\$183.28
OIL PAN GASKET CUMM	\$183.28			
☞ GWK4988280 (Part) · Main	1 ea			\$5.49
GASKET POWER STEERING	\$5.49			
☞ GWK5414049 (Part) · Main	1 ea			\$36.32
FUEL PUMP GASKET	\$36.32			
☞ GWK5468170 (Part) · Main	1 ea			\$1,170.47
GEAR HOUSING FRONT ST	\$1,170.47			
☞ GWK5440813 (Part) · Main	1 ea			\$20.52
AIR COMPRESSOR GASKET	\$20.52			
☞ GWK3685173CUM (Part) · Main	1 ea			\$93.02
CRANK SEAL FRONT CUMM	\$93.02			
☞ GWK4374074 (Part) · Main	3 ea			\$13.11
FUEL PUMP IDLER SCREW	\$4.37			
☞ GWK5719778CUM (Part) · Main	1 ea			\$13.21
GASKET, CAMSHAFT COVER S/AS 3679932CUM	\$13.21			
☞ GWK3686368 (Part) · Main (Archived)	1 ea			\$11.81
RECTANGULAR SEAL IDLE	\$11.81			
☞ GWK4299124 (Part) · Main	1 ea			\$15.43
IDLER GEAR PLATE O-RI	\$15.43			
☞ GWK4299125 (Part) · Main	1 ea			\$20.95
CAMSHAFT COVER REAR O	\$20.95			
☞ GWK4393089 (Part) · Main	1 ea			\$102.62
GEAR HOUSING GASKET F	\$102.62			

DESCRIPTION	SUMMARY
	Subtotal \$13,486.56
	Labor \$3,373.00
	Parts \$10,113.56
	Labor Markup + \$0.00 (0.0%)
	Parts Markup + \$0.00 (0.0%)
	Warranty Credits - \$0.00 (Fixed)
	Discount - \$0.00 (0.0%)
	Tax +\$0.00 (0.0%)
	Total \$13,486.56

RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
<div>#9007</div> <div>Shifter boot</div> <div>Reported Aug 13, 2024 by Stephen Trimble</div> <div>Replace if possible</div>		
<div>#8021</div> <div>Oil weep</div> <div>Reported May 21, 2024 by Stephen Trimble</div> <div>Engine oil weep from front , Joe knows about</div>		
<div>#9202</div> <div>Clutch issue</div> <div>Reported Aug 29, 2024 by Stephen Trimble</div> <div>Clutch not unloading, clutch brake not really working all the time , clutch not engaging when pedal down, truck kinda lurching forward</div>		



CX Energy Services  
PO Box 3450, 74028 RR 174, 74028 RR 174  
High Prairie, AB, T0G 1E0  
CA  
7805230245

Work Order Number: #4812  
Invoice Number:  
PO Number:

# WORK ORDER










## WORK ORDER DETAILS

Issue Date:	Wed, Sep 25, 2024 10:09 AM	#66 2019 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X4KJ959986
Actual Start Date:	Wed, Sep 25, 2024 10:10 AM	License Plate:	
Expected Completion Date:		Operator:	Stephen Trimble
Actual Completion Date:	Mon, Sep 30, 2024	Type:	Semi Truck
Duration:	5 days	Group:	
Repair Priority Class:	Scheduled	Odometer:	838,851km
Status:	Completed	Secondary Meter:	16,768hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

## LINE ITEMS

Item	Labor	Parts	Subtotal
 Torque rods A2rhs a3	\$120.00	\$321.20	\$441.20
 Rickylynn Peters (Contact)	5 hrs		\$120.00
 Installed new bushings.	\$24.00		
 FGRTTB6825 (Part) · Main	8 ea		\$321.20
V-ROD BUSHING TORQUE	\$40.15		
 Truck Preventative Maintenance Inspection	\$18.00	\$0.00	\$18.00
 Kurt Kerekanich (Contact)	0.5 hrs		\$18.00
	\$36.00		
 Air To Air Cooler Replacement	\$47.50	\$1,028.91	\$1,076.41
 MICHAEL ABLOG (Contact)	1.25 hrs		\$47.50
	\$38.00		
 GWKCAC61-1213TRP (Part) · Main	1 ea		\$1,028.91
COOLER-CHARGE AIR S/AS FGR44012517	\$1,028.91		
 Turn shut down or move it's rubbing on spring	\$6.00	\$0.00	\$6.00

Item		Labor	Parts	Subtotal
 Rickylynn Peters (Contact)	0.25 hrs \$24.00			\$6.00
 Ds stack rubbing		\$18.00	\$22.45	\$40.45
 Ernesto Ablog (Contact)	0.5 hrs \$36.00			\$18.00
 Welded put tin foil and replaced exhaust clamp				
 FGRSW50A3 (Part) · Main	1 ea \$22.45			\$22.45
EXHAUST CLAMP 5" SS				
 90pipe below bellow clamps loose		\$6.00	\$70.40	\$76.40
 Rickylynn Peters (Contact)	0.25 hrs \$24.00			\$6.00
 Installed new gasket, clamps.				
 GWK2866636CUM (Part) · Main	2 ea \$19.11			\$38.22
EXHAUST GASKET 4"				
 GWK90-0012 (Part) · Main	2 ea \$16.09			\$32.18
V BAND CLAMP				
 Tighten yoke transmission		\$36.00	\$0.00	\$36.00
 Kurt Kerekanich (Contact)	1 hr \$36.00			\$36.00
 engine heater repair		\$162.00	\$619.51	\$781.51
Diagnosis and repair engine heater.				
 Ernesto Ablog (Contact)	4.5 hrs \$36.00			\$162.00
 Re route engine heater and replaced coolant pump.				
 PWR25.2596.25.0100.2 (Part) · Main	1 ea \$619.51			\$619.51
D12 COOLANT PUMP				
 Front motor mount plate broken		\$126.00	\$154.65	\$280.65
 JOE NEMEC (Contact)	1 hr \$90.00			\$90.00
 Kurt Kerekanich (Contact)	1 hr \$36.00			\$36.00
 FGRM203039KUB2H (Part) · Main (Archived)				\$154.65
MOTOR MOUNT KIT-KENWORTH Archive one purchase order closed. We stocked atro version.				
	1 ea \$154.65			
 Engine Oil & Filter Replacement		\$6.00	\$229.59	\$235.59
 Rickylynn Peters (Contact)	0.25 hrs \$24.00			\$6.00
 MXF15W40 (Part) · Main	42 L \$4.07			\$170.94
ENGINE OIL, 15W40 BUL				

Item	Labor	Parts	Subtotal
 NXTDBL7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000			\$58.65
	1 ea \$58.65		
↳ Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$6.75	\$0.00	\$6.75
 Allan Bates (Contact)	0.25 hrs \$27.00		\$6.75
↳ Check Diff and Trans Oil	\$6.75	\$0.00	\$6.75
 Allan Bates (Contact)	0.25 hrs \$27.00		\$6.75
↳ Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$6.00	\$0.00	\$6.00
 Rickylynn Peters (Contact)	0.25 hrs \$24.00		\$6.00
↳ Tire Condition and Pressure Inspection Check all tires	\$6.75	\$0.00	\$6.75
 Allan Bates (Contact)	0.25 hrs \$27.00		\$6.75
↳ Torque Wheels Verify wheels are properly torqued	\$6.75	\$0.00	\$6.75
 Allan Bates (Contact)	0.25 hrs \$27.00		\$6.75
↳ Walk Around Inspection	\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact)	0.25 hrs \$90.00		\$22.50
↳ Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$6.75	\$4.67	\$11.42
 Allan Bates (Contact)	0.25 hrs \$27.00		\$6.75
 MNACHV259118-652 (Part) · Main STARPLEX EP2 TUBE Summer Grease	1 ea \$4.67		\$4.67

## DESCRIPTION

## SUMMARY

Subtotal	\$3,059.13
Labor	\$607.75
Parts	\$2,451.38
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$3,059.13

## RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
<b>#9403</b> Engine heater Reported Sep 14, 2024 by Stephen Trimble Timer runs and tries to fire but unsuccessfully, coolant temp not warming up		
<b>#9549</b> Engine heater attempts to fire but nothing Reported Sep 24, 2024 by Stephen Trimble		
<b>#9550</b> Air to air leak Reported Sep 24, 2024 by Stephen Trimble Possible air to air leak , can hear air leaking at front of hood, also pyro heating up faster since front cover replacement		
<b>#9572</b> [Inspection] Rubbing on hood Reported 11 months ago by Kurt Kerekanich • Truck Preventative Maintenance Checklist by Kurt Kerekanich Generated by the failed inspection item "Positive Air function" on the "Truck Preventative Maintenance Checklist" form submitted by Kurt Kerekanich on Sep 25, 2024 at 10:55 AM MDT		
<b>#9571</b> [Inspection] Stack Bushings Reported 11 months ago by Kurt Kerekanich • Truck Preventative Maintenance Checklist by Kurt Kerekanich Generated by the failed inspection item "Stack Bushings" on the "Truck Preventative Maintenance Checklist" form submitted by Kurt Kerekanich on Sep 25, 2024 at 10:55 AM MDT		
<b>#9569</b> [Inspection] Driveline and Steady Bearing Reported 11 months ago by Kurt Kerekanich • Truck Preventative Maintenance Checklist by Kurt Kerekanich Generated by the failed inspection item "Driveline and Steady Bearing" on the "Truck Preventative Maintenance Checklist" form submitted by Kurt Kerekanich on Sep 25, 2024 at 10:55 AM MDT		
<b>#9570</b> [Inspection] Engine and Transmission Mounts Reported 11 months ago by Kurt Kerekanich • Truck Preventative Maintenance Checklist by Kurt Kerekanich Generated by the failed inspection item "Engine and Transmission Mounts" on the "Truck Preventative Maintenance Checklist" form submitted by Kurt Kerekanich on Sep 25, 2024 at 10:55 AM MDT		



CX Energy Services  
PO Box 3450, 74028 RR 174, 74028 RR 174  
High Prairie, AB, T0G 1E0  
CA  
7805230245








Work Order Number: #5107  
Invoice Number:  
PO Number:






















# WORK ORDER

## WORK ORDER DETAILS

Issue Date:	Wed, Nov 6, 2024 9:54 AM	#66 2019 Kenworth W900
Scheduled Start Date:		VIN/SN: 1XKWD40X4KJ959986
Actual Start Date:	Wed, Nov 6, 2024 9:55 AM	License Plate:
Expected Completion Date:		Operator: Stephen Trimble
Actual Completion Date:	Fri, Nov 8, 2024	Type: Semi Truck
Duration:	2 days	Group:
Repair Priority Class:	Scheduled	Odometer: 868,802km
Status:	Completed	Secondary Meter: 17,278hr
Issued By:	JOE NEMEC	
Assigned to:		
Vendor:		
Labels:		

## LINE ITEMS

Item	Labor	Parts	Subtotal
 engine heater repair Diagnosis and repair engine heater.	\$19.50	\$0.00	\$19.50
 Roper Gorgichuk (Contact)  Swapped coolant lines around	0.5 hrs \$39.00		\$19.50
 A2 Output Yoke Nut Loose	\$19.50	\$50.90	\$70.40
 Roper Gorgichuk (Contact)	0.5 hrs \$39.00		\$19.50
 SPI1707018X (Part) · Main STRAPKIT SPL170	1 ea \$24.90		\$24.90
 FGRKIT2637 (Part) · Main ROCKWELL DIFF OUTPUT,	1 ea \$26.00		\$26.00
 A3 Lhs Brake Pad	\$19.50	\$201.65	\$221.15
 Roper Gorgichuk (Contact)	0.5 hrs \$39.00		\$19.50

Item		Labor	Parts	Subtotal
 FGRXSS714707QPK (Part) · Main	1 ea			\$56.65
BRAKE SHOE 16.5X7" Q+	\$56.65			
 GWKDB1657B (Part) · Main	1 ea			\$145.00
BRAKE DRUM 16.5 X 7 S/AS GWK16792X	\$145.00			
 A2 RHS Brake Shoes		\$19.50	\$201.65	\$221.15
 Roper Gorgichuk (Contact)	0.5 hrs			\$19.50
	\$39.00			
 FGRXSS714707QPK (Part) · Main	1 ea			\$56.65
BRAKE SHOE 16.5X7" Q+	\$56.65			
 GWKDB1657B (Part) · Main	1 ea			\$145.00
BRAKE DRUM 16.5 X 7 S/AS GWK16792X	\$145.00			
 Engine Oil & Filter Replacement		\$20.63	\$208.76	\$229.39
 Chad Caouette (Contact)	0.75 hrs			\$20.63
 ..	\$27.50			
 NTXP625128 (Part) · Main	2 ea			\$208.76
AIR FILTER W900	\$104.38			
 Drag Link Replacement		\$6.88	\$482.74	\$489.62
 Chad Caouette (Contact)	0.25 hrs			\$6.88
 put new drag link on	\$27.50			
 GWKL24VU8036B11 (Part) · Main (Archived)	1 ea			\$482.74
DRAW LINK KENWORTH	\$482.74			
 #10092 · [Inspection] Drag link worn out				
Generated by the failed inspection item "Drag Link" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Nov 6, 2024 at 11:15 AM MST				
 Truck Preventative Maintenance Inspection		\$39.00	\$0.00	\$39.00
 Roper Gorgichuk (Contact)	1 hr			\$39.00
	\$39.00			
 Engine Oil & Filter Replacement		\$9.75	\$357.69	\$367.44
 Roper Gorgichuk (Contact)	0.25 hrs			\$9.75
	\$39.00			
 MXF5W40 (Part) · Main	42 L			\$299.04
ENGINE OIL 5W40 BULK	\$7.12			
 NXTDBL7900 (Part) · Main	1 ea			\$58.65
OIL FILTER HIGH EFFICIENCY S/AS BD50000	\$58.65			



Item		Labor	Parts	Subtotal
↳ Air System Leaks		\$9.75	\$0.00	\$9.75
	Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.			
👤 Roper Gorgichuk (Contact)	0.25 hrs			\$9.75
	\$39.00			
↳ Check Diff and Trans Oil		\$7.25	\$0.00	\$7.25
👤 Allan Bates (Contact)	0.25 hrs			\$7.25
	\$29.00			
↳ Inspect and Service Trailer Hitch		\$0.00	\$0.00	\$0.00
	Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.			
↳ Tire Condition and Pressure Inspection		\$154.00	\$4,172.00	\$4,326.00
	Check all tires			
👤 Jayden Binet (Contact)	4 hrs			\$96.00
	\$24.00			
👤 Allan Bates (Contact)	2 hrs			\$58.00
	\$29.00			
🛒 KALDT890 (Part) · Main	8 ea			\$3,472.00
ROAD X DRIVE TIRES 11R 245	\$434.00			
🛒 CXEXZE2 (Part) · Main	2 ea			\$700.00
STEER TIRES 11R 24.5	\$350.00			
↳ Torque Wheels		\$4.80	\$0.00	\$4.80
	Verify wheels are properly torqued			
👤 Jayden Binet (Contact)	0.2 hrs			\$4.80
	\$24.00			
↳ Walk Around Inspection		\$22.50	\$0.00	\$22.50
👤 JOE NEMEC (Contact)	0.25 hrs			\$22.50
	\$90.00			
↳ Grease Unit		\$7.25	\$0.00	\$7.25
	Grease all grease points on unit, ie. u-joints, s-cams. steering linkage.			
👤 Allan Bates (Contact)	0.25 hrs			\$7.25
	\$29.00			

## DESCRIPTION

## SUMMARY

Subtotal	\$6,035.20
Labor	\$359.81
Parts	\$5,675.39
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$6,035.20

## RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
#10091 [Inspection] A2 RHS and A3 LHS brake shoes low Reported 9 months ago by Roper Gorgichuk • Truck Preventative Maintenance Checklist by Roper Gorgichuk Generated by the failed inspection item "Brake Lining Thickness 5/16"" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Nov 6, 2024 at 11:15 AM MST		
#10090 [Inspection] A2 output yoke nut loose Reported 9 months ago by Roper Gorgichuk • Truck Preventative Maintenance Checklist by Roper Gorgichuk Generated by the failed inspection item "Driveline and Steady Bearing" on the "Truck Preventative Maintenance Checklist" form submitted by Roper Gorgichuk on Nov 6, 2024 at 11:15 AM MST		
#10070 Tires Reported Nov 4, 2024 by Stephen Trimble Steering tires showing uneven wear		
#10072 Engine heater Reported Nov 5, 2024 by Stephen Trimble Coolant lines reversed , error code when starting truck		
#10068 Tires Reported Nov 4, 2024 by Stephen Trimble Badly need new drive tires		



CX Energy Services  
PO Box 3450, 74028 RR 174, 74028 RR 174  
High Prairie, AB, T0G 1E0  
CA  
7805230245

Work Order Number: #5909  
Invoice Number:  
PO Number:












# WORK ORDER

## WORK ORDER DETAILS

Issue Date:	Fri, Mar 7, 2025 1:32 PM	#66 2019 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X4KJ959986
Actual Start Date:	Fri, Mar 7, 2025 1:32 PM	License Plate:	
Expected Completion Date:		Operator:	Stephen Trimble
Actual Completion Date:	Fri, Mar 14, 2025	Type:	Semi Truck
Duration:	6 days	Group:	
Repair Priority Class:	Non-Scheduled	Odometer:	938,753km
Status:	Completed	Secondary Meter:	18,938hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

## LINE ITEMS

Item	Labor	Parts	Subtotal
 engine heater repair Diagnosis and repair engine heater.	\$76.50	\$426.44	\$502.94
 Kurt Kerekanich (Contact)  Replaced plug on heater	1.5 hrs \$38.00		\$57.00
 Roper Gorgichuk (Contact)  Cleaned water pump	0.5 hrs \$39.00		\$19.50
 PWR22.1000.31.930 (Part) · Main HYD 10-CONNECTOR KIT	1 ea \$35.90		\$35.90
 GWK5658098CUM (Part) · Main SEAL, O-RING	2 ea \$4.67		\$9.34
 GWK4307411RX (Part) · Main FUEL PUMP ACTUATOR	1 ea \$381.20		\$381.20
 Engine Brake Inspect	\$540.00	\$2,717.47	\$3,257.47

Item		Labor	Parts	Subtotal
 JOE NEMEC (Contact)				\$540.00
 Jake getting weak when oil temps get over 220F. Found some wear on jake slave pistons as well as rocker shafts. After repair it improved a bit but still not 100% changed jake solenoids and valve cover harness. Issue was reported to have started after issue with crankshaft position harness. Harness had been repaired no codes came back for crank shaft position but replaced that section of harness to eliminate possibility. Replaced all adjustment screws for intake and exhaust valves as oil coming out of the ends to lubricate valve bridge was excessive.				
		6 hrs		
		\$90.00		
 GWK2882081CUM (Part) · Main (Archived)		1 ea		\$709.94
	KIT, ENGINE BRAKE OVERHAUL	\$709.94		
 GWK4357177CUM (Part) · Main		1 ea		\$30.58
	PRESSURE RELIEF VALVE	\$30.58		
 GWK2882570 (Part) · Main		1 ea		\$194.67
	ROCKER SHAFT LEVER	\$194.67		
 GWK2882571 (Part) · Main		1 ea		\$330.50
	ROCKER SHAFT LEVER	\$330.50		
 GWK3686307CUM (Part) · Main		2 ea		\$439.16
	VALVE, ENGINE BRAKE CONTROL	\$219.58		
 GWK4059377CUM (Part) · Main		12 ea		\$447.96
	SCREW, RKR LEVEL ADJUSTING	\$37.33		
 GWK3686370 (Part) · Main		1 ea		\$354.96
	INJECTOR WIRING HARNE	\$354.96		
 GWK3104392 (Part) · Main		1 ea		\$88.49
	VALVE COVER GASKET IS	\$88.49		
 GWK5575345CUM (Part) · Main		1 ea		\$121.21
	HARNESS, 2020 X15 ETR CNT	\$121.21		

DESCRIPTION

SUMMARY

Subtotal	\$3,760.41
Labor	\$616.50
Parts	\$3,143.91
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$3,760.41