EP42-1

Repair History – 2007 John Deere 750 J LGP - Serial # T0750JX135740 2025

- Replace all Segments
- Replace & Program ECM Engine Controller completed by Brandt Tractor Ltd.
- Replace Fuel Pump
- Replace Temperature Sensor (Intake Manifold)
- Replace Engine Speed Sensor

2024

- Replace Water Pump, Gasket, Seal, and kit
- Replace Tilt Cylinder
- Replace Hydrostatic oil cooler bypass solenoid

2023

- Replace all Segments
- Rebuild Right Angle Cylinder (Nov) completed by Highmark Mechanical Inc.
- Repair Left Angle Cylinder (Aug) completed by Highmark Mechanical Inc.
- Replace Blower Fan for AC
- Replace Solenoid Valve (vehicle main hydraulic system)
- Replace Hydraulic filter, Transmission Filters, Thermostat, Gaskets

2022

- Replace Engine Oil pressure Sensor
- Repair Right rear final drive assembly completed by Brandt Tractor Ltd.
- Replace Wheel Speed Sensor

2021

- Replace Rails, cutting edges, corner bits
- Replace Top Carrier rollers
- · Replace Fuel injection tube, clamp, and cap screw
- Replace all segments

2020

- Replace Hydraulic Fan Motor
- Replace Coolant Filler Cap
- Replace wear plates, bushing, brackets for front idler both sides
- Replace cab mounts (isolators)
- Replace Receiver Dryer, o-ring, Thermal valve, steel lines for AC
- Repair Hardbar right side completed by Jena Machining Ltd.
- Replace Pin, self aligning bushing, seal, ring, elbow, hose (pivot shaft & crossbar)
- Replace v-belt, belt tensioner

<u> 2019</u>

- Replace left windowpane, rear window glass
- Replace injection nozzle, fuel lines
- Replace starter motor
- (Engine overhaul) @ 11035 Hrs. April 2019 completed by HH&M Contracting Ltd.