

R 21-1

Maintenance Log

Vin # CAL004890
Vehicle

2005 case 850 k crawler

hrs

Date	KMS	Description of Work	Parts Type / Other Info
Dec 4/23	3348 hrs	Backup alarm quit working.	Replaced backup alarm.
Nov 3/24	3530 hrs	Relays were acting up Dylan sorted Replaced 6 relay harness	Relay/ Relay harness
Nov 17/24	3511 hrs	Needed eng's service Changed oil/filters	Air filter/oil filter Fuel Filter
Nov 17/24	3511 hrs	Stereo was acting up/New Pioneer stereo-	Pioneer stereo
Feb 20/25	3580 hrs	ROPS front sweep stripped bolt.	welded new nut/replac hardware..
May 25/25	3600 hrs	Alternator quit charging/replaced with new batteries	New alternator and batteries
July 8/25	3650	O-ring in back of door motor let go. Scott Douglas fixed it	New o-rings.

SHOP - MAINTENANCE RECORD

2010

Sin # CAL004890

2005 CASE 850K Series 2
Unit No. _____

Date:	Component:	Description of Problem:	Corrective Action Taken:	Hrs/Odom	Assigned:	Done:
Jan 5 2022	Fluids in dozer	Needed fluid changed in all components	Changed Hydraulic fluid/final drive oil/engine oil/winch oil	2844 hrs	Alexis mechanical	✓
11 " "	Engine oil/filter	Needed fuel service	Changed engine oil/oil filter/fuel filter/air filter	2844 hrs	Alexis mechanical	✓
11 " "	Under carriage	under carriage need switch out	New rails/idlers/sprockets/carrier rollers/bottom rollers	2844 hrs	Alexis mechanical	✓
July 15 2022	Engine oil change	changed engine oil	Needed engine oil change/oil filter/fuel filter/air filter	3154 hrs	Charles Duperron	✓
July 15 2022	A/C control	A/C control failed/knob broke off	Changed ac control module	3154 hrs	Charles Duperron	✓
July 15 2022	windshield washer motor	Pump wouldn't pump washer fluid	Changed out washer pump for new one	3154 hrs	Charles Duperron	✓
Nov 18 2022	Heater HVAC system	Heater wasn't putting out heat	Replaced Heater control module	3200 hrs	Charles Duperron	✓
Nov 18 2022	work lights	work lights were poor	Replaced with LEH work lights	3200 hrs	Charles Duperron	✓
Nov 18 2022	Hydraulic lines	lines were cracked and rotted	changed out Hydraulic lines on angle and tilt rams	3200 hrs	Charles Duperron	✓
Oct 10 2023	Injection fuel system	Injector seemed to be missing	Replaced all 6 injectors from GIL industries	3337 hrs	Alexis mechanical	✓
Oct 17 2023	engine screen	Needed engine service	Changed engine oil/oil filter/fuel filter and air filters	3337 hrs	Charles Duperron	✓
Oct 18 2023	Final drive	Left final drive needed service	drained oil and re-filled with Boss all season PDH	3338 hrs	Charles Duperron	✓
Oct 22 2023	fuel pump	Mechanic suggested replace fuel pump	Tractor fluid. Replaced with new fuel pump	3338 hrs	Charles Duperron	✓
Dec 1 2023	Final right final drive	Top of it was leaking	re-sealed and replaced O-rings that were regum	3348 hrs	Scott's Field Service	✓
Dec 1 2023	Hydraulic pump	Hydraulic pump leaking	re-built/re-sealed at R and C Hydraulics Scott's Field Service	3348 hrs	Scott's Field Service	✓

oil filter Luber finer LFP 6015 fuel filters FP587F air filter from donaldson P781039
 sec donaldson P777634
 \\Server1\group folder\EQUIPMENT VEHICLES\Maintenance\SHOP - MAINTENANCE RECORD