| Unit | Model | Date | Work Order Details |
|------|--------|------------|--|
| 1683 | SY215C | 7/30/2023 | Installed packer |
| 1683 | SY215C | 7/30/2023 | Install hoe pack on unit |
| 1683 | SY215C | 9/22/2023 | Remove hydraulic line of unit have it sent to poplar to build new one and re install it |
| 1683 | SY215C | 10/1/2023 | Inspection of unit , looked for cracks and structural damage (stick , boom , track frame / car body and |
| | | | bucket) looked for defective leaking hydraulic hoses and hose integrity. Went over Operation of lights , |
| | | | horn and wipers and any other new damage to cab and body. No major concerns found |
| 1683 | SY215C | 10/20/2023 | Swap old packer attachment with new due to old one being wore out |
| 1683 | SY215C | 11/2/2023 | Unlock machine so they can move it. Won't start for them, start machine. Tag out hoe pack once machine |
| | | | is parked. |
| 1683 | SY215C | 11/2/2023 | Welded on new ice lugs |
| 1683 | SY215C | 11/2/2023 | Weld new ice lugs |
| 1683 | SY215C | 11/3/2023 | Remove hoe pack and install bucket |
| 1683 | SY215C | 11/19/2023 | Missing tooth try to locate tooth at poplar. No luck. Ordered a set plus one |
| 1683 | SY215C | 11/23/2023 | Find unit install bucket tooth into unit |
| 1683 | SY215C | 11/24/2023 | Swapped bucket over |
| 1683 | SY215C | 11/26/2023 | Find machine has no DEF. Grab DEF from service bay and fill tank. Run machine to clear codes and check operation - good. |
| 1683 | SY215C | 11/28/2023 | Fixed radio bracket and wiring to radio. Right side idler needs replaced |
| 1683 | SY215C | 12/10/2023 | Right idler and yolk failed. Crab walk unit to appropriate location. Inspected undercarriage. Make report |
| 1683 | SY215C | 12/15/2023 | Swap bucket |
| 1683 | SY215C | 12/20/2023 | Load up parts to take to machine. Position machine to split track. Pull 2 track pads. Notice that yoke is |
| | | | broken. Need track press to continue with repair - order additional parts needed. |
| 1683 | SY215C | 12/20/2023 | - loaded up idler and drove out to the unit staged machine to split tracks and removed track pads, was |
| | | | not able to split with what we had on site found yoke broken off of track adjuster so canceled track pin |
| | | | pressure and went back to office to order correct parts for the full repair. |
| 1683 | SY215C | 1/1/2024 | No radio range. Antenna missing. Install new antenna and test - no good. Inspect crimp - appears shielding |
| | | | wire interfering with copper. Replace crimp and test - good. |

| 1683 | SY215C | 1/29/2024 | - loaded up parts and head out to unit - lanced pin and split tracks , removed broken idler/recoil spring |
|------|--------|-----------|---|
| | | | installed new idler, wrapped tracks and welded in pin. |
| 1683 | SY215C | 1/29/2024 | Replace RH idler and tensioner spring. Adjust tracks |
| 1683 | SY215C | 1/29/2024 | Split tracks installed new idler and put tracks back together |
| 1683 | SY215C | 2/3/2024 | Install bucket on unit. Bucket missing teeth, drive to laydown and look for teeth. No teeth in stock. Parts ordered |
| 1683 | SY215C | 2/4/2024 | Change buckets |
| | SY215C | 2/17/2024 | Unit lost tooth keeper. Got to unit and didn't have right one in truck. Drive to laydown and find right keeper. |
| | | | Return to unit and install |
| 1683 | SY215C | 2/19/2024 | Install new tooth and pin |
| 1683 | SY215C | 2/28/2024 | Switch over buckets |
| 1683 | SY215C | 3/5/2024 | Travel out to unit and found both brackets on the steel bin lines one on each side are broken tied lines two |
| 1000 | 010450 | 0/0/0004 | keep from moving will need a welder to repair the brackets |
| | SY215C | 3/6/2024 | Weld brackets |
| | SY215C | 3/12/2024 | Inspect unit and order fittings to get twist wrist bucket to work |
| | SY215C | 3/15/2024 | Build jumper lines and find quick fitting and install twist wrist bucket |
| | SY215C | 3/15/2024 | Removed, built and installed hose on wrist |
| 1683 | SY215C | 4/6/2024 | Removed stump pan and inspected leak,found dipstick tube cracked at base and dripping. Ordered tube. |
| 1683 | SY215C | 5/1/2024 | Engine dipstick tube leaking on unit. Pulled out tube and part of it was stuck inside the block. Tap and |
| | | | install bolt inside. Heat up block around tube and hammer on bolt to eventually get it out. Install new tube |
| | | | and secure. Run up unit and ensure it's no longer leaking. Reinstall belly pan. |
| 1683 | SY215C | 5/1/2024 | Extract broken dipstick tube from engine block Install new. Units a go |
| 1683 | SY215C | 5/27/2024 | Got to unit found def codes on screen went back to the laydown and got the computer, got back to the unit |
| | | | the com cable isn't in the box. Looked unit over didn't see anything. Codes still there and unit is derated |
| 1683 | SY215C | 7/2/2024 | Repair and install new bucket lines |
| 1683 | SY215C | 7/17/2024 | Boost unit. Prime fuel system |
| 1683 | SY215C | 8/4/2024 | System was empty pulled a vac on system checked for leaks didn't find any. Charged system turned unit |
| | | | on found hot air blowing out of feet and cooler air out vents crossed with nights |
| 1683 | SY215C | 8/5/2024 | Put panels back on they need to run unit |

| 1683 | SY215C | 8/7/2024 | Inspect unit |
|------|--------|------------|---|
| 1683 | SY215C | 8/29/2024 | Swapped twist wrist bucket and boom to stick hoses to the other sany as ac isn't working |
| 1683 | SY215C | 8/29/2024 | -go to unit to check ac -ops wanted twist wrist bucket swapped out -swap buckets with 1684. Had to swap |
| | | | lines from 1683 as well -1683 load rollers are severely worn out |
| 1683 | SY215C | 10/29/2024 | Weld small crack on cheek. |
| 1683 | SY215C | 11/17/2024 | Check over unit while available. |
| 1683 | SY215C | 11/24/2024 | 1000hr service |
| 1683 | SY215C | 11/24/2024 | Perform 1000 hour service on unit. |
| 1683 | SY215C | 12/1/2024 | Heat and boost unit |
| 1683 | SY215C | 12/4/2024 | Drove to unit tightened up arm rest |
| 1683 | SY215C | 12/4/2024 | Fix armrest and straighten body panel |
| 1683 | SY215C | 12/23/2024 | Boost unit |
| 1683 | SY215C | 1/1/2025 | Drove to unit to repair track came off, more blocks required. Drove back to laydown for blocking. |
| | | | |
| 1683 | SY215C | 1/1/2025 | Boost unit |
| 1683 | SY215C | 1/2/2025 | Diagnose engine oil leak. No leak found while inspecting. Oil overfilled and spilled all around engine. Level |
| | | | adjusted. |
| 1683 | SY215C | 1/2/2025 | Helped Ken put tracks back on |
| 1683 | SY215C | 1/2/2025 | Track came off tried to get it on by myself couldn't get it got Connor to come over and give me a hand got |
| | | | track back on and adjusted |
| 1683 | SY215C | 1/3/2025 | Drive to laydown, find teeth. Only had enough to replace 2. Drive back and replaced teeth |
| 1683 | SY215C | 1/3/2025 | Drove to unit, removed tooth, drove to laydown, grabbed parts and returned, installed 2 new outer teeth. |
| 1602 | SY215C | 1/4/2025 | Bucket swap |
| | SY215C | | Repair bucket |
| | SY215C | 1/4/2025 | Gouge/weld cracked frog on bucket |
| _ | SY215C | 1/4/2025 | Sample engine and finals. Changed airfilter. Had wrong fuel filter and cabin air so notnchanged |
| 1003 | 312130 | 1/3/2023 | Sample engine and imats. Changed anniter. Had wrong fuet litter and cabin all so notrichanged |
| 1683 | SY215C | 1/6/2025 | Finals flushed and oil changed |
| 1683 | SY215C | 1/8/2025 | Swap bucket |
| 1683 | SY215C | 1/26/2025 | -clean bucket and wedge -install bucket |
| 1683 | SY215C | 2/2/2025 | Repaired hyd leak drove to yard to build new hose than drove back to w4 |
| 1683 | SY215C | 2/5/2025 | Flip cutting edge |

| 1683 | SY215C | 2/5/2025 | Removed, cleaned and flipped cutting edge. |
|------|--------|-----------|--|
| 1683 | SY215C | 2/5/2025 | Removed cutting edge. Buffed mating surfaces. Replaced hardware. Tightened to spec. |
| 1683 | SY215C | 2/8/2025 | Find plexiglass and drive out to w4, cut and install kick window |
| 1683 | SY215C | 2/8/2025 | Found plexiglass in welding sea can, drove to unit, measured and cut plexiglass for kick window. Installed |
| | | | window |
| 1683 | SY215C | 2/9/2025 | Stick cylinder scored real bad and leaking. Won't retract all the way and extends by itself. Possible |
| | | | contamination in system. Will need to pull and check spools |
| 1683 | SY215C | 2/9/2025 | Drove to unit, found stick cylinder is leaking very bad and chrome is scored deeply. Seems to have a |
| | | | sticking spool valve, got pulled off of unit to look at another. |
| 1683 | SY215C | 2/19/2025 | Drive to unit, get software flashed, remove exhaust cans to get cleared out |
| 1683 | SY215C | 2/20/2025 | Cut open after treatment canisters, remove catalysts, weld back shut |
| 1683 | SY215C | 2/23/2025 | Drive to machine, remove egr cooler, template and build/fabricate blocker plates |
| 1683 | SY215C | 2/23/2025 | Install egr block off plate and install exhaust cans back into unit |
| 1683 | SY215C | 2/26/2025 | Help with cylinder removal. |
| 1683 | SY215C | 2/26/2025 | Weld broken brackets and remove stick cylinder |
| 1683 | SY215C | 2/26/2025 | Remove stick cylinder |
| 1683 | SY215C | 2/28/2025 | Changed sensor |
| 1683 | SY215C | 3/16/2025 | Install stick cylinder Inspect for internal damages |
| 1683 | SY215C | 3/16/2025 | Replace stick cylinder. Clean related systems and tank. Tested unit for issues. Damage to spools from |
| | | | contamination from old cylinder. May need new spools for stick |
| 1683 | SY215C | 3/17/2025 | Polish damaged stick spoils and lap main control valve envelopes Test after repair |
| 1683 | SY215C | 3/19/2025 | Bucket cylinder hoses leaking from o rings replaced o rings and put unit back to work |
| 1683 | SY215C | 3/20/2025 | Boost unit checked oil levels while waiting for unit to charge |
| 1683 | SY215C | 4/3/2025 | 500 hour service completed |
| 1683 | SY215C | 4/3/2025 | 500 hr service complete. |
| 1683 | SY215C | 4/19/2025 | Steamed unit |
| 1683 | SY215C | 5/10/2025 | Rollers toast, reinstall track |
| 1683 | SY215C | 5/18/2025 | Full clean |
| 1683 | SY215C | 5/18/2025 | Full clean |
| 1683 | SY215C | 5/19/2025 | Steam |
| 1683 | SY215C | 5/19/2025 | Fullclean |
| 1683 | SY215C | 6/10/2025 | Tracks adjusted |
| 1683 | SY215C | 7/29/2025 | Demob |
| | | | |