| Unit | Model | Date | Work Order Details |
|------|-------|------------|--|
| 1759 | A45G | 7/19/2023 | Checked all levels. Started. Checked all functions and checked for leaks/ damage |
| 1759 | A45G | 7/29/2023 | Noted unit had a broken L arm rest. Ordered parts. |
| 1759 | A45G | 8/3/2023 | Travel to unit and install L armrest |
| 1759 | A45G | 10/1/2023 | Drove out to machine to install seatbelt. Found that seatbelt ordered was wrong. Drove back. Ordered |
| | | | right seat belt |
| 1759 | A45G | 10/3/2023 | Drive to machine. Replace seatbelt |
| 1759 | A45G | 10/13/2023 | Drive to the unit inspect final out what pressure Test test on hydraulic house quick couple election cap |
| | | | working good |
| 1759 | A45G | 10/15/2023 | Travel out to gypsum and wait for unit to come in. Inspected armrest and found it busted, attempted to get |
| | | | working enough for the day and it was too far gone. Removed the armrest and ordered replacement. |
| | | | |
| 1759 | | | Replace both arm rests |
| 1759 | | 11/17/2023 | |
| 1759 | | | Installed LH rear tire on unit |
| 1759 | | | Retourque wheel to 500 pounds |
| 1759 | A45G | 12/28/2023 | Both talegate cable ripped off. Come to the Yard made 2 cables. Go back to unit, install the working good. |
| 1759 | A45G | 3/26/2024 | Boost unit start |
| 1759 | A45G | 3/28/2024 | Run up to temp and drove around. Codes still present. Plugged in and troubleshot codes. Short to ground |
| | | | on reductand sensor. |
| 1759 | A45G | 3/28/2024 | Change out batteries and start up |
| 1759 | A45G | 3/29/2024 | Troubleshoot short to ground on def system. Def pressure switch failed |
| 1759 | A45G | 4/2/2024 | Swap out bad pressure sensor on def unit. Clear codes and run tests on system to verify fix. Unit needs a |
| | | | forced burn |
| 1759 | A45G | 4/3/2024 | Travel, got unit warmed up and performed force regen- good, DEF functional test- passed, NOx sensor test |
| | | | failed, cleaned sensors and plugs, reran test and passed, feild testing unit no codes, blew out back up |
| | | | alarm |
| 1759 | A45G | 7/6/2024 | Complaint of no start, slow cranking. Travel to unit and boost to start, verified charging system |
| | | | functioning. Travel back to shop. |
| 1759 | A45G | 8/2/2024 | Install new fire extinguisher bracket |
| 1759 | A45G | 10/23/2024 | Service |

| 1759 | 14FC | 11/24/2024 | Mechanic supervisor sign up on windshield, supervision didn't know anything about it, testing unit found |
|------|------|------------|--|
| 1/39 | A430 | 11/24/2024 | |
| | | | seat belt sensor wasn't registering, repaired wiring, LHF turn signal also not working, ordered bulb |
| | | | |
| 1759 | | 12/2/2024 | |
| 1759 | A45G | 12/8/2024 | Drive units to system three from the 7/8 so strong Co can work on it |
| 1759 | A45G | 3/17/2025 | Service |
| 1759 | A45G | 3/17/2025 | Service |
| 1759 | A45G | 4/18/2025 | Seat would not air up, broken wire ar compressor plug repair. Box lever detent worn for down position, |
| | | | have to hold lever down instead of pushing down and automatically goes down, with travel |
| | | | |
| 1759 | A45G | 5/12/2025 | Filled hyd for mechanic |
| 1759 | A45G | 5/12/2025 | Service |
| 1759 | A45G | 5/12/2025 | 1000hr pm Fixed hydraulic leak from quick sample port Got fuel and lube to fill hydraulic |
| 1759 | A45G | 5/30/2025 | 250hr pm on 1759 wiggle |
| 1759 | A45G | 6/9/2025 | Troubleshoot ecm comm interrupt code an Dpf system failure code. Found failed relay at RE05. Switched |
| | | | out relay and confirmed issue is gone. |
| 1759 | A45G | 7/1/2025 | Travel to unit found hydraulic leak on right side of unit at test port tighten fitting of test port and ran unit |
| | | | checked and found leak to be resolved |
| 1759 | A45G | 7/3/2025 | 2000hr pm on 1759 wiggle |
| 1759 | A45G | 7/3/2025 | 2000 hrs pm 1759 wiggle |
| 1759 | A45G | 7/17/2025 | Park brake alarm not deactivating, fuse blown for seat belt- replaced went to work |
| 1759 | A45G | 7/21/2025 | Travel to unit, reinstall all drivelines, guards and panels for dealer tech. Travel back to laydown. |
| | | | |
| 1759 | A45G | 7/22/2025 | Travel to unit, disconnect driveshafts again and tie up to move unit, assist ops moving unit out of work |
| | | | area. |
| | | | Travel to unit, disconnect driveshafts again and tie up to move unit, assist ops moving unit out of wor |