

NEW GEN

ENERGY SERVICES CORP

K20-8

Date: Dec 29-24

Hours:

Requested by:

Unit #: BL-01

KMs:

U.

What issues were found?

Marker light on lead
drive side are out.

Marker pass side pop at
back out

Doly legs gears are striped.

Describe what repairs were completed

- Switch out Front Light Blug

- all lights working

Completed by: Robin Bevans

Date: Dec 30 2024

Management Signature:

NEW GEN

ENERGY SERVICES CORP

Date: March 13/25	Hours:	Requested by:
Unit #: BCL 01	KMs:	

What issues were found?

Describe what repairs were completed

Check Fill all hubs
Grease unit
axle 2 PIS wheel seal
Fix repair marker lights

Completed by:

Chase

Date: March 13, 2025

Management Signature:

[Signature]

GST#889335089 RT0001 WHITE - CUSTOMER COPY * CANARY - STATEMENT COPY * PINK - BRANCH COPY

GST#889335089 RT0001 WHITE - CUSTOMER COPY * CANARY - STATEMENT COPY * PINK - BRANCH COPY