

Unit # RC 2**1975 INT'L TD20**Mileage _____ *EO1-14
BLUE* Hrs _____

SERIAL # 27596

Date	Description of Work	Parts Costs	Labour Costs
DEC/12 W0 n/a	Repair fan shaft (install new bearings , fanwheel and idler)	63.68	
	Install new rad	2644.17	
	Install new fan (propeller)	1433.26	
	Wash engine compartment		
	Install new Alt. belts and fan belts	163.83 20.51	
	Install new starter	390.00	
	Repair hyd. leak (suction pipe at tank)		
	Machine idler pulley for new seal (real seal and install new bearings) (Leo)	114.79	
JAN/13	Remove oil pan – fix liners leaking (Leo)		
	(Bracket and shaft supplied by M&M Equip. free of charge)		
MAR/13	Install new O rings on piston sleeves and new rod bearings, install 2 new engine thermostats (gaskets etc. M&M oil pan cracked – install used one (M&M), install new turbo, install 16 new lifters (Toppets)(M&M), install 2 new batteries (Aglands) (Leo)		
APR/13	Reupholster heavy equipment seat and replace plywood	168.00	
NOV14	Repair hydraulic line to cooler. Tighten bolt on turbo		
JAN27-15	SERVICE CHANGE OIL IN ENGINE, REPAIR LEFT FINAL CHIME PLANATERY, REPAIR BRAKES STUDS IN TURBO MANIFOLD, CHANGE 4 BOLTS ON AXLE CLAMPS, REPAIR DECELERATOR. 4900 HRS		

Unit # RC 2

1975 INT'L ID20

SERIAL # 27596