



1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

V33-3
SEP

Work Order Pending

WO # 3503	Customer: JAYMAR	Start Date: Feb 21/2026
Unit #: 520	Location: Slave Lake	End Date: Feb 21/26
Equip Desc: Winch Truck	Year: 2006	Make: Western Star
VIN: 5KKXAM00X6PX23033	Plate #: E91000	Model: 4900
KM: 1,672,354	Hours: 49,193	Requested by: Dave
Grouch List Checked: yes.		Grouch List Checked with Dave:
General Service		
Inspected Unit, Greased unit, checked oil levels tapped tranny oil up. topped mobile diff up checked tire pressures, adjusted brakes, torqued tires		
When installing USED parts, please specify.		

EXCESSIVE TIME DESCRIPTION

CVIP Hours _____ Repair Hours 3

Assigned Mechanic: Colt
Entered By: Shay

Signature: CG

Qty	Parts Requested/Parts Nos. /Parts Details

I certify that the above unit was repaired under my supervision

Name: _____	Sign: <u>[Signature]</u>
-------------	--------------------------



1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 3477	Customer: JAYMAR	Start Date: Feb 13/2026
Unit #: 520	Location: Slave Lake	End Date: Feb 23-26
Equip Desc: Winch Truck	Year: 2006	Make: Western Star
VIN: 5KKXAM00X6PX23033	Plate #: E91000	Model: 4900
KM: 1,672,354	Hours: 49,193	Requested by: Dave
Grouch List Checked:		Grouch List Checked with Dave:
- help with CVIP 1st diff Replace diff filter and cover		
Right hand steer seal leaking D/S Replace convex mirror		
Replace D/S windshield		
Rewire lights for tail frame and added a Junction Box		
When installing USED parts, please specify.		

EXCESSIVE TIME DESCRIPTION


CVIP Hours _____ Repair Hours 7

Assigned Mechanic: Eddie
Entered By: Shay

Signature: 

Qty	Parts Requested/Parts Nos. /Parts Details
1	RMS05 seal RH / ① 7 term junction Box # 821000EA
1	Diff plug # X121207 / ① Diff filter shield / ① Diff filter # 8163
1	Shock 85013 / ① DW01279GTN

I certify that the above unit was repaired under my supervision

Name:	Sign: 
-------	---



1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 3474	Customer: JAYMAR	Start Date: Feb 12/2026
Unit #: 520	Location: Slave Lake	End Date: Feb 24 2026
Equip Desc: Winch Truck	Year: 2006	Make: Western Star
VIN: 5KKXAM00X6PX23033	Plate #: E91000	Model: 4900
KM: 1,672,354	Hours: 49,193	Requested by: Dave
Grouch List Checked:	Grouch List Checked with Dave:	

Torqued wheels + tire pressures.

CVIP performed CVIP inspection

removed broken up cross member to gussets and had new cross member made, installed new crossmember and used a series of bolts nuts and washers. ~~for secure~~ new replaced steer shaft U-Joint and secured w/ snap rings. removed and replaced 3 Drive shaft U-Joints. torqued all bolts w/ blue When installing USED parts, please specify.

thread locker.

replaced Air bags but had to fabricate new upper mount bracket for rear left bag. Hooked up all air lines and fastened all nuts and bolts. EXCESSIVE TIME DESCRIPTION

replaced Left rear dust shield.

Driver removed driver step and installed plate from scrap ~~to~~ pile to secure the loose side, fastened bolts. Step ~~secure~~ secure.

CVIP Hours _____ Repair Hours 41.5 33

Assigned Mechanic: Yoshi LEAD
Entered By: Shay

Signature:

K14024384 ✓
K14024384 R ✓

Qty	Parts Requested/Parts Nos. /Parts Details	
4	Gussets	3 Air Bags 401358 9082 MP2 ✓
1	Crossmember	1 Dust Shield
1	Steer shaft U-Joint	2 metal plates
3	U-Joints (Driveline)	

I certify that the above unit was repaired under my supervision

Name: _____

Sign:

Truck 005.

4/1

CD188-3171

ED193 8288

707-3297

TR 102-3249

Sq6-3405

514-3432

L-34438

- Left Steer wheel seal

- Rear Right Shock Bracket Loose (Replace both shocks)

- Replace Both Axle 2 shocks along w/ crossmember

- Steer shaft U-Joint Pooched

- Backup alarm is quiet probably full of dirt

- Left rear cutter tire Has Bolt stuck in it

~~the 1 of the left Steer Lights are out~~

- ~~Rear~~ 3 U-Joints ~~beginning to have~~ have play

- Air Horn not working

- ~~At~~ Drive Axle 1 Right + Both rear Air Bags ~~are~~ are weather checked

- Rear Diff Panjo Bolts need to be tightened

- Right tail not working on marker

- Forward drive Right "Possible" wheel seal

~~- Left fender cracked in 2 spots needs to be welded.~~

- Rear leveling valve busted off

- Junction Box is Loose as frick

- Rear Left Dustshield missing Half.

- Tighten Transmission Belly Bar

- Driver Step Loose

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

DEC 17, 25 7/9



1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 3276	Customer: JAYMAR	Start Date: Dec /2025
Unit #: 520	Location: Slave Lake	End Date: Dec. 16/25
Equip Desc: Winch Truck	Year: 2006	Make: Western Star
VIN: 5KKXAM00X6PX23033	Plate #: E91000	Model: 4900
KM: 1,660,294	Hours: 48,560	Requested by: Dave
Grouch List Checked: yes		Grouch List Checked with Dave:
Coolant Leak		
Replaced 2 hoses ✓✓		
Replaced 2 clamps ✓✓		
When installing USED parts, please specify.		

EXCESSIVE TIME DESCRIPTION

CVIP Hours _____ Repair Hours 3

Assigned Mechanic: John
Entered By: Shay

Signature: *[Signature]* Jan 19/26

Qty	Parts Requested/Parts Nos. /Parts Details
1	Union Tube 8841462-4
14"	2 1/2" Silicone Hose 5515250
2	Clamps CT300LSS

I certify that the above unit was repaired under my supervision

Name: _____	Sign: <i>[Signature]</i>
-------------	--------------------------

☐ Check if you put on the retorque tags after working on tires



1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Dec 16, 25

Work Order Pending

WO # 3272	Customer: JAYMAR	Start Date: Dec 15 /2025
Unit #: 520	Location: Slave Lake	End Date: Dec 16/25
Equip Desc: Winch Truck	Year: 2006	Make: Western Star
VIN: 5KKXAM00X6PX23033	Plate #: E91000	Model: 4900
KM: 1,660,294	Hours: 48,560	Requested by: Dave
Grouch List Checked: yes		Grouch List Checked with Dave:
Exhaust leaks ✓ Changed clamp on drivers side DNC		
Change wiper blades ✓ Wiper blades fine changed nozzle on one		
Front rear diff leaks air ✓ cut out hole and put on new fitting		
Windows are weak to roll up		
Air leak under cab ✓		
Light out in skirt ✓ Replaced light out on tail fixed wire		
When installing USED parts, please specify.		
Changed both shocks on front & rear axle		
Repaired stair bracket on drivers side		
Greased		

EXCESSIVE TIME DESCRIPTION

CVIP Hours _____ Repair Hours 6.75

Assigned Mechanic: John
Entered By: Shay

Signature: 

Qty	Parts Requested/Parts Nos. /Parts Details
1	nozzle w3 6121
✓ 2	Shocks m85013
✓ 1	884PC1462 Air brake
6	wire 7740616

I certify that the above unit was repaired under my supervision

Name: _____	Sign: 
-------------	--

☐ Check if you put on the retorque tags after working on tires

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 3223	Customer: JAYMAR	Start Date: Nov26 /2025
Unit #: 520	Location: Slave Lake	End Date: Nov 26 2025
Equip Desc: Truck W/S 4900	Year: 2006	Make: Tandem Winch
VIN: 5KKXAM00X6PX23033	Plate #: E91000	Model:
KM: 1,657,765	Hours: 48,395	Requested by:
Grouch List Checked:	Grouch List Checked with Dave:	
* Winch Bracket *		
Bending wench brake		
heated up bracket corner w/ acetylene torch and hammered bracket till it was straight. Helped Eddie w/ fifth wheel release handle.		
<u>When installing USED parts, please specify.</u>		

EXCESSIVE TIME DESCRIPTION

CVIP Hours _____ Repair Hours 0.5

Assigned Mechanic: Yoshi
Entered By: Crystal

Signature: _____

Qty	Parts Requested/Parts Nos. /Parts Details

I certify that the above unit was repaired under my supervision

Name:	Sign:
-------	-------

☐ Check if you put on the retroviral tags after working on tires



1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 3218	Customer: JAYMAR	Start Date: Nov25 /2025
Unit #: 520	Location: Slave Lake	End Date: Nov25/25
Equip Desc: Tandem Winch Truck	Year: 2006	Make: W/S
VIN: 5KKXAM00X6PX23033	Plate #: E91000	Model: 4900
KM: 1,657,765	Hours: 48,395	Requested by: EDDIE
Grouch List Checked:		Grouch List Checked with Dave:
500hr Service		
Replaced oil pan and torque oil pan bolts to 35 pounds		
- Put new cap and plug on Hyd. ends		
- 2nd drive axle DS Replace ABS sensor		
- and Replace ABS Bracket		
- Straighten fifth wheel handle		
When installing USED parts, please specify.		
EXCESSIVE TIME DESCRIPTION		

CVIP Hours _____ Repair Hours 11

Assigned Mechanic: Eddie
Entered By: Crystal

Signature: 

Qty	Parts Requested/Parts Nos. /Parts Details
1	ABS Sensor 4410309092
1	ABS Sensor Bracket 577A23940
1	Cap PPDC8HK
1	oil pan 1504640 OSP may 28/25

I certify that the above unit was repaired under my supervision

Name:

Sign: 

☐ Check if you put on the retorque tags after working on tires

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466



10 Hrs Service Inspection Form

JAY-013

Hrs: 48,395
 Date: Nov 25/25 Unit # 520 Odometer: _____

Multipoint Inspection

Front Left			Front Right			Under Hood		
Pass	Fail		Pass	Fail		Pass	Fail	
☒		Headlight	☒		Headlight	☒		Horn
☒		Signal Light	☒		Signal Light	☒		Antifreeze Level
☒		Hazard Light	☒		Hazard Light	☒		Drive Belt
☒		Windshield		☒	Windshield	☒		Radiator Condition
☒		Cracked		☒	Cracked	PSI	Duration	Coolant Pressure test
☒		Chipped	☒		Chipped			
☒		Washer System	☒		Washer System	Under Vehicle		
☒		Wiper	☒		Wiper	☒		Suspension Comp
☒		Tire Tread	☒		Tire Tread	☒		Exhaust System
☒		Tire Pressure	☒		Tire Pressure	☒		Shocks
☒		PSI	☒		PSI	☒		Fuel Leaks
Rear Left			Rear Right					Oil Leaks
☒		Brake Light	☒		Brake Light	☒		Engine Oil Replaced
☒		Signal Light	☒		Signal Light	☒		Oil Filter Replaced
☒		Hazard Light	☒		Hazard Light	☒		Replace Air Filter
☒		Back-Up Light	☒		Back-Up Light	☒		Torque all Wheels
☒		Tire Tread	☒		Tire Tread	Fire Extinguisher (Check & Initial)		
☒		Tire Pressure	☒		Tire Pressure	Expiry Date:		
☒		PSI	☒		PSI	CVIP Exp Date:		
Fluids			Steering Components					
Checked Added			Pass Fail					
Front Differential	☒	☒	Left Ball Joints/King Pins					
Rear Differential	☒	☒	Right Ball Joints/King Pins					
Transfer Case	☒	☒	Left Tie Rods Ends					
Transmissions	☒	☒	Right Tie Rods Ends					
Power Steering	☒	☒	Center Link					
Brake Fluid	☒	☒	Pitman Arm					
Brakes			Steering Arm					
Left Front	☒	☒	Stabilizer Shock					
Left Rear	☒	☒	Sway Bars					
Right Front	☒	☒	Wheel Alignment					
Right Rear	☒	☒						
Emergency Brake	☒	☒						
Brake Cables	☒	☒						
Mechanic's Signature			Comments: 					
Next Service Due:								
Reviewed By:								



1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 2888	Customer: JAYMAR	Start Date: Aug 15/2025
Unit #: 520	Location: Slave Lake	End Date: Aug 15/2025
Equip Desc: Tandem Winch Truck	Year: 2006	Make: W/S
VIN: 5KKXAM00X6PX23033	Plate #: E91000	Model: 4900
KM: 1,647,448	Hours: 48,124	Requested by: Dave
Grouch List Checked: Yes		Grouch List Checked with Dave: NA
Check fluids and grease		
Checked fluids		
Greased		
Checked air pressures		
Changed 1 Passenger rear shock		
When installing USED parts, please specify.		

EXCESSIVE TIME DESCRIPTION

CVIP Hours _____ Repair Hours 3.5

Assigned Mechanic: John
Entered By: Annette

Signature: _____

Qty	Parts Requested/Parts Nos. /Parts Details

I certify that the above unit was repaired under my supervision

Name: _____	Sign: _____
-------------	-------------

☐ Check if you put on the retorque tags after working on tires



33

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 2673	Customer: JAYMAR	Start Date: May 31 /2025
Unit #: 520	Location: Slave Lake	End Date: May 31
Equip Desc: Semi truck	Year: 2006	Make: WS
VIN: 5KKXAM00X6PX23033	Plate #: E91000	Model: 4900
KM: 1,641,200	Hours: 47,920	Requested by: Dave

Grouch List Checked: No

Grouch List Checked with Dave:

3625

Install new speed sensor

speed / timing on Engine 1 5221641

When installing USED parts, please specify.

AS

EXCESSIVE TIME DESCRIPTION

CVIP Hours _____

Repair Hours _____

Signature

Assigned Mechanic: Dave

Signature: _____

Entered By: Annette

☐

Check if you put on the retorque tags after working on tires



OSP #:

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 2204	Customer: JAYMAR	Start Date: DEC 19 2024
Unit #: 520	Location: Slave Lake	End Date: Dec 19/24
Equip Desc: TRUCK	Year: 2006	Make: WS
VIN: X23033	Plate #: E91000	Model: 4900 WINCH TRUCK
KM: 1 624 030	Hours: 47 248	Requested by: DAVE
Grouch List Checked:		Grouch List Checked with Dave:
500 HRS SERVICE		
<u>When installing USED parts, please specify.</u>		

EXCESSIVE TIME DESCRIPTION

Greased unit checked lights check fluids changed oil/oil filters/fuel filters

CVIP Hours _____ Repair Hours _____

Assigned Mechanic: TRAE KLASSEN Signature: 
Entered By: HEATHER



Signature:



may 29/25

702 OSP #:

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 2620	Customer: JAYMAR	Start Date: May 20/2025
Unit #: 520	Location: Slave Lake	End Date: May 21/25
Equip Desc: Tandem Winch Truck	Year: 2006	Make: W/S
VIN: 5KKXAM00X6PX23033	Plate #: E91000	Model: 4900
KM: 1,639,132	Hours: 47,870	Requested by: Dave
Grouch List Checked: Yes		Grouch List Checked with Dave:
CHANGE ALTERNATOR (used alternator 110555 THO) ✓		
FIX BOOST PROBLEM		
changed Boost Pressure sensor 1619927/6V5048		
When installing USED parts, please specify.		
EXCESSIVE TIME DESCRIPTION		

CVIP Hours _____ Repair Hours 1

Assigned Mechanic: ^{Back} ~~Martine~~

Signature:

Entered By: Emmanuel



702 OSP #:

4/1
May 29/25

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 2627	Customer: JAYMAR	Start Date: May 22/2025
Unit #: 520	Location: Slave Lake	End Date: May 22/25
Equip Desc: Tandem Winch Truck	Year: 2006	Make: W/S 4900
VIN: 5KKXAM00X6PX23033	Plate #: E91000	Model:
KM: 1,639,260	Hours: 47,876	Requested by: Dave
Grouch List Checked: Yes		Grouch List Checked with Dave:
Inspection Turbo and harness Pulled intake tube off inspect inside of turbo and it was good		
When installing USED parts, please specify.		
3612 - inspect harness and by turbo boost sensor and found a rub wire and it was ground out to the engine engine		
- Pulled pin from connector and shrink tube the rub wire		
- Zip tie harness Back up		

EXCESSIVE TIME DESCRIPTION

CVIP Hours _____ Repair Hours 3Assigned Mechanic: Eddie Schafer
Entered By: Emmanuel

Signature:




Copy 11

OSP #:

3537

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 2504	Customer: JAYMAR	Start Date: Mar 31/2025
Unit #: 520	Location: Slave Lake	End Date: 3/31/25
Equip Desc: Tandem	Year: 2006	Make:
VIN: 5KKXAM00X6PX23033	Plate #: AB - E91000	Model: Western Star
KM: 1,637,682	Hours: 47,808	Requested by: Dave
Grouch List Checked: Yes		Grouch List Checked with Dave:
Full Service		
15 AXLE D.S. CLEVIS PINS MISSING		
REPLACED FUEL FILTERS PRIMARY & SECONDARY ✓		
USED 38.3L OF 5W40 OIL 3537		
NEW OIL FILTER ✓		
When installing USED parts, please specify.		
NEW POWER STEERING FILTER ✓ 3537		
		
EXCESSIVE TIME DESCRIPTION		
		

CVIP Hours _____ Repair Hours 4113

Assigned Mechanic: Roland
Entered By: Martine

Signature: 



500 Hrs Service Inspection Form

JAY-013

Hrs: 47,808Date: 3/31/25Unit # 520Odometer: 1637,682

Multipoint Inspection

Front Left			Front Right			Under Hood		
Pass	Fail		Pass	Fail		Pass	Fail	
✓		Headlight	✓		Headlight	✓		Horn
✓		Signal Light	✓		Signal Light	✓		Antifreeze Level
✓		Hazard Light	✓		Hazard Light	✓		Drive Belt
✓		Windshield	✓		Windshield	✓		Radiator Condition
		Cracked			Cracked	PSI	Duration	Coolant Pressure test
		Chipped			Chipped			
✓		Washer System	✓		Washer System	Under Vehicle		
✓		Wiper	✓		Wiper	✓		Suspension Comp
		Tire Tread			Tire Tread	✓		Exhaust System
✓	100	Tire Pressure	✓	100	Tire Pressure	✓		Shocks
		PSI			PSI	✓		Fuel Leaks
Rear Left			Rear Right					Oil Leaks
✓		Brake Light	✓		Brake Light	Y/N		Engine Oil Replaced
✓		Signal Light	✓		Signal Light	Y/N		Oil Filter Replaced
✓		Hazard Light	✓		Hazard Light	Y/N		Replace Air Filter
✓		Back-Up Light	✓		Back-Up Light	Y/N		Torque all Wheels
✓		Tire Tread	✓		Tire Tread	Fire Extinguisher (Check & Initial)		
100	100	Tire Pressure	100	100	Tire Pressure	Expiry Date:		
		PSI			PSI	CVIP Exp Date: <u>2/26</u>		
Fluids			Steering Components			<u>CU 8/4/0233</u>		
Checked Added			Pass Fail					
Front Differential	Y/N Y/N	✓	Left Ball Joints/King Pins					
Rear Differential	Y/N Y/N	✓	Right Ball Joints/King Pins					
Transfer Case	Y/N Y/N	✓	Left Tie Rods Ends					
Transmissions	Y/N Y/N	✓	Right Tie Rods Ends					
Power Steering	Y/N Y/N	✓	Center Link					
Brake Fluid	Y/N Y/N	✓	Pitman Arm					
Brakes	Pass Fail	✓	Steering Arm					
Left Front			Stabilizer Shock					
Left Rear			Sway Bars					
Right Front		✓	Wheel Alignment					
Right Rear								
Emergency Brake								
Brake Cables								
Mechanic's Signature			Comments: <u>REPLACED FUEL FILTERS</u> <u>5W40 OIL 38.3 LITERS</u> <u>NEW OIL FILTER</u> <u>NEW POWER STEERING FILTER</u>					
<u>[Signature]</u>								
Next Service Due:								
Reviewed By:								



OSP #:

Work Order Pending

- 3427 - Change v-joint on ~~input~~ input to #1 axle
- 3427 - Change brake shoes on axle #1 RHS
- 3427 - Change v-joint on axle #1 output, and the seal.
- 3427 - Change brake pot ✓ on axle #1 LHS, old one was loose
couldn't tighten bolts. When installing USED parts, please specify.
- 3427 - Change slack adjuster on axle #1 RHS and LHS

Signature: [Signature]





23

OSP #:

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 2296	Customer: JAYMAR	Start Date: Jan 28/2025
Unit #: 520	Location: Slave Lake	End Date: Jan Feb 1-25
Equip Desc: Tandem winch	Year: 2006	Make: WS 4900
VIN: 5KKXAM00X6PX23033	Plate #: E91000	Model:
KM: 1,627,707	Hours: 47,436	Requested by: Dave

Grouch List Checked: Yes

Grouch List Checked with Dave:

General check front end

Short in marker lights check, Took marker lights out of Rear Bump examine all pig tails, found no short.
Took all light out of Head ack Rack

When installing USED parts, please specify.

and found short passenger side light pig tail

Flap Ty with stub shaft it was seized and was in a tight spot

The stub shaft had 2 different U-Joint

1 Zip full cornd and 1 Ho H&F Round

Replace both steer axle slack adjuster and clevis

Replace leveling Valve Rod and adjusted Height

EXCESSIVE TIME DESCRIPTION

CVIP Hours _____ Repair Hours 26

17TY532-99

6-4-63 71-1

Assigned Mechanic: Eddie Signature: Hours
Entered By: Martine



OSP #:

1400 Tamarack Rd
Slave Lake, AB T0G 2A1 Canada
Phone: 780-849-3466

Work Order Pending

WO # 2246	Customer: JAYMAR	Start Date: Jan 10 2025
Unit #: 520	Location: Slave Lake	End Date: Jan 10/25
Equip Desc: Tandem	Year: 2006	Make: WS
VIN: 5KKXAM00X6PX23033	Plate #: E91000	Model: 4900
KM: 1,625,646	Hours: 47,299	Requested by: Dave

Grouch List Checked: YES

Grouch List Checked with Dave:

Change Dash cam

When installing USED parts, please specify.

EXCESSIVE TIME DESCRIPTION

CVIP Hours _____ Repair Hours 1Assigned Mechanic: Zack Signature: [Signature]
Entered By: Martine[Signature]
MC