

TIRESMITH INC.
13755 - 100 STREET GRANDE PRAIRIE AB T8V 4H4

PH: 780-532-3166
FX: 780-532-8939
EML: admin@tiresmith.ca

SOLD TO:
9120642
T-RUCKIN OILFIELD SERVICES LTD
BOX 448 STATION MAIN

Invoice GPR403690

(Copy)

SHIP TO
T-RUCKIN OILFIELD SERVICES LTD
BOX 448 STATION MAIN
GRANDE PRAIRIE
T8V 3A7
TEL: 780 876-4446

DATE: 25 Aug 06

GRANDE PRAIRIE AB
T8V 3A7
TEL: 780 876-4448

FAX: 780 518-1851

AB

PAGE: 1

YEAR	MAKE	MODEL		ENGINE
2022	GMC	Sierra 1500 1/2 Ton K1500 SLE		5.3 L 325 CID V8
PLATE NO	VIN	ODOMETER	UNIT NO.	WRITTEN BY
CRC3319	3GTUUBED3NG618543	114799	ST09	EM
TIME IN	PROMISED	TERMS	P.O.	TAG
2:28 PM		30 DAYS	ST09	

QTY	ITEM/DESCRIPTION	SIZE	TAX	NET	EXT.PRICE
4	170300048 COOPER DISCOVERER STRONGHOLD AT 10/E(118411)	LT265/65R18 (3PMS) 122T	G	389.00	1556.00
4	BLT BALANCE LIGHT TRUCK CW TY		G	29.00	116.00
4	20008 MISC TPMS SENSOR STEM	TPMS	G	8.95	35.80
4	TTL LIGHT TRUCK TIRE DISPOSAL		G	5.00	20.00
4	NTP NON REPAIRABLE TIRE PROTECTION		G	10.00	40.00
1	MSS MECHANICAL SHOP SUPPLIES GST Registration# 82058 1353 RT0001		G	N/C	N/C

Payment Method: OnAccount=1856.19

THE WHEELS ON YOUR VEHICLE REQUIRE RE-TORQUEING WITHIN 70 KMS. THIS SERVICE IS PROVIDED FREE OF CHARGE. PLEASE SEE US TO HAVE THIS DONE. FAILURE TO DO SO MAY RESULT IN A WHEEL OFF SITUATION. AIR SET AT _____ WHEEL NUTS HAND TORQUED _____ FT LBS



GST EXEMPT #: _____ PST EXEMPT #: _____

TERMS AND CONDITIONS

I request the above work to be done and the above materials to be supplied and installed on the following conditions.

I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of the done and materials supplied. I authorize you, your agents or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts there of to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

Signature: _____ for you Patronage!!!! Signature: _____

PARTS:	1591.80
LABOUR:	116.00
OTHER:	60.00
SUB-TOTAL:	1767.80
GST:	88.39
PST:	N/C
TOTAL:	1856.19



12308 100 Street
Grande Prairie, AB
T8V 4H7

Phone: (780) 532-8865
Administrative Fax: (780) 539-7510
Toll Free: (888) 532-8865
Parts Direct Line: (780) 539-3745
Parts Fax: (780) 830-4220
Service Direct Line: (780) 830-4200

INVOICE ORIGINAL

Work Order
#414197
T-Ruckin Oilfield Services Ltd
October 15, 2024
Svc. Adv Christie, Michelle
Cust. Ph. (780) 933-8258
Tag# 0661

Page 1 of 4
10/17/2024 17:35:38

To: T-Ruckin Oilfield Services Ltd

PO Box 448

Grande Prairie
T8V 3A7

AB

Year: 2022 Veh Id: 106324 Unit #: ST09
Make: GMC License #:
Model: Sierra 1500 4WD Crew CAB I Odo. In: 84,043
Colour: White Odo. Out:
V.I.N.#: 3GTUUBED3NG618543 Next Service:
Date In: 10/15/2024 In Service Date: 07/29/2022
Out: Cases: 9
Ext. War - - (mo/) - D: \$0.00 R/Lab. Rate 210.00
Promised Time: 10/16/2024 05:00:00 PM Call When Ready:

Cust copy

Case: 1 Customer notes that the engine light is on - advise - Time includes diagnosis up to this point
*recommended to replace all injectors.
Remove & Replace FUEL INJECTOR 5.3L Eng Both Banks, All Eight
Remove & Replace FUEL INJECTOR THROTTLE BODY ASSEMBLY - Reset 5.3L Eng Throttle Body Idle Air
Flow Compensation Reset

Quantity	Description/Correction	Retail	Price	Total
8.00	12626354 - GASKET-INT MANIF	\$5.38	\$5.38	\$43.06
1.00	12679463 - PIPE ASM-FUEL FEED INTER	\$48.34	\$48.34	\$48.34
1.00	12703596 - PIPE ASM-FUEL FEED	\$128.76	\$128.76	\$128.76
1.00	12703668 - PIPE ASM-FUEL FEED (CROSSRAIL)	\$88.39	\$88.39	\$88.39
2.00	12732622 - Injector	\$130.54	\$130.54	\$261.08
6.00	12732622 - Injector	\$130.54	\$130.54	\$783.24
			\$1,449.00	\$1,449.00

• Tech Cause: Verified customers concern that the ses lamp is on along with other lamps esc, traction control, scanned for codes and found current codes several codes p0204 cylinder #4 injector control circuit, p0300 engine misfire detected-related to p0204, p050d cold start rough idle related to p0204, p2b03 cylinder #4 fuel injection pulse performance. Followed diagnosis for p0204 doc id 5908701 Gained access to the ECM and tested at circuits 4904 and 4804 for cylinder #4 injector and found a reading of .5 Mega ohms, will require intake be removed to confirm at fuel injector approx. the same reading of .5 mega ohms across the injector.

• Tech Comments: made est. Removed intake manifold and tested directly at injector #4 and confirmed 4.3 Kohms present, new injector reads 1.7ohms. Confirmed fuel injector requires replacement. Recommend all 8 be replaced. Replaced all 8 fuel injectors with seals, required high pressure fuel lines and intake gaskets. Road tested and verified all repairs. SESlamp and all other relating lamps remain off.

• Completed by: Taylor, Jacinna Tech
License #: (119842A)

• Shop Charges -

Misc	\$23.32	Labour	\$1,449.00	Parts	\$1,352.87	Prepaid Parts Amt:	\$0.00		\$23.32	\$23.32
								Case Total:	\$2,825.19	



12308 100 Street
Grande Prairie, AB
T8V 4H7

Phone: (780) 532-8865
Administrative Fax: (780) 539-7510
Toll Free: (888) 532-8865
Parts Direct Line: (780) 539-3745
Parts Fax: (780) 830-4220
Service Direct Line: (780) 830-4200

INVOICE ORIGINAL

Work Order

#414197

T-Ruckin Oilfield Services Ltd

October 15, 2024

Svc.Adv Christie, Michelle

Cust.Ph. (780) 933-8258

Tag# 0661

Page 2 of 4

10/17/2024 17:35:38

Case: 2 vibration/pulsing when driving at 75-90kms - advise

Quantity Description/Correction

Price Total
\$84.00 \$84.00

- Tech Cause: Front tires are cupped and worn on the inboard edges, inspected front end components and frt end components are within spec, found that the p.s frt strut is leaking-recommnd both be replaced, requires tire rotation and wheel alignment.
- Tech Comments: made est. Struts are USA spec. Customer will source struts and install themselves.
- Completed by: Taylor, Jacinna Tech
License #: (119842A)
- Shop Charges -

Misc \$1.35 **Labour** \$84.00 **Parts** \$0.00 **Prepaid Parts Amt:** \$0.00 **Case Total:** \$85.35

Case: 3 # N222389722 Transmission Control Body Screen Failure - Exp 2/28/2025 -
Transmission Control Module Reprogramming with SPS (Includes Learn) 9107402 .5

Quantity Description/Correction

Price Total
\$0.00 \$0.00

- Tech Cause: # N222389722
- Tech Comments: Transmission Control Module Reprogramming with SPS (Includes Learn) as per # N222389722. Claim code: 18YY239753616 - Warranty
- Completed by: Taylor, Jacinna Tech
License #: (119842A)

Misc \$0.00 **Labour** \$0.00 **Parts** \$0.00 **Prepaid Parts Amt:** \$0.00 **Case Total:** \$0.00

Case: 4 # N232426400 Tailgate May Open Unexpectedly -
Replace Main Tailgate Switch

Quantity Description/Correction

Retail Price Total
1.00 85734717 - Switch - Warranty (FP) \$52.09 \$0.00 \$0.00
\$0.00 \$0.00

- Tech Cause: # N232426400
- Tech Comments: Replaced Main Tailgate Switch as per # N232426400. Verified operation, has multipro. - Warranty
- Completed by: Taylor, Jacinna Tech
License #: (119842A)

Misc \$0.00 **Labour** \$0.00 **Parts** \$0.00 **Prepaid Parts Amt:** \$0.00 **Case Total:** \$0.00



12308 100 Street
Grande Prairie, AB
T8V 4H7

Phone: (780) 532-8865
Administrative Fax: (780) 539-7510
Toll Free: (888) 532-8865
Parts Direct Line: (780) 539-3745
Parts Fax: (780) 830-4220
Service Direct Line: (780) 830-4200

INVOICE ORIGINAL
Work Order
#414197
T-Ruckin Oilfield Services Ltd
October 15, 2024
Svc.Adv Christie, Michelle
Cust.Ph. (780) 933-8258
Tag# 0661

Page 3 of 4
10/17/2024 17:35:38

Case: 5 # N242435631 Serial Data Gateway Module and Radio -
Serial Gateway Module and Radio Reprogramming with SPS 9107386 1.0

Quantity Description/Correction	Price	Total
	\$0.00	\$0.00
<ul style="list-style-type: none"> • Tech Cause: N242435631 • Tech Comments: Performed Serial Gateway Module and Radio Reprogramming with SPS as per : N242435631. Claim code: 0SY239756666, 80YZ239760852, 80YZ239761874. - Warranty • Completed by: Taylor, Jacinna Tech License #: (119842A) 		
	\$0.00	\$0.00

Misc \$0.00	Labour \$0.00	Parts \$0.00	Prepaid Parts Amt: \$0.00	Case Total: \$0.00
--------------------	----------------------	---------------------	----------------------------------	---------------------------

Case: 6 # N232431050 Automatic Exterior Lights May Not Activate As Required -
Body Control Module Reprogramming with SPS

Quantity Description/Correction	Price	Total
	\$0.00	\$0.00
<ul style="list-style-type: none"> • Tech Cause: # N232431050 • Tech Comments: Performed Body Control Module Reprogramming with SPS as per # N232431050. Claim code: 40YY239746238. - Warranty • Completed by: Taylor, Jacinna Tech License #: (119842A) 		
	\$0.00	\$0.00

Misc \$0.00	Labour \$0.00	Parts \$0.00	Prepaid Parts Amt: \$0.00	Case Total: \$0.00
--------------------	----------------------	---------------------	----------------------------------	---------------------------

Case: 7 2 Way Warranty Shuttle

Quantity Description/Correction	Price	Total

Misc \$0.00	Labour \$0.00	Parts \$0.00	Prepaid Parts Amt: \$0.00	Case Total: \$0.00
--------------------	----------------------	---------------------	----------------------------------	---------------------------

Case: 8 Added Operation: Tire Rotation (4) (Includes: Rotate Tires, Adjust Tire Pressures, Calibrate Sensors if Equipped, Brake Inspection.) - Tech Cause: Tire Rotation - Tech Comments: Performed Tire Rotation, rear brakes at 7mm, frt brakes at 10mm, torqued all wheel nuts, calibrated all sensors, verified t.p are within spec.

Quantity Description/Correction	Price	Total
	\$80.00	\$80.00
<ul style="list-style-type: none"> • Tech Cause: Tire Rotation • Tech Comments: Performed Tire Rotation, rear brakes at 7mm, frt brakes at 10mm, torqued all wheel nuts, calibrated all sensors, verified t.p are within spec. • Completed by: Taylor, Jacinna Tech License #: (119842A) 		

Misc	Labour	Parts	Prepaid Parts Amt:	Case Total: \$80.00
-------------	---------------	--------------	---------------------------	----------------------------



12308 100 Street
Grande Prairie, AB
T8V 4H7

Phone: (780) 532-8865
Administrative Fax: (780) 539-7510
Toll Free: (888) 532-8865
Parts Direct Line: (780) 539-3745
Parts Fax: (780) 830-4220
Service Direct Line: (780) 830-4200

INVOICE ORIGINAL

Work Order

#414197

T-Ruckin Oilfield Services Ltd

October 15, 2024

Svc.Adv Christie, Michelle

Cust.Ph. (780) 933-8258

Tag# 0661

Page 4 of 4

10/17/2024 17:35:38

Case: 9 Added Operation: 4 Wheel Alignment - Tech Cause: 4 Wheel Alignment - Tech Comments: Performed wheel alignment, adjsuted camber, caster and toe. Road tested and verified all repairs.

Quantity Description/Correction

Price Total
\$159.95 \$159.95

- Tech Cause: 4 Wheel Alignment
- Tech Comments: Performed wheel alignment, adjsuted camber, caster and toe. Road tested and verified all repairs.
- Completed by: Taylor, Jacinna Tech
License #: (119842A)
- Shop Charges - \$2.57 \$2.57

Misc	\$2.57	Labour	\$159.95	Parts	\$0.00	Prepaid Parts Amt:	\$0.00	Case Total:	\$162.52
									\$0.00

Notes

- Jaydean 780-933-8258
Michelle Christie - 10/15/2024 11:16:50

O U T	Indebtedness is hereby acknowledged for the "Total Charges" being all or the balance owing to repairs, parts & accessories described in this work order.		Currency:	Labour:	\$1,772.95
				Parts:	\$1,352.87
			Payment Ref:	Misc:	\$27.24
			Expiry Date:	Sub Total:	\$3,153.06
			P/O#:	G/HST:	\$157.65
			G/HST Reg # 105411359RT0001	PST:	\$0.00
				Tax Adjustment:	\$0.00
	10/17/2024				
	Date	Signature	Payment Type	Total:	\$3,310.71

Ken Sargent GMC Buick
 12308 100ST
 Grande Prairie AB T8V 4H7
 780 830 4200

414197

Customer: License No: Order No.: Date: 10/17/2024 04:40
Company: Odometer: VIN: 3GTUUBED3NG618543 Technician:

Vehicle GMC TRUCKS 2022 SIERRA 1500 K10743/K18743



Besides improved fuel economy, handling and safety, what do these measurements mean?

 **CASTER** is the tilt of the axis that the wheel steers around. It affects how the vehicle tracks as you drive down the road and can affect handling.

 **CAMBER** is the angle of the tire in relation to the road surface. It affects tire wear, and handling when turning.

 **TOE** is a measurement of how much the wheel is turned in or out from a straight-ahead position. It affects tire wear, handling and can make your steering wheel crooked.

Your vehicle has been aligned using a precision **HOFMANN** wheel aligner.

5.4.2, United States Domestic, US2024R1