

| Vehicle Details | | | | | |
|-----------------|-----------|--------------|------------|--------|--------|
| Registration | XA49AB | Next Service | | Litres | |
| Make | Kenworth | Rego Due | | Trans | N/A |
| Model | T404 | Engine # | 06R0977097 | Air | Yes |
| Model Series | | VIN | 435791 | Cyl | 0 |
| Model Code | | Build Date | | Body | TIPPER |
| Colour | Corkhills | Odometer | 711322 | Prod | |

| Invoice No. | Date | Odometer | Description | Type |
|--|------------|----------|--------------------------|---------|
| 2318 | 01/03/2025 | 0 | General Repairs | Invoice |
| | NPN03 | | Air Fittings | |
| | NPN03 | | 12V DC Solenoid | |
| | NPN03 | | Air fittings | |
| | LAB | | Labour | |
| Replace 12v Air Solenoid for tailgate lock | | | | |
| 2169 | 10/12/2024 | 711322 | Head Lights | Invoice |
| | IHL7RC | | LED Headlight | |
| | CONS | | General Consumables Used | |
| Replace front Headlights | | | | |
| 2143 | 25/11/2024 | 0 | Boost Hose | Invoice |
| | HE8701 | | Boost Hose 4x4x8 | |
| Replace boost hose at turbo outlet | | | | |
| 2122 | 04/11/2024 | 0 | Boost Hoses | Invoice |
| | HE8701 | | Boost Hose 4x4x8 | |
| | 848-66X | | Clamp Hose 105-113mm | |
| Replace boost hose from turbo to charge pipe | | | | |
| 2111 | 01/11/2024 | 0 | Exhaust stacks | Invoice |
| | 2792P75/JW | | Exhaust stack | |
| | FREIGHT | | Freight charges | |
| | 2547/JW | | 5" exhaust clamp | |
| | CONS | | General Consumables Used | |
| Replace exhaust stacks stolen from Yard | | | | |
| 2004 | 03/09/2024 | 700929 | B service | Invoice |
| | LF3620 | | Detroit Oil Filter | |
| | FF5206 | | Fuel Filter | |
| | FF5207 | | Fuel Filter | |
| | VECTON | | Vecton 15W40 Engine Oil | |
| | 2547/JW | | 5" exhaust clamp | |
| | CONS | | General Consumables Used | |
| | GREASE | | Black tack 450 gm | |
| B Service | | | | |
| 1913 | 12/07/2024 | 694328 | Jake Brake Fault | Invoice |

| Vehicle Details | | | | | |
|-----------------|-----------|--------------|------------|--------|--------|
| Registration | XA49AB | Next Service | | Litres | |
| Make | Kenworth | Rego Due | | Trans | N/A |
| Model | T404 | Engine # | 06R0977097 | Air | Yes |
| Model Series | | VIN | 435791 | Cyl | 0 |
| Model Code | | Build Date | | Body | TIPPER |
| Colour | Corkhills | Odometer | 711322 | Prod | |

| Invoice No. | Date | Odometer | Description | Type |
|-------------|--------------|----------|------------------------------------|------|
| | 23512897 | | Manifold Exhaust mid Mount | |
| | 8929357 | | Stud Exhaust Manifold | |
| | 23533983 | | Gasket Exhaust manifold | |
| | NPN03 | | 7/8" Plow Bolts | |
| | 8929285 | | Gasket | |
| | 8929529 | | Gasket turbo base S 60 | |
| | 32146 | | Tune Up kit Jacobs | |
| | 31282 | | Master piston 797 Jacobs | |
| | 714792-5002S | | Garrett Turbo charger with gaskets | |
| | CONS | | General Consumables Used | |
| | VECTON | | Vecton 15W40 Engine Oil | |
| | COOLANT | | Coolant | |

Replace cracked exhaust manifold. Replace master pistons in Jake Brakes, Re-kit Jake brakes.
Repair oil leak at filler pipe. Straighten steering wheel, Replace grain locks

| | | | | |
|------|------------|---|-----------------|---------|
| 1883 | 26/06/2024 | 0 | Truck Wash | Invoice |
| | SUBLET | | Hume Truck wash | |

Truck Wash

| | | | | |
|------|---------------|--------|------------------------|---------|
| 1748 | 29/11/2023 | 653456 | A Service | Invoice |
| | K066-310 | | Shock Rubbers | |
| | 11R22.5 DRIVE | | Double Coin drive tyre | |
| | NPN01 | | Tyre disposal | |
| | VFS6G-8 | | Rod End Clutch Link | |

A Service

Replace rear lower shock rubbers
Replace rose joints on clutch linkages
Replace 2 x drive tyres

| | | | | |
|------|------------|--------|--------------------------|---------|
| 1658 | 05/07/2023 | 625719 | A Service | Invoice |
| | CONS | | General Consumables Used | |

A Service

| | | | | |
|------|--------------|--------|------------------------------------|---------|
| 1844 | 11/04/2023 | 610631 | Turbo & Exhaust manifold gaskets B | Invoice |
| | 714792-5002S | | Garrett Turbo charger | |
| | 8929285 | | Gasket | |
| | 8929529 | | Gasket turbo base S 60 | |
| | LF3620 | | Detroit Oil Filter | |
| | FF5207 | | fuel filter | |
| | FF5206 | | Fuel Filter | |
| | K066-310 | | Shock Rubbers | |
| | K301-453 | | Jake brake switch | |
| | VECTON | | Vecton 15W40 Engine Oil | |

B Service

- Replace turbo

Vehicle Details

| | | | | |
|---------------------|-----------|---------------------|---------------|--------|
| Registration | XA49AB | Next Service | Litres | |
| Make | Kenworth | Rego Due | Trans | N/A |
| Model | T404 | Engine # | Air | Yes |
| Model Series | | VIN | Cyl | 0 |
| Model Code | | Build Date | Body | TIPPER |
| Colour | Corkhills | Odometer | Prod | |

| Invoice No. | Date | Odometer | Description | Type |
|---|--------------------|---------------|-----------------------------------|----------------|
| <ul style="list-style-type: none"> Fit new manifold gaskets Tighten indicator switch & replace Jake brake switch Replace all lower shock rubbers Tighten pitman arm pinch bolt Replace Jake brake switch | | | | |
| 1580 | 13/12/2022 | 0 | Cab mounts | Invoice |
| | K066-498 | | Cab bush assy | |
| Replace front Cab mounts | | | | |
| 1409 | 10/09/2022 | 595352 | A Service | Invoice |
| | CONS | | General Consumables Used | |
| A Service Repair tail lights & Reverse lights | | | | |
| 1281 | 18/11/2021 | 553724 | B service And Steering Box | Invoice |
| | TAS85124AR | | Reman steering box | |
| | LF3620 | | Detroit Oil Filter | |
| | FF5206 | | Fuel Filter | |
| | FF5207 | | fuel filter | |
| | VECTON | | Vecton 15W40 Engine Oil | |
| | 11R22.5 DRIVE | | Double Coin drive tyre | |
| | LAB | | Labour | |
| | NPN01 | | Tyre disposal | |
| Replace steering box B Service Replace 2 drive tyres | | | | |
| 1265 | 28/08/2021 | 533758 | B Service & brakes | Invoice |
| | LF3620 | | Detroit Oil Filter | |
| | FF5206 | | Fuel Filter | |
| | FF5207 | | fuel filter | |
| | VECTON | | Vecton 15W40 Engine Oil | |
| | KSMA3124707QP | | Brake Shoe Kit Meritor | |
| | ACX2123 | | Rotating Beacon | |
| B Service Replace brakes on rear axle | | | | |
| 1264 | 09/07/2021 | 0 | Front diff center | Invoice |
| | 4X1922 | | Wheel Stud | |
| | 6.5.3.1371KX | | Slip Yoke 1810 | |
| | 5.281 | | 1810 universal joint full round | |
| | DANA DIFF EXCHANGE | | Front diff | |
| | AP85W140 | | Diff oil | |
| | LAB | | Labour | |
| | 47693 | | Wheel Seal | |
| | CONS | | General Consumables Used | |

Vehicle Details

| | | | | |
|---------------------|-----------|---------------------|---------------|--------|
| Registration | XA49AB | Next Service | Litres | |
| Make | Kenworth | Rego Due | Trans | N/A |
| Model | T404 | Engine # | Air | Yes |
| Model Series | | VIN | Cyl | 0 |
| Model Code | | Build Date | Body | TIPPER |
| Colour | Corkhills | Odometer | Prod | |

| Invoice No. | Date | Odometer | Description | Type |
|-------------|------|----------|-------------|------|
|-------------|------|----------|-------------|------|

FREIGHT

Freight charges

Remove front diff center after power divider failure
Send to Truck Transmissions
Clean diff housings & flush wheel bearings fitting new seals
Refit Exchange diff center

| | | | | |
|-------------|-------------------|----------|--------------------------------|----------------|
| 1263 | 17/06/2021 | 0 | B service & repairs | Invoice |
|-------------|-------------------|----------|--------------------------------|----------------|

LAB Labour
NPN03 Exchange compressor
NPN03 Air dryer filter seal & nut
WWBG-12 Dust blower
LF3620 Detroit Oil Filter
FF5206 Fuel Filter
FF5207 fuel filter
VECTON Vecton 15W40 Engine Oil
128049 Locknut
210737 Seal through shaft
AC4001 Air dryer filter TRP

B service

- Replace thrust bearing on left king pin
- Replace compressor
- Fit new air blower in cab
- Replace air dryer filter

| | | | | |
|-------------|-------------------|---------------|--------------------------|----------------|
| 1098 | 28/01/2021 | 506907 | Annual Inspection | Invoice |
|-------------|-------------------|---------------|--------------------------|----------------|

H00500C Ride Height Valve universal
LAB Labour
CONS General Consumables Used

Annual Inspection
Replace both rear ride height valves

| | | | | |
|-------------|-------------------|----------------|------------------|----------------|
| 1042 | 20/10/2020 | 5003304 | A Service | Invoice |
|-------------|-------------------|----------------|------------------|----------------|

PUAO65 Oil Pump PTO
CONS Strata Flex hoses
LAB Labour
T224P Air Dryer filter
COOLANT Coolant
HYDRAULIC OIL Hydraulic oil
RX5004187 Compressor Exchange

A Service

- Replace PTO pump
- Replace compressor
- Replace hydraulic oil
- Replace water lines to compressor & w pump

| | | | | |
|------------|-------------------|---------------|------------------|----------------|
| 994 | 26/08/2020 | 484425 | C Service | Invoice |
|------------|-------------------|---------------|------------------|----------------|

R23539929 Water Pump S 60
CONS General Consumables Used
LAB Labour
LF3620 Detroit Oil Filter

Vehicle Details

| | | | | |
|---------------------|-----------|---------------------|---------------|--------|
| Registration | XA49AB | Next Service | Litres | |
| Make | Kenworth | Rego Due | Trans | N/A |
| Model | T404 | Engine # | Air | Yes |
| Model Series | | VIN | Cyl | 0 |
| Model Code | | Build Date | Body | TIPPER |
| Colour | Corkhills | Odometer | Prod | |

| Invoice No. | Date | Odometer | Description | Type |
|-------------|------------|----------|------------------------------|------|
| | FF5206 | | Fuel Filter | |
| | FF5207 | | fuel filter | |
| | WF2077 | | Water filter no DCA | |
| | SA003TRP | | Shock Absorber TRP | |
| | 8PK915 | | Drive Belt | |
| | V404P-10-6 | | Tap Heater | |
| | CM10037796 | | Hub front | |
| | 18G7901 | | Drain Tap | |
| | 131139 | | Accelerator Pedal roller kit | |
| | VECTON | | Vecton 15W40 Engine Oil | |
| | TFC450 | | Gear oil | |
| | AP85W140 | | Diff oil | |
| | TFC410 | | 10w gear oil | |

C Service

- Replace water pump
- Replace right front hub
- Replace leaking water tap at w/pump
- Replace belt tensioner
- Replace rear shock absorber
- Replace accelerator pedal roller

| | | | | |
|------------|-------------------|----------|------------------------------|----------------|
| 998 | 04/08/2020 | 0 | General Repairs | Invoice |
| | K348-87 | | Mattress | |
| | SB3700 | | Seat belt kit | |
| | SK554BHLSB | | Seat Cover KW ISRI Passenger | |
| | SKXTHDBHRSB | | Seat Cover Extreme HD | |
| | LAB | | Labour | |

- Replace drivers seat
- Fit new seat covers
- Fit new Mattress
- Free up brake pedal plunger (sticking)

| | | | | |
|------------|-------------------|---------------|----------------------|----------------|
| 978 | 21/04/2020 | 477427 | A Service | Invoice |
| | LAB | | Labour | |
| | HE8701 | | Host turbo hump hose | |

A Service

- Replace boost hose

| | | | | |
|------------|-------------------|---------------|---------------------------|----------------|
| 811 | 06/11/2019 | 461743 | B service | Invoice |
| | LF3620 | | Detroit Oil Filter | |
| | FF5206 | | Fuel Filter | |
| | FF5207 | | fuel filter | |
| | VECTON | | Vecton 15W40 Engine Oil | |
| | KSMA2124707QP | | Brake Shoes Meritor Drive | |
| | 47693 | | Wheel Seal | |
| | 839310 | | Bushing | |
| | NPN03 | | 5/16 Strata flex | |
| | NPN03 | | Strata flex fittings | |
| | S63-1001 | | Pad Clutch Pedal | |
| | 1500-0070 | | Bumper Rubber | |

Vehicle Details

| | | | | |
|---------------------|-----------|---------------------|---------------|--------|
| Registration | XA49AB | Next Service | Litres | |
| Make | Kenworth | Rego Due | Trans | N/A |
| Model | T404 | Engine # | Air | Yes |
| Model Series | | VIN | Cyl | 0 |
| Model Code | | Build Date | Body | TIPPER |
| Colour | Corkhills | Odometer | Prod | |

| Invoice No. | Date | Odometer | Description | Type |
|---|-------------------|---------------|---|----------------|
| B Service Brake shoes & wheel seal right rear drive left rear radius rod bushes Water hose to filter & top of radiator Replace clutch pedal rubber Replace rear cab bump rubber | | | | |
| 651 | 26/07/2019 | 451217 | Jacobs / Driving lights/ Clearance lights/ | Invoice |
| | 5623/100 | | 12 v Halogen Driving lamp kit | |
| | K213-3561 | | Covers driving light | |
| | 32146 | | Tune Up kit Jacobs | |
| | LAB | | Craig | |
| | K180-20463-460 | | Exhaust Pipe made to fit | |
| <ul style="list-style-type: none"> • Supply Driving light kit & light covers • Fit Exhaust pipe below turbo • Repair fuel tank cross over bar(bent up hitting exhaust) • Fit tune up kit to Jake Brakes | | | | |
| 630 | 22/06/2019 | 445043 | Jake Brakes / turbo A service | Invoice |
| | 172743 | | Turbo | |
| | 23508408 | | Seal Turbo Boost outlet | |
| | LAB | | Craig | |
| | K294-426RPAK | | Handle Door inside | |
| Remove rocker cover & locate broken spring in rear spool valve. replace spool & springs (second hand) Replace left door handle. Replace turbo (accidental damage) | | | | |
| 595 | 31/05/2019 | 0 | Oil Leak | Invoice |
| | LAB | | Craig | |
| | COOLANT | | Coolant | |
| | CONS | | General Consumables Used | |
| Replace leaking turbo drain hose Rotate turbo to help align drain pipe. Replace water hose clamps on water pump outlet hose | | | | |
| 581 | 09/05/2019 | 436620 | Transmission shifter XY shifter | Invoice |
| | R85-1236 | | Support Hood | |
| | LAB | | Craig | |
| | K4223RX | | X-Y Shifter gen 3 | |
| | K3681 | | harness transmission | |
| Replace X Y shifter & wiring harness Replace left bonnet support rubber | | | | |
| 558 | 30/04/2019 | 433035 | Tyres & Brake light short | Invoice |
| | LAB | | Labour | |
| | 11R22.5 DRIVE | | Double Coin drive tyre | |
| | NPN01 | | Tyre disposal | |

Vehicle Details

| | | | | | |
|---------------------|-----------|---------------------|------------|---------------|--------|
| Registration | XA49AB | Next Service | | Litres | |
| Make | Kenworth | Rego Due | | Trans | N/A |
| Model | T404 | Engine # | 06R0977097 | Air | Yes |
| Model Series | | VIN | 435791 | Cyl | 0 |
| Model Code | | Build Date | | Body | TIPPER |
| Colour | Corkhills | Odometer | 711322 | Prod | |

| Invoice No. | Date | Odometer | Description | Type |
|--|-------------------|---------------|--------------------------|----------------|
| <ul style="list-style-type: none"> Locate short in left rear tail light. Replace 4 x drive tyres front drive. | | | | |
| 547 | 10/04/2019 | 430331 | B service | Invoice |
| | VECTON | | Vecton 15W40 Engine Oil | |
| | LAB | | Labour | |
| | KWSW4 | | Switch cruise control | |
| | LF3620 | | Detroit Oil Filter | |
| | FF5207 | | fuel filter | |
| | FF5206 | | Fuel Filter | |
| B Service Replace cruise control switch | | | | |
| 494 | 13/03/2019 | 423046 | Batteries | Invoice |
| | LAB | | Sean | |
| | N70ZZHMF | | Battery | |
| Replace batteries clean battery terminals tighten right rear tarp cable on trailer | | | | |
| 493 | 11/02/2019 | 417651 | A Service | Invoice |
| | K213-3561 | | Covers driving light | |
| | LAB | | Craig | |
| | LAB | | Pete | |
| <ul style="list-style-type: none"> A Service Weld rear of body to light bar Repair cracks in rear of tipper area Replace rotors on right front dolly & left rear wheel Replace brake pads on all 4 dolly wheels tighten all wheel bearings | | | | |
| 442 | 15/01/2019 | 0 | Turbo boost hose | Invoice |
| | HE8701 | | Host turbo hump hose | |
| | LAB | | Craig | |
| Replace turbo hump hose at Boral quarry | | | | |
| 489 | 10/01/2019 | 409503 | Front Diff | Invoice |
| | LAB | | Labour | |
| | AP85W140 | | Diff oil | |
| | NPN03 | | Front diff repair | |
| | SUBLET | | Rebuild fornt diff | |
| Remove & replace front diff center | | | | |
| 427 | 04/01/2019 | 708542 | Annual Inspection | Invoice |
| | 73D2002 | | Shock Rubbers | |
| | LAB | | Craig | |
| Annual Inspection Replace right steer shock rubbers | | | | |

Vehicle Details

| | | | | |
|---------------------|-----------|---------------------|---------------|--------|
| Registration | XA49AB | Next Service | Litres | |
| Make | Kenworth | Rego Due | Trans | N/A |
| Model | T404 | Engine # | Air | Yes |
| Model Series | | VIN | Cyl | 0 |
| Model Code | | Build Date | Body | TIPPER |
| Colour | Corkhills | Odometer | Prod | |

| Invoice No. | Date | Odometer | Description | Type |
|---|-------------------|----------|------------------------------|---------|
| 407 | 26/11/2018 | 398829 | B service & repairs | Invoice |
| | 23533969 | | Dip Stick Gauge | |
| | 23533956 | | Tube for dip stick | |
| | VECTON | | Vecton 15W40 Engine Oil | |
| | LF3620 | | Detroit Oil Filter | |
| | WF2077 | | Water filter no DCA | |
| | FF5206 | | Fuel Filter | |
| | FF5207 | | fuel filter | |
| | 295/80R22.5 RY537 | | 295/80 R22.5 Yokohama | |
| | R23523998 | | Accessory Drive Detroit | |
| | LAB | | Ash Josh | |
| <ul style="list-style-type: none"> • Dip Stick gauge & tube • B Service • Replace Steer tyres • Clean out heater drain tubes (Water in cab form A/C) • Replace accessory drive (leaking oil) | | | | |
| 337 | 18/10/2018 | 384397 | A Service | Invoice |
| | LAB | | Jimmy & Josh | |
| | 8PK915 | | Drive Belt | |
| | K374-38KIT | | Shock Absorber Kit | |
| <ul style="list-style-type: none"> • A Service • Replace rear shock absorbers • Replace alternator drive belt • | | | | |
| 335 | 14/09/2018 | 368642 | B service. General repairs | Invoice |
| | AE4017 | | Aerial | |
| | LAB | | Labour | |
| | R134A | | Refrigerant Gas | |
| | CONS | | General Consumables Used | |
| | CONS | | General Consumables Used | |
| | KSMA3124720QP | | Brake Shoe Kit Front Axle KW | |
| | 23532122 | | Manifold Exhaust | |
| | 23525090 | | Gasket Exhaust Manifold | |
| <ul style="list-style-type: none"> • B Service • Replace tx valve • Rectify fault in cruise control • Replace Exhaust manifold • Replace door lock • Replace Christmas tree clips in door • Repair cracks in tipper • Replace steer brake linings | | | | |
| 304 | 12/07/2018 | 351129 | A/C Compressor | Invoice |
| | CM7949 | | A/C Compressor | |
| | R134A | | Refrigerant Gas | |

Vehicle Details

| | | | | |
|---------------------|-----------|---------------------|---------------|--------|
| Registration | XA49AB | Next Service | Litres | |
| Make | Kenworth | Rego Due | Trans | N/A |
| Model | T404 | Engine # | Air | Yes |
| Model Series | | VIN | Cyl | 0 |
| Model Code | | Build Date | Body | TIPPER |
| Colour | Corkhills | Odometer | Prod | |

| Invoice No. | Date | Odometer | Description | Type |
|-------------|----------|----------|-------------------------------|------|
| | 17530BLT | | Belt V 13A1345 | |
| | LAB | | Labour | |
| | TXX3015 | | TX Valve (Block valve female) | |

- Replace A/C Compressor & Drive Belt
- Tighten Exhaust gaskets
- Replace centre exhaust manifold
- Replace TX Valve

| | | | | |
|------------|-------------------|---------------|--------------------------|----------------|
| 221 | 02/07/2018 | 351189 | A Service | Invoice |
| | LAB | | Labour | |
| | CONS | | General Consumables Used | |
| | NPN03 | | Rod end | |

A Service and install park brake warning alarm
 Replace rod end on clutch link
 Fit new Christmas trees to right door trim
 Tighten clamps on exhaust

| | | | | |
|------------|-------------------|---------------|--------------------------|----------------|
| 219 | 02/07/2018 | 351189 | Park Brake Alarm | Invoice |
| | LAB | | Labour | |
| | HBA1224 | | Hand Brake Alarm 12/24V | |
| | CONS | | General Consumables Used | |

Install hand brake warning alarm

| | | | | |
|------------|-------------------|---------------|---|----------------|
| 217 | 05/06/2018 | 344185 | Low Power/ Injectors & Turbo | Invoice |
| | CONS | | General Consumables Used | |
| | NPN03 | | 1/2 Strata Flex | |
| | NPN03 | | 5/16 Strata Flex | |
| | 172743 | | Turbo | |
| | RB5235695 | | Injector Exchange Bosch Detroit | |
| | 5104701 | | Seal Injector tube backup | |
| | MAHP0237 | | Fuel Hose Filter to head | |
| | MAHH0200 | | Hose Fuel Pump to sec filter | |
| | MBHH0160 | | Hose Primary to fuel pump | |
| | LAB | | Labour | |
| | MC553B | | Microphone GME | |
| | K295-179 | | Valve Fuel Cut Off | |
| | 20820-6-6 | | Fitting Swivel Straight | |
| | TRP1615726 | | Charge Air Cooler | |
| | K85-1058-002 | | Support Fuel tank | |
| | T210089A | | Cooler fuel / oil | |

- Engine Low Power
- Locate and repair fault in wiring at ECM
- Pressure test Charge Air Cooler (leaking). Check fuel hoses for rubber in fuel. Replace fuel hoses. Remove fuel tanks & clean out. replace right front J bracket on fuel tank. Replace Charge air Cooler. Replace Fuel Injectors. Replace Fuel filters. Replace Fuel Cooler. Replace Turbo, (found waste gate valve missing). Make up Alloy edging for engine cowling.

| | | | | |
|------------|-------------------|--|--------------------------|----------------|
| 258 | 16/04/2018 | | A & B Service | Invoice |
| | L46-1029 | | Bug Screen | |

Vehicle Details

| | | | | | |
|--------------|-----------|--------------|------------|--------|--------|
| Registration | XA49AB | Next Service | | Litres | |
| Make | Kenworth | Rego Due | | Trans | N/A |
| Model | T404 | Engine # | 06R0977097 | Air | Yes |
| Model Series | | VIN | 435791 | Cyl | 0 |
| Model Code | | Build Date | | Body | TIPPER |
| Colour | Corkhills | Odometer | 711322 | Prod | |

| Invoice No. | Date | Odometer | Description | Type |
|-------------|---------------|----------|-------------------------------|---------|
| 163 | 16/04/2018 | 609172 | C Service & repairs | Invoice |
| | LF637 | | Oil Filter Power steer | |
| | A9-333T4726 | | Hub Assembly | |
| | 53-18 | | Wiper refill 18inch | |
| | CONS | | General Consumables Used | |
| | 85W140 | | Hypoid Diff Oil | |
| | OIL ENGINE | | Lubeolloy | |
| | K36-235 | | Clutch Bearing | |
| | 23516918 | | Valve non return fuel | |
| | PT50 GEAR OIL | | Gear oil | |
| | K301-419-2 | | Switch Pressure | |
| | K301-419-4 | | Pressure switch | |
| | F093400 | | Horton Solenoid & Filter assy | |
| | KA300029 | | Kit Servo Motor | |
| | ACX2123 | | Rotating Beacon | |
| | AF26417 | | Air filter | |
| | FF5206 | | Fuel Filter | |
| | FF5207 | | fuel filter | |
| | R824004 | | Slack adjuster Fine | |
| | LAB | | Labour | |
| | H3 | | H 3 Globe Driving light | |

C service
Tighten fuel hose at rear of engine. Perform cylinder drop out test, Move #3 injector to #2, low cylinder output still at #3.
Replace left side drive slack adjusters. Replace clutch pivot bearing on firewall. Replace wiper blades. Replace non return fuel valve in back of head. Replace beacon on cab. Repair broken chassis at tailgate lock area rear of body. Clean out diff breathers. Replace cruise brake switch & trailer low air switch. Fit new steer tyres. Replace Horton solenoid & filter.

| Vehicle Details | | | | | |
|-----------------|-----------|--------------|------------|--------|--------|
| Registration | XA49AB | Next Service | | Litres | |
| Make | Kenworth | Rego Due | | Trans | N/A |
| Model | T404 | Engine # | 06R0977097 | Air | Yes |
| Model Series | | VIN | 435791 | Cyl | 0 |
| Model Code | | Build Date | | Body | TIPPER |
| Colour | Corkhills | Odometer | 711322 | Prod | |

| Invoice No. | Date | Odometer | Description | Type |
|---|------------|----------|------------------|---------|
| 2318 | 01/03/2025 | 0 | General Repairs | Invoice |
| Replace 12v Air Solenoid for tailgate lock | | | | |
| 2169 | 10/12/2024 | 711322 | Head Lights | Invoice |
| Replace front Headlights | | | | |
| 2143 | 25/11/2024 | 0 | Boost Hose | Invoice |
| Replace boost hose at turbo outlet | | | | |
| 2122 | 04/11/2024 | 0 | Boost Hoses | Invoice |
| Replace boost hose from turbo to charge pipe | | | | |
| 2111 | 01/11/2024 | 0 | Exhaust stacks | Invoice |
| Replace exhaust stacks stolen from Yard | | | | |
| 2004 | 03/09/2024 | 700929 | B service | Invoice |
| B Service | | | | |
| 1913 | 12/07/2024 | 694328 | Jake Brake Fault | Invoice |
| Replace cracked exhaust manifold. Replace master pistons in Jake Brakes, Re-kit Jake brakes. Repair oil leak at filler pipe. Straighten steering wheel, Replace grain locks | | | | |
| 1883 | 26/06/2024 | 0 | Truck Wash | Invoice |
| Truck Wash | | | | |
| 1748 | 29/11/2023 | 653456 | A Service | Invoice |
| A Service Replace rear lower shock rubbers Replace rose joints on clutch linkages Replace 2 x drive tyres | | | | |
| 1658 | 05/07/2023 | 625719 | A Service | Invoice |
| A Service | | | | |

Vehicle Details

| | | | | |
|---------------------|-----------|---------------------|---------------|--------|
| Registration | XA49AB | Next Service | Litres | |
| Make | Kenworth | Rego Due | Trans | N/A |
| Model | T404 | Engine # | Air | Yes |
| Model Series | | VIN | Cyl | 0 |
| Model Code | | Build Date | Body | TIPPER |
| Colour | Corkhills | Odometer | Prod | |

| Invoice No. | Date | Odometer | Description | Type |
|---|------------|----------|------------------------------------|---------|
| 1844 | 11/04/2023 | 610631 | Turbo & Exhaust manifold gaskets B | Invoice |
| B Service <ul style="list-style-type: none">• Replace turbo• Fit new manifold gaskets• Tighten indicator switch & replace Jake brake switch• Replace all lower shock rubbers• Tighten pitman arm pinch bolt• Replace Jake brake switch | | | | |
| 1580 | 13/12/2022 | 0 | Cab mounts | Invoice |
| Replace front Cab mounts | | | | |
| 1409 | 10/09/2022 | 595352 | A Service | Invoice |
| A Service Repair tail lights & Reverse lights | | | | |
| 1281 | 18/11/2021 | 553724 | B service And Steering Box | Invoice |
| Replace steering box B Service Replace 2 drive tyres | | | | |
| 1265 | 28/08/2021 | 533758 | B Service & brakes | Invoice |
| B Service Replace brakes on rear axle | | | | |
| 1264 | 09/07/2021 | 0 | Front diff center | Invoice |
| Remove front diff center after power divider failure Send to Truck Transmissions Clean diff housings & flush wheel bearings fitting new seals Refit Exchange diff center | | | | |
| 1263 | 17/06/2021 | 0 | B service & repairs | Invoice |
| B service <ul style="list-style-type: none">• Replace thrust bearing on left king pin• Replace compressor• Fit new air blower in cab• Replace air dryer filter | | | | |
| 1098 | 28/01/2021 | 506907 | Annual Inspection | Invoice |
| Annual Inspection Replace both rear ride height valves | | | | |
| 1042 | 20/10/2020 | 5003304 | A Service | Invoice |

Vehicle Details

| | | | | |
|---------------------|-----------|---------------------|---------------|--------|
| Registration | XA49AB | Next Service | Litres | |
| Make | Kenworth | Rego Due | Trans | N/A |
| Model | T404 | Engine # | Air | Yes |
| Model Series | | VIN | Cyl | 0 |
| Model Code | | Build Date | Body | TIPPER |
| Colour | Corkhills | Odometer | Prod | |

| Invoice No. | Date | Odometer | Description | Type |
|--|------------|----------|--|---------|
| A Service | | | | |
| <ul style="list-style-type: none">• Replace PTO pump• Replace compressor• Replace hydraulic oil• Replace water lines to compressor & w pump | | | | |
| 994 | 26/08/2020 | 484425 | C Service | Invoice |
| C Service | | | | |
| <ul style="list-style-type: none">• Replace water pump• Replace right front hub• Replace leaking water tap at w/pump• Replace belt tensioner• Replace rear shock absorber• Replace accelerator pedal roller | | | | |
| 998 | 04/08/2020 | 0 | General Repairs | Invoice |
| <ul style="list-style-type: none">• Replace drivers seat• Fit new seat covers• Fit new Mattress• Free up brake pedal plunger (sticking) | | | | |
| 978 | 21/04/2020 | 477427 | A Service | Invoice |
| A Service | | | | |
| <ul style="list-style-type: none">• Replace boost hose | | | | |
| 811 | 06/11/2019 | 461743 | B service | Invoice |
| B Service Brake shoes & wheel seal right rear drive left rear radius rod bushes Water hose to filter & top of radiator Replace clutch pedal rubber Replace rear cab bump rubber | | | | |
| 651 | 26/07/2019 | 451217 | Jacobs / Driving lights/ Clearance lights/ | Invoice |
| <ul style="list-style-type: none">• Supply Driving light kit & light covers• Fit Exhaust pipe below turbo• Repair fuel tank cross over bar(bent up hitting exhaust)• Fit tune up kit to Jake Brakes | | | | |
| 630 | 22/06/2019 | 445043 | Jake Brakes / turbo A service | Invoice |
| Remove rocker cover & locate broken spring in rear spool valve. replace spool & springs (second hand) Replace left door handle. Replace turbo (accidental damage) | | | | |

Vehicle Details

| | | | | |
|---------------------|-----------|---------------------|---------------|--------|
| Registration | XA49AB | Next Service | Litres | |
| Make | Kenworth | Rego Due | Trans | N/A |
| Model | T404 | Engine # | Air | Yes |
| Model Series | | VIN | Cyl | 0 |
| Model Code | | Build Date | Body | TIPPER |
| Colour | Corkhills | Odometer | Prod | |

| Invoice No. | Date | Odometer | Description | Type |
|---|------------|----------|---------------------------------|---------|
| 595 | 31/05/2019 | 0 | Oil Leak | Invoice |
| Replace leaking turbo drain hose Rotate turbo to help align drain pipe. Replace water hose clamps on water pump outlet hose | | | | |
| 581 | 09/05/2019 | 436620 | Transmission shifter XY shifter | Invoice |
| Replace X Y shifter & wiring harness Replace left bonnet support rubber | | | | |
| 558 | 30/04/2019 | 433035 | Tyres & Brake light short | Invoice |
| <ul style="list-style-type: none">• Locate short in left rear tail light.• Replace 4 x drive tyres front drive. | | | | |
| 547 | 10/04/2019 | 430331 | B service | Invoice |
| B Service Replace cruise control switch | | | | |
| 494 | 13/03/2019 | 423046 | Batteries | Invoice |
| Replace batteries clean battery terminals tighten right rear tarp cable on trailer | | | | |
| 493 | 11/02/2019 | 417651 | A Service | Invoice |
| <ul style="list-style-type: none">• A Service• Weld rear of body to light bar• Repair cracks in rear of tipper area• Replace rotors on right front dolly & left rear wheel• Replace brake pads on all 4 dolly wheels• tighten all wheel bearings | | | | |
| 442 | 15/01/2019 | 0 | Turbo boost hose | Invoice |
| Replace turbo hump hose at Boral quarry | | | | |
| 489 | 10/01/2019 | 409503 | Front Diff | Invoice |
| Remove & replace front diff center | | | | |
| 427 | 04/01/2019 | 708542 | Annual Inspection | Invoice |
| Annual Inspection Replace right steer shock rubbers | | | | |
| 407 | 26/11/2018 | 398829 | B service & repairs | Invoice |
| <ul style="list-style-type: none">• Dip Stick gauge & tube• B Service• Replace Steer tyres | | | | |

Vehicle Details

| | | | | | |
|---------------------|-----------|---------------------|------------|---------------|--------|
| Registration | XA49AB | Next Service | | Litres | |
| Make | Kenworth | Rego Due | | Trans | N/A |
| Model | T404 | Engine # | 06R0977097 | Air | Yes |
| Model Series | | VIN | 435791 | Cyl | 0 |
| Model Code | | Build Date | | Body | TIPPER |
| Colour | Corkhills | Odometer | 711322 | Prod | |

| Invoice No. | Date | Odometer | Description | Type |
|---|------------|----------|------------------------------|---------|
| <ul style="list-style-type: none"> Clean out heater drain tubes (Water in cab form A/C) Replace accessory drive (leaking oil) | | | | |
| 337 | 18/10/2018 | 384397 | A Service | Invoice |
| <ul style="list-style-type: none"> A Service Replace rear shock absorbers Replace alternator drive belt | | | | |
| 335 | 14/09/2018 | 368642 | B service. General repairs | Invoice |
| <ul style="list-style-type: none"> B Service Replace tx valve Rectify fault in cruise control Replace Exhaust manifold Replace door lock Replace Christmas tree clips in door Repair cracks in tipper Replace steer brake linings | | | | |
| 304 | 12/07/2018 | 351129 | A/C Compressor | Invoice |
| <ul style="list-style-type: none"> Replace A/C Compressor & Drive Belt Tighten Exhaust gaskets Replace centre exhaust manifold Replace TX Valve | | | | |
| 221 | 02/07/2018 | 351189 | A Service | Invoice |
| A Service and install park brake warning alarm Replace rod end on clutch link Fit new Christmas trees to right door trim Tighten clamps on exhaust | | | | |
| 219 | 02/07/2018 | 351189 | Park Brake Alarm | Invoice |
| Install hand brake warning alarm | | | | |
| 217 | 05/06/2018 | 344185 | Low Power/ Injectors & Turbo | Invoice |
| <ul style="list-style-type: none"> Engine Low Power Locate and repair fault in wiring at ECM Pressure test Charge Air Cooler (leaking). Check fuel hoses for rubber in fuel. Replace fuel hoses.Remove fuel tanks& clean out. replace right front J bracket on fuel tank. Replace Charge air Cooler. Replace Fuel Injectors. Replace Fuel filters.Replace Fuel Cooler. Replace Turbo, (found waste gate valve missing). Make up Alloy edging for engine cowlng. | | | | |
| 258 | 16/04/2018 | | A & B Service | Invoice |
| 163 | 16/04/2018 | 609172 | C Service & repairs | Invoice |

Vehicle Details

| | | | | | |
|--------------|-----------|--------------|------------|--------|--------|
| Registration | XA49AB | Next Service | | Litres | |
| Make | Kenworth | Rego Due | | Trans | N/A |
| Model | T404 | Engine # | 06R0977097 | Air | Yes |
| Model Series | | VIN | 435791 | Cyl | 0 |
| Model Code | | Build Date | | Body | TIPPER |
| Colour | Corkhills | Odometer | 711322 | Prod | |

| Invoice No. | Date | Odometer | Description | Type |
|--|------|----------|-------------|------|
| C service Tighten fuel hose at rear of engine. Perform cylinder drop out test, Move #3 injector to #2, low cylinder output still at #3. Replace left side drive slack adjusters. Replace clutch pivot bearing on firewall. Replace wiper blades. Replace non return fuel valve in back of head. Replace beacon on cab. Repair broken chassis at tailgate lock area rear of body. Clean out diff breathers. Replace cruise brake switch & trailer low air switch. Fit new steer tyres. Replace Horton solenoid & filter. | | | | |