

iconicturbos@gmail.com (905) 808-0553 684 Mud Street East Stoney Creek, ON. L8J 3C9

Warranty policy

At Iconic Turbos Inc., We use very strict guidelines to make sure you get the best quality turbos, parts, and services. We will repair or replace any new or rebuilt turbocharger/CHRA and parts that are found to be defective due to failure of material or workmanship for a period of twelve (12) months from the date of the invoice. This warranty is limited to the turbocharger ONLY, and does not include any parts associated with, attached, or connected to the turbocharger. This warranty does not cover incidental or consequential damage or expenses of any kind.

This warranty applies to the original purchaser and is NOT transferable.

**To validate your warranty, you must keep receipts of your new oil feed line and oil filter. **

NO refunds will be issued for turbochargers that have been installed or any special-order items.

This warranty does NOT apply to any turbo that has been subjected to oil related problems, improper installation, damage from foreign objects, accidents, modifications made to the turbo by the purchaser, or if the turbo has been disassembled by anyone other than Iconic Turbos Inc. If any adjustments or modifications need to be made, please contact us for troubleshooting.

If any conditions are not respected, Iconic Turbos Inc. reserves the right to refuse validation of the warranty. Turbochargers will not be assembled if deemed unfit for use. For any work left unpaid past 30 days, turbocharger(s) and related part(s) become property of Iconic Turbos Inc.

For us to warranty the turbo or parts, it must be returned to us for inspection in an as-is condition. Any disassembly will automatically void your warranty. NO exceptions.

*** Iconic Turbos Inc is NOT responsible for any shipping cost ***

Please make sure that the turbo has been drained of all oil and is placed in a plastic bag. Make sure the turbo is packaged in a box properly.

Iconic Turbos Inc is NOT responsible for any damage that may have occurred during shipping.