



Kenworth Truck Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

XX/XX/2026

Subject: CE031: MX Component Specific Emissions Warranty for EMY2022

PACCAR MX-11 and MX-13 Engines

Expiration Date: None



This notice applies to your vehicle; Your VIN(s) can be found on the front or back of this page.

Dear Kenworth Customer,

This notice is sent to you in accordance with the requirements of the Canadian Environmental Protection Act, 1999.

This is not a recall or campaign. You do not need to schedule an appointment with your dealer unless you experience a problem with your vehicle.

This letter has been sent to inform you that Kenworth Truck Company has extended the warranty coverage on certain emissions components installed on your vehicle(s). Your vehicle(s) contain(s) one or more of the parts listed in this letter. **No action is needed on your part.**

The Emissions Warranty Coverage for the components listed in the table below has been extended to 10 years, 435,000 vehicle miles/700,000 km, or 22,000 engine hours from the original warranty registration date, whichever comes first.

Table 1 Parts Covered by Extended Warranty Coverage (EWC Code 9202162)

Part Name	Part Number	Result of Failure
Fuel Injector (MX-13, EPA21)	2314737PEX ⁽¹⁾ 2383579PEX ⁽¹⁾ 2394548PEX ⁽¹⁾ 2403776PEX ⁽¹⁾ 2403201PEX ⁽¹⁾ 2403778PEX ⁽¹⁾ 2423652PEX ⁽¹⁾ 2423654PEX ⁽¹⁾ 2426854PEX ⁽¹⁾ 2426856PEX ⁽¹⁾ 2429855PEX ⁽¹⁾ 2428774PEX ⁽¹⁾ 2452062PEX ⁽¹⁾ 2460410PEX ⁽¹⁾	Inefficient fuel injector performance can lead to insufficient regeneration and high soot loading of DPF due to uneven fuel burning.



A **PACCAR** COMPANY

Kenworth Truck Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

	2460412PEX ⁽¹⁾ 2460414PEX ⁽¹⁾	
Fuel Injector (MX-11, EPA21)	2314736PEX ⁽¹⁾ 2383578PEX ⁽¹⁾ 2394547PEX ⁽¹⁾ 2403775PEX ⁽¹⁾ 2403200PEX ⁽¹⁾ 2403777PEX ⁽¹⁾ 2423651PEX ⁽¹⁾ 2423653PEX ⁽¹⁾ 2426853PEX ⁽¹⁾ 2426855PEX ⁽¹⁾ 2429854PEX ⁽¹⁾ 2428773PEX ⁽¹⁾ 2452061PEX ⁽¹⁾ 2460409PEX ⁽¹⁾ 2460411PEX ⁽¹⁾ 2460413PEX ⁽¹⁾	Inefficient fuel injector performance can lead to insufficient regeneration and high soot loading of DPF due to uneven fuel burning.
DPF Delta Pressure Sensor (MX-13, EPA21)	2200138PEX ⁽¹⁾	Failures of the Delta Pressure Sensor may result in inaccurate monitoring of the DPF/SCR could have the potential to compromise the DPF/SCR system effectiveness and affect tailpipe emissions of NOx and/or particulate matter.
Fuel Injection Pump (MX-13, EPA21)	2185361PE ⁽¹⁾ 2344776PEX ⁽²⁾	Failures of the Fuel Injection Pumps that result in inaccurate monitoring of exhaust gases have the potential to compromise SCR system effectiveness and affect tailpipe emissions of NOx.
DPF Delta Pressure Sensor (MX-11, MX-13, EPA21)	2200138 ⁽¹⁾	Failures of the Delta Pressure Sensor that result in inaccurate monitoring of the DPF/SCR have the potential to compromise the DPF/SCR system effectiveness and affect tailpipe emissions of NOx and/or particulate matter.
⁽¹⁾ Components that were included in a previous letter. ⁽²⁾ Additional component added to Extended Warranty Coverage.		

If you have previously paid to replace one of the components listed in the tables above, you may be eligible for reimbursement of the cost of parts and labor. Please provide your Kenworth



Kenworth Truck Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

Dealer with a receipt for the repair and your dealer will file a claim on your behalf. If approved, your dealer will issue reimbursement.

To locate your nearest dealer please scan the QR code at the top of this letter or use the Dealer Locator at www.Kenworth.com. When contacting your selected Kenworth dealer, refer to Extended Warranty Code (EWC) **9202162** and the VIN listed on this letter.

If you are the lessor of this vehicle, federal regulations require you to forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, please email the last 8 digits of the VIN and the new owner's name and address to servicebulletins@paccar.com.

Sincerely,

Kenworth Customer Service