

Register: Fleet Repair Register

Project	Team	Created By	Created Date	Document Version	Fleet Item:	
904GYO - Gladstone Yard & Office	Site Team	Plant Loftus	Wed, 11 Dec 2024, 2:24 pm	V1	LFC 341 - CAT 12M Grader	See the form for more details
904GYO - Gladstone Yard & Office	Site Team	Daniel Poulsen	Wed, 20 Nov 2024, 5:11 pm	V1	LFC 341 - CAT 12M Grader	See the form for more details
904GYO - Gladstone Yard & Office	Site Team	Imelda Stratton	Mon, 28 Oct 2024, 1:48 pm	V1	LFC 341 - CAT 12M Grader	See the form for more details
904GYO - Gladstone Yard & Office	Site Team	Daniel Poulsen	Wed, 25 Sep 2024, 11:18 am	V1	LFC 341 - CAT 12M Grader	See the form for more details
903GYO - Gladstone Yard & Office	Site Team	Scott McAlary	Tue, 27 Feb 2024, 5:44 pm	V2	LFC 341 - CAT 12M Grader	See the form for more details
903GYO - Gladstone Yard & Office	Site Team	Scott McAlary	Wed, 31 Jan 2024, 5:49 pm	V3	LFC 341 - CAT 12M Grader	See the form for more details
903GYO - Gladstone Yard & Office	Site Team	Scott McAlary	Thu, 21 Dec 2023, 9:48 am	V2	LFC 341 - CAT 12M Grader	See the form for more details
903GYO - Gladstone Yard & Office	Site Team	Scott McAlary	Wed, 29 Nov 2023, 5:40 am	V2	LFC 341 - CAT 12M Grader	See the form for more details

Fleet Repair Register

Plant Loftus
Created Wed, 11 Dec 2024, 2:24 PM (UTC+10:00)

Fleet Item: LFC 341 - CAT 12M Grader

1.0 - FLEET REPAIR REGISTER

Issue Description	Issue Rectification	Parts Used	Date Repaired	Time Taken	Technician	Comments	Photos
Engine oil low, left door not opening from inside, AM/FM radio not working	Topped up engine oil approx 1L, repaired door linkage, radio unit u/s		Mon, 25 Nov 2024	1	Martin Beckett		

Form Template Revision No.: 01

Fleet Repair Register

Daniel Poulsen
Created Wed, 20 Nov 2024, 5:11 PM (UTC+10:00)

Fleet Item: LFC 341 - CAT 12M Grader

1.0 - FLEET REPAIR REGISTER

Issue Description	Issue Rectification	Parts Used	Date Repaired	Time Taken	Technician	Comments	Photos
Tyre o-ring failed POS 5	Remove and replace. reinflate	O-ring 25"	Fri, 15 Nov 2024			Bridgestone 63322	

Form Template Revision No.: 01

Fleet Repair Register

Imelda Stratton

Created Mon, 28 Oct 2024, 1:48 PM (UTC+10:00)

Fleet Item:

LFC 341 - CAT 12M Grader

1.0 - FLEET REPAIR REGISTER

Issue Description	Issue Rectification	Parts Used	Date Repaired	Time Taken	Technician	Comments	Photos
A/C not working	Fitted new pressure switch	Pressure switch	Thu, 24 Oct 2024	2	Benjamin Bentley		

Form Template Revision No.: 01

Fleet Repair Register

Daniel Poulsen
Created Wed, 25 Sep 2024, 11:18 AM (UTC+10:00)

Fleet Item: LFC 341 - CAT 12M Grader

1.0 - FLEET REPAIR REGISTER

Issue Description	Issue Rectification	Parts Used	Date Repaired	Time Taken	Technician	Comments	Photos
Drive tyre flat	Replaced o-ring, pump back up		Tue, 03 Sep 2024			Bridgestone inv 61824	

Form Template Revision No.: 01

Fleet Repair Register

Scott McAlary
Created Tue, 27 Feb 2024, 5:44 PM (UTC+10:00)

Fleet Item: LFC 341 - CAT 12M Grader

1.0 - FLEET REPAIR REGISTER

Issue Description	Issue Rectification	Parts Used	Date Repaired	Time Taken	Technician	Comments	Photos
Faulty hoses Damaged cover	Replaced 3 hydraulic hoses and panel beater cover	3 x hoses	Tue, 27 Feb 2024	4 hrs	Scott McAlary		

Form Template Revision No.: 01

Fleet Repair Register

Scott McAlary
Created Wed, 31 Jan 2024, 5:49 PM (UTC+10:00)

Fleet Item: LFC 341 - CAT 12M Grader

1.0 - FLEET REPAIR REGISTER

Issue Description	Issue Rectification	Parts Used	Date Repaired	Time Taken	Technician	Comments	Photos
Fully assess for defects	Assessed unit on site and ordered parts		Mon, 29 Jan 2024	6	Scott McAlary		
Fixed some service issues	Replace skirts and shims on turntable Replaced cups in lift and slide balls Replaced fuel / water sep and exhaust filter.		Wed, 31 Jan 2024	8	Scott McAlary		

Form Template Revision No.: 01

Fleet Repair Register

Scott McAlary

Created Thu, 21 Dec 2023, 9:48 AM (UTC+10:00)

Fleet Item:

LFC 341 - CAT 12M Grader

1.0 - FLEET REPAIR REGISTER

Issue Description	Issue Rectification	Parts Used	Date Repaired	Time Taken	Technician	Comments	Photos
Exhaust tip broke off Burnt rotating beacon Filled airfilter with carbon via rebreathing	Rebuild exhaust tip got exhaust from Gladstone exhaust 90mm 90 degree and 90mm pipe Replace rotating beacon cut and joined wiring Replaced air filter	Rotating beacon 2 inner and primary air filter 90mm pipe and bend	Thu, 21 Dec 2023	6 hrs	Scott McAlary		 See full page photos attached at end of PDF

Form Template Revision No.: 01

No GPS information available

Captured by: Scott McAlary
Captured on: 20 Dec 2023, 1:17 pm
Tags: No photo tags attached
Description: Before
Comments:
No comments attached.




No GPS information available

Captured by: Scott McAlary
Captured on: 20 Dec 2023, 1:15 pm
Tags: No photo tags attached
Description: Before
Comments:
No comments attached.



No GPS information available

Captured by: Scott McAlary
Captured on: 20 Dec 2023, 1:26 pm
Tags: No photo tags attached
Description: Before
Comments:
No comments attached.



No GPS information available

Captured by: Scott McAlary
Captured on: 21 Dec 2023, 8:43 am
Tags: No photo tags attached
Description: After
Comments:
No comments attached.



Fleet Repair Register

Created Wed, 29 Nov 2023, 5:40 AM (UTC+10:00)
Scott McAlary

Fleet Item: LFC 341 - CAT 12M Grader

1.0 - FLEET REPAIR REGISTER

Issue Description	Issue Rectification	Parts Used	Date Repaired	Time Taken	Technician	Comments	Photos
Fit new number plates	Fitted new plates	Rivets *8	Wed, 29 Nov 2023	1 hr	Scott McAlary		

Form Template Revision No.: 01