

W1T96342420499863

YEAR

MODEL

2021

MB

ACTROS

13/08/2021

11/06/2021 12:00:00AM RO#: M106142 DATE: 11/06/2021 CUST: QS COMMODITIES ODOM: 1001 TOTAL: \$2351.35 ADVISOR: Peter Boys
BRANCH: 447MB SALE TYPE: C

OP_CODES
67MB10ZZ000099

OP_DESC
WINDOWS

COMPLAINT
REPLACE WIND SCREEN

CAUSE

CORRECTION
replace w/screen

11/06/2021 12:00:00AM RO#: M106143 DATE: 11/06/2021 CUST: QS COMMODITIES ODOM: 1841 TOTAL: \$2238.64 ADVISOR: Peter Boys
BRANCH: 447MB SALE TYPE: III

```
OP_CODES
00MB10ZZPD|40MBZZZZZZA
```

OP_DESC
CARRY OUT PRE-DELIVE carry out wheel align

COMPLAINT
FRONT AND REAR ALIGNMENT - NO AXLE BEND

CAUSE

CORRECTION
PREDELIVERY INSPECTION|

11/06/2021 12:00:00AM RO#: M106145 DATE: 11/06/2021 CUST: QS COMMODITIES ODOM: 1845 TOTAL: \$13756.40 ADVISOR: Peter Boys
BRANCH: 447MB SALE TYPE: |||||

```
OP_CODES
88MB0000|88MBZZZZZA|88MBZZZZZB|43MBZZZZZA|40MBCOVERS|91MBZZZZZB|67MB10ZZ000099|54MBZZ
ZZZA|54MB10ZZ000099.BAK|43MBZZZZZB
```

OP_DESC
exterior trim CHROME HUB & NUT COV WINDOWS ELECTRICAL REPAIRS 4 ELECTRICAL REPAIRS

COMPLAINT
SUPPLY AND FIT JOST JSK37 GREASY TURNTABLE ON 20mm PLATE^1270mm HIGH|SUPPLY AND FIT BLACK
PLASTIC GUARDS^ON CHROME POLES WITH PLASTIS GUARD MOUNTS^LOOP KITS, DTB MUDFLAPS WITH
MARKER PLATES^TAIL LAMPSON NEW BRACKETS^STAINLESS INSERTS IN GUARDS|ALLOY WALK

CAUSE
|||||||

CORRECTION
|||||||

9/08/2021 12:00:00AM RO#: M107684 DATE: 09/08/2021 CUST: QS COMMODITIES ODOM: 1900 TOTAL: \$687.99 ADVISOR: Peter Boys
BRANCH: 447MB SALE TYPE: I

```
OP_CODES
27MBZZZZZZB
```

OP	DESC
1	1
2	2
3	3
4	4
5	5
6	6
7	7
8	8
9	9
10	10
11	11
12	12
13	13
14	14
15	15
16	16
17	17
18	18
19	19
20	20
21	21
22	22
23	23
24	24
25	25
26	26
27	27
28	28
29	29
30	30
31	31
32	32
33	33
34	34
35	35
36	36
37	37
38	38
39	39
40	40
41	41
42	42
43	43
44	44
45	45
46	46
47	47
48	48
49	49
50	50
51	51
52	52
53	53
54	54
55	55
56	56
57	57
58	58
59	59
60	60
61	61
62	62
63	63
64	64
65	65
66	66
67	67
68	68
69	69
70	70
71	71
72	72
73	73
74	74
75	75
76	76
77	77
78	78
79	79
80	80
81	81
82	82
83	83
84	84
85	85
86	86
87	87
88	88
89	89
90	90
91	91
92	92
93	93
94	94
95	95
96	96
97	97
98	98
99	99
100	100

COMPLAINT
SUPPLY AND FIT BREATHERS TO^BOTH DIFFS AND GEAR BOX^AD BLUE TANK

CAUSE

CORRECTION

Component Serial Number

VIN

223210

473909C0613593

W1T96342420499863

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

13/08/2021

23/10/2021 12:00:00AM RO#: M109495 DATE: 23/10/2021 CUST: QS COMMODITIES ODOM: 48405 TOTAL: \$764.35 ADVISOR: Zoe Millington
BRANCH: 447MB SALE TYPE: M

OP_CODES
00MBMRSERV

OP_DESC
M & R SERVICE

COMPLAINT
CARRY OUT M & R SERVICE^SUPPLY AIR HOSE FOR CAB AND DRIVERS SIDE STEP PANEL

CAUSE
DC 21118SV^00530602 1.0 Perform Annual Inspection^00600001 0.3^00503501 0.2 General Telligent maintenance
lubrication^00605601 0.2

CORRECTION
Initial and MS print^Top up engine oil 3L^Grease jack shaft 0.4kg^Start service and fill extra worksheet^checked all oil
levels^topped up diff - 75w90 3L^inspected vehicle for defects^Greased turntable^fitted up air blower in cab as
requested^tightened mu

10/12/2021 12:00:00AM RO#: M110673 DATE: 10/12/2021 CUST: QS COMMODITIES ODOM: 0 TOTAL: \$0.00 ADVISOR: Kristie Scott
BRANCH: 447MB SALE TYPE: I

OP_CODES
00STNOSHOW

OP_DESC
APPOINTMENT NO SHOW

COMPLAINT
CARRY OUT 80,000K SERVICE

CAUSE

CORRECTION

23/12/2021 12:00:00AM RO#: M111022 DATE: 23/12/2021 CUST: QS COMMODITIES ODOM: 91483 TOTAL: \$2423.16 ADVISOR: Tyler Day
BRANCH: 447MB SALE TYPE: I||M|W|C

OP_CODES
54MH0099|01MB|54MB0099|00MB10ZZSTDSE|43MB000099|01MBZZZZZ

OP_DESC
ELECTRICAL REPAIRS 1|ENGINE MECH 1|ELECTRICAL REPAIRS 1|STANDARD SERVICE||ENGINE MECH 2

COMPLAINT
SUPPLY & FIT SPOT LIGHTS^*** PICKING UP 03/01/22|SUPPLY & FIT DIFF & GEARBOX BREATHERS|CHECK ALL
LIGHTS|CARRY OUT ENGINE SERVICE & TOP TUNE|Vehicle dropping air quickly.|Replace missing ad Blue cap.

CAUSE
||REPORT ONLY|DC - 21120SV ^00530602 1.5 Telligent time-based maintenance - annual Perform^005035010.2
General Telligent maintenance lubrication Perform^(with additional Telligent maintenance)^00532001 0.7 Telligent periodic
maintenance safety-related^ope

CORRECTION
Already fitted to vehicle.||DROVE TRUCK ONTO PIT^JACKED CAB OVER^INSPECTED TRUCK AND CHECKED
FLUIDS^NO EXTRA WORK FOUND^REQUESTED PARTS^DROPPED OIL^REPLACED OIL AND FUEL
FILTERS^INSTALLED NEW BUNG^CARRIED OUT VALVE SET^FILLED WITH 41L OF OIL^WIPER BLADES

Component Serial Number

VIN

223210

473909C0613593

W1T96342420499863

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

13/08/2021

24/02/2022 12:00:00AM RO#: M112516 DATE: 24/02/2022 CUST: QS COMMODITIES ODOM: 129516 TOTAL: \$276.98 ADVISOR: Troy Hart
BRANCH: 447MB SALE TYPE: M

OP_CODES

00MB

OP_DESC

TELLIGENT SERV 1

COMPLAINT

CARRY OUT INSPECTION 40K

CAUSE

CORRECTION

carry out the inspection service as per check sheet^ top up the water levels and check for safety^carry out the initial and the final quick test^ check for the oil level found out its down by 6015^ fill up with 10w40 6.15l^ ^ found out l side fuel tank st

Component Serial Number

VIN

223210

473909C0613593

W1T96342420499863

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

13/08/2021

Repair Order History

AmtPriceExtended

SlsId : RA971002227:01 Total : \$2,406.34

Date Invoice : 08/28/2024

OdomIn: 572,655

OdomOut: 572,655

Sold Operations

OpsId : 1 Job : 00 CHECK AND REPORT OIL LEAK AT SUMP

Cause :

Correction : Inspect oil leak at sump

1.00	OIL SEPARATOR	1,141.96	1,141.96
1.00	SEALING RING	4.36	4.36
-1.00	Adjust Parts Price [[Warranty Only]]	0.01	-0.01

OpsId : 2 Job : 00 CHECK AND REPORT ON OIL LEAK AT INJECTORS

Cause : Hard / brittle material of engine cylinder # 3 & 4 High pressure fuel injector line oil seals causing en

Correction : Tilt over cab and check for engine oil leak from upper section of engine

1.00	HIGH PRESSURE LINE	192.23	192.23
1.00	HIGH PRESSURE LINE	212.35	212.35
2.00	METAL SEAL	32.01	64.02
1.00	Adjust Parts Price [[Warranty Only]]	0.02	0.02

OpsId : 3 Job : 79 CARRY OUT THERMO RECALL

Cause : SM3311 required

Correction : COMPLAINT - THERMOS901 - SM3311;

1.00	SEAL	16.31	16.31
1.00	THERMOSTAT	230.75	230.75
-1.00	Adjust Parts Price [[Warranty Only]]	16.31	-16.31

SlsId : RA920032884:02 Total : \$1,588.18

Date Invoice : 06/26/2025

OdomIn: 613,663

OdomOut: 613,663

Component Serial Number

VIN

223210

473909C0613593

W1T96342420499863

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

13/08/2021

Sold Operations

OpsId : 4 Job : ASR Exhaust flex leaking - Remove exhaust flex inspect for diesel leak

Cause :

Correction : C - Exhaust flex leaking - Remove exhaust flex inspect for diesel leak

0.00 Choose appropriate Labour Guide for type of work to be performed 0.00 0.00

OpsId : 6 Job : ASR replace exhaust flex and clamps

Cause :

Correction : exhaust flex split and bypassing fuel externally when carrying out dpf regen - replace exhaust flex e

1.00 EXHAUST GAS LINE 385.75 385.75

1.00 PIPE CLAMP 181.49 181.49

1.00 PARTS KIT PIPE CLAMP 153.09 153.09

0.00 Staging Room 0.00 0.00

0.00 Choose appropriate Labour Guide for type of work to be performed 0.00 0.00

0.00 EXHAUST GAS LINE 399.25 0.00

1.00 PIPE CLAMP 187.85 187.85

0.00 PARTS KIT PIPE CLAMP 158.46 0.00

0.00 PARTS REQ BY BV - 24/6 0.00 0.00

0.00 STAGE ROOM PLEASE 0.00 0.00

SIId : RA920032884:01 Total : \$5,645.39

Date Invoice : 05/30/2025

OdomIn: 613,663

OdomOut: 613,663

Sold Operations

OpsId : 2 Job : ASR ACM ECU INTERNAL FAULT

Cause : DONE - HP

Correction : Remove exhaust covers to access ACM. Remove ACM.

0.00 CU AGN 6,337.39 0.00

0.00 ex overseas 0.00 0.00

0.00 VIN REQ - stocked item was pre-programmed 0.00 0.00

0.00 CU AGN 3,405.44 0.00

0.00 CU AGN 3,309.06 0.00

0.00 Daimler cancelled order after advising ETA 2 weeks, Steven pola following up 0.00 0.00

1.00 CU AGN 4,115.39 4,115.39

SIId : RA920029078:02 Total : \$104.00

Date Invoice : 03/27/2025

OdomIn: 613,663

OdomOut: 613,663

Sold Operations

OpsId : 3 Job : 99 MISC

Cause : RE-RAISE TO RA920032876

Correction :

0.00 RE-RAISE TO RA920032876 - AGED OUT 0.00 0.00

SIId : RA920029078:01 Total : \$1,485.00

Date Invoice : 12/13/2024

OdomIn: 613,663

OdomOut: 613,663

Component Serial Number

VIN

223210

473909C0613593

W1T96342420499863

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

13/08/2021

Sold Operations

OpsId : 1 Job : EA ADBLUE FAULTS ON DASH - CHECK AND REPORT
Cause : DONE - HP
Correction : C - ADBLUE FAULTS ON DASH

SlId : RA920028744:02 Total : \$3,775.87 Date Invoice : 11/14/2024 OdomIn: 607,913 OdomOut: 607,913

Sold Operations

OpsId : 2 Job : 99 LOW ADBLUE MESSAGE ON DASH
Cause : EGR ACTUATOR INTERNALLY BINDING IN EFFECT HAS WORN EGR VALVE FLAP
Correction : Diagnosis: Inspect and confirm fault - found faults in mcm for EGR actuator values incorrect

1.00	RECIRCULATION VALVE	1,039.59	1,039.59
1.00	METAL SEAL	45.67	45.67
1.00	ACTUATOR MOTOR	1,792.24	1,792.24
6.00	HEXAGON NUT	12.65	75.90
4.00	STUD BOLT	15.19	60.76
1.00	LEVER	53.18	53.18
1.00	DRAIN SCREW	32.02	32.02
1.00	Adjust Parts Price [[Warranty Only]]	0.01	0.01

SlId : RA920028744:01 Total : \$1,380.96 Date Invoice : 11/12/2024 OdomIn: 607,913 OdomOut: 607,913

Sold Operations

OpsId : 1 Job : 99 EXHAUST FAULT ON DASH
Cause :
Correction : Cause:

0.00	KALLUMS DESK	0.00	0.00
1.00	MISC SHOP SUPPLIES	0.00	0.00
4.00	COOLANT - ALLIANCE PRIMECOOL GP P-40	12.74	50.96

SlId : RA920028415:03 Total : \$2,280.54 Date Invoice : 12/12/2024 OdomIn: 606,173 OdomOut: 606,183

Sold Operations

OpsId : 3 Job : 15 NOX SENSOR FAULT PRESENT.
Cause : done
Correction : CARRIED OUT LOOKING INTO EXHAUST GAS FAULT ON DASH

1.00	NOX SENSOR	1,755.54	1,755.54
------	------------	----------	----------

SlId : RA920028415:02 Total : \$548.36 Date Invoice : 12/09/2024 OdomIn: 606,173 OdomOut: 606,183

Component Serial Number

VIN

223210

473909C0613593

W1T96342420499863

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

13/08/2021

Sold Operations

OpsId : 4 Job : 15

OIL LEVEL AND OIL PRESSURE FAULTS PRESENT.

Cause :

Correction : COMPLAINT:

1.00	PRESSURE TRANSDUCER	122.51	122.51
0.00	OIL PRESSURE SENSOR	223.77	0.00
0.00	CLAYTONS RACK	0.00	0.00
1.00	SEALING RING	4.07	4.07
1.00	OIL PRESSURE SENSOR	223.77	223.77
1.00	Adjust Parts Price [[Warranty Only]]	0.01	0.01

SlId : RA920028415:01 Total : \$12,829.76

Date Invoice : 11/30/2024

OdomIn: 606,173

OdomOut: 606,183

223210

473909C0613593

W1T96342420499863

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

13/08/2021

Sold Operations

OpsId : 1 Job : BD ATTEND BREAKDOWN- Location Address: Warrego Hwy; Opposite Costc
 Cause : done
 Correction : C:Serpentine Belt Damage

OpsId : 2 Job : 90 CONTINUE FROM BREAKDOWN
 Cause : Robbed part coming in
 Correction : CAUSE:

1.00	BELT TENSIONER	815.45	815.45
1.00	POLY V BELT	73.38	73.38
1.00	POLY V BELT	142.31	142.31
0.00	bring to aidan - breakdown	0.00	0.00
1.00	MAJOR ASSEMBLY CARRIER	437.50	437.50
1.00	THREE PHASE ALTERNATOR	1,886.76	1,886.76
1.00	CORE - THREE PHASE ALTERNATOR	319.12	319.12
0.00	CORE MUST BE CLEANED AND RETURNED IN ORIGINAL PACKAGING	0.00	0.00
2.00	GUIDE PULLEY	118.61	237.22
1.00	COOLANT PUMP	517.53	517.53
1.00	CORE - COOLANT PUMP	89.56	89.56
0.00	CORE MUST BE CLEANED AND RETURNED IN ORIGINAL PACKAGING	0.00	0.00
0.00	SEAL	46.66	0.00
1.00	SUCTION LINE	605.09	605.09
1.00	REFRIGERANT LINE	222.37	222.37
1.00	FILTER DRYER	340.61	340.61
1.00	VISCOUS CLUTCH	1,585.22	1,585.22
1.00	HOLDER	32.47	32.47
1.00	PARTS KIT PLUG	138.73	138.73
0.00	SUPPLY UNIT	2,345.35	0.00
0.00	CORE - SUPPLY UNIT	383.82	0.00
0.00	CORE MUST BE CLEANED AND RETURNED IN ORIGINAL PACKAGING	0.00	0.00
1.00	METERING UNIT	1,923.73	1,923.73
1.00	CORE - METERING UNIT	324.85	324.85
0.00	CORE MUST BE CLEANED AND RETURNED IN ORIGINAL PACKAGING	0.00	0.00
0.00	STAGE ROOM PLEASE	0.00	0.00
4.00	FLAT SEAL	16.64	66.56
4.00	FLAT SEAL	21.69	86.76
4.00	FLAT SEAL	18.68	74.72
4.00	FLAT SEAL	15.83	63.32
0.00	HCV BAY #10	0.00	0.00
40.00	COOLANT - ALLIANCE PRIMECOOL GP P-40 (205L) - QABP AFM4604205	6.21	248.40
0.93	R134A AC GAS	90.00	83.70
-1.00	CORE - THREE PHASE ALTERNATOR	319.12	-319.12
-1.00	CORE - COOLANT PUMP	89.56	-89.56

Component Serial Number

VIN

223210

473909C0613593

W1T96342420499863

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

13/08/2021

Sold Operations (Cont.)

-1.00 CORE - METERING UNIT

324.85

-324.85

1.00 Adjust Parts Price [[Warranty Only]]

59.43

59.43

SlsId : RA920022461:01 Total : \$8,986.16

Date Invoice : 04/19/2024

OdomIn: 0

OdomOut: 469,867

223210

473909C0613593

W1T96342420499863

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

13/08/2021

Sold Operations

OpsId : 1 Job : 00 Glue LHS Mirror covers on – top one in cab, needs new lower one.

Cause : LHS mirror covers fell off due to road vibration

Correction : used scissor lift to reach mirror cover mount

1.00 **COVER BOTTOM LEFT** 44.79 44.79

0.00 **Bay 11** 0.00 0.00

OpsId : 2 Job : 00 Check and report on Top of LHS Door – air leak / whistle noise.

Cause : Door seal split and allowing bypass of air into cab

Correction : Took vehicle on long drive to get up to sufficient speeds

OpsId : 3 Job : 00 Check / quote LHS bottom step.

Cause : LHS bottom step impact damaged

Correction : inspected LHS bottom step

OpsId : 6 Job : 00 RHS Teflon Turntable pad missing.

Cause : RHS teflon turntable pad missing. left hand rising off plate

Correction : cleaned out turntable pad bolt

OpsId : 8 Job : 00 Check / quote RHS steer guard

Cause : All panel quoting done on job line 3

Correction :

OpsId : 9 Job : 00 RHS Door Strap & STEP – check & quote

Cause : all panel quoting done on job line 3

Correction :

OpsId : 11 Job : 00 Remove radiator & intercooler – clean out cotton seed

Cause : FOREIGN MATTER

Correction : CORRECTION: REMOVED FAN HUB AND FAN BLADE,

1.00 **GASKET** 62.13 62.13

2.00 **FULL FACE GASKET** 15.15 30.30

2.00 **FULL FACE GASKET** 16.78 33.56

2.00 **FULL FACE GASKET** 20.98 41.96

2.00 **FULL FACE GASKET** 18.79 37.58

OpsId : 12 Job : 00 Wheel alignment – please check over all suspension bushes & shockies fr

Cause : customer request

Correction : Inspected all suspension bushes and shock absorbers. all ok

OpsId : 13 Job : 00 Front fog lights turn off directional fog lights & fog light activation.

Cause :

Correction : C: disable front fog light fault detection

OpsId : 14 Job : 00 Remove front wheel hub caps – just fit STD benz nut covers.

Cause : customer request

Correction : ordered left front tyre benz nut covers

10.00 **COVERING** 15.59 155.90

0.00 **HCV BAY #11** 0.00 0.00

223210

473909C0613593

W1T96342420499863

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

13/08/2021

Sold Operations (Cont.)

OpsId : 25 Job : 60 RH steer gaurd & step repairs

Cause :

Correction : C - Rh steer guard & step repairs

1.00	ENTRANCE - BOTTOM RIGHT	594.10	594.10
1.00	HINGED DOOR	86.90	86.90
0.00	EX MELB	0.00	0.00
2.00	FOOTPLATE L & R SHORT	37.03	74.06
1.00	FOOTPLATE	44.82	44.82
1.00	FOOTPLATE	44.82	44.82
4.00	EXPANSION RIVET	5.65	22.60
1.00	FENDER	338.18	338.18
1.00	FENDER	261.84	261.84
1.00	SPLASH GUARD MAT	206.79	206.79
1.00	SPLASH GUARD	120.78	120.78
14.00	EXPANSION RIVET	5.65	79.10
0.00	BAY 10	0.00	0.00
4.00	RAISED HEAD SCREW FOR PL.	1.31	5.24
5.00	HEXAGON HEAD BOLT	5.67	28.35
0.00	BAY 10	0.00	0.00

OpsId : 26 Job : 60 Quote LHS bottom step.

Cause :

Correction : Inspected and quoted repairs for LHS step/gaurd assembly

1.00	ENTRANCE - BOTTOM LEFT	565.43	565.43
0.00	EX MELB	0.00	0.00
1.00	HINGED DOOR	86.90	86.90
0.00	EX MELB	0.00	0.00
2.00	EXPANSION RIVET	5.65	11.30
2.00	FOOTPLATE L & R SHORT	37.03	74.06
1.00	FOOTPLATE	44.82	44.82
1.00	FOOTPLATE	44.82	44.82

OpsId : 27 Job : ASR Door seal replacement (relevent to job # 2)

Cause :

Correction : C: LH door seal perished and split

1.00	DOOR SEAL	295.78	295.78
0.00	In Stock	0.00	0.00

SIId : RA920022456:01 Total : \$871.85

Date Invoice : 04/19/2024

OdomIn: 469,867

OdomOut: 469,867

223210

473909C0613593

W1T96342420499863

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

13/08/2021

Sold Operations

OpsId : 4 Job : 00 AD Blue tank – check breather – Tank sucked in.

Cause : tank sucked in, quoted new parts, truck to be rebooked

Correction : C: inspected truck. found tank to be sucked in

OpsId : 5 Job : 00 Check all fuel tank rubbers – LHS missing.

Cause : loss of tension in bolt caused rubber to fall out

Correction : inspected fuel tank straps

1.00 **PAD** 99.61 99.610.00 **HCV BAY #10** 0.00 0.00

OpsId : 7 Job : 00 Move tank forward RHS – RUBBNG ON DRIVE GUARD

Cause : tank rubbing on guard

Correction : loosened tank strap.

OpsId : 15 Job : 00 Bump idle up – blowing headlights.

Cause : DONE

Correction : - C: No fault found

OpsId : 22 Job : 60 Rear cab bushes perished

Cause :

Correction : CAUSE: EXCESSIVE MOVEMENT IN ELASTOMER BUSHES CAUSING KNOCK IN CAB

2.00 **ELASTOMER BEARING** 21.62 43.240.00 **Quick Repair Shelf** 0.00 0.00**Rejected Operations**

OpsId : 19 Job : 49 Adblue tank repairs

Cause :

Correction :

1.00 **110 LITRE ADBLUE TANK** 1,822.71 1,822.710.00 **EX MELB** 0.00 0.00

SIsId : RA920022455:01 Total : -\$10,738.06

Date Invoice : 04/19/2024

OdomIn: 469,867

OdomOut: 469,867

223210

473909C0613593

W1T96342420499863

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

13/08/2021

Sold Operations

OpsId : 1 Job : 00 Glue LHS Mirror covers on – top one in cab, needs new lower one.

Cause : LHS mirror covers fell off due to road vibration

Correction : used scissor lift to reach mirror cover mount

-1.00 **COVER BOTTOM LEFT** 45.59 -45.59

0.00 **Bay 11** 0.00 0.00

OpsId : 2 Job : 00 Check and report on Top of LHS Door – air leak / whistle noise.

Cause : Door seal split and allowing bypass of air into cab

Correction : Took vehicle on long drive to get up to sufficient speeds

OpsId : 3 Job : 00 Check / quote LHS bottom step.

Cause : LHS bottom step impact damaged

Correction : inspected LHS bottom step

OpsId : 4 Job : 00 AD Blue tank – check breather – Tank sucked in.

Cause : tank sucked in, quoted new parts, truck to be rebooked

Correction : C: inspected truck. found tank to be sucked in

OpsId : 5 Job : 00 Check all fuel tank rubbers – LHS missing.

Cause : loss of tension in bolt caused rubber to fall out

Correction : inspected fuel tank straps

-1.00 **PAD** 106.99 -106.99

0.00 **HCV BAY #10** 0.00 0.00

OpsId : 6 Job : 00 RHS Teflon Turntable pad missing.

Cause : RHS teflon turntable pad missing. left hand rising off plate

Correction : cleaned out turntable pad bolt

OpsId : 7 Job : 00 Move tank forward RHS – RUBBING ON DRIVE GUARD

Cause : tank rubbing on guard

Correction : loosened tank strap.

OpsId : 8 Job : 00 Check / quote RHS steer guard

Cause : All panel quoting done on job line 3

Correction :

OpsId : 9 Job : 00 RHS Door Strap & STEP – check & quote

Cause : all panel quoting done on job line 3

Correction :

OpsId : 11 Job : 00 Remove radiator & intercooler – clean out cotton seed

Cause : FOREIGN MATTER

Correction : CORRECTION: REMOVED FAN HUB AND FAN BLADE,

-1.00 **GASKET** 66.99 -66.99

-2.00 **FULL FACE GASKET** 17.09 -34.18

-2.00 **FULL FACE GASKET** 17.99 -35.98

-2.00 **FULL FACE GASKET** 23.39 -46.78

-2.00 **FULL FACE GASKET** 21.19 -42.38

223210

473909C0613593

W1T96342420499863

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

13/08/2021

Sold Operations (Cont.)

OpsId : 12 Job : 00 Wheel alignment – please check over all suspension bushes & shockies fr
 Cause : customer request
 Correction : Inspected all suspension bushes and shock absorbers. all ok

OpsId : 13 Job : 00 Front fog lights turn off directional fog lights & fog light activation.
 Cause :
 Correction : C: disable front fog light fault detection

OpsId : 14 Job : 00 Remove front wheel hub caps – just fit STD benz nut covers.
 Cause : customer request
 Correction : ordered left front tyre benz nut covers

-10.00	COVERING	15.99	-159.90
0.00	HCV BAY #11	0.00	0.00

OpsId : 15 Job : 00 Bump idle up – blowing headlights.
 Cause : DONE
 Correction : - C: No fault found

OpsId : 22 Job : 60 Rear cab bushes perished
 Cause :
 Correction : CAUSE: EXCESSIVE MOVEMENT IN ELASTOMER BUSHES CAUSING KNOCK IN CAB

-2.00	ELASTOMER BEARING	25.69	-51.38
0.00	Quick Repair Shelf	0.00	0.00

OpsId : 25 Job : 60 RH steer gaurd & step repairs
 Cause :
 Correction : C - Rh steer guard & step repairs

-1.00	ENTRANCE - BOTTOM RIGHT	637.49	-637.49
-1.00	HINGED DOOR	97.99	-97.99
0.00	EX MELB	0.00	0.00
-2.00	FOOTPLATE L & R SHORT	39.69	-79.38
-1.00	FOOTPLATE	47.99	-47.99
-1.00	FOOTPLATE	47.99	-47.99
-4.00	EXPANSION RIVET	6.08	-24.32
-1.00	FENDER	362.49	-362.49
-1.00	FENDER	294.99	-294.99
-1.00	SPLASH GUARD MAT	232.49	-232.49
-1.00	SPLASH GUARD	129.99	-129.99
-14.00	EXPANSION RIVET	6.08	-85.12
0.00	BAY 10	0.00	0.00
-4.00	RAISED HEAD SCREW FOR PL.	1.39	-5.56
-5.00	HEXAGON HEAD BOLT	5.67	-28.35
0.00	BAY 10	0.00	0.00

OpsId : 26 Job : 60 Quote LHS bottom step.
 Cause :
 Correction : Inspected and quoted repairs for LHS step/gaurd assembly

Component Serial Number

VIN

223210

473909C0613593

W1T96342420499863

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

13/08/2021

Sold Operations (Cont.)

-1.00	ENTRANCE - BOTTOM LEFT	637.49	-637.49
0.00	EX MELB	0.00	0.00
-1.00	HINGED DOOR	97.99	-97.99
0.00	EX MELB	0.00	0.00
-2.00	EXPANSION RIVET	6.08	-12.16
-2.00	FOOTPLATE L & R SHORT	39.69	-79.38
-1.00	FOOTPLATE	47.99	-47.99
-1.00	FOOTPLATE	47.99	-47.99

OpsId : 27 Job : ASR Door seal replacement (relevent to job # 2)

Cause :

Correction : C: LH door seal perished and split

-1.00	DOOR SEAL	332.49	-332.49
0.00	In Stock	0.00	0.00

Rejected Operations

OpsId : 19 Job : 49 Adblue tank repairs

Cause :

Correction :

-1.00	110 LITRE ADBLUE TANK	2,049.99	-2,049.99
0.00	EX MELB	0.00	0.00

SIsId : RA920018152:03 Total : \$25.00

Date Invoice : 12/28/2023

OdomIn: 469,867

OdomOut: 469,867

Sold Operations

OpsId : 23 Job : 22 A4 Rh lower airbag clip missing

Cause : Parts never recieved

Correction :

0.00	SPRING SHEET METAL LOCK	1.73	0.00
0.00	SMALL CLIP - BOTTOM	0.00	0.00
1.00	FREIGHT 445	25.00	25.00
0.00	SPRING SHEET METAL LOCK	1.73	0.00
0.00	SMALL CLIP - BOTTOM	0.00	0.00

SIsId : RA920018152:02 Total : \$10,738.06

Date Invoice : 12/22/2023

OdomIn: 469,867

OdomOut: 469,867

223210

473909C0613593

W1T96342420499863

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

13/08/2021

Sold Operations

OpsId : 1 Job : 00 Glue LHS Mirror covers on – top one in cab, needs new lower one.

Cause : LHS mirror covers fell off due to road vibration

Correction : used scissor lift to reach mirror cover mount

1.00 **COVER BOTTOM LEFT** 45.59 45.59

0.00 **Bay 11** 0.00 0.00

OpsId : 2 Job : 00 Check and report on Top of LHS Door – air leak / whistle noise.

Cause : Door seal split and allowing bypass of air into cab

Correction : Took vehicle on long drive to get up to sufficient speeds

OpsId : 3 Job : 00 Check / quote LHS bottom step.

Cause : LHS bottom step impact damaged

Correction : inspected LHS bottom step

OpsId : 4 Job : 00 AD Blue tank – check breather – Tank sucked in.

Cause : tank sucked in, quoted new parts, truck to be rebooked

Correction : C: inspected truck. found tank to be sucked in

OpsId : 5 Job : 00 Check all fuel tank rubbers – LHS missing.

Cause : loss of tension in bolt caused rubber to fall out

Correction : inspected fuel tank straps

1.00 **PAD** 106.99 106.99

0.00 **HCV BAY #10** 0.00 0.00

OpsId : 6 Job : 00 RHS Teflon Turntable pad missing.

Cause : RHS teflon turntable pad missing. left hand rising off plate

Correction : cleaned out turntable pad bolt

OpsId : 7 Job : 00 Move tank forward RHS – RUBBING ON DRIVE GUARD

Cause : tank rubbing on guard

Correction : loosened tank strap.

OpsId : 8 Job : 00 Check / quote RHS steer guard

Cause : All panel quoting done on job line 3

Correction :

OpsId : 9 Job : 00 RHS Door Strap & STEP – check & quote

Cause : all panel quoting done on job line 3

Correction :

OpsId : 11 Job : 00 Remove radiator & intercooler – clean out cotton seed

Cause : FOREIGN MATTER

Correction : CORRECTION: REMOVED FAN HUB AND FAN BLADE,

1.00 **GASKET** 66.99 66.99

2.00 **FULL FACE GASKET** 17.09 34.18

2.00 **FULL FACE GASKET** 17.99 35.98

2.00 **FULL FACE GASKET** 23.39 46.78

2.00 **FULL FACE GASKET** 21.19 42.38

223210

473909C0613593

W1T96342420499863

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

13/08/2021

Sold Operations (Cont.)

OpsId : 12 Job : 00 Wheel alignment – please check over all suspension bushes & shockies fr
 Cause : customer request
 Correction : Inspected all suspension bushes and shock absorbers. all ok

OpsId : 13 Job : 00 Front fog lights turn off directional fog lights & fog light activation.
 Cause :
 Correction : C: disable front fog light fault detection

OpsId : 14 Job : 00 Remove front wheel hub caps – just fit STD benz nut covers.
 Cause : customer request
 Correction : ordered left front tyre benz nut covers

10.00	COVERING	15.99	159.90
0.00	HCV BAY #11	0.00	0.00

OpsId : 15 Job : 00 Bump idle up – blowing headlights.
 Cause : DONE
 Correction : - C: No fault found

OpsId : 22 Job : 60 Rear cab bushes perished
 Cause :
 Correction : CAUSE: EXCESSIVE MOVEMENT IN ELASTOMER BUSHES CAUSING KNOCK IN CAB

2.00	ELASTOMER BEARING	25.69	51.38
0.00	Quick Repair Shelf	0.00	0.00

OpsId : 25 Job : 60 RH steer gaurd & step repairs
 Cause :
 Correction : C - Rh steer guard & step repairs

1.00	ENTRANCE - BOTTOM RIGHT	637.49	637.49
1.00	HINGED DOOR	97.99	97.99
0.00	EX MELB	0.00	0.00
2.00	FOOTPLATE L & R SHORT	39.69	79.38
1.00	FOOTPLATE	47.99	47.99
1.00	FOOTPLATE	47.99	47.99
4.00	EXPANSION RIVET	6.08	24.32
1.00	FENDER	362.49	362.49
1.00	FENDER	294.99	294.99
1.00	SPLASH GUARD MAT	232.49	232.49
1.00	SPLASH GUARD	129.99	129.99
14.00	EXPANSION RIVET	6.08	85.12
0.00	BAY 10	0.00	0.00
4.00	RAISED HEAD SCREW FOR PL.	1.39	5.56
5.00	HEXAGON HEAD BOLT	5.67	28.35
0.00	BAY 10	0.00	0.00

OpsId : 26 Job : 60 Quote LHS bottom step.
 Cause :
 Correction : Inspected and quoted repairs for LHS step/gaurd assembly

Component Serial Number

VIN

223210

473909C0613593

W1T96342420499863

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

13/08/2021

Sold Operations (Cont.)

1.00	ENTRANCE - BOTTOM LEFT	637.49	637.49
0.00	EX MELB	0.00	0.00
1.00	HINGED DOOR	97.99	97.99
0.00	EX MELB	0.00	0.00
2.00	EXPANSION RIVET	6.08	12.16
2.00	FOOTPLATE L & R SHORT	39.69	79.38
1.00	FOOTPLATE	47.99	47.99
1.00	FOOTPLATE	47.99	47.99

OpsId : 27 Job : ASR Door seal replacement (relevent to job # 2)

Cause :

Correction : C: LH door seal perished and split

1.00	DOOR SEAL	332.49	332.49
0.00	In Stock	0.00	0.00

Rejected Operations

OpsId : 19 Job : 49 Adblue tank repairs

Cause :

Correction :

1.00	110 LITRE ADBLUE TANK	2,049.99	2,049.99
0.00	EX MELB	0.00	0.00

SIsId : RA920018152:01 Total : \$4,102.63

Date Invoice : 12/20/2023

OdomIn: 469,867

OdomOut: 469,867

Component Serial Number

VIN

223210

473909C0613593

W1T96342420499863

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

13/08/2021

Sold Operations

OpsId : 16 Job : 00 check & carry out any service items as required

Cause :

Correction : CARRY OUT MAINTENANCE INSPECTION;

1.00	FILTER PACKAGE	69.95	69.95
1.00	SCREW PLUG	36.50	36.50
1.00	TS FUEL FILTER	193.07	193.07
1.00	SEPERATOR FILTER CARTRIDGE	165.54	165.54
1.00	AIR FILTER INSERT	335.68	335.68
2.00	AIR FILTER	61.21	122.42
1.00	STEERING FILTER ELEMENT	12.43	12.43
1.00	ADBLUE FILTER ELEMENT	156.68	156.68
1.00	DUST FILTER	90.62	90.62
1.00	TS DPF	832.69	832.69
1.00	CORE - TS DPF	1,942.95	1,942.95
0.00	CORE MUST BE CLEANED AND RETURNED IN ORIGINAL PACKAGING	0.00	0.00
0.00	CLAYTONS RACK	0.00	0.00
1.00	KIT ADBLUE FILTER	31.61	31.61
1.00	AIR DRIER FILTER ELEMENT	143.00	143.00
0.00	PIT 2	0.00	0.00
1.00	TS WIPER BLADE	62.73	62.73
1.00	IN FREIGHT 479	25.00	25.00
-1.00	CORE - PARTS KIT, PARTICUL FIL	1,942.95	-1,942.95
1.00	WORKSHOP SUNDRIES	50.00	50.00
1.00	HAZ WASTE & ENVIRO DISPOSAL	16.00	16.00
40.00	ENGINE - ALLIANCE PRIME ENGINE GLOBAL 10W40 (205L) - QABP AFM4982	8.03	321.20
-1.00	Adjust Parts Price [[Warranty Only]]	24.92	-24.92

SIsId : RA920006876:01 Total : \$1,172.78

Date Invoice : 11/11/2022

OdomIn: 269,745

OdomOut: 269,750

Sold Operations

OpsId : 1 Job : 32 STEERING WANDERING & TRUCK DRIFTING OVER THE ROAD

Cause : FRONT SHOCK ABSORBERS INTERALLY BYPASSING (OVERHEATING AFTER 2-3 HOURS DF

Correction : Drove truck in

2.00	SHOCK ABSORBER	429.64	859.28
------	-----------------------	--------	--------

SIsId : RA920005713:03 Total : \$143.24

Date Invoice : 10/20/2022

OdomIn: 247,671

OdomOut: 247,671

223210

473909C0613593

W1T96342420499863

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

13/08/2021

Sold Operations

OpsId : 4 Job : 60 INSPECT AND REPORT ON KNOCKING NOISE
 Cause : Done JB - WORN RUBBER COMPONENTS NOT COVERED BY WARRANTY
 Correction : CAUSE - CAB BUSHES PERISHED ALLOWING KNOCKING NOISE TO BE PRESENT;
 2.00 ELASTOMER BEARING 22.13 44.26
 -1.00 Adjust Parts Cost [[Warranty Only]] 0.02 -0.02

SIsId : RA920005713:02 Total : \$686.25

Date Invoice : 10/19/2022

OdomIn: 247,671

OdomOut: 247,671

Sold Operations

OpsId : 5 Job : 47 FUEL TANK LEAKING.
 Cause : Done JB
 Correction : C-FUEL TANK LEAKING.

SIsId : RA920005713:01 Total : \$2,065.51

Date Invoice : 09/30/2022

OdomIn: 247,671

OdomOut: 247,671

Sold Operations

OpsId : 1 Job : 00 CARRY OUT SERVICE AS PER DATA SHEET & HISTORY
 Cause : SERVICE DUE
 Correction : CARRIED OUT SERVICE AS PER SERVICE SHEET
 1.00 FILTER PACKAGE 64.65 64.65
 1.00 SCREW PLUG 34.61 34.61
 1.00 TS FUEL FILTER 179.80 179.80
 1.00 FILTER CARTRIDGE 150.77 150.77
 1.00 DUST FILTER 86.55 86.55
 2.00 AIR FILTER 57.83 115.66
 2.00 RING,GENERAL,METAL 2.55 5.10
 1.00 TS WIPER BLADE 59.97 59.97
 39.00 ENGINE - ALLIANCE PRIME ENGINE GLOBAL 10W40 (205L) - QABP AFM4982: 8.03 313.17
 12.00 GEAR OIL - ALLIANCE PRIME TRANS PLUS MB 75W90 (205L) - QABP AFM430 22.15 265.80
 5.00 COOLANT - ALLIANCE PRIMECOOL GP P-40 (205L) - QABP AFM4604205 5.37 26.85
 41.00 HAZ WASTE & ENVIRO DISPOSAL 0.40 16.40
 4.90 CONSUMABLES 7.25 35.53
 OpsId : 3 Job : 67 Wiper Blades streaking.
 Cause : Done JB - CLAIMED ON SERVICE
 Correction : C - WIPER BLADES STREAKING

SIsId : RA920003268:02 Total : \$274.55

Date Invoice : 07/19/2022

OdomIn: 204,282

OdomOut: 204,283

Sold Operations

OpsId : 1 Job : 00 200K INSPECTION SERVICE
 Cause : Done KG
 Correction : 200K inspection service.
 1.00 MISC SHOP SUPPLIES 13.55 13.55

Component Serial Number

VIN

223210

473909C0613593

W1T96342420499863

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

13/08/2021

SlId : RA920003268:01 Total : \$1,431.58

Date Invoice : 07/05/2022

OdomIn: 204,282

OdomOut: 204,283

Sold Operations

OpsId : 2 Job : 67

SUBLET TO REPLACE WINDSCREEN

Cause :

Correction :

1.00 WINDSHIELD

959.99

959.99

SlId : RA920002000:03 Total : \$0.00

Date Invoice : 06/21/2022

OdomIn: 179,402

OdomOut: 179,402

Rejected Operations

OpsId : 2 Job : 00

Quote parts

Cause :

Correction :

1.00 INDERCATOR LIGHT LED

48.29

48.29

0.00 IN STOCK

0.00

0.00

1.00 WINDSHIELD

959.99

959.99

0.00 IN STOCK

0.00

0.00

1.00 CU, DISTANCE SENSOR

5,767.49

5,767.49

0.00 BORDER GERMANY!@!@!@!

0.00

0.00

SlId : RA920002000:01 Total : \$2,110.23

Date Invoice : 05/26/2022

OdomIn: 179,402

OdomOut: 179,402

Sold Operations

OpsId : 1 Job : 00

ENGINE SERVICE?? - BEST BASIC

Cause : Done JB

Correction : CORRECTION:

1.00 FILTER PACKAGE

63.39

63.39

1.00 TS FUEL FILTER

176.26

176.26

1.00 SCREW PLUG

33.94

33.94

1.00 FILTER CARTRIDGE

147.83

147.83

2.00 AIR FILTER

54.97

109.94

1.00 AIR FILTER INSERT

315.54

315.54

1.00 DUST FILTER

84.81

84.81

1.00 TS WIPER BLADE

58.81

58.81

2.00 BULB P21/5W 24V

3.25

6.50

1.00 WORKSHOP SUNDRIES

19.60

19.60

40.00 Engine-ALLIANCE PRIME ENGINE GLOBAL 10W40-PUMP IN

7.14

285.60

5.00 Gear-ALLIANCE PRIME AXLE PLUS 235.8 75W90-PUMP IN

17.16

85.80

4.00 Coolant-ALLIANCE PRIMECOOL GP P-40-205L DRUM

5.16

20.64

1.00 HAZ WASTE & ENVIRO DISPOSAL

33.40

33.40